Occurrence Summaries 01/01/2017 to 31/12/2017 Region(s): All Club:



Christopher Thorpe Executive Manager, Operations The Gliding Federation of Australia Inc.

31-Dec-2017



The Gliding SOAR Accident	The Gliding Federation of Australia Inc SOAR Accident and Incident Occurrences								
General Statistics									
Date From:	Date From: 01/01/2017								
Date to:	31/12/2017								

VSA NSWGA GQ SAGA WAGA Tota Nil 41 33 26 35 11 14 Substantial 5 6 5 1 3 26 Minor 14 11 13 5 3 4 Write-off 4 2 2 3 4
Nil 41 33 26 35 11 14 Substantial 5 6 5 1 3 2 Minor 14 11 13 5 3 4 Write-off 4 2 4 2 4
Substantial 5 6 5 1 3 2 Minor 14 11 13 5 3 4 Write-off 4 2 2 4 2 4
Minor 14 11 13 5 3 4 Write-off 4 2 2 4 2 4 2 4 2 4 3 4 3 4 3 4 3 4
Write-off 4 2
Total 64 50 46 41 17 21
Injury
VSA NSWGA GQ SAGA WAGA Tota
Nil 59 48 42 41 16 20
Serious 1
Minor 1 2 3 1
Fatal 3 1
Total 64 50 46 41 17 21
Phases
VSA NSWGA GQ SAGA WAGA Tota
Launch 12 13 6 10 4
Landing 23 12 23 7 4 6
Thermalling 4 1 3 1 3 1
In-Flight 15 18 9 17 6 6
Ground Ops 7 4 4 5 1 2
Outlanding 2 2 1 1 3
Type of Flight
VSA NSWGA GQ SAGA WAGA Tota
Local 22 19 20 15 6 8
Cross-Country 8 4 3 4 4 2
Competition 14 6 1 5 5 3
Training/Coaching 12 15 16 11 1 5
Ground Ups 5 4 4 5 1 1
ALF 3 2 2 1 Total 64 50 46 41 17 21



The Gliding Federation of Australia Inc SOAR Accident and Incident Occurrences **Classification Level 1** 01/01/2017 Date From: 31/12/2017 Date to:

Level 1	

	VAG	VSA	SAGA I	SWG.	GQ	Total
Airspace	7	18	11	14	7	57
Consequential Events	2	3	3			8
Environment			1	1		2
Operational	7	41	22	31	34	135
Technical	1	2	4	4	5	16
Total	17	64	41	50	46	218





The Gliding Federation of Australia Inc SOAR Accident and Incident Occurrences Classification Level 2 Date From: 01/01/2017 Date to: 31/12/2017

Level 2						
	GQ	NSWGA	SAGA	VSA	WAGA	Total
Aircraft Control	11	5	3	10	4	33
Aircraft Loading	1					1
Aircraft Separation	7	11	8	14	5	45
Airframe	4	8	4	6		22
Airspace Infringement		3	3	4	2	12
Communications		2	1	1		4
Crew and Cabin Safety	1			1		2
Fire Fumes and Smoke			1			1
Flight Preparation/Navigation	1	1	5	3		10
Fuel Related		1	1	1		3
Ground Operations	3	3	2	5	1	14
Low Circuit			3	3	2	8
Miscellaneous	1	6	2	3		12
Powerplant/Propulsion	1	3	2			6
Runway Events	6	2	3	9		20
Systems	4	1	2	2	1	10
Terrain Collisions	6	3		2	2	13
Wildlife		1	1			2
Total	46	50	41	64	17	218





The Gliding Federation of Australia Inc SOAR Accident and Incident Occurrences Classification Level 3 Date From: 01/01/2017 Date to: 31/12/2017

Level 3

	GQ	NSWGA	SAGA	VSA	WAGA	Total
Abnormal Engine Indications			1			1
Aircraft preparation	1	1		2		4
Aircraft Separation Issues	3	6	2	4		15
Airspace Infringement		3	3	4	2	12
Birdstrike		1	1			2
Collision				2		2
Collision with terrain	1	2		2		5
Control issues	2			2	1	5
Controlled flight into terrain	3				1	4
Depart/App/Land wrong runway		1				1
Doors/Canopies	1	1	2	2		6
Electrical			1			1
Engine failure or malfunction		2	1			3
Exhaustion		1	1			2
Fire			1			1
Flight controls	2		1	1	1	5
Flight crew incapacitation				1		1
Furnishings & fittings				1		1
Fuselage/Wings/Empennage		3	2			5
Ground handling	1			1		2
Ground strike	2	1			1	4
Hard landing	7	3	1	2	1	14
Hydraulic				1		1
Incorrect configuration		1	1			2



Inter-crew communications	1					1
Landing gear/Indication	1	4		3		8
Loading related	1					1
Loss of control				2		2
Low Circuit			3	3	2	8
Near collision	4	5	6	8	5	28
Objects falling from aircraft	1					1
Other Airframe Issues	1					1
Other Communications Issues		2	1	1		4
Other Flight Prep/Nav Issues			5	1		6
Other Ground Ops Issues	1			1		2
Other Miscellaneous	1	1	2	3		7
Other Runway Events			1	3		4
Other Systems Issues	2	1				3
Pilot Induced Oscillations			1			1
Propeller malfunction	1					1
Rope break/Weak link failure		1				1
Rope/Rings Airframe Strike		3				3





Accident and Incident Summaries

Date	1-Jan-2017	Regior	1		NSWGA		SOA	AR Repo	ort Nbr		S-	0885
Level 1	Operational		Leve	12	A	∖irfran	ne		Level	3	Landing	
											gear/Indic	ation
A/C Mod	el 1		IMC A	-9A	Callair		A/C	Model	2			
Injury	Nil	Dama	age	Su	bstantial	Pha	se	Launo	h		PIC Age	59
While un	der aerotow and	just as t	he tow	ving	combinati	i <mark>on h</mark> a	d left	the gr	ound th	ne coi	mmand pilo	t in the
glider not	ticed the right m	ain landi	ng gea	r of	the tow p	lane h	ad co	ome ad	rift and	was	hanging dov	wn. The
glider pilo	ot informed the t	tow pilot	of the	e pro	blem, whe	ereupo	on th	e comb	ination	towe	ed to a heig	ht where the
glider cou	uld safely release	e. The tov	v pilot	ele	cted to lan	d at a	near	by Reg	ional A	irport	where eme	ergency
services v	vere available ar	nd alerted	d the c	cont	rol tower.	The to	ow pi	lot was	cleare	d to l	and and ma	de an
engine-of	ff landing. The to	w plane	touch	ed d	lown on th	e left	main	gear a	nd gen	tly se	ttled onto t	he right main
gear, whe	ereupon the tow	plane ge	ntly tu	urne	d through	180 d	egre	es. The	pilot w	as ur	hurt and th	e aircraft
suffered	minor damage to	o the righ	t mair	n gea	ar, and the	unde	rside	of the	right w	ing a	nd aileron.	The aircraft
was remo	oved from the ru	nway by	aerod	rom	e staff and	1 subs	eque	ntly tra	insport	ed to	a maintena	nce facility
by flatbe	d truck. Subsequ	ent inspe	ection	reve	ealed a bac	lly we	lded	joint fr	om a p	revio	us repair to	the shock
absorber	strut had failed,	allowing	the le	eg to	separate.							
1				1	1	-	_	4	-2.0-		2.	Cashi yang yang yang yang yang yang yang yang
W W	Carly Carly					-		- Sealt	and the		A COL	The State
and states		-	-1					-		-	a series and	and heard streams
- de la	store a						-	1		1		Part Contractor
-											1	and the second second
A COL					-		-	"		~	Statutes:	THE REAL FRANCE
	a Blog								-			Califie - March
	MARCH STOR		-	2	The state of the s					A	And States	and a strange of
				-						V	and a set	and the second s
1000		-	25.			-	-	-			and the state	A STATE OF
								1. A.	1412.00			
									-	-		
					America M	1	1	-				and the second s
												and the second
		ALADS										and the second
			12		The second		5				an atter	1
	A A A A A A A A A A A A A A A A A A A				State State State	200		Total Common				The same of the sa
Start C		Minuter -	100		Contraction of	and the second	一	TT	- Free	Service.	ATT COMMENT	Contra 12
	A REAL PROPERTY AND A REAL				No. of Lot of Lo	and the second se	100		and the second second	and the second s	the second se	the second s

Date	1-Jan-2017	Regior	1	GQ			SOAR Report Nbr				S-	0890
Level 1	Operational		Leve	el 2 Runway E			vent	ents Level 3			Runway excursion	
A/C Model 1			Ven	tus-2	2cM		A/C	Model	2			
Injury	Nil	Dama	age	Nil Pł		Pha	se Landing		ng		PIC Age	74

The pilot arrived back at the home airfield after a cross-country flight at about 4,000 ft AMSL. While descending to crosswind circuit height there was a significant wind change consequent of a large thunderstorm to the south-east of the airfield. The pilot landed with about 20 knots tailwind component resulting in the aircraft entering the run-off area at the end of the runway. No damage was done to the aircraft or property. Investigation revealed the pilot had not flown much in the previous 12 months and was lacking currency.



Date	2-Jan-2017	Region		NSWGA		SOA	R Repo	ort Nbr	S	-0897
Level 1	Operational		Level 2	Run	way E	vents	5	Level 3	Depart/A	pp/Land
									wrong rur	าพลง
A/C Mode	el 1	Pi	latus B4-	PC11AF		A/C	Model	2	-	
Injury	Nil	Dama	ge	Nil	Pha	ise	Landi	ng	PIC Age	69
The pilot	misidentified the	runway a	and calle	d landing o	on one	e runv	way wh	ile intending	g to land els	sewhere. The
pilot calle	d joining downw	ind for th	ne operat	ional runw	ay 18	while	e positi	oned south-	west of the	airport
(refer dia	gram). While obs	ervers in	itially tho	ought the p	ilot w	as co	nductii	ng a right-ha	nd circuit, t	the pilot
headed in	a north-easterly	/ directio	n and cro	ssed runwa	ay 18	midfi	eld los	ing a lot of h	eight in the	e process. The
pilot then	overflew the th	reshold o	f runway	27 at abou	ut 400	ft an	d carri	ed out a left	turn, open	ing the dive
brakes du	ring the turn. Th	e pilot lin	ied up ov	er the east	ern b	ound	ary of t	he airfield t	o cross the	operational
runway d	iagonally at abou	it 60 - 100	0 ft and la	anded ahea	ad of I	parke	d glide	rs and cars i	n a grassed	area on a
heading p	arallel and to the	e south o	f runway	23. While	the gr	assec	d area i	s suitable fo	r landing, it	; is not
designate	d as a landing ar	ea. Other	r than the	e location, 1	the la	nding	, was n	ormal and th	nere was no	o significant
crosswind	l component. The	e pilot ha	s a relati	vely low to	tal nu	mber	r of hou	irs and high	number of	launches,
with little	soaring experier	nce. While	e the pilo	t had flow	n with	n an II	nstruct	or at this air	field on a fe	ew occasions
the previo	bus year, this was	s the pilo	t's first so	DIO flight. It	t was	deter	mined	that the plic	ot lost orien	tation due to
overioad	caused by relativ	e inexper	rience co	upled with	a tirs		i filght a	at an unfam	lliar airtield	. The pllot
was debri	ered by the CFI a	ind subse	quent fil	gnts were s	satista	actory	/.			
	8	25	040	60	в	Acres 6	\$40 14C0 09			

Date	3-Jan-2017	Region		VSA			SOAR Report Nbr				S-0930	
Level 1	Operational		Level 2 Aircraft			raft Co	Control Level 3			3	Hard landing	
A/C Mod	el 1	Astir CS 77					A/C Model 2					
Injury	Nil	Dama	age	ge Substantial P			ise Landing				PIC Age	81
An exper	An experienced and current pilot misjudged the flare and the glider bounced back into the air. Subsequent											
mishandl	mishandling of the recovery resulted in the aircraft touching down heavily before coming to rest. The											



Accident and Incident Summaries

undercarriage bulkhead was substantially damaged. The pilot was counselled on approach and round out procedures and undertook two further training flights with the CFI.

Date	4-Jan-2017	Region		VSA		SOAR Report Nbr				S-0924		
Level 1	Airspace	l	Level 2	el 2 Airspace Infri			ingement Level 3			Airspace Ir	nfringement	
A/C Model 1 Mini-N			/lini-Nim	i-Nimbus C			A/C Model 2					
Injury	Nil	Damag	ge	Nil	Pha	se	Thern	nalling		PIC Age	50	

During a cross-country flight the experienced pilot flew into controlled airspace without a clearance. The infringement was identified by the pilot's CFI following a review of the pilot's OLC trace. The infringement occurred despite the pilot carrying appropriate maps and GPS navigation device and may have been caused by inattention. The pilot was counselled.



Date	4-Jan-2017	Regior	Region VSA SOAR Report Nb			ort Nbr		S-(0891			
Level 1	Airspace		Level	2	Aircra	ft Sep	arati	on	Level	З	Near collis	ion
A/C Mod	el 1	Pi	per PA-	-25	-235/A1		A/C	Model	2	Binc	ler EB29 DR	
Injury	Nil	Dama	age		Nil	Pha	ise	In-Flig	ght		PIC Age	70
On day 1	of the 2017 Wor	ld Glidin	g Cham	pic	onships a t	owing	com	binatio	n appr	oache	ed, from belo	ow and
behind, a	motor glider on	the right	climbi	ng	under pov	ver. Tł	ne to	w pilot	turned	sligh	tly left to pr	ovide
clearance	e but the motor g	lider cor	tinued	to	drift towa	rd the	tow	ing con	nbinatio	on's fl	ight path. Tl	he pilot of
the towe	d glider attempt	ed to ale	t the to	ow	pilot to th	e pote	ential	l conflic	t but t	his tra	ansmission v	vas given at
a late sta	ge and the tow p	oilot did r	ot read	ct. S	Seconds la	ter th	e mo	tor glid	er pass	ed fro	om right to l	eft over and
between	the tow plane an	nd glider	under t	tow	v with sepa	aratio	n esti	mated	at less	than	100ft. The t	ow plane is a



Accident and Incident Summaries

two-seat, side by side Pawnee with the pilot sitting in the in the left seat. It is possible the tow pilot's vision was impeded up and to the right by the cockpit roof.



Date	7-Jan-2017	Region		VSA		SOA	AR Repo	ort Nbr		S-	0892
Level 1	Operational		Level	2 Terra	in Co	llisior	าร	Level	3	Collision w	ith terrain
A/C Mod	el 1		AS	G29		A/C	Model	2			
Injury	Nil	Dama	age	Substantial	Pha	se	Grour	nd Ops		PIC Age	39
Whilst to was caug	wing the glider a ht against the ve	round th hicle. Th	e aproi e eleva	n area the tov tor was subst	w vehi antia	icle tı lly da	urned s maged	harply	and t	he elevator	of the glider





Date	9-Jan-2017	Regior	1		VSA		SOA	AR Repo	ort Nbr		S-	0907
Level 1	Operational		Leve	el 2	Airc	raft Co	ontro	Ĩ	Level	З	Wheels up	landing
A/C Mod	el 1		AS	W-27	7-18		A/C	Model	2			
Injury	Nil	Dama	age		Minor	Pha	ise	Landi	ng		PIC Age	73
The pilot	he pilot advised that he was flying a straight-in approach and believed he was not allowed by the											
competit	ion rules to pull-	up to dis	sipate	e ene	ergy. He ha	id not	flow	n a stra	ight-in	appro	oach previo	usly and
became p	preoccupied man	ipulating	; the i	flaps	and airbra	akes to	o slov	v down	to land	ding s	peed. Due t	o this
preoccup	ation and a high	workloa	d he f	forgo	t to lower	the u	nder	carriage	e and c	omple	ete the pre-	landing
checks. La	anding mishaps ι	usually o	ccur c	due t	o high wor	kload	, so it	t is imp	ortant	to get	some of th	e tasks, like
The pilot advised that he was flying a straight-in approach and believed he was not allowed by the competition rules to pull-up to dissipate energy. He had not flown a straight-in approach previously and became preoccupied manipulating the flaps and airbrakes to slow down to landing speed. Due to this preoccupation and a high workload he forgot to lower the undercarriage and complete the pre-landing checks. Landing mishaps usually occur due to high workload, so it is important to get some of the tasks, like lowering the undercarriage, out of the way early. Refer also OSB 01/14 'Circuit and Landing Advice'.											ce'.	

Date	10-Jan-2017	Regior	on NSWGA			SOA	AR Repo	ort Nbr		S-	0900	
Level 1	Operational		Leve	el 2	Terra	ain Co	lisior	าร	Level	3	Ground st	rike
A/C Mod	el 1		А	rcus	М		A/C	Model	2			
Injury	Nil	Dama	age		Minor	Pha	ise	Outla	nding		PIC Age	50
The pilot	s were competing	g in the \	Norld	Glid	ling Champ	bionsh	ips 2	017 an	d had b	een t	asked into t	he hills to
the East o	of the airfield. Co	nditions	were	роо	r with the	rmal a	ctivit	y going	to 5,0	Oft. Th	he comman	d pilot
headed s	outh-east in the l	hope of o	catchi	ng a	thermal in	n the ł	nills. /	After co	overing	45 kil	lometres the	e glider was
at 1500ft	AGL in an area w	ith few	outlar	ndin	g options,	so the	com	mand p	oilot sta	arted	the motor a	ind headed
back tow	ards the airfield.	About 2	0 kms	fror	n the airfie	eld an	d at a	ı height	ofabo	ut 35	00ft the pilo	ot shut down
the engin	e with the view t	o gliding	g the r	ema	ining dista	ance. l	Jnfor	tunate	ly, the o	comm	nand pilot di	id not follow



Accident and Incident Summaries

the correct procedure and the engine did not automatically retract. After a while the command pilot, thinking there was a fault in the auto retract system, manually applied the propeller brake and stopped the propeller in the correct vertical position for retraction. However, the brake had to be released in order to activate the manual retract switch and the propeller moved from the vertical position as the pylon started to retract. This led to the propeller jamming against the engine-bay doors, resulting in the electric retraction mechanism overloading and activating the circuit breaker. Having lost height while retracting the motor, and with the additional drag of the propeller and open engine bay, the pilot decided to conduct an outlanding. Although the glider was over a suitable landing field, the pilot chose not to land in it due to the presence of SWER lines on the approach and down one side, and headed towards another paddock a few kilometres further away. An unsuccessful attempt was made to climb away in weak lift but after several minutes flying in and out of the lift the pilot elected to give it away.



An attempt was again made to start the motor but this was unsuccessful as the pilot did not realise the circuit breaker had tripped. The aircraft was by now too low to complete a circuit to the intended paddock and the pilot noticed trees and powerlines on the approach. In addition, the right half of the paddock lengthways was about two metres higher than the left side. Flying at 75 knots, the pilot flew a high approach to avoid the trees and power line and aligned the aircraft to land on the left-hand lower side of the paddock. The aircraft touched down in the middle of the paddock at high speed, and the command pilot initiated a ground loop to prevent the aircraft running into the boundary fence. The rudder was substantially damaged and one wingtip skid was broken. Causal factors include a lack of familiarity with the engine management system, high workload and poor decision making. Being aware of the dangers of continuing into marginal circumstances, setting boundaries, having a sound knowledge of rules and procedures, disciplined adherence to minima and performance requirements, prioritisation of options, and planning to deal with potential situations will act as defences against unsafe conditions.





Date	11-Jan-2017	Regior	1		VSA		SOA	R Repo	ort Nbr		S-	0911
Level 1	Consequential	Events	Leve	el 2	Lo	ow Cir	cuit		Level	3	Low Circui	t
A/C Mod	el 1		٨S	W 27	/18		A/C	Model	2			
Injury	Nil	Dama	age		Nil	Pha	ise	Landi	ng		PIC Age	64
This incid	ent occurred on	Day 2 of	the 3	4th I	FAI World	Glidin	g Cha	mpion	ships a	t Bena	alla Vic. The	pilot
crossed t	he finish line fro	m the Ea	st app	oroxi	mately 3kr	ns fro	m th	e runwa	ay thre	shold	at 200ft AG	iL and
continue	d down to below	100ft A0	GL jus [.]	t bef	ore the Hu	ume F	reew	ay. The	pilot p	ulled	up to about	t 150ft AGL
to cross t	he freeway then	descend	ed to	abo	ut 50ft AG	L. Sho	rtly a	fterwa	rds the	pilot	pulled up to	o about 50ft
to cross s	ome trees on th	e bounda	ary of	a ca	nal running	g para	llel to	o the fr	eeway.	The p	pilot again d	lescended,
this time	to within about	20ft of th	ie gro	und	and held t	his he	ight f	or abo	ut 1 km	n befo	ore clearing	the airfield
boundary	/ fence. The pilot	: landed l	nalfwa	ay do	own the ru	nway	some	e 800 m	netres l	ater. ⁻	The pilot wa	as cited for
dangerou	is flying, counsel	led and r	eceiv	ed a	scoring pe	nalty.						

Date	11-Jan-2017	Regior	n		NSWGA		SOA	R Repo	ort Nbr		S-	0948
Level 1	Airspace		Leve	el 2	Aircra	ft Sep	arati	on	Level	3	Aircraft Se	paration
											Issues	
A/C Mod	el 1			U/K			A/C	Model	2	U/K		
Injury	Nil	Dam	age		Nil	Pha	ise	In-Flig	ght		PIC Age	
GFA rece	ived an anonym	ous repoi	t fron	n CA	SA that all	eged	glider	s were	operat	ing at	t a Regional	Airport
contrary	to the condition	s in a NO	TAM t	hat \	was active	at the	e time	e. The a	allegati	on wa	as that the N	IOTAM
advised t	hat gliders woul	d only be	opera	ating	to the We	est of	the A	irfield,	yet glio	ders v	vere seen to	the



Accident and Incident Summaries

East. Investigation revealed that the reporter had misread the NOTAM, which merely stated that glider operations would be using either runway 08/26, or the grass strip to the West of runway 17/35.

Date	11-Jan-2017	Region)	NSWGA		SOA	AR Repo	ort Nbr		S-	0953
Level 1	Airspace		Level 2	Aircra	aft Sep	arati	on	Level	3	Aircraft Se	paration
										Issues	
A/C Mod	el 1					A/C	Model	2	S.A.	A.B. AIRCRA	FT CO 340B
Injury	Nil	Dama	age	Nil	Pha	ase	In-Flig	ght		PIC Age	
A SAAB 3	40B aircraft was	operatin	g a pass	enger servio	e fron	n a Re	egional	airport	to Sy	/dney. As th	e aircraft
was taxyi	ing out they obse	erved a gl	ider tug	and glider t	ake-o	ff fro	m the c	operatio	onal r	unway and	depart to the
north-we	est. Shortly after	take-off f	rom the	operationa	l runw	/ay ai	nd at ap	oproxin	nately	/ 1000 ft the	SAAB crew
received	a TCAS RA (Reso	lution Ad	visory) a	and observe	d a gli	der h	eading	toward	ls the	m from the	north-west,
possibly t	to join the down	wind leg f	for the o	perational	runwa	y. Th	e SAAB	Captai	n esti	mated that	the
horizonta	al distance was a	pproxima	tely 1-2	NM and the	e vertio	cal di	stance	was ap	proxir	mately 200'.	. When an
RA is issu	ed, pilots are exp	pected to	respon	d immediate	ely unl	less d	oing sc	would	jeopa	ardise the sa	afe
operation	n of the flight. Th	e SAAB c	rew foll	owed their S	Standa	ard O	peratin	g Proce	dure	s and mano	euvred to
prevent o	conflict with the	glider. As	require	d by law, th	e Aircı	raft C)perato	r repor	ted th	ne TCAS RA	to the ATSB.
The oper	ator noted that t	he TCAS	RA was	triggered in	the SA	AAB b	ecause	the gli	der h	ad a transpo	onder fitted
and oper	ating. This allow	ed the flig	ght crev	/ to de-conf	lict wit	th the	e glider	traffic.			

Date	12-Jan-2017	Regior	۱	SAGA		SOA	AR Repo	ort Nbr		S-	0917
Level 1	Operational		Level	2 Run	way E	vent	S	Level	3	Runway ui	ndershoot
A/C Mod	el 1		Che	rokee II		A/C	Model	2			
Injury	Nil	Dam	age	Minor	Pha	se	Outla	nding		PIC Age	62
During a	A/C Model 1 Cherokee II A/C Model 2 Injury Nil Damage Minor Phase Outlanding PIC Age 62 During a local flight, the low hours pilot flying a low performance glider got caught out by heavy sink. The pilot attempted to make it back to the takeoff point but ran out of height and landed safely in a paddock										
pilot atte	mpted to make	t back to	the ta	keoff point bi	ut ran	out c	of heigh	it and la	andeo	d safely in a	paddock
adjacent	the field.										

Date	12-Jan-2017	Region		VSA		SOA	AR Repo	ort Nbr		S-	0893
Level 1	Airspace		Level 2	Aircra	aft Sep	arati	on	Level	3	Collision	
A/C Mod	el 1		ASG-2	9E		A/C	Model	2	ASG	-29E	
Injury	Nil	Dama	ge	Minor	Pha	ase	Thern	nalling		PIC Age	52
On day 3	of the 2017 Wo	rld Gliding	Champio	onships, tv	vo glid	lers c	ollided	in mid-	air w	hile therma	lling about
44kms fr	om Benalla aero	drome alo	ng the fii	st leg som	ne 15 r	ninut	es afte	r the st	art. A	nalysis reve	aled the
collision	collision occurred near the top of the thermal being shared by six gliders. The two gliders involved were										
about 100ft apart vertically. Just prior to the collision another glider had resumed course for the turnpoint,											
which wa	as observed by th	ne pilot of	the lowe	r of the tw	vo glid	ers ir	nvolved	in the	collisi	ion. Shortly	afterwards,
the lowe	r glider flew thro	ugh strong	ger lift, w	hich place	ed it at	t a sin	nilar he	ight to	the c	ther glider t	that was
now only	several metres	behind and	d higher.	At the mo	ment	of co	llision,	the rela	ative	positions of	the two
gliders su	iggests a double-	blind scen	nario whe	ere neithei	r pilot	had s	sight of	the oth	ner gl	ider. The sta	arboard wing
top surfa	ce and leading e	dge of the	lead glic	ler struck 1	the lef	ft win	gtip of	the oth	ier, ai	nd both pilo	ts felt the
impact. B	Both gliders were	only supe	erficially	damaged a	and re	main	ed cont	rollable	e. On	e pilot flew	back to
Benalla a	erodrome and tl	ne other co	onducted	l a precaut	tionar	y out	landing	onap	rivate	e airstrip abo	out 19 kms





Date	13-Jan-2017	Regior	۱		GQ		SOA	R Repo	ort Nbr		S-I	0901		
Level 1	Operational		Leve	el 2	Airc	raft Co	ontro	_	Level	3	Hard landi	ng		
A/C Mod	el 1	S	unda	ncer	D13/15		A/C	Model	2					
Injury	Nil	Dama	age	Su	bstantial	Pha	ise	Landi	ng		PIC Age 67			
The pilot had recently taken delivery of a new touring motor glider and, after a few assessment flights with										flights with a				
check pilo	ot, flew back to t	he home	airfie	eld. C	On landing	the pi	ilot m	nisjudge	ed the f	lare r	esulting in t	he aircraft		
touching	down heavily an	d rebour	nding	into	the air. Th	e pilo	t misl	handled	d the re	cove	ry from the	bounce and		
the aircra	ift impacted on t	he nose	whee	l, wh	ich collaps	ed ca	using	the ro	tating p	prope	ller to strike	the ground.		
Contribut	ing factors inclue	de limite	d exp	erier	nce on typ	e and	low c	urrenc	у.					





Date	14-Jan-2017	Regior	1		GQ		SOA	R Repo	ort Nbr		S-	0961	
Level 1	Airspace		Leve	el 2	Aircra	ift Sep	arati	on	Level	З	Aircraft Se	paration	
											Issues		
A/C Mod	el 1		Н	K 36	тс		A/C	Model	2	N/A			
Injury	Nil	Dama	age		Nil	Pha	ise	In-Flig	ght		PIC Age 52		
The moto	or glider was tran	siting th	e Sun	shine	e Coast CT	R at 1	5,000	ft and	reporte	ed, to	ATC, sightir	ng a UAV at	
the mout	h of the Maroocl	hy River	at app	oroxi	mately the	e same	e altit	ude. Tl	nis posi	tion i	s 2.5nm froi	m YBSU	
(Sunshine	e Coast Airport).	The pilot	wasi	unab	le to give	any de	etails	beyon	d small	and c	dark. The UA	AV was	
unable to	be sighted from	the Con	trol T	owe	r and there	e were	e no c	other re	eports.				

Date	14-Jan-2017	Regior	1	NSWGA		SOA	AR Repo	ort Nbr		S-I	0894	
Level 1	Technical		Level	2 Powerplant/Propulsion Level 3 Engine fail				ure or				
				malfunction					n			
A/C Mod	el 1		DG-	1000M		A/C	Model	2				
Injury	Nil	Dama	age	Nil	Pha	ise	Launc	h		PIC Age 52		
After self	-launching to a s	afe heigh	it the c	command pilo	t atte	mpte	d to sh	ut dow	n the	engine but	could only	
reduce th	rottle to 5,000 R	PM. The	comm	and pilot turi	ned of	f witł	n ignitic	on and	subse	quently retr	acted the	
engine no	ormally. Inspection	on reveal	ed the	throttle cabl	e whe	el ha	d becor	ne par	tly de	tached from	the throttle	
body spir	ndle. The engine	had only	run fo	or 11 hrs since	e repla	ceme	ent.					





Date	14-Jan-2017	Region	VSA	SOAR Report Nbr	S-0898



Accident and Incident Summaries

Level 1	Airspace	Le	Level 2 Aircraft Separation				on	Level	3	Collision	
A/C Model 1			Ventus-2a			A/C Model 2			Ven	tus-2cT	
Injury	Serious	Damage	V	Vrite-off	Pha	ise	In-Flig	ght		PIC Age	34

FACTUAL INFORMATION

On day 4 of the 34th FAI World Gliding Championships two gliders collided in mid-air at about 4,860 feet AMSL over Yerong Creek NSW, in VFR conditions in Class G airspace. Both pilots successfully egressed by parachute but suffered injury upon landing. One pilot suffered a broken ankle and the other pilot received a broken nose and a compressed vertebra. Both aircraft descended in an uncontrolled manner before impacting terrain. The Rescue Coordination Centre was contacted, and emergency services attended. Both pilots were airlifted to hospital. The Australian Transport Safety Bureau (ATSB) was notified of the accident but declined to investigate.

1.1 History of flight

The 34th World Gliding Championships were being conducted from Benalla, Vic aerodrome from 9 January 2017 – 21 January 2017. On day 4 of the championships 37 pilots were competing in the 15-metre class. A Fixed (Racing) Task had been set for the Class, heading North to Morundah NSW, then East to The Rock NSW and then returning to Benalla Vic for a total distance of 419.1 kms (A Fixed (Racing) Task is a fixed course, typically consisting of three or four 'turnpoints'. The pilots must fly to each turnpoint in the correct order before heading to the finish line).



Accident and Incident Summaries

Turnpoint	Distance	Direction	Observation zone
01NST	15.7 km	180°	To Next Point, Line 10km
55MORU	166.4 km	009°	Cylinder R=500m
69ROCK	82.9 km	117°	Cylinder R=500m
00Benalla A/D	169.8 km	215°	To Previous Point, Ring 8km
Total:	419.1 km		
	J	ļ	ASA
J.		(
	Mr.	×-6	CA Bala

Fig.1 Task Sheet

Earlier in the flight conditions were such that there were some Cumulus clouds present. However, as the flight progressed the sky cleared, with the top of conviction reaching just over 5,600ft AMSL. The wind was from the South-west at speeds in excess of 19 knots. Thermal conditions were gusty, with climbs averaging around 400 feet per minute. In these conditions around half of the class (approximately 20 gliders) flew more or less as a single group (gaggle) such that they remained within reach of each other. The two gliders involved in the mid-air collision were part of this group. Launching for the class commenced at around 1224 hours EDST, and the 13 tow planes took 26 minutes to launch all 37 gliders. The German registered Ventus 2a (DE) launched by aerotow from near the front of the grid at 1325 hours. The Australian registered Ventus 2ct (O1) launched by aerotow from near the back of the grid 15 minutes later at 1240 hours. The two gliders first met up at 1315 hours, when glider O1 joined glider DE that was thermalling near the start line and



Accident and Incident Summaries

about 800ft higher in company with several other gliders. Glider DE started at 1347 hours at a height of 5700ft AMSL. Glider O1 started two minutes later at 5,600ft AMSL. Both aircraft were in the company of several other gliders that started around the same time. Both glider DE and glider O1 flew in the company of around 18 other gliders along the first two legs, and the gaggle rounded the second turnpoint for the trip home at around 1558 hours, with glider O1 slightly ahead of glider DE. The pilot of glider O1 later stated: "The first leg to Morundah was straight forward and I was able to push fairly hard as we approached Lake Urana, trying to shake off the tentative gaggle that we had caught up with. The gaggle behaviour, as on previous days, was fairly ordered with a couple of aggressive types mixed in as usual, but nothing too uncomfortable. By the time we got to the first turn I found myself out in front by 5km or so, having taken a more westerly line than most. The second leg to The Rock was spent trying not to get run down by the now large gaggle, but the inevitable happened just prior to the turn and I was caught by about eight of the faster guys, with another 15 or so hot on their heels. After turning The Rock for the 160km run home into the wind, I had my teammates just below, and about 15km along the leg we took a 3kt climb to 5,000 ft, close to the inversion. As I left this climb, I noticed the group of eight or so gliders about 1 or 2km ahead on track turning right, and I decided to fly through the left edge of their thermal without stopping. As I entered the edge of the thermal, I let my speed wash off to around 75kts indicated and seemed to be clear of all the circling gliders, which were a bit above me." Approximately 17 kms SSW of The Rock, on the final leg to Benalla, glider DE was circling in a thermal with several other gliders and turning to the right. Glider O1 in the company of at least eight other gliders at similar altitudes left a thermal approximately 3 kms back along track at 5135 feet and was flying towards the thermal occupied by Glider DE and at least 5 other gliders. At 1614:09, Glider O1 entered the edge of the thermal and flew into lift. The pilot veered to the left away from the thermal centre and slowed down slightly, which put Glider O1 on the tangent to the thermal circle of glider DE and about 100ft lower. Logger data shows that at this point glider DE straightened out from the thermal turn on a heading for the finish line as the pilot lowered the nose to increase speed. Simultaneously, glider O1 was on a collision course with glider DE as it gained height from the thermal lift. At 1614:21 glider O1 collided with glider DE at a height of about 5,040 ft AMSL. The pilot of glider DE heard a loud bang and the glider pitched forward. Realising the glider had collided with another glider, the pilot ejected the canopy and bailed out, whereupon a static line deployed the parachute. The pilot landed heavily and suffered a broken left leg. The pilot of glider O1 stated that their "last memory of normality was shifting back to negative flap with a couple of gliders well out to my right, in my mind I felt comfortable that I was clear of any conflict". The pilot of glider O1 stated: "In the seconds following impact I found myself watching my hands eject the canopy frame and push it away into the airflow, then undo the harness. The next instinct was to try to get out in the same manner as I do on the ground, using my arms to lever down to raise myself up high enough to get my right foot under me to lift my body out over the side. This proved impossible due to the G loads being imposed. I tried a few variations of this, trying to go left and then right, all the while getting more anxious to get out, knowing that I was heading for the ground at a good rate. By now I was yelling at myself to "do something different" as this approach clearly was no good. All I could think to do was stick my already retracted right leg over the side to grab the airflow and this quickly pulled me around so that I could get both legs over the side and then roll the rest of me over the side and under the right wing. Having no idea of my height or where I was relative to the aircraft, I immediately found and pulled the ripcord, the chute deploying seemingly instantly. I've done a few jumps under round chutes a long time ago but was unprepared for the shock of the opening, which certainly knocked the wind out of me." The pilot of glider O1 managed to abandon the aircraft at about 2,000ft AMSL, and soon after deploying the parachute landed heavily in a paddock. The pilot of glider DE landed in another paddock about 520 metres away a short time later. The pilot of glider O1 went to the aid of the other pilot, who appeared immobile after landing. 1.2. Injuries to persons

The pilot of DE landed heavily on their posterior, and then was dragged backwards 40 metres across the ground by the parachute. The pilot suffered a fractured vertebra, some bruising and minor abrasions. The pilot of DE landed heavily and sustained a broken left leg, some bruising and minor abrasions. Both pilots were airlifted to Canberra hospital. The pilot of O1 was released from hospital on 17 January, and the pilot of DE was released two days later.



Accident and Incident Summaries



Fig. 2 Emergency services on site (Victoria Police Photo).

1.3 Damage to aircraft

At impact glider O1 suffered catastrophic damage; the pilot's head smashed the Perspex canopy, the fuselage broke behind the engine bay, and half the tailplane broke away together with 2 metres of the outboard port wing. Glider DE appears to have suffered only minor damage from the collision. While under parachute descent the pilot of DE observed their glider to be complete and in a stable flat spin until it hit terrain. The pilot of O1 stated: *"In an instant I heard and felt a violent unseen impact, was aware of broken perspex, strong airflow and that my glider was immediately unflyable. My perception was that the glider pitched down steeply at impact and started spinning to the left in a violent unnatural action. The broken perspex was from my head breaking through the canopy, caused by the impact that took off most of the tailplane, broke the fuselage at the engine bay and took 6ft off the left wing." When under parachute descent after a low-level egress, the pilot of glider O1 observed their glider falling vertically, with its port wing low, without oscillating. They observed damage to the tail and fuselage and heard a loud impact as the glider struck the ground. Both aircraft were substantially destroyed on impact and have been written off by their respective insurers. Glider DE was repatriated to Germany.*



Accident and Incident Summaries



Fig 3. Damaged aircraft (Victoria Police photos).

1.4 Other damage

There was no damage sustained by objects other than the two aircraft.

1.5 Personnel information

The pilot of glider O1 held a GFA Glider Pilot Certificate that met the competency standards equivalent to the ICAO compliant Glider Pilot Licence issued in accordance with the Civil Aviation Safety Regulations, Part 61 Manual of Standards. The pilot held a GFA Level 2 Instructor endorsement and had in excess of 3,000 Hours gliding experience accumulated over nearly 5,000 flights. The pilot had 200 hours/60 launches on type and had flown 140 hours/40 launches in the previous 90 days. The pilot held a valid GFA Medical Actioner's Certificate of Fitness dated 19 September 2016. The pilot of glider DE, a German National, held an EASA issued ICAO Sailplane Pilot Licence endorsed for sailplanes and powered sailplanes. The pilot also held a Sailplane Flight Instructor endorsement, Their flight experience was not disclosed. The pilot held a valid German Class 2 Medical Certificate dated 25 November 2016.

1.6 Aircraft information

Glider DE is a Schempp-Hirth Ventus 2a, registered in Germany as D-9222. It was constructed in 1994 and issued serial number 2. The pilot was the registered owner/operator. It had a valid Certificate of Airworthiness and its most recent Maintenance Release was issued 31 March 2016 and expiring 14 April 2017, which indicated that the aircraft was equipped and maintained in accordance with existing regulations and approved procedures. At the time of the accident the aircraft had flown 3,090.6 hours over 673 flights. Glider O1 is a Schempp-Hirth Ventus 2ct powered (sustainer) glider, registered in Australia as VH-IKB. It was constructed in Germany in 2004 and issued serial number 129. The pilot's brother was the registered owner/operator. It had a valid Certificate of Airworthiness and its most recent Maintenance Release was issued 8 October 2016 and expiring 7 October 2017, which indicated that the aircraft was equipped and



Accident and Incident Summaries

maintained in accordance with existing regulations and approved procedures. At the time of its last annual inspection the aircraft had flown 1,564.15 hours over 419 flights.

1.7. Meteorological information

At the time of the occurrence, the wind was from the south-west at 19 knots. Conditions were clear skies and visibility was greater than 10 miles. Thermals were rising to 5000 feet AMSL, with some to 5500 feet AMSL.

1.8 Airspace

The airspace in the accident area was designated as Class G airspace and was classified as uncontrolled. In uncontrolled airspace, pilots operate on the principle of see-and-avoid. Maintaining an effective lookout for aircraft and other hazards is therefore a prime task for a pilot to avoid collisions, particularly when flying in uncontrolled airspace. However, there are limitations in the human visual system that serve to make collision avoidance difficult by visual means alone.

The 'see-and-avoid' principle can be enhanced by the use of electronic conspicuity aids that enable the proximity of other airspace users to be known. There are several types of electronic conspicuity aids currently available, which include transponders and radios, but each has its own limitations. In this case both aircraft were equipped with functioning radios and a type of electronic conspicuity aid called FLARM (FLARM was invented in Switzerland in 2004 in response to a high number of fatal mid-air collisions between gliders, which despite the principle of 'see and avoid', were still occurring in good visibility. FLARM is a flight alarm system that transmits the position and altitude of an aircraft over a low-powered, short-range radio to other FLARM-equipped aircraft once every second. The system is capable of displaying the proximity of other FLARM-equipped aircraft to pilots and providing an audible and visual warning if there is a risk of collision).

1.9. Communication

A dedicated competition frequency was in use for alerted see-and-avoid when gliders were operating outside a designated CTAF.

1.10 Flight Recorders

Both gliders had PowerFlarm systems installed that were functioning for the duration of the flight. The Flarm system, if properly installed and maintained, is usually reliable in glider installations. However, when multiple gliders fly intentionally close to one another, in curved banked turns, the system may not reliably handle conflict resolution in order to inform the pilot of a threat. This is partially due to GPS precision, small error margins, multiple targets and the rapid change in vector of the potential threats.

1.11. Wreckage and impact information

The gliders impacted near Yerong Creek NSW, which is situated about 50 km South-West of Wagga Wagga at location 35°23'29.59"S and 146°59'6.75"E.



Accident and Incident Summaries



1.12. Survival aspects

Neither pilot was injured in the collision, and both were able to abandon the aircraft by parachute. **1.13. Organisational and management information**

Planning for the 2017 World Championship spanned more than two years and a robust Risk Management Plan was developed and tested during the January 2016 'pre-world' championship event that was also run from Benalla, Vic. The organisers applied a clear process to identify risks, set an acceptable level for risks and took steps to keep risks at that level. Risks were managed by assessing potential consequences and likelihood, working out clear actions and designing a response plan.

Key responsibilities were assigned to specific people in areas such as operations management, task setting, marshalling gliders and launch operations. Risk review processes were implemented, registers of occurrences and complaints were maintained and monitored, risks were reviewed, communication and consultation processes were implemented, and all team members were trained on risk management. The organisation, rules and governance arrangements for the 2017 World Gliding Championships (WGC) were publicly available on the competition website. The championships were conducted in accordance with Federation Aeronautique Internationale (FAI) Rules, as managed by the International Gliding Commission (IGC). These rules include task setting, starting, finishing, scoring and operational requirements. The rules also mandated use of FLARM to aid in collision avoidance, and the wearing of parachutes in competition flights. Note that these rules did not exclude flying in gaggles in thermals, nor team flying practices to provide competitive advantage. The FAI Competition Rules were supplemented by local procedures. Pilots also had access to the GFA Competition Safety Pack dated October 2013, which contained detailed operational safety guidance for competitors, including lookout and collision avoidance issues. This was a reference document for the Mandatory Pilots Safety Briefing conducted on Thursday 5th January.

2. ANALYSIS

2.1. Pilot Qualifications

Both pilots were appropriately qualified for the flight, were in current flying practice and held valid medical certificates.

2.1. Collision



Accident and Incident Summaries

Flarm and logger records for all aircraft in the 15 metres class were made available. Analysis of these records revealed that glider O1 approached glider DE from the rear, flying about 160 ft below. From 1614:17 to 1614:20 hours, glider O1 was below glider DE, with a very small elevation difference, before the collision occurred. Glider O1 and glider DE collided when O1 slowed down and climbed in lift at the edge of the thermal and the pilot of DE lowered the nose to increase speed on exiting the thermal. An evaluation of the logger records suggests that the pilot of glider DE did not have an opportunity to recognise the approach of glider O1, which was approaching from behind and below. In contrast, the pilot of the glider O1 had glider DE in front of them most of the time and should have been able to see it. However, as there were several gliders in the immediate vicinity of glider O1, the pilot's focus may have been on other gliders they deemed more of a threat.



Fig.5: Simulated view (The IGC logger files for all aircraft in 15-metre class were loaded into the 'Silent Wings' flight simulator program in order to review the pilot's view just prior to the collision) from glider O1 as the pilot manoeuvres slightly left on entering the edge of the thermal approximately 20 seconds before impact. Gliders in thermal are circled. Glider DE is circled orange. Another glider (G1) is out of frame to the pilot's right.

Using the Flarm Range Analyser (flarm.com) revealed that both Flarms were performing to the minimum recommended range for the device. The Flarm radio log shows 31 aircraft in the Vicinity at the time of the collision. A review of the logger traces by the manufacturer confirmed that Flarm warnings were given at 16:14:17 and 16:14:19 just prior to the collision.



Accident and Incident Summaries



operational flight recorders.

2.4 Flight Recorder Analysis

Initial situation at 1614:03 hours

Glider DE was at an altitude of 5,020 ft and was circling in a thermal with six other gliders. Glider O1 and two other gliders (G1 and JH) approached the thermal from a north-north-easterly direction at an altitude of 4,860 ft, with glider G1 slightly ahead and to the right of glider O1. The red lines depicted under show a collision alert on the Flarm for gliders DE and O1.



Accident and Incident Summaries



Glider DE was at an altitude of 5,030 ft and glider O1 was at an altitude of 4,860 ft. Gliders DE and XY were directly in front of glider O1, glider G1 was in front of but displaced slightly to the right of glider O1, and another three gliders (FB, BB and JH) were behind glider O1 on the right. At this stage glider DE has rolled out of the turn and is heading off on track. The red line shows a collision alert of the Flarm of glider DE.



Accident and Incident Summaries



Approach of the two aircraft at 1614:14

Glider DE is at an altitude of 5,0230 ft and glider O1 is at an altitude of 4,940FT. Gliders DE and XY are now directly in front of glider O1, with glider G1 closer and to the right of glider O1. Glider G1 has pulled into the thermal to the right and glider JH is continuing through the thermal. The red line shows a collision alert of the Flarm of glider O1.



<u>Approach of the two aircraft at 1614:18</u> Glider DE at an altitude of 5,042 ft and glider O1 is at an altitude of 4,970 ft.





Accident and Incident Summaries

Glider O1 collides with glider DE from below at an altitude of about 5,040 ft. From time 1613:53 the pilot of glider DE would not have sighted glider O1 due to the blind arc limitations as the glider was turning to the right. In the 20 seconds before the collision, Glider DE would have been visible to the pilot of glider O1 if its pilot was looking in the right direction.

2.5 Organisation Risk Management

An investigation of the competition organisation's risk movement system revealed a positive safety culture, where steps were taken by the organisers to reduce safety hazards as they were identified. The Organisers actively worked to reduce risk, which resulted in some significant improvement and reduction in reported incidents. During the championship pilots were repeatedly warned about the risks of aggressive flying, sharp pullups, turning inside other gliders in thermals, joining thermals incorrectly, and poor lookout or situational awareness. They were specifically briefed on the limitations of FLARM for collision avoidance, and on the proximity data recorded. Mandatory data loggers were used and traces analysed, to assist in investigating allegations of dangerous flying, as well as instances where near misses had occurred. Some fixed video recordings assisted in capturing useful data on near misses. The Safety Officer used Pilot Briefings, meetings with pilots, meetings with Team Captains and video recordings to highlight risk and safety issues. **2.6 Pilot Risk Management**

Pilots are responsible for managing their own risk and displaying sound airmanship. Glider pilots are taught to lookout at all times, manage workload, mitigate risk, correct errors, and make good decisions. However, a single person can be more easily overwhelmed when faced with multiple decisions to make, and task management can quickly become difficult for even seasoned pilots when things go wrong. Consequently, errors can and will be made. All pilots participating in the competition were competent, experienced and current. However, by its very nature competition flying has several threats that increase the likelihood of pilots making an error that could lead to reduced safety margins or may contribute to an incident or accident. The type of threats that competition pilots need to manage include:

- Environmental issues such as, flying with other gliders, flying from an unfamiliar airfield, weather changes, unpredictable lift, different terrain with changes in height above sea level, partly unlandable country, or flat but very small paddocks;
- Navigational challenges;
- Physiological factors, such as fatigue, dehydration, hunger, hypoxia, impatience, frustration, optimism bias and overconfidence;
- Time pressure on the ground (including Launch delays) and in flight;
- Pressure to get home;
- Risk of outlanding;
- Final glides.

All the above threats increase the likelihood of pilots making an error that could lead to reduced safety margins or may contribute to an incident or accident. 'See-and-avoid' is recognised as the main method that a pilot uses to minimise the risk of collision when flying in visual meteorological conditions. 'See-and-avoid' is directly linked with a pilot's skill at looking outside the cockpit and becoming aware of what is happening in their surroundings. Its effectiveness can be greatly improved if the pilot can acquire skills to compensate for the limitations of the human eye (refer

https://www.atsb.gov.au/publications/1991/limit see avoid.aspx). The primary method for implementing 'see-and-avoid" is lookout, which involves seeing potential hazards and assessing information prior to reacting. The primary source of information is vision. Whether it is aircraft attitude, position, physical hazards or other traffic, what a pilot sees is processed by the brain and used to build up situational awareness. The human eye is a very complex system. Its function is to receive images and transmit them to the brain for recognition and storage. About 80 per cent of our total information is received through the eye, which is therefore our prime means of identifying what is going on around us. In the air the pilot depends on their eyes to provide most of the basic input necessary for flying the aircraft, e.g. attitude, speed, direction and proximity to opposing traffic. As air traffic density and aircraft closing speeds increase, the problem of mid-air collision increases considerably, and so does the importance of effective scanning. The eye, and



Accident and Incident Summaries

consequently vision, is vulnerable to many things including, but not limited to, dust, fatigue, emotion, age, and optical illusions. In flight, vision is influenced by atmospheric conditions, glare, lighting, canopy deterioration and distortion, aircraft design, acceleration forces and so forth. Most importantly, the eye is vulnerable to the vagaries of the mind. We can 'see' and identify only what the mind permits us to see. Another inherent eye problem is the narrow field of vision. Although our eyes accept light rays from an arc of nearly 200°, they are limited to a relatively narrow area (approximately $10 - 15^{\circ}$) in which they can actually focus on and classify an object. Anything perceived on the periphery must be brought into that narrow field to be identified. Motion or contrast is needed to attract the eyes' attention, and the field of vision limitation can be compounded by the fact that at a distance an aircraft on a steady Collision Course will appear to be motionless. The aircraft will remain in a seemingly stationary position, without appearing to move or to grow in size, for a relatively long time, and then suddenly bloom into a huge mass, almost filling the canopy. A large smear or dirty spot on the canopy can hide a converging aircraft until it is too close to be avoided. Light also affects our visual efficiency. Glare during flight directly into the sun makes objects hard to see and scanning uncomfortable. An aircraft that has a high degree of contrast against the background will be easy to spot, while one with low contrast at the same distance may be impossible to see (especially against a cluttered background). A dirty, scratched, opaque or distorted canopy will make matters worse. While gliders have large canopies and theoretically offer an excellent field of view to the pilot, there are still blind arcs. The following diagram illustrates the field of view from a glider; the yellow cone is the narrow area in which we focus.



avoiding action. Collision avoidance was by lookout and visual detection, which has limitations, and the



Accident and Incident Summaries

presence of multiple aircraft in the immediate vicinity meant there were many potential targets requiring the pilots' attention.

It was found that:

- Both pilots were certified and qualified for the flight in accordance with existing regulations.
- The maintenance records of each aircraft indicated that the aircraft were equipped and maintained in accordance with existing regulations and approved procedures.
- Both aircraft were airworthy when dispatched for flight.
- All flight controls of both aircraft were operating correctly at impact and suffered damage due to the forces of impact with terrain.
- Multiple aircraft operating in close proximity would have demanded pilot attention and may have degraded overall situational awareness.
- All gliders have significant blind arcs, most notably below and behind.
- Glider DE was in the field of view of the pilot of glider O1 for several seconds before impact.
- Glider O1 was below and behind glider DE and outside the field of view of the pilot of glider DE.

Date	15-Jan-2017	Regior	۱	WAGA			AR Repo	ort Nbr		S-0981	
Level 1	Airspace	Level 2 Airspace II			e Infri	Infringement Level 3			3	Airspace Infringement	
A/C Mod	el 1		Astir	CS		A/C	Mode	2			
Injury	Nil	Dam	age	Nil	Nil Phase In-Flight			ght		PIC Age	69
This incic	lent occurred du	ring the 2	2017 Wes	tern Austra	alian G	Glidin	g Cham	pionsh	ips at	: Beverley W	VA. The pilot
did not n	naintain adequat	e toleran	ce to the	airspace li	mits a	nd ve	ertically	[,] infring	ed co	ontrolled air	space by less
than 100) If while travelling enroute and received a scoring penalty. When flying near airspace boundaries								oundaries		
pilots mu	ist ensure they u	se sensib	le tolerar	ices to airs	pace.						

Date	15-Jan-2017	Region	1	WAGA		SOAR Report Nbr				S-0962		
Level 1	Airspace		Level 2	Airspac	e Infri	ringement Level 3			3	Airspace Infringement		
A/C Mod	/C Model 1			Ventus-2c			A/C Model 2					
Injury	Nil	Dama	age	Nil	Pha	se	In-Flig	ght		PIC Age	63	

This incident occurred during the 2017 Western Australian Gliding Championships at Beverley WA. The pilot failed to maintain adequate situational awareness and vertically infringed controlled airspace by over 1500ft while thermalling enroute and received a scoring penalty. The pilot noted that they were relying on a visual and aural warning from the flight logger that either did not happen (the logger was giving problems) or was missed. The type of navigational units found in gliders are not approved navigation systems and cannot be used as the primary means of navigation. Non-approved portable electronic devices with Global Positioning System functionality can only be used for situational awareness. AirServices document 'Using GNSS as an Air Navigational Tool' states: *"The use of a GNSS can significantly assist VFR pilots. However, it should only be used to supplement visual navigation techniques, not as a primary navigation source"*. When flying near airspace boundaries pilots must ensure they use sensible tolerances to airspace. AIP ENR 1.1, paragraph 19.12 states: *"For aircraft operating in close proximity to an airspace boundary where there is a risk of an airspace infringement, the pilot in command should consider obtaining a clearance to enter the airspace or altering track to remain well clear."* Pilots should always navigate using CASA approved data and charts. Airspace files provided by competition organisers or downloadable from the internet are unapproved and should not be relied upon.

Date	15-Jan-2017	Region		GQ	SOAR Report Nbr		S-0895
Level 1	Operational	Lev	vel 2	Runway E	vents	Level 3	Runway excursion



Accident and Incident Summaries

A/C Model 1		H 36	Dimona		A/C	Model 2					
Injury	Nil	Damage	Minor	Phase		Landing		PIC Age	58		
The commar	nd pilot lande	d the motor gli	der 'engine of	f' but	faileo	d to maintain a	Idequ	uate speed o	ontrol		
during the round-out and bounced upon touchdown. As the glider rebounded it veered to the left but the											
pilot recovered and flew back over the bitumen runway. The glider touched down smoothly but during											
subsequent taxying towards the runway exit the pilot noticed a vibration in the rear of the aircraft. The pilot											
taxied onto t	he grass verg	e of the runwa	y and the airc	raft st	oppe	d abruptly. Or	exiti	ng the aircr	aft the pilot		
noticed the t	ailwheel was	flat. The pilot	eft the aircraf	ft in sit	u wh	nile a new inne	r tub	e and tyre v	vas obtained		
and subsequ	ently refitted	. Despite the g	lider occupyin	g the f	far er	nd of the runw	ay fo	r nearly two	hours while		
it was being	repaired, the	Duty Instructo	r assessed the	e glider	r was	sufficiently di	splac	ed so as not	; to pose a		
risk and gliding operations continued. Contributing factors to the incident include the pilot's limited											
experience o	on type, an ex	cessively worn	tailwheel tyre	e, and f	failur	e to remove tl	ne da	maged glide	er from the		
runway expeditiously.											

Date	15-Jan-2017	Region	1	VSA			AR Repo	ort Nbr		S-0896	
Level 1	Operational		Level 2	el 2 Airfran			me Level 3			Doors/Can	opies
A/C Mod	el 1	DG-1000S				A/C Model 2					
Injury	Nil	Dama	ge Nil		Pha	ase Laund		h		PIC Age	
The rear canopy opened during aerotow. The command pilot, who was flying solo, released from tow and											

The rear canopy opened during aerotow. The command pilot, who was flying solo, released from tow and landed normally. The command pilot advised that the rear canopy was locked during the pre-boarding walkaround inspection but noticed another member open the canopy and then close it. The pilot assumed the other member had re-locked the canopy and did not re-check it. This incident highlights the importance of launch point hygiene and not to interfere with aircraft that has already been configured for launch.

Date	16-Jan-2017	Region		WAGA		SOA	R Repo	ort Nbr		S-	0899	
Level 1	Airspace	Lev	el 2	Aircra	aft Sep	arati	on	Level	3	Near collis	ion	
A/C Mod	el 1	SZD-48-1 "Jantar Standa			2"	A/C Model 2 LS				-18		
Injury	Nil	Damage		Nil Ph		ase Thermalling		nalling		PIC Age	63	
This incid	ent occurred du	ring the 2017	West	tern Austra	alian G	Glidin	g Cham	pionsh	ips. T	he Jantar pi	ilot was	
completi	ng the first turn i	n a thermal v	vhen	an LS8 wa	s obse	rved	joining	from tl	he no	orth. The Jan	ıtar pilot	
expected	to see the LS8 p	ilot turn wide	to al	low the Ja	ntar te	o con	tinue ti	urning l	but tł	ne LS8 proce	eeded to	
move un	der the Jantar's f	light path, ca	using	the Jantai	^r pilot	to pu	ll up to	avoid	a coll	ision. The Ja	intar's	
airspeed	was dropping th	rough 40kts,	preve	nting its p	ilot fro	om ta	king ev	asive a	ction	by turning.	The pilot of	
the LS8 h	ad seen the Jant	ar and believ	ed he	could safe	ely joir	า und	erneat	h, unav	vare o	of the Janta	r pilot's	
speed dil	emma. Separatio	on was 100 ft	but w	ould have	e been	muc	h lower	if the J	lanta	r pilot had r	not pulled up.	
When joi	ning another glio	ler or numbe	r of gl	iders alrea	ady in	a the	rmal, tl	ne pilot	of th	ne joining gl	ider should	
establish	establish themselves on the opposite side of the circle to the nearest glider. GFA rules of the air stipulate the											
minimum separation between gliders is 200ft horizontally and vertically.												

Date	16-Jan-2017	Regior	1	VSA			SOA	R Repo	ort Nbr		S-0905	
Level 1	Operational		Leve	el 2	Flight			Level 3		Other Fligh	nt Prep/Nav	
				Preparation/Navigation						Issues		
A/C Mod		Piper PA-25-235			A/C Model 2			2	ASV	/ 27-18		
Injury	Nil	Dama	age		Nil	Nil Phase Launch		h		PIC Age	63	
This incid	ent occurred du	ring the 3	84th F	AI W	/orld Glidiı	ng Cha	ampio	onships	at Ben	alla V	ic. The tow	pilot was
following	instructions from	n the gro	ound o	crew	to take up	slack	in th	ie rope	just af	ter th	e rope had b	been
attached	attached to the tow plane and then the "all out" signal was given. The tow pilot felt a jerk on the rope as the											



Accident and Incident Summaries

glider pilot released on initial acceleration for the launch and then heard a 'Stop, Stop, Stop" command over the radio. The tow pilot checked the mirrors to confirm the glider had released and then coasted to a stop. Investigation revealed a break down in situational awareness by the ground crew, who gave the "all out" take-off command to the tow pilot prior to the glider pilot being ready for launch and the glider's canopy still open. The glider pilot released the rope as the glider accelerated forward.

Date	16-Jan-2017	Region		VSA			SOAR Report Nbr			S-0906	
Level 1	Technical		Level 2	el 2 Systems				Level 3		Hydraulic	
A/C Mod	el 1	Piper PA-25-235		25-235		A/C Model 2					
Injury	Nil	Dama	ge	Nil	Pha	hase Launch		;h		PIC Age	62
This incid taxied to	ent occurred dur position for the f	ing the 34 irst launc	4th FAI V ch of the	Vorld Glidi day, both	ng Cha brake	ampio slave	onships cylinde	at Ben ers faile	alla V ed and	'ic. As the to d one wheel	w plane was locked. The

aircraft was removed from service and a Licensed Aircraft Maintenance Engineer replaced the brake pads, replenished the brake fluid and bled the lines of air.

ment
ailed
/el
3
nd

Date	17-Jan-2017	Region		NSWGA		SOAR Report Nbr				S-0910	
Level 1	Airspace		Level 2	Airspac	ngement Level			3	Airspace Infringement		
A/C Model 1		ASW 28-18				A/C Model 2					
Injury	Nil Dama		ge	Nil F		ase Therr		nalling		PIC Age	45
This incident occurred on Day 7 of the 34th FAI World Gliding Championships at Benalla Vic. The pilot failed											
to maintain adequate situational awareness and infringed controlled airspace by over 200ft while											
thermalling close to the airspace boundary and received a scoring penalty. This incident highlights the											
importance of pilots maintaining adequate separation from airspace boundaries, both laterally and											
vertically. When flying near airspace boundaries pilots must ensure they use sensible tolerances to airspace.											
AIP ENR 1.1, paragraph 19.12 states: "For aircraft operating in close proximity to an airspace boundary											
where there is a risk of an airspace infringement, the pilot in command should consider obtaining a clearance											
to enter the airspace or altering track to remain well clear."											

Date	18-Jan-2017	Region		VSA			SOAR Report Nbr				S-1945	
Level 1	Operational		Leve	vel 2 Miscella		cellar	neous		Level 3		Other Miscellaneous	
A/C Mod	el 1	A/C					Model	2	N/A			
Injury	Nil	Damage			Nil	Phase		N/A			PIC Age	
REPCON REPORT - ATSB Reference AR201700005												
Reporter's concern												



Accident and Incident Summaries

The reporter expressed a safety concern related to the safety culture which was encouraged and allowed to continue at the recent World Gliding Competition held at Benalla in January 2017. The reporter advised that there was known risk taking and aggressive flying from competitors which has resulted in at least two midair collisions during the competition. There are videos posted on the competition YouTube channel taken by pilots holding hand held cameras in the cockpit of a single seat glider while flying in a thermal with multiple gliders in the area. These 'gaggles' require full pilot attention to the actual flying in the thermal, but also to maintain separation from the multiple gliders flying in close proximity. These videos are an example of the known behaviours, which were allowed to continue during the competition – being rewarded by posting on the competition channel – rather than the pilot being educated on the safety implications. **Regulator's response (Regulator 1)**

The Gliding Federation of Australia Inc (GFA), the organisation responsible for the administration of sport and recreational gliding and sailplane activities in Australia, was supplied with the report. The following is a version of the GFA's investigation report:

The Gliding Federation of Australia Inc. has investigated the reported concerns, namely that:

- the competition organisers 'encouraged and allowed to continue at the recent World Gliding Competition held at Benalla in January 2017' a negative safety culture.
- 'there was known risk taking and aggressive flying from competitors which has resulted in at least two mid-air collisions during the competition.'
- there were 'videos posted on the competition YouTube channel taken by pilots holding hand held cameras in the cockpit of a single seat glider while flying in a thermal with multiple gliders in the area.'
- 'these 'videos are an example of the known behaviours, which were allowed to continue during the competition being rewarded by posting on the competition channel rather than the pilot being educated on the safety implications.'

Agreed issues

The Gliding Federation of Australia Inc (GFA) agrees that there were two mid-air collisions between gliders during the 2017 World Gliding Championships (WGC2017). These are the subject of investigation by GFA, and were reported to ATSB and CASA in accordance with our agreements and obligations.

The first accident resulted in minor air-to-air contact, with both gliders landing safely and pilots uninjured. The second accident resulted in loss of both gliders, bail-out action by both pilots and some consequential injuries. These facts are not disputed.

GFA agrees that there are YouTube videos taken by pilots flying single-seater gliders while flying in thermal gaggles with multiple other gliders in the area, including on the WGC2017 YouTube channel. The presence of gliding inflight videos and related comments on social media is not disputed.

Disagreed issues

GFA specifically disagrees with allegations that the World Gliding Championships 2017 organisers have either:

- encouraged or allowed to continue an unsafe safety culture
- encouraged or allowed to continue unsafe airmanship standards and operational practices
- encouraged risk taking and aggressive flying practices

• rewarded pilots for unsafe behaviours, rather than pilots being educated on safety implications. This response provides context on:

- how safety and operations in the 2017 World Gliding Championships were managed
- specific pilot safety briefing topics and presentations, addressing risks in gaggle flying and flying in close proximity to other gliders in competition, and pilot behaviour and risk appetite
- task setting arrangements and other responses to reduce the risks of large gaggles forming or collisions with other aircraft
- the primacy of Pilot In-Command responsibility for in-flight actions and decisions.

Overview



Accident and Incident Summaries

Sensationalised reports, although very good at generating public attention, are seldom balanced or objective and this report is believed to be no exception.

Our investigation did not reveal any evidence to support the allegation that the organisers were fostering a negative safety culture. To the contrary, investigations revealed that the organisers had a strong focus on risk management during the competition period as we will elaborate further.

During the course of the competition, there were two mid-air collisions and two near misses.

Each of these are being investigated, and analysis suggests the limitations of both single pilot operations and 'see-and-avoid', coupled with blind arcs and field of view limitations contributed to these events. While the reporter was correct that there were videos posted on social media by pilots using hand-held cameras, the use of hand-held cameras was the exception rather than the rule. When it was brought to the attention of the organisers, pilots were briefed not to use them and, to the organiser's knowledge, all pilots complied. **Dangerous recreational activity**

Gliding is a 'dangerous recreational activity' because it involves the significant risk of physical harm and a risk will be 'significant' if there is a real chance that it will materialise.

Some level of physical risk is implicit to any sport and recreation. Like many sports and recreational activities, gliding involves high-speed, extreme effort, exposure to height, close proximity to other aircraft and environmental factors such as the weather.

To the outside observer, such risks may be considered unacceptable. However, participants accept that risk is involved when participating in these activities. At the same time, the organisers are aware of their responsibility and take steps to support the safety of participants, spectators, volunteers and the general public.

Competition statistics

The competition commenced on 5 January 2017 with the first of three practice days. These practice days allowed the organisers to fine tune their operations and identify risks that were not previously foreseen. The competition commenced in earnest on 10 January 2017 and over the course of the next ten days, pilots flew tasks on eight days, although some classes flew more task days than others due to poor weather conditions precluding the launch of the entire fleet.

During the course of the event, the organisers were launching, from a single runway strip, up to 115 gliders each day in under 90 minutes. Over the course of the event, the thirteen tow planes conducted 1,019 glider launches, and self-launching sailplanes flew 105 launches.

There were a total of 3,267 movements at Benalla airfield, Victoria (Vic.), over the 17 days of the competition. The glider pilots flew tasks of up to 750 kilometres in distance and covered over 450,000 kilometres during the period; flying as far afield as Rankin Springs and West Wyalong, NSW to the North, Mount Beauty, Vic. to the East, Thornton, Vic. to the South and St Arnaud, Vic. to the West.

Competition risk management

The organisation

Planning for the 2017 World Championship spanned more than two years and a robust Risk Management Plan was developed and tested during the January 2016 'pre-world' championship event that was also run from Benalla, Vic. The organisers applied a clear process to identify risks, set an acceptable level for risks and took steps to keep risks at that level. Risks were managed by assessing potential consequences and likelihood, working out clear actions and designing a response plan. The organisers also met with emergency service personnel, CASA staff and the aerodrome operator to assist in the development of the risk management plan.

Key responsibilities were assigned to specific people in areas such as operations management, task setting, marshalling gliders and launch operations. Risk review processes were implemented, registers of occurrences and complaints were maintained and monitored, risks were reviewed, communication and consultation processes were implemented, and all team members were trained on risk management. In fact, all of the organisation team, contractors, volunteers, and participants involved in the event were informed and aware of the risk management process.



Accident and Incident Summaries

On each flying day the organisers sent an email advisory to all major airspace users in the task area. The advisory provided details of the task area, operational altitudes expected for the day, the direction gliders would be heading, and estimated arrival times at nominated 'choke points' on the return to Benalla. Rules and governance

The organisation, rules and governance arrangements for the 2017 World Gliding Championships (WGC) at Benalla are provided at the competition website.

The championships were conducted in accordance with Fédération Aéronautique Internationale (FAI) Rules, as managed by the International Gliding Commission (IGC).

These rules include task setting, starting, finishing, scoring and operational requirements.

The rules also mandated use of FLARM (FLARM is an EASA-approved electronic system used to selectively alert pilots to potential collisions between aircraft. It is not formally an implementation of ADS-B, as it is optimized for the specific needs of light aircraft, not for long-range communication or ATC interaction.) to aid in collision avoidance, and the wearing of parachutes in competition flights. Note that these rules did not exclude flying in gaggles in thermals, nor team flying practices to provide competitive advantage. The FAI Competition Rules were supplemented by Benalla Local Procedures. This document also summarises the competition organisation and names of officers in various roles.

Pilots also had access to the GFA Competition Safety Pack dated October 2013, which contained detailed operational safety guidance for competitors, including lookout and collision avoidance issues. This was a reference document for the Mandatory Pilots Safety Briefing conducted on Thursday 5th January. <u>The organising team</u>

The WGC Contest Director was [Name 1], an experienced world competition pilot and GFA Executive member. While he had overall responsibility for the safe and effective conduct of a viable competition activity, he was assisted by a large team of officers and operational staff, each contributing to safety outcomes.

[Name 2], another experienced international competition pilot, was the competition Task Setter, responsible each day for designing and setting cross-country soaring tasks for three separate classes of gliders, cognizant of meteorological conditions and available soaring time.

[Name 3], an experienced pilot and instructor, was the appointed Safety Officer, representing the GFA Operations Department in the competition organisation. He conducted and arranged daily safety briefings during the competition.

[Name 3] also advised the Competition Director on safety issues, liaised with GFA Executive Manager Operations on accidents and incidents, and worked with both Team Captains and the Pilots Safety Committee on issues of concern. He assisted in investigation of the collision accidents. He also worked with the Contest Director and Task Setter on spatial and temporal aspects of task design to reduce the probability of large thermal gaggles and conflicts between gliders.

The pilots

Pilots are also responsible for managing their own risk and displaying sound airmanship.

Glider pilots are taught to lookout at all times, manage workload, mitigate risk, correct errors, and make good decisions. However, a single person can be more easily overwhelmed when faced with multiple decisions to make, and task management can quickly become difficult for even seasoned pilots when things go wrong. Consequently, errors can and will be made.

All pilots participating in the competition were competent, experienced and current. However, by its very nature competition flying has a number of threats that increase the likelihood of pilots making an error that could lead to reduced safety margins, or may contribute to an incident or accident. The type of threats that competition pilots need to manage include:

- environmental issues such as, flying with other gliders, flying from an unfamiliar airfield, weather changes, unpredictable lift, different terrain with changes in height above sea level, partly unlandable country, or flat but very small paddocks
- navigational challenges
- physiological factors, such as fatigue, dehydration, hunger, hypoxia, impatience, frustration, optimism bias and overconfidence


Accident and Incident Summaries

- time pressure on the ground (including Launch delays) and in flight
- pressure to get home
- risk of outlanding
- final glides.
- All these threats increase the likelihood of pilots making an error that could lead to reduced safety margins, or may contribute to an incident or accident.

To quote from former World Gliding Champion Karol Staryszak, 8 May 2016:

'It is often said that the organiser should do this or that... They should call a day, they should create an easier task, they should make sure there are outlanding fields along the task route, they should not launch so many gliders at the same time, etc. But the task is not an order, you do not have to fly it; the decision to fly is yours and yours only!

Whether I go over an area with no fields and no option to return, or my final glide is below the glide path, or I fly in a gaggle, or in the clouds—this decision is only MINE!'

Task setting responses to reduce collision risk

The World Gliding Championships was a highly competitive event, with elite and experienced pilots flying very fast on long cross-country tasks, often in close company, often shadowing their competitors. AS/NZS 31000 Risk Management highlights that risk (and opportunity) has dimensions of probability (likelihood) and consequence. The probability of mid-air collision in gliding events is increased when pilots fly in large gaggles in thermals, with large numbers of aircraft in the rising air mass in close relative proximity. The probability of gaggle flying occurring is a function of:

- weather
- task design and
- pilot behaviour, competitiveness and risk appetite.

The probability of gaggle flying occurring is higher in 'blue' conditions, without cumulus clouds marking thermal position and cloud shape indicating thermal strength. During much of the competition period, blue days were experienced.

A number of measures were consciously addressed to discourage gaggle flying and reduce collision risk. These measures are based upon increasing spatial (distance) and temporal (time) separation of gliders in a competition. These included:

- setting different tasks for the three classes involved in the competition
- increasing spatial separation between the tasks, in particular on the first leg of the task, sending classes out in differing directions
- using dispersed start lines, SW, NW, NE and SE of Benalla AD, for the different classes, to reduce start gaggle size
- setting tasks of long duration relative to the projected soaring meteorological conditions, to encourage pilots to make rapid progress and not linger in groups or gaggles
- minimising overlaps between tasks for the three classes, and planning for temporal separation and minimum crossing angles where overlaps occurred
- planning Assigned Area Tasks, rather than fixed turnpoint tasks, to encourage pilot decisions to turn at dispersed locations and achieve greater separation.

All pilots were repeatedly warned about the risks of aggressive flying, sharp pullups, turning inside other gliders in thermals, joining thermals incorrectly, and poor lookout or situational awareness. They were specifically briefed on the limitations of FLARM for collision avoidance, and on the proximity data recorded. Mandatory data loggers were used and traces analysed, to assist in investigating allegations of dangerous flying, as well as instances where near misses had occurred. Some fixed video recordings assisted in capturing useful data on near misses. The Safety Officer used Pilot Briefings, meetings with pilots, meetings with Team Captains and video recordings to highlight risk and safety issues.

Inflight videos and social media

There are no rules governing the use of cameras and recording devices in aircraft and gliders. These are not prohibited by the competition rules applying to the WGC event.



Accident and Incident Summaries

GFA does not encourage the use of handheld cameras and devices for recoding inflight video, particularly in high workload situations, or where distraction may have adverse consequences. For this reason, GFA prefers that when cameras and recording technology are used, they should be either fixed mount or swivel on a fixed base, or else on headband or cap mount. They should not require constant viewfinder monitoring by the operator.

GFA has also found video footage to be beneficial to safety, training and instruction. A near miss between a climbing motor glider and a climbing glider/tow plane combination during the WGC event was recorded on video, which was in turn used to re-educate the pilots concerned and brief all pilots. Other accidents have seen video recording information used in accident investigation.

The decision to use a camera, data recorder, or other technology in the cockpit, at any given time, is primarily an issue for the Pilot In-Command. They are responsible for their own decisions and flight management. No amount of prescription or rule setting will change that.

Similarly, the decision to post still photos or video recordings of inflight situations on social media (Twitter, FaceBook, YouTube, Instagram etc.) is also an issue for the pilot-in-command and the owner of the social media account.

GFA does not accept that the organisers were encouraging risk taking and aggressive flying, rewarding pilots for unsafe behaviours in use of inflight video on social media. It is evident from much of the video on social media that pilots were trying to record and highlight the increased risk in gaggles, not glorify the practice. Many video clips used fixed mounts. Some handheld recordings were clearly made by gliders at the top of the thermal gaggle, not enmeshed in the higher risk environment lower down. Some recordings show the pilot stowing the camera in order to deal with higher priority airmanship tasks. Use of handheld cameras was a safety briefing topic on 19th January. Thermalling safety and lookout in gaggles were safety briefing topics on 13th January.

Safety culture

The safety culture of the event was positive and was supported by the organisers, the team captains from the 27 competing nations, the internationally appointed stewards and the jury members. A safety committee was convened, comprising one competitor from each of the three classes and the competition safety officer. The safety committee dealt with concerns raised by pilots about the flying conduct of other pilots.

The competition rules required a compulsory safety briefing at the beginning of the competition and regular safety communication throughout. At the start of the competition on 5 January 2017, a general safety briefing was delivered, and further safety briefings were delivered as issues became apparent. All reported safety concerns were investigated using GPS records of the flights that enabled a reasonably accurate assessment of the actions of each pilot. In most cases, the complaint was found to be not sustained, and often involved less than ideal decision making by the pilots involved or unfortunate coincidences. In cases where poor behaviour by a pilot was evident, that pilot was interviewed, together with their team captain, and presented with the evidence so they could see how their behaviour had created a hazardous situation. The pilots and team captains were then placed on notice that a repeat of such behaviours would result in significant penalties. In all cases, the pilots did not re-offend. The process of self-awareness and the use of peer feedback, made pilots aware of their vulnerability to different types of errors, decision styles and biases.

Risk mitigation strategies

There is considerable evidence of actions by WGC officers to brief, educate, oversee and intervene where necessary to promote the required safety first culture.

A Fly-Tool Safety Reporting process was specifically introduced to facilitate reporting of issues by international pilots, supplementing the GFA accident and incident reporting system which many of them were unfamiliar with. Pilot Safety Reports were also introduced to allow pilots to advise who was causing concerns re safety.

Rules and Competition Safety Guide documents were provided for reference by teams and pilots.



Accident and Incident Summaries

A pilot safety committee was formed, to assist the safety officer and contest director. A mandatory safety briefing was held before the competition, and then each morning during the competition. These briefings included:

- close call re climbing motor-glider and tow plane-glider combination, recorded on video camera
- changes to procedures to improve separation between tow planes and motor gliders
- role of pilot safety committee, nominations and election of pilot representatives
- safety advice re gaggle flying, flying in close company, techniques for joining thermals, clearance, lookout, leaving
- dangers in gaggle flying
- analysis of first collision, gaggle safety and lookout when flying straight, flight trace analysis video
- analysis of complaint, flight trace regarding overtaking in straight flight
- use of pilot safety reports, nomination of pilots causing concerns to other pilots
- presentation by pilot involved in second collision and bail-out
- flying too close in cruise
- winning versus safety, relative priorities
- use of cameras in flight.

Task design measures described above were used to reduce the probability of gaggle flying in thermals and between thermals.

Summary

Overall GFA found the safety culture was positive and steps were taken to reduce safety hazards as they were identified. The Organisers actively worked to reduce risk, which resulted in some significant improvement and reduction in reported incidents.

A report is being prepared for the international Gliding Commission to encourage some rule changes that would reduce the risk faced by pilots. Many of these changes have already been implemented in Australia with proven benefit.

The organisers also identified methods to extract meaningful data from the GPS flight records to help identify pilots with a higher risk profile, and can also be used to issue penalties to the worst offenders.

Regulator's response (Regulator 2)

CASA has reviewed the REPCON and the information contained in the report and has the following comments:

There appears to be little evidence to support the claim that the organisers encouraged aggressive flying practices, increased risk taking and rewarded unsafe behaviour.

The GFA response provided to the REPCON did not suggest that adverse safety outcomes were as a result of the use of handheld cameras and highlighted the safety measures taken by the organisers when this issue was identified during the competition.

CASA attended the event also during this time and witnessed the competition mass briefing prior to operations, observed the departures and return of all glider classes on 16th of January 2017 and it was clearly evident that the organisers consciously attempted to address close proximity operations by deconfliction of routes and briefed pilots on the priorities of safe flight rather than winning.

It is CASA's opinion that while some persons may have used handheld devices to capture video, there does not appear to be any suggestion that unsafe operations or behaviours were actively encouraged by the WGC organisers, in fact tangible evidence exists that the organisers addressed known and emerging safety risks at the time of the high tempo operations.

CASA considers the steps, investigations and mitigators that the GFA have provided in response to the REPCON as appropriate under the circumstances of the World Gliding Competition at Benalla.

Date	21-Jan-2017	Region		WAGA	SOAR Repo	ort Nbr	S-0908
Level 1	Operational	Le	vel 2	Ground Ope	erations	Level 3	Taxiing collision/near
							collision



A/C Model 1	Standard Libelle 201 B A/C Model 2											
Injury	Nil	Damage Minor Phase Ground Ops PIC Age										
Whilst towing to the launch point on a narrow taxiway, the vehicle driver moved over to allow a car to pass												
in the opposite direction. During the course of this manoeuvre the trailing edge of the starboard aileron												
struck a star	struck a star picket that the driver did not see. The collision uncoupled the tow hitch and the aircraft pivoted											
about the sta	ar-picket resu	lting in the trai	ling edge of th	ne por	t win	g impacting th	ie bao	ck of the car	. While the			
car was signi	ficantly dama	ged, the glider	suffered only	minoi	r dan	hage and was	cleare	ed to fly afte	er a thorough			
inspection. T	his accident h	nighlights the n	eed to mainta	in situ	atior	nal awareness	wher	n towing a g	lider. It also			
serves as a reminder to drivers of vehicles on manoeuvring areas that they must yield to all aircraft,												
including glio	ders under to	Ν.										

Date	21-Jan-2017	Regior	n 🛛	VSA		SOA	AR Repo	ort Nbr		S-	0932
Level 1	Operational		Level 2	Rur	nway E	vent	S	Level	3	Other Run	way Events
A/C Mod	el 1		Janu	is B		A/C	Model	2	Unk	nown	
Injury Nil Damage Nil Phase Landing PIC Age 6								63			
The glide	r launched from	runway 2	17 on the	e last gliding	g flight	t of th	ne day v	with th	e inte	ention of lan	ding long on
runway C)9, into a south-e	asterly c	rosswind	, to finish n	ear th	e har	ngars. V	Vhen tl	ne stu	ident pilot j	oined
downwin	id and made a ra	dio broa	dcast the	re were no	other	aircr	aft on t	he run	ways	or in the cir	cuit area. As
the aircra	aft passed the mi	d-downv	vind posi	tion the co	mman	d pilo	ot notic	ed a po	owere	ed aircraft o	n the taxiway
about to	enter runway 17	. The cor	nmand p	ilot made t	wo rae	dio tr	ansmis	sions o	n the	CTAF to ale	rt the
powered	aircraft to the g	ider's int	entions	out no resp	onse v	vas h	eard. A	fter the	e stuc	lent turned	onto the
base leg	the command pi	ot obser	ved the p	owered air	rcraft o	on ru	nway 1	7 lining	g up fo	or take-off,	so the aiming
point wa	s modified to allo	ow the gl	ider to p	ass well bey	yond t	he ru	nway ii	ntersec	tion.	As the powe	ered aircraft
took-off the glider passed behind and above and a safe landing ensued. The glider pilots did not hear any								hear any			
radio call	s from the powe	red aircr	aft.								

Date	22-Jan-2017	017 Region GQ SOAR Report Nbr S-0912									
Level 1	Airspace		Level	2 Aircra	ift Sep	arati	on	Level	3	Near collis	ion
A/C Mod	el 1		IS-2	28B2		A/C	Model	2	Gyro	ocopter	
Injury	Nil	Dama	age	Nil	Pha	se	Landi	ng		PIC Age	69
Upon ret	urning to the air	field follo	wing ar	i air experier	nce flig	ght, tl	he glide	er flew	throu	gh heavy si	nk and lost a
significan	t amount of hei	ght. The c	ommar	id pilot had i	ntend	ed to	join a	standaı	d left	t-hand circu	it for the
operation	nal runway but d	ue to the	loss of	height decid	led to	cond	uct a ri	ght-har	nd cir	cuit. The gli	der pilot
gave a br	gave a broadcast on the CTAF and emphasised the glider was entering downwind for a right-hand circuit.										
Shortly a	fterwards the gli	der pilot	heard a	radio broad	cast fr	om a	nother	aircraf	t in ci	rcuit and id	entified a
gyrocopt	er on mid-down	wind for a	a left-ha	nd circuit. T	he gyr	осор	ter was	on fina	al app	broach as th	e glider pilot
approach	ed the base leg.	As the gl	ider tur	ned onto the	e base	leg t	he pilot	t made	a CTA	AF broadcas	t advising
turning b	ase from the rig	ht-hand s	ide of t	ne circuit bu	t did n	ot re	ceive a	n ackno	owled	lgement for	m the
gyrocopt	er pilot, which co	ontinued	its desc	ent across th	ne glid	er's f	light pa	ith. Wh	ile th	e glider was	s now about
300ft beł	nind the gyrocop	ter and c	ommitt	ed to landing	g, the g	glider	r pilot v	vas unc	once	rned as ther	e were
options t	o land on the gra	ass verges	s either	side of the r	unway	/. The	gyroco	opter la	inded	and stoppe	ed on the
runway t	hreshold markin	gs, so the	glider	pilot elected	to lan	d on	the gra	ss to th	ne left	t of the bitu	men runway
in case th	e gyrocopter tax	kied off to	o the rig	ht as they te	end to	do at	t this re	gional	airpo	rt. Upon lan	ding the
glider rol	led past the gyro	copter at	: a mini	mal but safe	distan	ice. It	t was la	ter det	ermir	ned that the	gyrocopter
had hear	d the glider's rac	lio calls b	ut had i	not sighted t	he glic	ler in	circuit	•			

Date 22-Jan-2017 Region NSWGA SOAR Report Nbr S-0918
--



Level 1	Operational		Level 2	2 Aircraft Contro				Level 3		Hard landing	
A/C Mod	el 1		LS	4-a		A/C	Model	2			
Injury	Nil	Dama	age S	Substantial	Pha	ise	Landi	ng		PIC Age	71
The low h	nours pilot repor	ted expe	riencing	strong lift o	n the	base	leg and	l did no	ot pro	perly manag	ge the flight
profile, re	esulting in the fi	hal appro	ach bein	g flown too	fast a	nd to	o high.	In an e	effort	to slow dov	vn the pilot
increased	the amount of	airbrake v	when clo	ose to the gr	ound	and ι	uninten	tionally	y pusł	ned the sticl	< forward at
the same	time. The glide	struck th	ie groun	d nose first,	rebo	undeo	d into t	he air a	nd th	en crashed	down hard.
The forward fuselage suffered substantial damage. Causal factors include inexperience, lack of flying											
currency, and mishandling of the controls. The pilot underwent remedial training.											

Date	26-Jan-2017	Region		VSA		SOA	R Repo	ort Nbr		S-	0913	
Level 1	Operational	Le	Level 2 Runway Events Level 3 Runway incursion									
A/C Mod	el 1	[uo Dis	cus		A/C	Mode	2				
Injury	Nil	Damage	Sul	ostantial	Pha	se	Landi	ng		PIC Age	63	
Following	g an otherwise ur	neventful 'co	nversio	on to type'	' flight	t, the	aircrat	ft retur	ned to	o the circuit	. The pilot	
under co	nversion had littl	e experience	in larg	ge span hig	gh per	form	ance t	wo-sea	t airci	raft and tur	ned onto	
final appi	roach too high. D	uring the de	scent t	he pilots n	otice	d a tr	actor o	occupyi	ng ru	nway 'grass	left' close to	
the bitun	nen runway near	their aiming	point	and headir	ng tov	wards	s them.	. The Pi	lot un	der conver	sion decided	
to land o	n runway 'Grass l	eft' to the l	eft of tl	he tractor,	as th	is wa	s consi	dered t	he be	est option b	ecause the	
tractor w	as too close to th	ne bitumen r	unway	to land sa	fely o	n it, a	and the	e grass v	verge	to the righ	t did not	
have an a	dequate oversho	oot area. De	pite th	ie pilot app	plying	; full a	airbrak	e short	ly afte	er turning o	nto final, the	
aircraft re	emained in an ov	ershoot pos	tion sc	the instru	ictor	took	contro	l at abo	ut 10	0 ft AGL wh	en the	
aircraft w	vas about half-wa	iy down the	runwa	y, and flew	/ an 'S	5' turr	n to the	e right t	o los	e height wit	hout gaining	
distance.	As the instructor	r rolled out o	of the 'S	5 turn' and	llined	l up f	or the	flare, th	ne pilo	ots noticed	the tractor	
had turne	ed to the right to	wards the C	ub han	gar, and w	vas tra	avelir	ng acro	ss the i	ntenc	led landing	path. The	
instructo	r executed a stee	ep low- level	evasiv	e turn to th	he rig	ht an	d narro	owly mi	ssed	the tractor.		
Unfortun	ately, the right w	ingtip struc	the gi	round duri	ng th	e mai	noeuvr	e and t	he air	craft slewe	d, touching	
down wit	h sideways mom	entum and	liding	some 40m	in th	e dire	ection (of landi	ng. N	o person wa	as injured	
but the a	ircraft was substa	antially dam	aged; s	uffering a	broke	en tai	lboom	i, dama	ged e	elevator and	l a collapsed	
undercar	riage. The tractor	r driver was	a liceno	ced pilot w	/ho w	as on	the ae	erodron	ne ma	anagement	committee,	
and the t	ractor was being	used to slas	n the r	unway gra	ss. In	e tra	Ctor Wa	as not f	itted	with an air	band radio	
and the d	iriver was not usi	ng a nand-n	eld rad	IO as its ba	attery	was	flat. At	this AL	A the	ere is no req	uirement for	
a vHF rac	ilo to be carried i	by the tracto	r oper	ator. while	e the i	tracto	or drive	er was i		ar with the	principles of	
see and a	ivoid and did scal	n the sky for	aircrai	t before e	nterir	ng the	e runw	ay, the	аск с	of a servicea	ible radio	
Impeded	the driver's situa	itional awar	eness.	i ne tractor	r arive	er firs	st saw i	the glid	er ne	ading towa	as the	
tractor fr	om the left, so th	ie driver turi	ied to	the right to	o mo\	/e ou		e way o	niy to	see the gli	der turn	
toward th	ite ractor once a	gain. As a co	nseque	ence of this	s acci	dent,	the ae	eroaron	ne ma	anagement	committee	
listoning	watch on the CT	or using ven	ues or	all aircraft	Main Main	as dr		enicie d	will	lso bo coor	dinated with	
the airfie		AF allu give i	ναγιΟ	an dhùidh	. widli	itella		livilles	wiii d	130 DE COOL		
the airfie	iu users.											





Date	28-Jan-2017	Region	I	WAGA		SOAR Report Nbr				S-0915	
Level 1	Consequential E	vents Level 2 Low Circuit Level 3					3	Low Circuit			
A/C Mod	Model 1 Hornet A/C Model 2							2			
Injury	ury Nil Damage Nil Phase Landing									PIC Age	68
The pilot	made a late decis	sion to b	reak off	the flight ar	nd the	n pro	ceedeo	d to fly a	a low	and modifie	ed circuit.
During ev	very flight pilots n	eed to c	onsider	when to sta	rt hea	ding	for the	circuit	joinir	ng area. The	decision will
be influe	nced by wind stre	ength and	d directi	on, and the	locati	on fo	r the ci	rcuit joi	ining	area. Pilots	must make a
positive decision to join the circuit to land, and plan to arrive at the circuit joining area between 800 ft –									800 ft –		
1,000 ft AGL, depending on glider performance.											





Date	29-Jan-2017	Regior	า	GQ		SOA	AR Repo	ort Nbr		S-	0914
Level 1	Operational		Level 2 Airframe Level 3				3	Landing	Landing		
									gear/Indication		
A/C Mod	Model 1 Blanik L13 A1 A/C Model 2										
Injury	Nil Damage Nil Phase Landing PIC Age 48									48	
The flight	t was to convert	an exper	ienced a	erotow pilo	t to w	inch l	launchi	ng. The	'stuc	lent' had 4 f	lights earlier
in the da	y in the Blanik ar	nd had de	emonstra	ted good te	echniq	ue. A	fter a s	imulate	ed lau	inch failure	at a height
of 200 ft,	the 'student' lar	nded stra	ight ahea	id on the ru	inway	cent	reline.	Upon t	oucho	down the Ur	ndercarriage
collapsed	l and the aircraft	came to	an abrup	ot halt due	to the	appli	ication	of whe	el bra	ike when th	e
undercar	riage is retracted	d. The co	ckpit fille	d with the f	fumes	of bu	urnt rul	ber fu	mes a	ind a small a	amount of
smoke. B	oth Pilots were a	able egre	ss withou	ıt harm. It v	was de	eterm	ined th	at the	unde	rcarriage wa	as not
properly locked in the 'down' position. The POH requires the pilot to check for correct locking by a firm									/ a firm		
rearward pull on the undercarriage operating lever without turning the handle inboard.											

Date	31-Jan-2017	Regior	on VSA SOAR Report Nbr S-0919					0919				
Level 1	Consequential	Events	Leve	12	Lo	ow Cir	cuit		Level	3	Low Circui	t
A/C Mod	el 1			Ka 6	5		A/C	Model	2			
Injury Nil Damage Nil Phase Landing PIC Age												
The low h	The low hour's pilot was participating in a Regional coaching course with the aim of achieving some Badge											
flights. W	hile the pilot int	ended to	fly the	eir c	lub's SZD	51 Jun	ior ir	n which	they w	/ere f	amiliar, the	aircraft was
unavailat	ole so a fellow clu	ıb memb	er offe	ered	l the use o	f a KA	6. Th	e pilot	undert	ook a	type conver	rsion flight
two days	earlier and was	assessed	as cor	mpe	tent. On t	he day	/ of tł	ne incic	lent the	e pilot	t was attem	pting a 50km
cross-cou	intry flight to qua	alify for a	Silver	^r Bac	dge. The p	ilot wa	as the	e secon	d of te	n pilo	ts launch an	d took off
on RWY 1	7 by aerotow at	approxir	nately	131	L5 hours ir	nto a b	lue s	ky. At a	ipproxi	mate	y 1400ft AG	iL the pilot
released from tow having observed another glider nearby climbing rapidly in a thermal. The pilot did not								t did not				
locate the expected strong lift but found a weak thermal just to the north-west of the airfield in which a							which a					



Accident and Incident Summaries

climb was attempted. Observers on the ground noticed the glider's inner wing drop and its nose pitch down followed by a recovery to normal flight on at least two occasions while turning in the thermal. Shortly afterwards the pilot elected to break off the flight as the glider was drifting away from the airfield without any appreciable height gain. The pilot flew into wind on the dead side of RWY 17 and as the glider approached the airfield the pilot noticed the Air Ambulance aircraft taxying on RWY 26 for take-off into the West.



The pilot increased airspeed to quickly cross the extended centreline of RWY 26 and gave a radio call advising of intent to land on RWY17. Unfortunately the radio was off-station and the broadcast was not heard by the Air Ambulance pilot or the gliding operation. The effect of increasing speed was to increase the rate of descent. After passing clear of the RWY 26 centreline the pilot recognised the glider was now low and decided to modify the circuit. At a height of about 400ft AGL the pilot turned 180 degrees to enter a mid-downwind for RWY 17, shortly followed by a 90 degree turn to the right to enter a base leg. The pilot turned onto base prior to crossing the boundary of RWY 26 and then turned onto final approach. The turn onto final was over-ruddered and under-banked, and the pilot was lucky the aircraft had sufficient speed that it did not enter a spin. After the glider made a safe landing on glider RWY17, the Air Ambulance departed. Subsequent investigation revealed:

1. The pilot did not properly understand the speeds to fly the aircraft and was flying too slow for much of the flight.

2. The glider radio was off-channel by 0.1 MHz. The channel selector is easily moved and was most likely knocked prior take-off.

3. The glider pilot could have safely conducted a 'straight-in' approach to RWY 17 but, due to being overloaded and unfamiliar with the aircraft, did not consider this option.

The pilot was debriefed by an instructor and the danger of low-level skidding turns was reinforced. Investigation revealed the pilot's low hours, inexperience on type, flying from an unfamiliar airfield, early release from tow and failure to find a workable thermal caused the pilot to become stressed and



Accident and Incident Summaries

overloaded. This led to handling errors and poor decision making. The pilot agreed to undertake a checkflight exploring spin recognition and recovery, and then to complete a few local soaring flights to familiarise them with both the aircraft and site.



It was determined that the engine stalled after it backfired but an initial inspection could find nothing obviously wrong with the engine, which ran normally when tested. Further investigation identified a small split in the underside of a vacuum hose between a solenoid and the left carburetor. When power was applied and the pressure increased in this hose, the split would open leading to unbalanced carburettors. The damaged hose was replaced and the engine is operating normally.





Date	4-Feb-2017	Region	1	GQ		SOA	R Repo	ort Nbr		S-	0921
Level 1	Technical		Level 2	Powerp	lant/P	ropu	lsion	Level	3	Propeller r	nalfunction
A/C Mod	el 1		TST-1	.0M		A/C	Model	2			
Injury	Nil	Dama	age S	ubstantial	Pha	ase	Launo	h		PIC Age	64
Shortly a	fter take-off and	at a heig	ht of abo	ut 200 fee	t AGL 1	the pi	ilot hea	ird a th	ump	and the eng	ine surged.
The aircr	aft immediately	lost powe	er so the	pilot set th	e engi	ne to	idle, lo	wered	the r	iose down t	o maintain
forward s	speed, and then	shut the o	engine do	own. The p	ilot tu	rned	the air	craft to	the r	ight at the c	ross strip to
take adva	antage of a longe	er runway	and land	ded safely.	Subse	quen	t inspe	ction re	eveale	ed damage t	o propeller
mount, p	ropeller drive be	elt and the	e propell	er. Investig	ation	revea	led tha	it one c	of the	two bolts th	nat attach a
bracket a	t the top of the	reduction	ı box hou	sing had n	ot bee	n tigł	ntened	proper	ly and	d had looser	ned over
time due	to vibration. Thi	s resulted	d in a stre	ess fracture	e of th	e bolt	: head,	which	broke	off and allo	wed the
propeller	shaft to move f	orward ar	nd down.	In turn, th	is resu	lted i	in the c	lrive be	elt cor	ning off and	l tangling
around th	ne hub of the pro	opeller. T	he destru	ictive force	es insta	antly	created	d by the	e sudo	den imbalan	ce of the
propeller	shaft cracked tw	vo of the	three na	rrow suppo	ort sec	tions	of the	reducti	ion bo	ox housing.	Fatigue
breaks ar	e usually caused	l by insuff	ficient tig	htening an	d the	lack c	of prop	er prelo	oad o	r clamping f	orce. This
results in	movement betw	veen the	parts of	he assemb	ly and	l the l	bendin	g back a	and fo	orth or cycli	c stressing of
the faste	ner. Eventually,	cracks wil	I progres	s to the po	int tha	at the	bolt ca	an no lo	onger	support its	designed
load. At t	his point the bo	t fails wit	h varying	g conseque	nces.	For th	ne bolt	to be p	rope	rly loaded ai	nd prevent
prematu	re failure, a desi	gnated an	nount of	torque mu	st be a	applie	ed. Prop	per tor	que re	educes the p	ossibility of
the bolt l	oosening while i	n service.	The cori	ect torque	to ap	ply w	hen yo	u are ti	ghter	ning an asse	mbly is
based on	many variables.	The bolt	is subjec	ted to two	stress	es wł	nen it is	s tighte	ned.	These stress	es are
tension a	nd torsion. Tens	ion is the	desired	stress, whi	le tors	ion is	the un	desirat	ole sti	ress caused	by friction. A
large per	centage of appli	ed torque	e is used t	o overcom	ne this	fricti	on, so 1	that on	ly ten	sion remain	s after
tightenin	g.										





Date	4-Feb-2017	Region VSA				SOAR Report Nbr				S-0922		
Level 1	Operational	Level 2 Ground Op				perations Level 3			3	Taxiing collision/near		
										collision		
A/C Mod	C Model 1 ASW 27-18 A/C Model 2 Mosquito											
Injury	Nil	Damage Nil Phase Ground Ops								PIC Age	77	
During a	gliding Competit	petition the three classes were given separate times to marshal to allow for an order						an orderly				
gridding	process. One pile	ot marsha	alled late	and positic	oned t	heir g	glider ir	the m	idst o	f another cl	ass that was	
in the pro	ocess of gridding	. Upon re	alising th	e error the	e pilot	rever	sed the	e glider	out c	of the position	on with the	
towing ve	ehicle and, despi	te other	pilots call	ing on the	driver	to st	op, its	left win	igtip r	missed the r	udder of	
another g	glider by centime	etres. Th	e pilot the	en attempt	ed to	drive	forwa	d but v	vas st	opped by th	ne other	
pilots jus	ilots just prior to the wingtip colliding with the other glider. Manoeuvring a glider with a towing vehicle in											
close pro	se proximity to other gliders is unwise as the driver has a limited field of view. In such cases it is safer to							: is safer to				



Accident and Incident Summaries

unhitch the glider from the vehicle and move it by hand. The driver was counselled by the Competition Safety Officer.

Date	10-Feb-2017	Region		GQ		SOA	R Repo	ort Nbr		S-	0927	
Level 1	Airspace		Level 2	Aircra	ft Sep	arati	on	Level	3	Near collis	ion	
A/C Mod	el 1	Stan	ndard Lib	elle 201 B		A/C	Model	2	Emb	oraer EMB-1	.20 ER	
Injury	Nil	Dama	ge	Nil	Pha	ise	In-Flig	ght		PIC Age	63	
When ab	When about nine kilometres south-west of the home airfield and at about 5700 feet, the pilot initiated a left											
turn to ei	urn to enter a thermal. After turning through approximately 120 degrees the pilot saw an Embraer ERJ 170-											
100 LR pa	100 LR passenger jet operated by a Northern Australia Regional Airline in a left-hand bank heading towards											
the Wello	amp Regional ai	rport. The	Airliner	passed abo	out 50	0 fee	t belov	v and a	bout	300 to 500 r	metres from	
the glider	. The glider pilot	did not h	lear any r	adio calls	on the	e CTA	F (126.)	7 MHz)	and o	does not kno	ow whether	
the pilots	of the airliner s	aw the glio	der. The	CFI noted t	hat th	nere ł	nas bee	n an in	creas	e in the nun	nber of	
airliners f	rom one particu	lar airline	and dial	ogue has b	een o	pene	d with 1	the airl	ine to	inform the	m of the	
gliding op	erations. Discus	sions were	e also ha	d with the	Regio	nal G	FA AA8	&A Offic	cer ar	nd it was det	termined	
that the (Club would conti	nue to rer	main on t	he existing	g Mult	icom	freque	ncy bu	t that	its pilots we	ould briefed	
on the hi	gh risk areas clos	se to the b	oroadcast	area bour	ndary.							

Date	11-Feb-2017	Region		SAGA		SOA	AR Repo	ort Nbr		S-	0929	
Level 1	Operational	L	Level 2 Runv			vent	S	Level	3	Other Runway Events		
A/C Mod	el 1	М	arianne	e 201B		A/C Mode			AS-ŀ	(13		
Injury	Nil	Damage	mage Nil		Pha	Phase Laund		:h		PIC Age	88	

A glider was cleared to launch by winch while another glider was established on final approach. A member in the control van observed the potential conflict and tried to stop the launch to no avail. A message was then relayed to the winch driver by radio after the "all out" signal had been given but the winch driver did not hear the call due to engine noise. The launch proceeded normally. The pilot of the landing glider saw what was happening and deviated to the right of the runway centreline to provide clearance and landed without further incident. Lookout is the principal method for implementing see-and-avoid. Effective lookout means seeing what is 'out there' and assessing the information that is received before making an appropriate decision. Nothing should happen with regard to taking up slack until the Pilot In-Command (PIC) has ascertained the airspace is clear for launch (Operational Safety Bulletin (OSB) 02/06(1) 'Airspace Clear For Launch' refers). The winch driver also has a part to play in maintaining operational safety, and should have a good overview and understanding of what is happening in the circuit including what aircraft have departed or are inbound. Therefore, winch drivers should wear a quality headset and maintain a 'radio watch' in order to enhance both situational awareness and safety (Operational Safety Bulletin (OSB) 01/13 'Wearing of Headsets - Pilots of Self Launching Gliders and Winch Drivers' refers).

Date	14-Feb-2017	Region		SAGA		SOAR Report Nbr				S-0931		
Level 1	Environment	L	evel 2		Wildli	fe		Level	3	Birdstrike		
A/C Mod	el 1	St	emme S	510-VT		A/C	Model	2				
Injury Nil Damage Nil Phase Thermalling PIC Age 51												
While the	While the glider was thermalling at about 6,300ft AGL enroute during a competition flight, an eagle											
approach	ed from the left	and attack	ed the g	glider, imp	acting	the i	nboard	leadin	g edg	e of the por	t wing.	
Although	the pilots could	not see any	y damag	ge, the con	nman	d pilo	t electe	ed to re	eturn	to base at s	low speed.	
Other pilots in the competition also reported aggressive behaviour by the eagles. Subsequent inspection												
revealed	revealed the aircraft was undamaged. Although hirds and glider pilots often share the same thermal and can											

operate near each other with relative safety, birds can and do occasionally come into contact with a glider.



Accident and Incident Summaries

While it is uncommon that a bird strike causes any harm to aircraft crew, many result in damage to aircraft. Wedge-tailed Eagles are territorial and are known to defend around their nest sites from other Wedge-tailed Eagles and the occasional model airplane, hang glider, glider, fixed-wing aircraft and helicopter.



Date	14-Feb-2017	Regior	1 I	VSA		SOA	AR Repo	ort Nbr		S-0935	
Level 1	Operational		Level 2	Airc	raft C	ontro		Level	3	Control iss	sues
A/C Mod	el 1		Discus	s CS		A/C	Model	2			
Injury Nil Damage Nil Phase Launch PIC Age 70										70	
The hand	grip slid off the	control c	olumn at	100 ft AGL	. durin	g an	aeroto	w launo	ch. Th	e pilot relea	ased from
tow and	completed a safe	e landing.	It is belie	eved the gl	ue sec	uring	; the ha	nd-grip	o to tł	ne control co	olumn
became s	became soft in the heat, therby allowing it to slide free during the take-off. The hand grip was re-attached										
and secu	red by a set scre	w.									

Date17-Feb-2017RegionNSWGASOAR Report NbrS-0937



Level 1	Operational		Level 2	Mis	cellan	eous		Level	3	Rope/Ring	s Airframe	
	-								-	Strike		
A/C Mod	el 1		ASH 30) Mi		A/C	Model	2	Pipe	er PA-25-235	5	
Injury	Nil	Dama	ige	Minor	Pha	se	Landi	ng		PIC Age	65	
On Day 5	of the 2017 Aus	stralian Tw	vo Seat N	ationals th	e glide	ers w	ere grio	dded or	۱ run	way 04 and	the tow	
planes w	ere instructed to	land on r	runway 2	9 and taxy	to the	laun	ch poir	nt. Two	self-l	aunching sa	ilplanes, an	
ASH 30 a	nd an Arcus, ele	cted to tal	ke-off fro	m runway	29 as	it was	s more	into wi	nd. B	ecause the	ASH 30 did	
not have	a steerable nos	e wheel, tl	he pilots	positioned	the gl	ider d	on the	centrel	ine of	^f runway 29	behind the	
displaced	isplaced threshold while the Arcus was parked off to the side of the runway. The crew of the ASH 30 were											
donning	lonning their parachutes in preparation for launch as one of the tow planes turned onto final approach. The											
tow pilot	, who had just c	ompleted	their firs	t launch, el	ected	to la	nd on t	he righ	t-han	d grass verg	ge of runway	
29 clear o	of the ASH 30. T	he tow pil	lot then f	lew a shall	ow ap	proad	ch with	the air	n of t	ouching dov	<i>w</i> n adjacent	
to the ma	arked threshold,	despite b	eing brie	fed earlier	to lan	d wel	l beyoi	nd the d	displa	ced thresho	old. During	
the cours	e of the approa	ch the tow	v plane d	rifted towa	irds th	e bitı	umen r	unway	and t	he trailing r	ope and	
rings fell	across the right-	hand win	gtip of th	e ASH 30 c	ausing	g mine	or dam	age. Th	e ASI	H 30 was rer	noved from	
the runw	ay and did not f	ly. A 55 m	etre tow	rope hang	s abou	t 40 f	feet be	low a to	ow pl	ane at appro	oach speeds.	
Conseque	ently, tow pilots	should alv	ways app	roach high	and la	and lo	ong in p	orefere	nce to	o cutting it f	ine near	
people o	people or objects on the ground, and should avoid landing over the top of parked gliders. If the tow pilot has											
any doub	t about obstacle	e clearanc	e, wheth	er it be bui	ldings,	vehi	cles, pa	arked o	r taxy	ving aircraft	or people	
(especial	especially people), they should drop the rope. When a rope is dropped, it loses forward momentum very											
quickly a	nd ends up drop	ping almo	st vertica	ally to the g	ground	I.						





Date	18-Feb-2017	Regior	1		GQ		SOA	AR Repo	ort Nbr		S-0936	
Level 1	Operational		Leve	2	A	Airfrar	ne		Level	3	Doors/Can	opies
A/C Mod	el 1		Tw	in A	stir		A/C	Model	2			
Injury	Nil	Dama	age		Nil	Pha	ise	Thern	nalling		PIC Age	38
The front	The front canopy opened in-flight during private passenger flight. Just prior to launch the passenger secured											
the cano	the canopy and the command pilot observed that the canopy appeared to be locked. The wing-runner, an											
experience	ced solo pilot, die	d not obs	erve t	he c	canopy to l	be 'pro	oud' (of the f	rame a	nd co	nsidered it t	to be locked.
The laund	ch and subseque	nt flight v	was no	orma	al until the	cano	ру ор	ened a	bout 2	0-25 r	minutes into	the flight.
The comr	The command pilot landed shortly thereafter. Upon landing the passenger was asked to open and close the											
canopy o	n the ground. W	hen oper	ning an	nd cl	losing the	canop	y the	e passer	nger wa	as see	n to pull the	e knob down



Accident and Incident Summaries

and back, rather than just back. When pulled down and back the pins engage in the slots/tubes but the knob does not slide completely forward. The canopy appeared to be closed and locked from inside and outside but was not fully secured and the pins disengaged during flight. Pilots flying with untrained persons should provide a thorough briefing on the correct operation of the canopy, and ensure the canopy is properly locked by either visual inspection or by asking the wing-runner to check.

Date	18-Feb-2017	Region			WAGA		SOA	AR Repo	ort Nbr		S-	0941	
Level 1 Operational			Leve	12	Airc	raft Co	aft Control Level				Wheels up landing		
A/C Mod	el 1	ASH 31 Mi				A/C	Model	2					
Injury	Nil	Damage Nil Phase Landing PIC Age 62							62				
The evne	he experienced pilot was undertaking a 'round the clubs' cross-country flight in a new self-launching glider												

The experienced pilot was undertaking a 'round the clubs' cross-country flight in a new self-launching glider. Weather conditions were fine but thermals were only going to 3,700ft AGL. A new electronic navigation device had been installed in the glider but the pilot was not relying on it as they were unsure that the pilot profile and final glide calculations were correct. The aircraft carried two fully charged batteries, one of which was used to power the aircraft and the other was being charged by the aircraft's solar panels. The flight started well and the pilot was unconcerned about the low ceiling. Having rounded the first turn point, the pilot was at 1,000ft AGL over an area with small and wet paddocks. In reach of a landable paddock, the pilot lowered the undercarriage and started the engine. After a short climb at about 6900 revs, the engine began to misfire, as it had done on a previous flight, and the pilot assumed the battery was low. The pilot cooled and stowed the engine and headed on task towards the second turn point. At this time the batteries were swapped so as to equalise the voltage in each. On nearing the second turn point the pilot reached a height that the navigation system suggested with provide a safe final glide home. While thermalling shortly afterwards the pilot heard a tapping noise that was thought to be the cover for the water dump valve flapping, but was later found to be the fuel filling pump running. Nearing home and at a height of about 1,500ft the pilot again started the engine. While the engine ran satisfactorily, all the electrical instruments went blank. When the pilot believed final glide for a straight-in approach had been established, the engine was again cooled and stowed. During the final approach the pilot set landing flap and proceeded to land with the wheel retracted. Due to the electrical failure, the undercarriage warning did not activate. While the pilot recalled doing the pre-landing checks, they merely looked at the undercarriage lever and perceived it to be in the correct position. The CFI noted that this incident resulted from a chain of stressful events. The crucial factor being that the pilot did not physically check the position of the landing gear lever. This is not uncommon when pilots fly a straight-in approach. The chances of identifying an error while flying a normal, standard circuit, is significantly higher than when on final glide for a straight-in approach. Causal factors include inexperience on type and a high level of stress that led to inattention to detail.





Date	18-Feb-2017	Region		SAGA		SOA	R Repo	ort Nbr		S-	0942	
Level 1	Airspace	L	evel 2	Aircra	ft Sep	aratio	on	Level	3	Near collis	ion	
A/C Mod	el 1	Gro	b G 103	B Twin II		A/C	Model	2	DG-	1000S		
Injury	Nil	Damage	e	Nil	Pha	ase	Landi	ng		PIC Age	56	
A DG100	1 landed on RWY	' 23 Grass R	ight wh	ile a Twin	Astir	was o	n its ba	ise leg i	for th	e same run	way. After	
exiting th	xiting the glider, the crew of the DG1001 made no effort to vacate the strip but were awaiting a retrieve											
vehicle.	vehicle. The student flying the Twin Astir under instruction flew the glider into an undershoot position											
behind th	ne DG1001. The I	nstructor ir	n the Tw	in Astir as	sume	d com	nmand	and to	ok ac	tion to prev	ent a landing	
behind th	ne DG1001 and o	verflew the	e DG100	1 at a low	heigh	it, esti	imated	at abo	ut 20	to 30 ft. Th	e Instructor	
in the Tw	in Astir chose no	t to land or	n the gr	avel runwa	ay alo	ngside	e becau	use of a	perc	eived risk o	f conflict	
with a lau	unch that was ab	out to com	mence	on RWY G	rass Le	eft. In	vestiga	tion re	veale	d a breakdo	wn in	
procedur	procedures, namely: a glider launch was commenced while the Twin Astir was established on a late final											
approach	; the wing runne	r for the ae	erotow l	aunch was	s inexp	perier	nced; a	nd the	crew	of the DG10	001 made no	
effort to	effort to vacate the runway for the following glider.											

Date	22-Feb-2017	Region			GQ		SOA	AR Repo	ort Nbr		S-	0938
Level 1	Operational		Level 2 Terrain (in Col	lisior	าร	Level	3	Ground str	rike
A/C Mod	el 1	W	Whisper Motorglider					Model	2			
Injury	Nil	Dama	Damage Substantial Ph				ise	Launc	h		PIC Age	68
When the and aircr	e pilot started the aft tipped onto n	e engine to taxi downhill the speed built up rapidly. The pilot applied the brakes nose destroying propeller and possibly damaging the engine. Two weeks prior to the										



Accident and Incident Summaries

accident the pilot had been working on the aircraft's transponder. As some of the transponder wiring was routed near the throttle, the throttle was manipulated to ensure it was not binding and had been left in the half to three-quarter open position. The accident flight was the first flight since this maintenance was undertaken. Around midday the pilot completed his flight checks but omitted to set the throttle for starting. When the pilot started the engine it surged into life and the aircraft quickly accelerated downhill. The pilot immediately activated the hand brake, which resulted in the aircraft pitching forward and the propeller striking the ground.

Date	25-Feb-2017	2017 Region VSA SOAR Report Nbr S-0940									0940	
Level 1	Operational	Lev	vel 2		Airfrar	ne		Level	3	Furnishing	s & fittings	
A/C Mod	el 1	Euro	fox T	OW T2		A/C	Model	2	PW	-5 "Smyk"		
Injury	Nil	Damage		Nil	Pha	se	Launc	h		PIC Age	68	
At aroun	around 2500' AGL the tow pilot noticed the PW 5 was being flown erratically. The tow pilot used the											
radio to s	adio to speak with the glider pilot, who advised the release knob could not be reached. As the glider was											
directly a	directly above the airfield, the tow pilot instructed the glider pilot to move into high tow position so the tow											
pilot cou	ld activate the tu	ıg's release. F	ollow	ing release	e of th	e rop	e from	the to	w pla	ne, the glide	er pilot was	
able to re	eposition themse	lves and mar	iged t	o activate	the to	ow re	lease. T	he rop	e fell	to the grou	nd and was	
lost. Both	n aircraft comple	ted a success	ful lar	nding. Sub	seque	nt inv	/estigat	ion rev	vealed	d the seat ba	ack	
adjustme	ent had failed, ca	using the glid	er pil	ot to move	e rearv	wards	and av	way fro	m the	e release. Th	ne seat	
adjustme	adjustment is a fabric cushion that is adjusted by folding and secured to the rear bulkhead by Velcro. The											
glue adhe	ering the Velcro	strip to the re	ar bu	lkhead ha	d faile	d, the	ereby a	llowing	the o	cushion to s	lip from its	
intended	intended position during take-off.											

Date	25-Feb-2017	Regior	า	GQ		SOA	AR Repo	ort Nbr		S-	0943
Level 1	Airspace		Level 2	Aircra	ift Sep	arati	on	Level	3	Aircraft Se	paration
										Issues	
A/C Mod	el 1		Twin	Astir		A/C	Mode	2	TST	-10M	
Injury	Nil	Dam	age	Nil	Pha	ise	Thern	nalling		PIC Age	65
While the	hermalling during the conduct of an Air Experience Flight, the Twin Astir was joined below by a d sailplane operating engine-off. The pilot of the powered sailplane turned in the opposite direction										
to the Tw	powered sailplane operating engine-off. The pilot of the powered sailplane turned in the opposite direction to the Twin Astir, and despite several radio calls from the Twin Astir pilot requesting the other pilot change										
direction	, the powered sa	ilplane c	ontinued	to turn in t	the op	posit	e direc	tion wh	nile cli	imbing towa	ards the Twin
Astir. The	e Twin Astir pilot	left the t	hermal b	efore sepa	ration	was	compro	omised	. The	pilot of the	powered
sailplane	sailplane later stated that aircraft separation was significant enough to not pose a safety threat.										
Notwiths	Notwithstanding, convention dictates that when joining a thermal where another glider is circling, the										
joining gl	joining glider must circle in the same direction. The pilot of the motor glider was counselled by the CFI.										

Date	26-Feb-2017	Regior	1	SAGA		SOA	AR Repo	ort Nbr		S-0944	
Level 1	Operational		Level 2 Ground Operati				ons	Level	3	Taxiing collision/near	
								collision			
A/C Mod	el 1		LS	4		A/C	Model	2			
Injury	Nil	Dama	age	Minor	Pha	ise	Grour	nd Ops		PIC Age	70
After tow	ing the glider to	launch p	oint, the	e driver man	ioeuve	ered t	oward	s a gras	sed a	rea where t	he gliders
are usual	ly parked. After	crossing	he oper	ational runv	vay, tł	ne dri	ver bed	came fo	ocusse	ed on a tow	plane that
was taxyi	was taxying towards its parking area behind the launch point. To ensure the tow plane had sufficient room										
to park, t	park, the driver towed the glider closer to an access road. While the driver was concentrating on avoiding										



Accident and Incident Summaries

the tow plane, the starboard wing of glider struck a sign alongside the access road causing damage to its aileron.

Date	1-Mar-2017	-2017 Region VSA SOAR Report Nbr S-0963						0963			
Level 1	Operational		Level	2	Flight			Level	3	Aircraft pr	eparation
				Prepara	tion/Na	vigatio	on				
A/C Mod	el 1		Euro	fox K2	A	A/C M	1odel	2			
Injury	Nil	Dama	age	Nil	Phase	e La	aunc	h		PIC Age	68
While tax	ying the tow pla	ne to pos	sition fo	r a launch th	ne pilot r	receive	ed a	hand s	ignal	and radio ca	all to stop.
Upon sto	pping the pilot re	ealised th	hat the t	ow plane wa	as dragg	ging a c	conci	rete tie	e-dow	n weight at	tached to
the right	wing tie down p	oint. The	tug wa	s initially und	occupied	d and p	parke	ed adja	cent	to the airstr	ip in
readiness	s for a launch. Dເ	ie to the	windy o	onditions, a	20kg co	oncrete	e blo	ck had	been	attached to	o the into-
wind (rig	ht-hand) wing at	tachmen	t point,	opposite to	the entr	ry doo	or and	d out o	f sight	t of the pilo	t when
boarding	. When launchin	g was rea	dy to c	ommence th	e tow pi	ilot bo	barde	d the t	ow p	lane but for	got to
complete	a pre-boarding	check. As	a cons	equence, the	e pilot di	lid not	: noti	ce the ⁻	tie-do	wn weight	was still
attached	. The tug had mo	ved abou	ut four i	netres befor	e it was	s stopp	ped a	nd no	dama	ge was don	e to the
aircraft. 1	he pilot noted t	ne <i>"Incid</i>	ent was	witnessed b	y about	t ten pe	eople	e, inclu	ding d	about 6 insti	ructors and
the RM/C) - not a good tin	ne to stuj	ff up!" (onsequent o	of this in	ncident	it the	club h	as rei	nforced the	need for
pilots to	diligently comple	te their l	ore-boa	rding checks	, and th	ne conc	crete	blocks	s will b	pe painted i	n hi-visibility
colours a	nd the attachme	nt clip fla	agged.								





Date	3-Mar-2017	Regior	1	WAGA		SOA	R Repo	ort Nbr		S-	0976
Level 1	Airspace		Level	2 Aircra	ift Sep	arati	on	Level	3	Near collis	ion
A/C Mod	el 1		Vent	us-2cM		A/C	Model	2	Pipe	er PA-31-350)
Injury	Nil	Dama	age	Nil	Pha	ise	Thern	nalling		PIC Age	
It was rep	ported that a Pipe	er Chieft	ain eng	gaged in Chart	ter op	eratio	ons was	s instru	cted l	by Air Traffi	c Control to
orbit at 10,000ft about 10NM east of the 'GRENE' IFR waypoint for sequencing into Perth airport. While											



Accident and Incident Summaries

conducting the orbit, the pilot reported a near miss with a glider. There was no observed traffic on surveillance. Investigation identified the glider pilot from OLC records. The glider pilot reported conducting a 180 km cross-country flight from Beverley, WA. When coming out of a thermalling turn onto a westerly course about 10 NM east of Greenhills, WA, the glider pilot observed the Piper Chieftain on a northerly heading and approaching the glider from the left and slightly behind. The glider pilot observed the Piper Chieftain slightly deviate from course and, when clear of the glider, return to its original course. The glider pilot noted that both aircraft were at a similar altitude with lateral separation under 150 m. The pilot was not monitoring the Area Frequency at the time. The Airservices Australia Aeronautical Information Publication (AIP) notes that glider pilots are encouraged, but not required, to monitor the area VHF when operating above 5,000 ft in Class G airspace. The AIP further states: "Except for operations in controlled airspace, gliding operations may be conducted no-radio, or may be on frequencies 122.5MHZ, 122.7MHZ or 122.9MHZ, which have been allocated for use by gliders. ... Except when operationally required to maintain communications on a discrete frequency listed above, glider pilots are expected to listen out on the area VHF and announce if in potential conflict." The GFA Airways and Radio Procedures manual states: "Gliders are encouraged, but not required, to monitor the area frequency when operating in Class E Airspace." This exemption from the Rule exists to allow glider pilots to communicate on one of the discreet safety frequencies when flying in the company of other gliders to enhance situational awareness. However, where a pilot is flying alone, they should monitor the Area Frequency as an aid to collision avoidance. For further information, refer to OSB 02/14 'See-and-Avoid for Glider Pilots'.

Date	4-Mar-2017	Regior	n 🛛	GQ		SOA	R Repo	ort Nbr		S-	0947
Level 1	Operational		Level 2		Flight			Level	3	Aircraft pr	eparation
				Prepara	tion/N	aviga	ation				
A/C Mod	el 1		IS-28	B2		A/C	Model	2			
Injury	Nil	Dama	age	Nil	Phas	se	In-Flig	ght		PIC Age	68
The aircr	aft was flown wi	th the gro	ound-han	dling rod ir	ncorrec	ctly st	towed	inside a	a rear	bulkhead ii	nspection
hole behi	nd the rear seat	The gro	und-hand	lling rod, w	hich is	usec	d to aid	in liftir	ng the	e tail to fit th	ne tail dolly
after land	ling and also sec	ures the	rudder cl	lock, and h	ad bee	en po	sitione	d in the	e tail (overnight to	secure the
control s	urface. During th	e Daily Ir	spection	the inspec	tor ren	nove	d the g	round-	hand	ling rod froi	m the tail
and pass	ed it to one of th	e studen	ts to stov	<i>i</i> n the fus	elage.	Durir	ng the I	pre-boa	arding	g checks the	command
pilot noti	ced the ground-	nandling	rod was i	not in its us	sual pos	sitior	n and a	search	of th	e cockpit co	ould not
locate it.	Believing the gro	ound-han	dling rod	was with t	he oth	er gr	ound h	andlin	g devi	ices in the r	etrieve
vehicle, t	he command pil	ot comple	eted all p	re-flight ch	iecks ai	nd th	e aircr	aft was	clear	ed for flight	t. Following
an uneve	ntful flight and la	anding th	e retriev	e crew cou	ld not l	locat	e the g	round-	handl	ling rod, so	a further
search of	the glider was c	onducted	d. The gro	und-handl	ing rod	l was	subse	quently	locat	ted inside a	rear
bulkhead	inspection hole	behind t	he rear se	eat. This ind	cident l	highl	ights tł	ne need	l for a	a dedicated	level of
focus wh	en conducting cr	itical insp	pections a	and pre-flig	ght che	cks, ۱	withou	t interr	uptio	n. The conc	ept of a
sterile en	vironment shou	d be ado	pted dur	ing all critic	cal duti	es or	activit	ies, suo	ch as t	the Daily Ins	spection and
completi	on of check lists.										

Date	4-Mar-2017	Regior	1	SAGA		SOA	R Repo	ort Nbr		S-0950	
Level 1	Operational		Level 2	el 2 Miscellaneous Level 3 Other Miscellane						cellaneous	
A/C Mod	A/C Model 1 A/C Model 2										
Injury	Nil	Dam	age	Nil	Pha	ise	Launc	h		PIC Age	68
During a wire bein the stude second w	winch launch the g lifted into the ent released and rire had not beer	e launchin air and ir complete secured	ng cable nmediat ed a lanc at the la	picked up t ely lowered ing straight unch point	he sec the n ahead	ond v ose o d. For	wire. Tł f the gl r reasor	ne stud ider. W ns that	ent p /ith sa were	ilot noticed afe speed es not determ	the second tablished, ined, the



Date	11-Mar-2017	Regior	1	VSA		SOA	R Repo	ort Nbr		S-	0959
Level 1	Operational		Level	2 Mis	cellan	neous Level 3 Other Miscellaneous					
A/C Mod	el 1		Twi	n Astir		A/C	Model	2			
Injury	Nil	Dama	age	Minor	Pha	ise	Launc	h		PIC Age	66
The club	has a total of ten	membe	rs, five	of whom we	re in a	ttend	lance o	n the d	lay. A	round 10am	i two
members	drove down to t	the winch	n and tl	ne winch driv	er pre	pare	d it for	operat	ions.	The second	member
hooked t	ne two cables on	to the re	trieve v	ehicle. The c	ables	were	towed	on a s	light o	curve along	the eastern
third of t	ne runway to the	launch p	ooint, v	hereupon th	ey we	ere ta	ken off	the ca	r but	not secured	. After
leaving th	e cables at the l	aunch po	int the	member dro	ve to	the o	ther sid	le of th	ie run	way to get	their glider
from the	hangar. The Twi	n Astir w	as tow	ed to the lau	nch po	oint a	nd thei	n later	positi	oned close a	alongside the
wires, an	d in such a positi	on that i	ts take-	off path was	direct	tly to	wards t	he seco	ond w	vire. The sec	ond wire,
with the	drogue chute an	d trace a	ttached	, was not sec	cured a	and t	his wer	nt unno	oticed	by the pilot	s and crew.
The sortion	e was to be a mu	tual fligh	t betw	een two instr	uctors	s. The	comm	and pil	lot wa	as to fly the	launch
because t	he second pilot	was not o	current	It was inten	ded th	ne tw	o pilots	would	l shar	e the flying	and that the
second p	lot would condu	ct the cir	cuit an	d landing. Du	ie to s	mall ı	numbe	rs, ther	e was	s only one m	nember at
the laund	h point to mana	ge the lau	unch ar	d run the wi	ng. Th	ne glio	der was	s launcl	hed a	round 11am	and during
the grour	nd roll the glider	over ran	the sec	ond, unsecu	red, ca	able, v	which v	vas pic	ked-u	ip by the tai	lskid. The
glider bee	ame airborne w	ith the se	econd c	able, includir	ng the	attac	hed dr	ogue c	hute a	and trace, ca	aught in the
tailskid. T	he pilot in comm	nand rep	orted d	ifficulty main	tainin	g spe	ed and	attituo	de du	ring the laur	nch and the
climb rate	e was poor. At al	out 500	ft AGL t	he command	l pilot	relea	sed an	d pitch	ed fo	rward but th	ne speed
began to	decay to close to	o the stal	l. The c	ommand pilo	ot furtl	her lo	wered	the no	se to	increase sp	eed and the
second p	lot reported hea	ring a te	aring so	ound and attr	ibute	d the	noise t	o the t	ailskio	d departing	the fuselage.
Once free	e of the cable the	e pilot in	comma	nd flew a mo	odified	l circu	it and	the glio	der la	nded safely.	The second
pilot prov	vided the followi	ng sketch	of the	launch point	layou	it just	: prior t	o launo	ch.		







Accident and Incident Summaries

2. The inert cable will be secured on all future winch launches.3. Retrieve vehicle drivers will be briefed on the importance of ensuring the cables are laid straight and as

close to the runway edge as possible.

GFA is also reviewing the winch launching manual to improve guidance for the laying of cables.

Date	12-Mar-2017	Region		GQ		SOA	AR Repo	ort Nbr		S-	0951	
Level 1	Operational		Level 2		Airfrar	ne		Level	3	Objects fa aircraft	lling from	
A/C Mod	el 1	Р	Piper PA-2	25-235		A/C	: Model	2				
Injury	Nil	Dama	ge	Minor	Pha	ise	Landi	ng		PIC Age	25	

The tow plane was established on final approach when, at approximately 350 feet AGL, it was struck by a gust that destabilised the aircraft and shifted the pilot in the seat. After re-establishing the glide slope the pilot inadvertently activated the tow release with their leg while repositioning in the seat. The tow rope fell onto a car travelling along the highway at speed and the car's occupants safely recovered the rope without further incident or injury. Subsequent inspection and testing of the release system did not reveal any fault. Attempts to replicate the problem revealed that excessive back-pressure on the release lever from a shoe or clothing can result in activation of the release but that such would be a rare occurrence.



Date	14-Mar-2017	Region		SAGA		SOA	R Repo	ort Nbr		S-	0952
Level 1	Consequential	Events	Level 2	Lo	ow Cir	cuit		Level	3	Low Circui	t
A/C Mod	el 1		DG-10	00S		A/C	Model	2			
Injury	Nil	Damag	ge	Nil	Pha	se	Landi	ng		PIC Age	26



Accident and Incident Summaries

On establishing final glide at the end of a cross-country race, the pilot conducted a very marginal approach to the operational runway. At approximately 15kms out the glider was well over glide and the angle looked good, so the pilot pushed hard. At approximately 4km out and 1km from the finish line, the numbers on the instruments still looked good but the picture from the cockpit was starting to look poor. The pilot started to slow up gently and a little height was gained from pulling up but the picture improved only slightly. At this point the terrain beneath the glider was poor and the pilot elected to continue towards the airfield, having discounted diverting to an alternative runway as too risky. The pilot continued with the approach and cleared trees and powerlines by approximately 200ft during the turn onto final approach. The landing was uneventful. The command pilot was very experienced but was not current on type and usually flew gliders with significantly better glide performance. The command pilot misjudged the altitude required to cross the finish in order to join base leg at a safe altitude, and noted after the flight that the glider's altimeter was reading 160ft higher, probably due to atmospheric pressure changes during flight. The pilot's judgement may have been also influenced by another glider ahead that was at a similar height. The pilot was issued a 500 point scoring penalty by the competition organisers.

Date	17-Mar-2017	Regior	n	GQ		SOA	AR Repo	ort Nbr		S-	0955
Level 1	Operational		Level 2	Run	iway E	vent	S	Level	3	Runway in	cursion
A/C Mod	el 1					A/C	Model	2			
Injury	Nil	Dama	age	Nil	Pha	ase	Grour	nd Ops		PIC Age	
At the en	d of the day's op	eration t	he cont	ol van was	being	towe	d back	to its u	sual p	barking plac	e. Before windows to
crossing i	rossing the end of the operational runway the driver stopped the vehicle and looked out of the windows to beck for aircraft on approach or entering the runway. Satisfied that it was safe to cross, the driver entered										
the runu	aircrait on appro	bach or e	entering a glidar	flow overb	. Salis			abovo	+ to cr	oss, the un	/er entered
therunw	ay and shortly al	terwarus	a gliuei	new overn			SU leet	above	the ve	enicie. The c	Jommanu
pilot in th	ne glider had see	n the veh	icle sto	and assum	ed the	e driv	er had	it sight	ed. Tł	ne comman	d pilot was
unconcer	ned when the ve	ehicle ent	ered th	e runway as	there	was	no risk	of colli	sion.	The driver o	of the vehicle
was unwa	was unware of how big a blind spot exists for the driver of the tow vehicle when looking left out of the										
passenge	r's window. In fu	iture the	driver v	ill exit the v	ehicle	e to cl	neck fo	r appro	achin	ig aircraft.	

Date	18-Mar-2017	Region	VSA		SOA	AR Repo	ort Nbr		S-0954		
Level 1	Operational	Lev	Level 2 Runwa		Events Level			3	Other Run	way Events	
A/C Mod	el 1	SZD-	51-1 Junior		A/C	Mode	2	Cess	sna 152		
Iniury	Nil	Damage	Nil	Pha	se	Landi	ng		PIC Age	64	

The glider pilot took a launch for a local flight after having earlier satisfactorily completing an annual flight review. During the course of the flight the pilot was contacted by the ground operation and informed that no one else required the aircraft and that the pilot could land long at the end of the flight so as to position the glider near the hangars. Sometime later the pilot joined circuit and gave a downwind call on the CTAF advising of the intention to land on the operational runway. During the base leg the pilot noticed a glider and tow plane were positioned for launch on runway grass right, and that a Cessna aircraft was on final approach for the bitumen runway. The glider pilot elected to land on runway grass left and turned onto final approach, with the Cessna now on the ground some 500 metres ahead. The glider pilot, realising the Cessna would probably turn left in front of the glider in order to taxi clear of the operational runway, made a radio call advising the Cessna pilot not to turn left. Shortly afterwards the Cessna turned left at the taxiway and stopped as the glider flew past just above the ground. The glider pilot stated "this was a dangerous situation which followed from poor decision making on my part when on Base re where to land, a fixation on landing near the hangar, and a delayed appreciation of the relative positions of my aircraft and the Cessna when approaching the cross Runway, at which point my options were limited. I must have observed the powered aircraft landing on 09 and exiting on that taxiway literally hundreds of times. Had I not observed the Cessna holding on the Runway, I may have been able to retract the airbrakes and gain sufficient height to clear the taxiway. I do not think fatigue was a factor". Good operating procedures and flying standards are developed



Accident and Incident Summaries

over time and built on the experience of many pilots and many mistakes. Pilots should always be aware that even slight departures from standard accepted good practice can have severe consequences. There is no doubt that convenience can be a seductive force and very many pilots (and clubs) have been tempted into bad decisions and choices for no other reason.



Date	19-Mar-2017	Region		SAGA		SOA	AR Repo	ort Nbr		S-I	0956
Level 1	Airspace		Level 2	2 Airspac	e Infri	ngen	nent	Level	3	Airspace Ir	nfringement
A/C Mode	el 1		Glasflu	igel 304		A/C	Model	2			
Injury	Nil	Dama	ge	Nil	Pha	ise	In-Flig	ght		PIC Age	

The pilot was competing in the South Australian State Gliding Championships from Gawler airfield. The airspace around Gawler is complex and the local club has an agreement with the RAAF and AirServices for release of some airspace blocks upon application. While flying towards a turn point, the pilot inadvertently entered controlled airspace for a period of 3.5 minutes after mistakenly believing the glider was in an area that had been released for the competition. The pilot noted that all pilots had been warned of the airspace limitations at briefing and suggested a number of factors contributed, viz.:-

- 1. Electronic airspace warnings from the flight computer were turned off by the pilot in the belief there would be continuous false alerts in this environment, although the pilot subsequently learned that the airspace file had been specifically developed for this competition.
- 2. Although the pilot carried appropriate maps and charts folded ready for immediate reference as mitigation for lack of electronic airspace warnings, the pilot still misidentified the glider's position relative to the airspace boundary.



Accident and Incident Summaries

3. The pilot suspected complacency and stress played a part as the pilot had flown in this area many times in the past, and Self-imposed flight objectives may have contributed to a lack of situational awareness regarding the boundary of the airspace limits. The pilot was also concerned about the potential risk due to height above the steps on final glide later in the flight because of the effect of a sea breeze.

Date	19-Mar-2017	Regior	1	SAGA		SOA	AR Repo	ort Nbr		S-0957	
Level 1	Airspace		Level 2	Airspac	e Infri	ingen	nent	Level	3	Airspace Ir	nfringement
A/C Mod	el 1		LS 4	-a		A/C	Model	2			
Injury	Nil	Dama	age	Nil	Pha	ase	In-Flig	ght		PIC Age	56
The pilot airspace release o controlle Compour automati	was competing i around Gawler is f some airspace I d airspace. The p nding the error, t on) due to nume	n the Sou complex blocks up ilot advis he pilot o rous fals	uth Austra k and the bon applic sed that t disregard e alarms	alian State local club l ation. On t he breach ed airspace consequen	Glidin has an the firs occurr e warn t of th	g Cha agre st leg red d ings ne dai	ampion ement of the ue to ir from th ily varia	ships fi with th task th attenti a flight ation in	rom G ne RA/ e pilo ion to t com airsp	awler airfie AF and AirSe t inadverter navigation. puter (disus ace blocks.	ld. The ervices for ntly entered e of

Date	24-Mar-2017	Regior	۱ I	GQ		SOA	AR Repo	ort Nbr		S-	1020
Level 1	Operational		Level 2	Grou	nd Op	eratio	ons	Level	3	Other Gro	und Ops
										Issues	
A/C Mod	el 1					A/C	Mode	2			
Injury	Minor	Dam	age	Nil	Pha	ase	Grou	nd Ops		PIC Age	75
While dis	connecting an u	nder-ten	sion rop	e from the r	novin	g retr	ieve ve	hicle in	prep	aration for	an autotow
launch, t	he member suffe	ered rope	burn to	their hand	and w	as ta	ken to	hospita	l for r	medical trea	itment. The
key to av	oiding a rope bu	rn is to a	void tou	ching the ro	pe un	til the	e vehicl	e has s	toppe	ed. If it is ne	cessary to
handle a	moving rope, the	en use su	itable g	oves or clot	hing b	etwe	en you	r skin a	ind w	hatever's ca	using the
friction.	A person should :	seek med	lical trea	tment imm	ediate	ely if t	he rop	e burn	is dee	eper than th	e upper
layers of	skin and hair.										

Date	24-Mar-2017	Regior	1 I	GQ		SOA	AR Repo	ort Nbr		S-	0958
Level 1	Operational		Level 2	Run	way E	vents	S	Level	3	Runway ex	cursion
A/C Mod	el 1		Astir (S77		A/C	Model	2			
Injury	Nil	Dama	age	Nil	Pha	ise	Outla	nding		PIC Age	37
The pilot	selected an outl	anding pa	addock th	at was 370)m lon	g, sli	ghtly do	ownhill	with	contour bar	nks. From
the air, th	ne pilot observed	l neither	the slope	of the pad	ldock i	nor tł	he cont	our bai	nks. T	he final app	roach was
over a fo	rest and higher t	han usua	l due to t	he pilot's c	autior	n abo	ut the t	trees. A	s a re	sult, touch	lown
occurred	just over halfwa	y down t	he paddo	ck, whereu	ipon c	onto	ur banl	ks twice	e rela	unched the	glider,
resulting	in a ground run	that wen	t past the	end of the	e cultiv	/ated	paddo	ck, ove	r a fa	rmhouse en	try road and
10m into	the next croppe	d paddoo	k withou	t damage t	o the	aircra	aft. For	tunatel	y for	the pilot the	ere were no
fences al	ongside the entr	y road. Tl	he CFI no	ted that de	spite	much	n trainir	ng the p	oilot la	acks consist	ency, i.e. the
pilot doe	s not always resp	ond in a	ond in an identical manner when presented with multiple identical situations. Th							uations. The	
pilot has	since undergone	extensiv	e reasses	sment and	clear	ed fo	r solo f	light.			

Date	1-Apr-2017	Regior	1 I	SAGA	SOAR Repo	ort Nbr		S-0986
Level 1	Airspace		Level 2	Aircraft Sep	aration	Level	3	Near collision
A/C Mod	el 1		DG10	00S	A/C Mode	2	Zod	iac



Accident and Incident Summaries

Injury	Nil	Damage	Nil	Phase	In-Flight	PIC Age	55
It was report	ted that the pi	lot of an RA-A	us registered a	aircraft too	k avoiding action w	hile on the o	downwind
leg of the op	erational run	way to avoid a	glider flying d	irectly towa	ards it. The pilot sta	ited that the	e aircraft
were betwee	en 30 and 50 r	netres apart a	t the time. A r	adio call wa	as subsequently ma	de to the gl	ider pilot but
no response	was received.	Around the re	eported time o	of this incid	ent a glider was cor	nducting the	ermalling
exercises and	d had drifted a	across the run	way onto the a	active side of	of the circuit. At tha	at point the	trainee
glider pilot e	lected to fly to	oward the circ	uit joining are	a but the fli	ght path was again	st the traffic	: flow. The
gliding instru	ictor asked the	e student to tu	urn onto down	wind arour	nd the same time th	hat the powe	ered aircraft
saw the glide	er. Neither cre	w of the glide	r saw the pow	ered aircra	ft or heard its radio	transmissic	on. Both
aircraft com	pleted a norm	al landing. As	a consequence	e of this inc	ident the gliding clι	ub has reinfo	orced the
need of its p	ilots to remair	າ clear of the a	active circuit a	rea, keep a	good lookout, and	to also bew	are of
aircraft on th	ne inactive sid	e. Instructors v	will ensure the	eir air work	is completed at a h	eight suffici	ent to
enable the st	tudent to arriv	/e at the circui	it joining area	at an appro	priate height for th	ie prevailing	; conditions,
and will also	reinforce to s	tudents appro	priate ways to	modify the	eir circuits.		

Date	1-Apr-2017	Regior	۱		GQ		SOA	AR Repo	ort Nbr		S-	0960
Level 1	Operational		Leve	el 2	Airc	raft Co	ontro		Level	3	Hard landi	ng
A/C Mod	el 1		F	PW-6	5U		A/C	Model	2			
Injury	Nil	Dama	age		Minor	Pha	se	Landi	ng		PIC Age	75
A normal	circuit was flow	n but the	pilot	faile	d to flare	corred	ctly a	nd flew	the air	craft	onto the gro	ound causing

A normal circuit was flown but the pilot failed to flare correctly and flew the aircraft onto the ground causing it to hit hard and bounce, stall, and hit hard again. The pilot stated that when "coming in on finals I reached what I thought was round out height but as I started to round out I hit the ground and bounced. I was too slow to catch it and hit the ground again. The port wing touched the ground and slewed the glider around onto the bitumen where I regained control and rolled down the runway for a short distance and then back onto the grass." The pilot was on solo checks and had performed an adequate flight with the duty instructor that morning. Conditions were calm and favourable for a solo flight. The pilot is an older person who has recently come back into gliding after a long break. The pilot went solo a few weeks earlier after many flights with the Club's instructors but had struggled to maintain consistency. Potential causal factors include inexperience, high workload, incorrect landing technique and over controlling the glider in pitch following a bounced landing. The pilot also noted that an operation to treat cataracts several weeks earlier may have affected depth perception.

Date	2-Apr-2017	Region		WAGA		SOA	AR Repo	ort Nbr		S-	0966		
Level 1	Airspace		Level 2	Aircra	aft Sep	arati	on	Level	3	Near collis	ion		
A/C Mod	el 1	SZD-48	-1 "Janta	ar Standard	2"	A/C	Model	2	SZD	-50-3 "Puch	acz"		
Injury	Nil	Dama	nge	Nil	Pha	ise	In-Flig	ght		PIC Age	51		
While tra	velling north at 3	3500 ft ar	nd about	1km due e	ast of	the a	irfield,	the Jan	itar p	ilot noticed	the flash of a		
shadow a	as the Puchacz fle	ew overhe	ead from	the rear le	eft qua	rter.	The Pu	chacz p	asseo	d directly ov	erhead the		
Jantar by	less than 100ft s	eparatio	n. The Ja	ntar pilot fl	ew pa	rallel	to the	Puchad	hacz and tried to contact the				
other air	craft by radio to	no avail. 1	The pilot	of the Puc	hacz d	id no	t sight	the Jan	tar. It	is apparent	t that while		
the glide	rs crossed paths	at differe	nt heigh	ts and spee	d, blin	id arc	: limitat	ions of	the F	Puchacz mad	de it difficult		
for the pi	lot to sight the o	ther glide	er. It may	have beer	n possi	ble tl	he Pucł	nacz pilo	ot to	have sighted	d the other		
glider ha	d they been look	ing to the	e right ar	d significar	ntly do	wn. I	Howeve	er, the o	comm	nand pilot's	attention		
was dired	cted elsewhere a	t the criti	cal time.	It was note	ed tha	t neit	her air	craft wa	as fitt	ed with FLA	RM. The		
primary r	method for imple	menting	'see-and	-avoid' is lo	okout	t, whi	ich invo	lves se	eing	potential ha	zards and		
assessing	; information prio	or to reac	ting. The	primary so	ource o	of inf	ormatio	on is vis	sion. I	Pilots must i	maintain a		
good loo	kout and adequa	tely comp	pensate	for any airc	raft bl	ind s	pots. Tl	nis mea	ns av	oiding long	periods at a		



Accident and Incident Summaries

constant heading and checking that the airspace is clear before turning. For further information, refer to OSB 02/14 'See-and-Avoid for Glider Pilots'.

Date	5-Apr-2017	Region		SAGA		SOA	R Repo	ort Nbr		S-	0974
Level 1	Operational		Level 2	Run	way Ev	vents	5	Level	3	Runway in	cursion
A/C Mod	el 1		LS 4-a	ГОР		A/C	Model	2	Pipe	er PA-25-235	5/A1
Injury	Nil	Dama	ge	Nil	Pha	se	Launc	h		PIC Age	26
As the gli	der towing comb	pination be	ecame ai	rborne a d	lark co	loure	ed vehi	cle appi	roach	ed to enter	the runway.
The vehic	cle driver sudden	ly noticed	l the tow	plane and	lglider	and	immed	iately s	topp	ed just prior	to entering
the runw	ay proper. The c	ombinatio	on flew pa	assed the v	vehicle	with	n a vert	ical sep	arati	on of about	25 feet.
Investiga	tion identified th	e vehicle o	driver ha	d looked b	out not	seer	n the to	wing co	ombii	nation until	the runway
was abou	it to be entered.	The phene	omenon	of "We loo	ok but	we d	o not s	ee" is k	nowr	n as "inatter	ntional
blindness	s". It refers to the	e fact that	we ofter	ו think we	see ev	eryth	ning we	e' re loo	king	at but this is	s far from
true. Wh	ile people often	relate this	(cognitiv	/e) tunnel [,]	vision	and a	auditor	y exclus	sion t	o high-stres	s events, in
reality we	e are experiencir	ng these pl	henomer	na all the ti	ime - a	lbeit	to a gr	eater o	r less	er degree. 1	The member
concerne	d published an a	rticle in th	ne club m	lagazine st	ressing	g the	need t	o be vi	gilant	when cross	ing all
runways	on the taxiways,	kiways, both in aircraft and motor vehicles. The Club Operations/Training panel is also								el is also	
working	king with the aerodrome manager to extend the taxiways back to the runway thresholds to minimise										
crossing	conflicts.										

Date	6-Apr-2017	Regior	1	GQ		SOA	AR Repo	ort Nbr		S-	0965
Level 1	Operational		Level 2	Terra	ain Co	llisior	าร	Level	3	Collision w	vith terrain
A/C Mod	el 1	l	KR-03A F	uchatek		A/C	: Model	2			
Injury	Nil	Dama	age	Minor	Pha	ise	Landi	ng		PIC Age	64

The sortie was a currency check being conducted by an Instructor. The pilot under check had completed a normal landing when, just after touchdown and while the aircraft had a lot of momentum, the crew heard a loud bang from the main undercarriage and a felt a shock indicating the glider had hit something on the ground. Subsequent investigation of the runway revealed the glider's main wheel had impacted an ant mound. Several other ant mounds, consequent of recent rains, were found in the runway and all were levelled. Inspection of the main undercarriage revealed one leg to be twisted laterally about 10 degrees and the wheel was displaced vertically sideways about 10 degrees. The aircraft has been sent away for repair.



Date	7-Apr-2017	Region		GQ	SOAR Repo	ort Nbr	S-0967
Level 1	Operational	Lev	vel 2	Aircraft Co	ontrol	Level 3	Hard landing



Accident and Incident Summaries

A/C Model 1		AS	K-21Mi	A/0	CModel 2	N/A		
Injury	Nil	Damage	Minor	Phase	Landing		PIC Age	54

The pilot was a highly experienced power pilot with airline experience who had converted to gliders after 14 training flights. This incident occurred on the pilot's first solo glider flight. The final approach commenced high into a pilot-estimated 10 knot headwind, resulting in a steep approach with 1/2 to 3/4 airbrake. On short final the pilot recognised an increased sink rate and corrected by use of the elevator whilst reducing the brake setting to about 1/2. As the pilot began a slightly high flare a high sink rate was observed and the nose was further raised in an attempt to arrest the sink rate. To avoid a tail strike the pilot then pitched forward on the control column and the aircraft landed heavily on the main wheel and the aircraft then oscillated between the back wheel and front wheel before coming to rest with the steerable nose wheel assembly substantially damaged. The pilot will undergo some further training before flying solo. Causal factors include low experience, possibly wind gradient, incorrect technique for dealing with the high rate of sink on approach, and over controlling the glider in pitch during flare and hold off prior to ground impact. In addition, in this type of aircraft the nose and tail wheels have a small clearance between the ground, which enhances the tendency for the aircraft to oscillate around the main wheel if the recovery from a heavy landing is misjudged. To avoid this, pilots should always aim to touch down with minimum energy, in a twopoint attitude whereby the tail wheel and main wheel touch simultaneously (or slightly tail wheel first). Before authorising any first solo flight, an instructor must be confident that the student has fully completed all the required pre-solo requirements to a consistently satisfactory standard, including consistently safe, well judged circuits and landings. Whilst some pilots with extensive experience in other flying disciplines may quickly master the basic flying skills of gliding, it is still necessary to ensure that they are taught and fully understand the glider-specific judgement required, particularly in the circuit and landing phases. In simple terms, they need to be taught to think like a glider pilot, which may in some cases require the discarding of some previous learning. In consideration of Duty of Care and legal liability, it is particularly important that not only must all sequences be known to have been properly covered, but they must be properly recorded as such.



Date	7-Apr-2017	Region		GQ	SOAR Repo	ort Nbr	S-0968
Level 1	Operational		Level 2	Aircraft Co	ontrol	Level 3	Hard landing
A/C Mod	el 1		ASK-2	21	A/C Mode	2	



Accident and Incident Summaries

InjuryNilDamageNilPhaseLandingPIC Age60During the final approach the student, who is close to solo standard, flared high. The Instructor, who is
relatively new to the role, was late to take control and the aircraft landed heavily. The student had displayed
good flying skills and the instructor was quite relaxed. As a consequence, the instructor was not prepared
when the student mishandled the flare. This is not an uncommon occurrence and even experienced
instructors can be lulled into a false sense of security. Notwithstanding the experience level of the pilot
under check, Instructors must always guard themselves against unexpected reactions during the critical
stages of flight by adopting a defensive posture; i.e. having their hands and feet ready to take control.60

Date	8-Apr-2017	Region	1	NSWGA		SOA	R Repo	ort Nbr		S-	0964
Level 1	Operational		Level 2 Runway Events Level 3 Runway in						cursion		
A/C Mod	el 1					A/C	Model	2	Pipe	er PA25-235	
Injury	Nil	Dama	age	Nil	Pha	ise	Landi	ng		PIC Age	62
On short	final the tow pilo	ot had to	execute a	go-aroun	d due	to th	e likelił	nood of	[:] a rur	nway incurs	ion by a
retrieve v	ehicle. At this pr	ivate airs	strip runw	ays 33, 30	and 2	7 for	m an a	rrowhe	ad in	the south-e	ast corner of
the airfie	ld. On this day, ru	unway 33	3 was the	operationa	al run	way g	iven w	ind stre	ength	and direction	on (NNW at 5
– 10kts).	The 'pie-cart' and	d glider p	ark area	were on th	e east	ern s	ide of 3	33, site	d app	roximately	80m in from
the thres	hold. The tow pla	ane had j	ust launcl	hed the Clu	ıb's tv	vo-se	ater or	ı a trair	ning fl	ight that inv	olved a pre-
planned s	simulated rope b	reak at a	bout 900f	t AGL. Foll	owing	; relea	ase to t	ow pilo	ot con	nmenced a	wide circuit
to allow t	o allow time for the two-seater to land. The pilots in the two-seater radioed their intention to conduct a							onduct a			
crosswing	d landing on runy	vav 27 S	hortly aft	erwards th	e nilo	t of a	single	-seat gl	ider i	nined circuit	t and radioed

crosswind landing on runway 27. Shortly afterwards the pilot of a single-seat glider joined circuit and radioed their intention to land on runway 30, which was more into wind. The driver of the retrieve vehicle, who was heading towards the two-seater on runway 27, stopped on runway 30 to let the single-seat glider land. The tow plane, which was landing on the operational runway (RWY 30) initiated a go-around due to the vehicle incursion. Investigation revealed the driver of the retrieve vehicle was unfamiliar with the rules for ground operations at this airfield, which required retrieve vehicles to be driven outside the runway makers and not on the runway. The vehicle driver was counselled.

Date	12-Apr-2017	Region	1	NSWGA		SOAR Repo		ort Nbr		S-0969	
Level 1	Operational		Level 2	el 2 Air		ame		Level 3		Fuselage/Wings/Empe	
										nnage	
A/C Mod	el 1		Standard Cirrus			A/C	Model	2			
Injury	Nil	Dama	age	Nil Ph		ise Launch		h		PIC Age	59
The pilot	rigged the Stand	lard Cirru	s that m	orning and	exper	ience	d some	e difficu	lty at	taching the	
tailplane	tailplane. Once the aircraft was rigged it was taken to the flight line and the pilot completed the pre-										
boarding checks. The pilot then entered the cockpit and prepared for flight. While checking the controls for											
full and free movement the pilot noticed the elevator felt strange and made a noise. Nearby members											
informed	the pilot that th	e tailplan	ne was ir	correctly ri	gged.	The p	ilot lef	t the co	ockpit	and correct	tly fitted the
tailplane	The pilot had or	nly recent	tly acqui	red the airc	raft ar	nd ha	d no pr	evious	expe	rience with	the type.
This Stan	dard Cirrus is an	early mo	del and	the attachn	nent o	fthe	tailplar	ne can b	oe qu	ite tricky an	d many
pilots str	pilots struggle to properly fit it. The elevator is mounted by hooking the pushrod between two bearings, and										
then by dropping the trailing edge of the elevator to locate a "T" fitting at the pivot point into a locking											
bolt. Much of this is done by feel, although there is a small clear view window directly above the pushrod to											
visually check the correct location of the pushrod between the bearings. Unfortunately, it is possible to											
locate and lock the "T" fitting without the pushrod being properly located in the bearings, and in this case											
the clear view window wasn't very clear and will be fixed. To ensure the elevator is correctly fitted, pilots											
should always perform the following checks to ensure proper assembly:											



Accident and Incident Summaries

- Use the inspection hole (window) in the elevator to verify that the hook properly mates with the bearings.
- Swing the Elevator through its full range of motion. It should move smoothly, without rattling or the sound of the hook rubbing inside the faring.
- Move the control stick fore and aft, from stop to stop. Do this slowly and rapidly while watching the elevator. The elevator should follow every movement of the control stick smoothly and exactly. It should be evident that the control linkage is both pushing and pulling the elevator.
- Notice the angle of the Elevator with the control stick fully aft. The fairing should be fully concealed within the vertical fin. If the hook is not properly mated with the ball bearings the leading edge of the Elevator will not dip far enough.
- Perform a positive control check! This will confirm that the hook is both pushing and pulling the nose of the Elevator.



Image and above assembly notes adapted from http://www.standardcirrus.org/Elevator.php

Date	12-Apr-2017	Regior	۱	SAGA			SOAR Report Nbr				S-0972	
Level 1	Airspace	Lev		el 2	I 2 Aircraft Sep			aration		3	Near collision	
A/C Mod	el 1	HK 36 TTC				A/C Model 2 Diar			Diar	mond DA 40		
Injury	Nil	Dama	age		Nil	Pha	se	In-Flight			PIC Age	51
The command pilot was conducting an Air Experience Flight with a person who holds both GA and RAAus												
pilot qualifications. While the motor glider was tracking from the training area back to the inbound approach												
point of this controlled airport, the FLARM/Transponder instrument display showed another aircraft												
following. As the motor glider approached the inbound approach point, the command pilot sighted the other												
aircraft behind and to the right. As the motor glider arrived over the inbound approach point the command												
pilot noticed the other aircraft getting closer. Just after the command pilot made an inbound call to the												



Accident and Incident Summaries

control tower, the other aircraft flew under the motor glider by about 500ft and then also made an inbound call to the control tower. The command pilot called the other aircraft on the radio but did not receive a response. When nearing the airport the command pilot heard the other aircraft respond to Air Traffic Control instructions and gave another radio call, asking the pilot of the other aircraft if they had seen the motor glider. The other pilot confirmed they had, which is why they descended below the motor glider. The other aircraft made a report to the ATSB, indicating their pilot was unaware of the motor glider until the motor glider pilot made the inbound call.

Date	15-Apr-2017	Regior	n		GQ		SOAR Report		ort Nbr		S-0970	
Level 1	Operational		Leve	Level 2 Terrain C		ain Col	ollisions		Level 3		Controlled flight into terrain	
A/C Model 1			SZD-55-1			A/C	Model	2				
Injury	Minor	Dama	age	W	/rite-off	f Phase Landi		Landing			PIC Age	54

FACTUAL INFORMATION

At about 1539 Eastern Standard Time on 15 April 2017, while conducting a low-level and high-speed circuit onto runway 12 at McCaffrey's Field Qld, the pilot flew into the ground during the final approach. The aircraft impacted forcefully on its nose and came to rest about 100 metres from the point of impact. The aircraft suffered substantial damage, with the vertical and horizontal stabilisers separating from the fuselage.



Figure 1: Damaged aircraft.

Pilot Information

At the time of the accident the command pilot held a GFA Glider Pilot Certificate endorsed for Air Experience Instructing and had accumulated 2,326 Hours over 1,561 Launches. While an experienced pilot, he only had 9 fights for 25 hours on type.

Aircraft information

The aircraft was maintained by a GFA approved maintenance organisation. The Maintenance Release (MR) was issued on 23 July 2016 and recorded total flight time as 1062.23 hours for 410 flights. The aircraft was due for its next inspection on 22 July 2017. The MR records the aircraft had flown 55 hours for 22 flights since 24 July 2016 up until the date of the accident flight. There were no outstanding maintenance items recorded in the MR prior to the accident.

Meteorology

The weather at the time of the accident was good visual meteorological conditions (VMC). **Flight data recorder**



Accident and Incident Summaries

No flight data was available.

Medical information

The command pilot held a valid GFA Medical Practitioner's Certificate of Fitness. The medical standards applicable for the issuing of this Certificate are the Austroads standards for the issue of a driver's licence medical certificate for a private motor vehicle.

Airfield information

McCaffrey Field is uncertified Aeroplane Landing Area (ALA) operated by the Darling Downs Soaring Club and situated approximately 4.5 NM WNW of Jondaryan Qld. It has a single grass runway (12/30) of 1200 metres length. The airfield is 1,215 ft above mean sea level. The Common Traffic Advisory Frequency is 126.7 MHz. The terrain around the airfield is flat with few trees, and there are no obstacles, hills or mountains of any influence in the vicinity.

ANALYSIS

Flight

The pilot was returning from a cross-country task and was established on final glide to the home airfield at 15Nm. The glider was established about 500ft above the calculated glide path based on a 3-knot ring setting, and the pilot was flying at a speed of 70 to 75 knots. At 10 miles the pilot changed to the CTAF and monitored communications between another glider and the ground discussing wind strength and direction, and the number of the operational runway. Just prior to entering the circuit the pilot heard a base leg joining call from the other glider pilot and then visually acquired it. The other glider was established on a long, wide base. Due to the high circuit speed of the SZD 55 (about 90 to 100 knots), the pilot made a radio call to the other glider pilot advising he would be turning base early and landing first. The SZD 55 pilot then completed a high-speed turn onto a final approach at such a low height as to be concerned about the port wingtip touching the ground. Upon levelling out the pilot realised he had not lowered the undercarriage and immediately set about lowering the landing gear. The pilot changed hands on the control stick to use his right hand to manipulate the undercarriage lever and, in so doing, caused the glider to pitch forward and impact the ground nose first at high speed.



Accident and Incident Summaries



Figure 2: Initial impact site with skins from the nose of the glider embedded.



Figure 4: Damage to the nose of the glider. Pilot



Accident and Incident Summaries

The pilot was medically fit and qualified to undertake the flight. He held a Glider Pilot Certificate and was endorsed for low level finishes in August 2006. Fatigue and stress were evaluated as potential factors, but analysis was inconclusive. In the accident the pilot suffered a minor cut and bruise to the right eye that was attributed to the flight computer being flung from its mount and was transported by ambulance to the local Base Hospital for observation.

Aircraft

The aircraft struck the ground at high speed in a steep nose down attitude. The nose first impacted with the ground well forward of the instrument panel, leaving part of the lower fuselage skin embedded in the grass runway surface. The bottom of the fuselage was crushed but the cockpit structure of nylon woven into the carbon fibre weave prevented the fuselage from shattering on impact and contributed to the survivability of the pilot. The tail boom, fin and empennage broke away at impact and was located about 100 metres behind the final resting place of the fuselage. The root end forward of the starboard wing spar suffered severe cracking. There was no evidence of any pre-impact failure or system malfunction.

Findings

- The pilot confirmed they had not completed the pre-landing checklist, probably due to the distraction of dealing with the other glider in the circuit.
- Due to cockpit ergonomics, where the undercarriage control lever is situated on the starboards side of the cockpit, the pilot had to change hands on the control stick to lower the undercarriage. It is likely the pilot, flying with his non-preferred left hand, inadvertently pitched forward on the control column as he was pushing forward with his right hand to lower the undercarriage.

CONCLUSIONS

- 1. The command pilot was appropriately qualified and medically fit for the flight.
- 2. The aircraft had a valid Maintenance Release and had been maintained in accordance with relevant requirements.
- 3. The pilot did not configure the aircraft for landing and omitted to complete the pre-landing configuration checklist.
- 4. The aircraft struck the ground during the final approach due to misapplication of the controls by the pilot.
- 5. The aircraft was capable of normal operation up until the time of impact with terrain.

SAFETY ADVICE

Circuit and landing are high workload environments and pilots are encouraged to reduce their workload by configuring the aircraft for landing at an early stage. GFA training is to lower the undercarriage once the decision to land has been made and the undercarriage should be down before the circuit is joined. When the aircraft is configured early, the risk off a mishap from the omission of the pre-landing checklist, for whatever reason, will be reduced. Refer also to <u>OSB 01/14</u> 'Circuit and Landing Advice'. This accident also highlights the risk of injury to the pilot from poorly secured navigation devices in the cockpit. It is recommended that the security of installations of flight computers and other similar devices be assessed and approved by an Annual Inspector. The advice in GFA's '<u>Guidance on Mounting Cameras on Sailplanes and Powered Sailplanes</u>' may inform appropriate actions.

Date	17-Apr-2017	Region		NSWGA		SOAR Report Nbr				S-0971		
Level 1	Airspace	2		el 2 Aircraft S		eparation		Level 3		Near collision		
A/C Mod	el 1	LS 1-f					A/C Model 2 Pi			ver PA25-235		
Injury	Nil	Dama	age	Nil	Pha	ase In-Flight		PIC Age	76			
Near miss between a towing combination and an LS1 glider. The LS1 was tracking towards another glider, a												
standard Libelle, that was thermalling about 2 kms from the airfield. The LS1 pilot's focus was on the												
thermalling Libelle when they noticed the towing combination to starboard, which was climbing past very												
close. The towing combination did not appear on Flarm. The tow pilot had also sighted the thermalling												
Libelle and was towing towards it in order to drop the glider under tow in the thermal. The tow pilot												


Accident and Incident Summaries

reported conditions being hazy and stated: *"I simply don't know why I did not see (the LS1) on collision course but when on a collision course the angle does not change so (the LS1) may have remained behind the canopy frame, or under (the tow plane's) wing... or I could have been looking in the wrong direction at the instant."* The pilot of the LS1 stated they were looking up at the Libelle and did not se the towing combination until it was quite close. The LS1 pilot said: *"My lookout was clearly inadequate."* Later investigation determined that there were FLARM malfunction issues but the incident resolves into inadequate lookout by both the pilot of the LS1 and the pilot of tow plane. The LS1 pilot did not see the towing combination soon enough and the tow pilot did not see the LS1 at all. This incident highlights the importance of good Lookout and working Flarm to facilitate alerted see-and-avoid.



Date	17-Apr-2017	Region		NSWGA SOAR Report Nbr				S-	0973			
Level 1	Operational		Level 2	Airc	raft Co	ontro	_	Level	3	Wheels up	landing	
A/C Mod	el 1		Horn	et		A/C	Model	2				
Injury	Nil	Dama	age	Nil	Phase Landing				PIC Age	75		
This expe	This experienced pilot advised that he failed to retract the undercarriage during his post-release check, and											
then retr	hen retracted it during the pre-landing check. A visual inspection to confirm the undercarriage was in the											
down po	lown position was not made, and the aircraft was landed with the wheel retracted. The pilot stated that his											
most rece	ent flying had be	en in glid	ers with a	fixed und	ercarr	iage,	and be	lieves	he cal	lled "wheel	fixed" when	
doing his	post-release che	ck and le	ft the un	dercarriage	e dowi	n. He	did no	t recall	checl	king the und	dercarriage	
lever to t	he placards durir	ng the pre	e-landing	check. OSE	3 01/1	4 'Cir	cuit &	Landin	g Adv	ice' confirm	s that the	
pre-landi	pre-landing checklist is a 'check' and not an 'action' list. The undercarriage should be lowered as soon as the											
decision	ecision to break off the flight has been made and preferably before entering the circuit. The pre-landing											
check sho	ould be used to v	erify the	undercar	riage lever	is ma	tched	d to the	lower	ed po	sition on th	e placard.	

Date	21-Apr-2017	Regior	on NSWGA				SOA	AR Repo	ort Nbr		S-	1004
Level 1	Airspace		Leve	evel 2 Aircra		ift Sep	arati	on	Level	3	Aircraft Se	paration
									Issues			
A/C Mod	el 1		DG	i-1000S	5		A/C	Model	2	BRN	1 Aero Brist	ell
Injury	Nil	Dam	age	N	lil	Pha	ise	Landi	ng		PIC Age	68



Accident and Incident Summaries

The glider was aerotowed from the grass glider strip situated close and parallel to the left of the main runway on a training flight. Some 16 seconds earlier, a powered aircraft had reported on a 1½-mile final for a touch and go on the main runway, and 23 seconds after the combination commenced take off another glider reported downwind for the glider strip. The gliding instructor was unaware of the presence of the powered aircraft or, apparently, the other glider. About one minute after take-off, at 300 feet AGL, a simulated cable break was executed, with the glider turning right into a light crosswind and continuing onto a reciprocal heading in order to line up and land back on the grass take off strip. In so doing, the glider infringed the extended centreline of the main runway and the powered aircraft, now already on the ground, applied heavy braking and aborted its touch and go. The glider then reported on short final before landing back on the glider strip and the other glider subsequently landed on a safe area to the left of the glider strip. Pilots must always be situationally aware and maintain "alerted see and avoid". That requires a thorough lookout aided by efficient monitoring and use of the radio. Before any take off, pilots need to establish that the airspace is clear. Even more so when conducting low-level emergency exercises, pilots must positively ensure that there is no conflicting traffic and remain alert and aware throughout the exercise. Causal factors include an inadequate radio listening watch that led to a lack of situational awareness that was possibly exacerbated by such Human Factors as:

- 'task fixation' to the exclusion of recognising the developing threat from the presence of the other two aircraft, or
- 'motion induced blindness' from fixating ahead and missing the peripherals.

Date	22-Apr-2017	Regior	egion SAGA				SOA	R Repo	ort Nbr		S-	0977
Level 1	Operational		Leve	Level 2 F			t		Level	3	Other Fligh	nt Prep/Nav
				Preparation/Navigation				Issues				
A/C Mod	el 1	ASK-21Mi					A/C	Model	2	N/A	L.	
Injury	Nil	Dam	age		Nil	Pha	se	In-Flig	ght		PIC Age	
The stude was disco renewed complian	ent was participa overed the stude their membersh ce.	ating in a nt was w ip, and tl	n AAFC ithdra ne orga	C fligl wn fi anise	ht training rom the a ers have s	g activ ctivity ince a	ity w and meno	ith an e counse led the	expired elled. Tl ir proce	GFA he stu edure	membership udent subsects to identify	o. When this quently 1 non-

Date	23-Apr-2017	Region		NSWGA		SOAR Report Nbr				S-0975		
Level 1	Airspace	L	evel 2	Aircra	ift Sep	oarati	on	Level	3	Near collis	ion	
A/C Mod	el 1		Astir	CS		A/C	: Model	2	Heli	copter		
Injury	Nil	Damag	ć	Nil	Pha	ase	In-Flig	ght		PIC Age		
The Glide	The Glider was launched by winch to a height of 1,200ft AGL but no lift was found, so the pilot joined											
downwin	downwind for a left-hand circuit. At a height of about 900 ft AGL the pilot made a downwind call on the											
CTAF. Ap	CTAF. Approximately halfway on the downwind leg at a height of approximately 750 ft, the glider pilot											
observed	bserved a white helicopter 400 metres ahead on a reciprocal heading, displaced about 200 ft vertically and											
100 metr	es laterally to th	e right. The	glider	pilot rocke	d the	glide	r's wing	gs and r	nade	a call on the	e CTAF but	
did not g	et a response fro	om the helio	opter p	oilot. Earlie	r in th	ne day	y the sa	me or s	simila	r helicopter	was	
observed	transiting close	to the airst	rip on a	Northerly	head	ing b	elow th	ermalli	ing gli	iders withou	it having	
been hea	rd to make any o	calls on the	CTAF. 1	his airfield	l is a h	not sp	ot for l	ow-lev	el tra	nsiting aircra	aft and the	
CFI recen	CFI recently arranged for the airfield to be depicted on the aeronautical charts with appropriate symbology											
and a CT/	AF annotated. De	espite this,	some tr	ansiting pi	lots co	ontin	ue to p	ose a h	azard	to the glidir	ng operation	
by not m	onitoring the ap	propriate fr	equenc	y when in	the vi	cinity	of this	airfield	l. The	ATSB has b	een	
informed												



Date	29-Apr-2017	Regior	n	GQ SOAR Report N			ort Nbr		S-	0978	
Level 1	Operational		Level 2	Run	iway E	vent	5	Level	3	Runway ex	cursion
A/C Mod	el 1		Twin	Astir		A/C	Mode	2			
Injury	Nil	Damage Nil Phase Launch			h		PIC Age				
During the initial ground roll on an aerotow launch the glider's left wing dropped to the ground and the											
glider sta	lider started to veer to the left. The pilot corrected but in so doing the prevailing crosswind caused the right										
wing to c	ontact the groun	d and th	e glider v	eered right	towa	rd th	e airfie	ld bour	ndary	fence. The J	oilot picked-
up the rig	ght wing, release	d from to	ow and ii	itentionally	drop	oed tl	he left v	wing to	initia	ite a ground	l loop away
from the	fence. It was rep	orted th	at the pe	rson runnir	ng the	wing	let go	after oi	nly or	e step. This	incident
highlight	s the importance	of the w	ing runn	er maintain	ing a	wings	s level p	ositior	n as fa	r into the la	unch as
possible	possible to allow the pilot to gain control authority, and for pilots to release from tow as soon as control has										
been lost	been lost.										

Date	30-Apr-2017	Region VSA SOAR R			R Repo	ort Nbr		S-	0980			
Level 1	Operational		Level 2	Mis	scellar	neous		Level	3	Other Mis	cellaneous	
A/C Mod	el 1		ASK-21	lMi		A/C	Model	2				
Injury	Nil	Dama	ge	e Nil Phase In-Flight						PIC Age	59	
It was rep	t was reported that a glider was observed to do loop below 1000ft AGL on the downwind leg of a Military											
Aerodror	verodrome. Investigation revealed the reporter was mistaken. The glider was carrying a logging device and											
analysis o	analysis of the flight trace revealed a loop was conducted at 11:58, about 1NM to the West of the runway,											
some 5 n	ninutes prior to t	he glider j	oining th	e downwi	nd leg	ofth	e circu	it. The	glider	did not des	scend below	
1200ft A	GL during the ma	noeuvre.	This info	rmation w	as pro	video	l to the	report	er wł	no, while so	mewhat	
perplexe	d that their recol	lection of	events d	iffers, ackı	nowle	dged	they m	ust hav	ve be	en mistaker	n. While it is	
not good	practise to cond	luct aerob	atics in a	circuit are	ea, and	d that	aerob	atics ar	e pro	hibited with	nin 2 NM and	
below 2,0	below 2,000 feet above the level of a certified or registered aerodrome, Military aerodromes and uncertified											
aerodron	nes are subject t	o local req	Juiremen	ts. In this o	case tl	he gli	ding clu	ıb had	prohi	bited aerob	atics,	
including	ncluding spins, at this site and the command pilot has been counselled.											

Date	7-May-2017	Region NSW				SOA	AR Repo	ort Nbr		S-	1040
Level 1	Airspace		Level 2	Aircra	ift Sep	arati	on	Level	3	Aircraft Se	paration
										Issues	
A/C Mod	el 1	1 Twin Astir A/C Model 2 AMD - ZODIAC (CH640				
Injury	Nil	Dama	age	Nil	Pha	ase	In-Flig	ght		PIC Age	59
A glider a	nd tow plane combination departed the airfield for the Southern Training Area. Air Traffic Control										
(ATC) req	ATC) requested that the combination remain connected due to an ILS practice flight from another										
aerodron	ne. The tow pilot	read ba	ck the ins	truction, b	ut the	glide	r pilot (did not	hear	the request	and
released	from tow shortly	thereaf	ter. ATC v	vas informe	ed of t	he gl	ider's s	eparati	on bι	ut continued	l to allow the
aircraft c	onducting the ILS	S to conti	nue its a	oproach ev	en tho	bugh	they di	d not h	ave si	ight of the g	lider. The
tower ins	tower instructed the glider to operate south of the local parachute drop zone to provide separation from the										
other aire	other aircraft. Procedure at the aerodrome has been changed and ATC will also confirm the glider pilot has										
received	and understood	the instr	uction.								

Date	13-May-2017	Regior	n NSWGA			SOA	AR Repo	ort Nbr		S-	0984
Level 1	Operational	Level 2		2 Miscellan		eous	;	Level	3	Winch Per	formance
								Issue			
A/C Mod	el 1	1	KR-03A	Puchatek		A/C	Model	2			
Injury	Nil	Dama	age	Nil	Pha	ise	Launch		PIC Age	42	



Accident and Incident Summaries

The sortie was a training flight for an experienced glider pilot who had just joined the club and was undertaking a conversion to winch launching. The launch was to include a simulated power loss at the winch to assess the student's reactions. The simulation was to be done at a height sufficient for the pilot under training to complete a modified circuit, and the instructor personally briefed the winch driver for the exercise. A loss of power was identified in the glider at a height of about 850 ft AGL, and the pilot under training reacted promptly and correctly. A modified circuit was flown and the glider landed without incident. At the winch end the driver had reduced the power so quickly that the engine stalled. A number of attempts by the winch driver to restart the engine proved futile and the winch rope fell onto a neighbouring property and across high voltage power lines (11,000v). One of the ground crew then took hold of the rope and removed it from the powerlines, despite the power lines remaining active. This action by the ground crewman was contrary to Club Instructions, which is to stop traffic and call the power company to remove the rope from the power lines due to the risk of electrocution (although the club uses polypropylene rope, it can still conduct electricity if it is moist or contaminated with conductive material). The power company subsequently confirmed there was no damage to infrastructure. The CFI has implemented further training for the winch drivers, and is considering only conducting practice launch failures with the winch displaced further away from infrastructure, and/or using the reciprocal runway. The procedure to be used by winch drivers when simulating launch failures is being reinforced at morning briefings. The CFI has arranged for the power company to provide a safety lecture to club members.

Date	13-May-2017	Region		NSWGA SOAR Report Nb			ort Nbr		S-0985			
Level 1	Operational		Level 2	Terra	ain Co	llisior	าร	Level	3	Collision w	vith terrain	
A/C Mod	el 1		TST-8 Al	pin DM		A/C	Model	2	Gro	b G 109		
Injury	Minor	Dama	age S	ubstantial	Pha	ase	Grour	nd Ops		PIC Age	70	
The glide	r was recently pu	urchased	from a c	eceased es	tate a	nd ha	ad beer	i transp	orteo	d to the airfi	eld for some	
minor ma	intenance by the	e local Ai	rworthin	ess Mainte	nance	Orga	inisatio	n. Insp	ectior	n revealed a	dditional	
work was	ork was required to the engine to bring it up to operational standard, including replacement carburettors											
and a fue	nd a fuel system upgrade. The pilot, who had been assisting with the maintenance, decided to start the											
engine ar	ngine and run it up for assessment. The glider had been parked nose-first into a hangar, which also housed											
a Grob 10	Grob 109. The pilot, working alone, pushed the glider backwards about 10 metres out of the hangar and											
placed tw	/o 4"x2" wooder	chocks a	it the ma	inwheel. W	/ith th	e glic	ler faci	ng the I	nanga	ar, the pilot	sat in the	
front sea	t and proceeded	to start t	he engir	e. After sor	me ini [.]	tial d	ifficulty	, the ei	ngine	started wit	h a roar and	
at high re	evs. The glider ju	nped the	chocks	and moved	towa	rds th	ie hang	ar. The	pilot	pulled on the	ne	
handbrak	e to stop the gli	der but th	ne cable	had either o	discon	necte	ed or bi	roken, a	and th	ne glider mo	ved into the	
hangar. C	One wing struck a	hangar j	oost, the	other wing	struc	k a ve	ehicle ir	n the ha	angar	and the for	ward	
fuselage	impacted the no	se of a pa	rked Gr	ob 109 mot	or glid	ler. A	fter the	e collisio	on the	e pilot had c	lifficulty	
turning o	turning off the engine as the instrument panel had been bent backward obscuring the ignition key. The											
throttle v	hrottle was noted to be in the full open position, however it may have been altered after the event. The											
glider wa	glider was substantially damaged and the Grob 109 suffered minor damage. The pilot suffered cuts and											
bruising t	to the face, and v	vas trans	ported t	o hospital.								



Accident and Incident Summaries



After repair or replacement of an engine in an aircraft, it is necessary to check out engine performance on the ground prior to any flight test. During these tests, it is often required that the engines be run at or near full power and it is therefore necessary to physically restrain the aircraft. The most common way of restraining a sailplane is to use the wheel brake in conjunction with wheel chocks. However, this method should be used with caution during part or full power engine run-up tests because of the danger of the wheel brake failing, and the chocks may move or the aircraft wheels may ride-up and over them, especially if the chocks are not properly positioned. The ideal solution would be to also tether the aircraft to a fixed object. When ground running an engine of a glider that is having maintenance carried out on it, the person at the glider's controls must have sound knowledge of both the engine and aircraft systems to ensure the starting or running does not endanger any person or damage the aircraft. Before starting an aircraft engine: 1. Position the aircraft away from people and objects, and preferably pointing into the prevailing wind to ensure adequate airflow over the engine for cooling purposes. 2. Make sure that no property damage or personal injury will occur from the propeller blast or jet exhaust or the aircraft isself. 3. Check the throttle is set correctly. 4. Ensure the wheel brake is functioning and that the aircraft is secured against unwanted movement.





Date	13-May-2017	Region	egion SAGA SOAR Rep			R Repo	ort Nbr		S-	0989	
Level 1	Technical		Level 2		Systen	ns		Level	3	Flight cont	rols
A/C Mod	el 1		Astir	CS		A/C	Model	2	N/A		
Injury	Nil	Dama	ge	Nil	Phase In-Flight					PIC Age	
While de	-rigging the aircr	aft for its	annual ir	spection i	t was i	notic	ed that	the sat	fety p	in used to s	ecure the
elevator	'Hotellier coupli	ng was inc	correctly	located ar	nd inef	fectiv	/e (refe	r photo	ograp	hs below). T	he aircraft
was last r	vas last rigged and dual inspected in November 2016, and it had been flown for several months in this										
condition	. The elevator co	oupling on	the Asti	r series gli	ders ca	an be	visuall	y inspe	cted	for security	during the
Daily Insp	ection by lookin	g from be	hind and	below the	e eleva	tor w	vith the	e rudde	r offs	et to the lef	t. Over many
years the	re have been a s	teady run	of incide	ents arising	g from	the c	disconn	ection	of l'H	otellier cou	plings on
gliders, m	nany of which oc	curred du	e to inco	rrect assei	mbly d	uring	; rigginį	g. GFA i	ssued	d AD 177 to	alert
members	members to these problems (refer http://tinyurl.com/yc8ggeq3). This incident highlights the importance of										
conducti	ng a thorough Du	ual Inspect	tion befo	re releasir	ng the	aircra	aft to se	ervice, a	and it	also confiri	ms the vital
role a tho	ole a thorough Daily Inspection plays in our risk management system.										





Date	17-May-2017	Regior	Region SAGA SOAR Report Nbr				S-	1005			
Level 1	Technical		Level	2	Syste	ms		Level	3	Electrical	
A/C Mod	el 1	DG-1000S A/C Model 2									
Injury	Nil	Dama	age	Nil	Pha	ase	In-Flig	ght		PIC Age	19
During a	During a solo flight, the pilot reported that a FLARM Power Error and shutdown occurred. The pilot decided										
to return	to return to the airfield and executed a normal circuit and landing. Investigation revealed the FLARM circuit										
breaker h	had tripped, the i	radio syst	em wa	as display	ing 'Low E	atter	y' and t	he trar	nspon	der was not	t working. It
was also	noted that the ca	abin batt	ery ha	d been se	lected by	the p	ilot but	when	the fi	n battery wa	as selected
there wa	here was no change to the symptoms. It was determined that the aircraft batteries had not been recharged										
from the	from the previous day due as charging facilities were not available.										

Date	20-May-2017	Regior	1	GQ	Q SOAR Report Nbr				S-0987			
Level 1	Operational		Level 2	Airc	raft Co	ontro		Level	3	Wheels up	landing	
A/C Mod	A/C Model 1 Discus bT A/C Model 2											
Injury	Nil	Damage Nil Phase Landing PIC Age 81							81			
The pilot	he pilot lowered the undercarriage for landing but the wheel retracted on touchdown. The pilot was flying											
with an a	vith an arm/shoulder injury and was unable to fully extend their arm in order to lock the undercarriage											
down. GF	A Operational Re	egulatior	3.2.2(c)	states that	a pilo	t sha	ll not fl	y as pil	ot in d	command o	f a sailplane	
if he or sl	ne is temporarily	unfit du	e to illnes	s or injury.	A per	son i	s deem	ed to b	e unf	it where the	e medical	
deficienc	y may interfere v	vith the s	afe oper	ation of an	aircra	ft. Pil	lots suf	fering	from a	a physical in	jury should	
take step	ake steps to ensure any limitations of movement will not adversely impact the operation of the aircraft											
before fly	efore flying in command.											

Date 20-May-2017 Region SAGA SOAR Report Nbr S-0990	
---	--



Level 1	Airspace		Level 2	Aircra	paration		Level 3		Aircraft Separation		
										Issues	
A/C Mod	el 1		DG-1000S			A/C Model			ICP Savannah		
Injury	Nil	Dama	age	Nil	Pha	ise	Launo	h		PIC Age	55
The pilot	of a powered ai	rcraft con	ducted a	low overfl	ight of	^f a gli	der aw	aiting a	laun	ch to land o	n the
bitumen	men glider strip directly ahead rather than on the main gravel runway. The crew of the glider estimated										
separatio	on to be about 40) feet. Ae	rodrome	operating	proce	dures	requir	e that p	oowe	red aircraft	pilots must
use the g	ravel strip for la	nding who	en gliding	g operation	s are i	n pro	gress.	The pilo	ot had	d developed	a practice of
landing o	n bitumen strips	in prefer	rence to t	he gravel s	trips a	it the	home	airfield	to re	duce wear a	and tear on
the aircra	aft. The pilot ack	nowledge	ed that la	nding over	the gl	ider p	bosed a	in unne	cessa	ary risk of co	ollision, and
has since	reflected on the	eir practic	e and re-	familiarise	d then	nselv	es with	the ae	rodro	ome operati	ng
procedur	es.										

Date	21-May-2017	Region		NSWGA		SOA	R Repo	ort Nbr		S-	0988	
Level 1	Operational		Level 2		Airfrar	ne		Level	3	Doors/Car	iopies	
A/C Mod	el 1		AS-K	13		A/C	Model	2				
Injury	Nil	Dama	ge	Nil	Pha	ise	Launc	h		PIC Age	57	
The aircra	aft had just been	returned	to servic	e after the	e fittin	g of a	new c	anopy.	The p	oilot reporte	ed having	
difficulty	getting both of t	he canopy	y locking	pins to en	gage a	and ca	alled a	membe	er of t	he ground o	crew for	
assistanc	e. The crew pers	on observ	ed the ca	anopy was	seale	d wel	l exterr	hally an	d cor	nfirmed the	rear lock was	
engaged	and the lock han	dle in secu	ured pos	ition. The ا	passer	nger i	n the fi	ront sea	at adv	ised that th	e locking pin	
was not e	engaged in the ca	anopy fran	ne, howe	ever this w	as mis	hear	d by bo	th the	comn	nand pilot a	nd crew	
member.	member. The pilot pushed-up on the canopy frame overhead to confirm the canopy was locked and the											
launch pr	oceeded. At app	roximatel	y 500 fee	et on the w	/inch l	auncl	h the ca	anopy f	lew c	pen with co	onsiderable	
energy ar	nd a loud bang. T	he comm	and pilot	immediat	ely lo	wered	d the no	ose of t	he gli	ider to get c	lear view of	
horizon a	nd, together wit	h the pass	senger, m	nade two b	orief a	nd co	ncerte	d attem	pts to	o pull canop	y closed.	
Unfortun	ately the force o	f the airflo	ow preve	nted the c	anopy	from	n being	closed	, so tł	ne comman	d pilot	
released	from the cable a	nd assesse	ed the op	otions. As i	t was	no lo	nger po	ossible	to coi	nduct a lanc	ling straight	
ahead, th	e command pilo	t commen	nced a lef	ft-hand tur	n for a	a moo	dified c	ircuit. I	Durin	g the turn th	ne airflow	
forces on	the canopy chai	nged and t	the comr	nand pilot	was a	ble to	o secur	e the c	anopy	y with the as	ssistance of	
the passe	nger and a safe	landing er	isued. Th	ie mainten	ance	perso	nnel in	specte	d the	canopy and	advised it	
will need	some minor adj	ustment a	s it settle	es in. In the	e mea	ntime	e, canoj	oy lock	ing wi	ill be checke	ed and	
confirme	d by both pilots	prior to ev	ery laun	ch, or by a	third	party	extern	ally ch	eckin	g both locks	if one of the	
occupant	s is not a qualifie	ed pilot. Th	ne minor	defects se	ection	of the	e Main	tenanc	e Rele	ease has bee	en endorsed	
to this ef	fect.											

Date	24-May-2017	Region GQ				SOAR Report Nbr				S-1262		
Level 1	Technical		Level 2		Syster	ns		Level	3	Flight cont	rols	
A/C Mod	el 1	Sta	ndard Lik	elle 201 B		A/C	Mode	2				
Injury	Nil	Dama	age	Nil	Pha	ise	In-Flig	ght		PIC Age	77	
Following	g a successful wir	nch launc	h, the pil	ot found th	iey we	ere ur	nable to	o increa	ase th	e airspeed a	bove 50	
knots and	d decided to join	circuit to	land. In	order to m	aintaiı	n airs	peed d	uring tl	he fin	al approach	, the pilot	
only used	l a small amount	of airbra	ke for gli	de slope co	ontrol.	The	pilot co	mplete	ed a s	uccessful la	nding, albeit	
further d	own the runway.	The pilo	t had pre	vious expe	rience	on t	ype bu	t this w	as on	ly their third	d flight in	
this parti	cular aircraft. Sul	osequent	investig	ation revea	led th	at th	e pedal	adjust	ment	cable, in th	e position	
the pilot	would have had i	it, could e	easily fou	I the contr	ol colu	ımn a	and res	trict its	forwa	ard movem	ent (refer	
photogra	ph below). The a	ircraft ov	vner, wh	o is somew	hat ta	ller t	han the	e pilot f	lying,	had not pre	eviously	
experien	ced this issue. Th	e owner	stated th	at they adj	ust th	e rud	der pe	dals so	they a	are further f	forward,	



Accident and Incident Summaries

which reduces the length of the adjustment cable protruding from the seat pan so that it cannot interfere with the control column. In addition, the owner tucks the handle under the seat cushion after it is adjusted. Pilots flying aircraft with similar rudder pedal cables should ensure the cable and handle are secured, either under the cushion or the pilot's leg to prevent it interfering with the controls. Although the pre take-off check of controls for full and free movement should have identified this restriction, the pilot's lack of familiarity with this aircraft may have led to the restriction going unnoticed.



Date	28-May-2017	Region SAGA SOAR Repor				ort Nbr		S-I	0992			
Level 1	Operational		Level 2 Aircraft				Ĩ	Level	3	Pilot Induced		
										Oscillation	S	
A/C Mod	A/C Model 1 SZD-51-1 Junior A/C Model 2											
Injury	Nil	Dama	age	Minor	Pha	ase	Landi	ng		PIC Age	62	
The pilot	had rounded out	during t	he fina	phase of lar	nding	and v	vas beg	inning	the h	old-off phas	e when the	
glider bal	looned about 1 n	neter. Th	ne pilot	responded b	y pusl	hing t	he stic	k forwa	rd an	d closed the	e airbrakes,	
which res	which resulted in an increase in speed and the glider touched down and rebounded into the air. The pilot											
levelled t	he aircraft but op	pened th	e airbra	kes causing	the aiı	rcraft	to aga	in touc	h dov	vn. Subsequ	ent	



Accident and Incident Summaries

mishandling of the controls led to a series of bounces, or Pilot-induced oscillations, before the aircraft came to rest. The top of the pilot's head hit the canopy causing it to crack. The aircraft suffered no other damage. Pilot-induced oscillations occur when the pilot of an aircraft inadvertently commands an often increasing series of corrections in opposite directions, each an attempt to cover the aircraft's reaction to the previous input with an overcorrection in the opposite direction. The correct action when becoming airborne after a bounced landing is to select and hold a steady level attitude and retract the airbrakes. A second attempt at the landing can then be made but be careful when opening the airbrakes.

Date	2-Jun-2017	Region GQ SOAR Report Nbr							S-	0995		
Level 1	Operational	Le	vel 2		Airfrar	ne		Level	3	Other Airf)ther Airframe Issues	
A/C Mod	el 1		ASK-2	1Mi		A/C	Mode	2	N/A			
Injury Nil Damage Minor Phase In-Flight								PIC Age	65			
The pilot flying was undertaking a currency check flight operating from rear cockpit. After a normal take-									nal take-off			
and climb to 4000', the engine was shut down the propeller stop was activated. The pilot flying and the												
instructor, observing the propeller continuing to windmill, both attempted to engage propeller stop to no												
avail. The	e flight was aban	doned and a	succe	ssful landi	ng wa	s con	ducted	with th	ne pro	peller towe	er in the	
extended	l position and th	e propeller v	/indmi	illing. Upoi	n inspe	ectior	n, it wa	s obser	ved t	hat the prop	peller stop	
had shea	red off and scuff	⁻ marks were	evide	nt on both	prope	eller k	olades.	The pro	opelle	er stop assei	mbly was	
bent bac	kwards, and the	re was minor	dama	ge caused	to the	e prop	beller to	ower sł	nroud	. The persor	n who	
dispatche	ed the aircraft fo	r launch reca	lled h	earing a no	oise as	the a	aircraft	entere	d the	main runw	ay but	
believed	the noise had co	me from a n	earby	maintenar	nce ha	ngar.	A subs	equent	t chec	k of the run	way located	
the plastic sleeve from the propeller stop, revealing it was damaged during take-off. It is believed that the												
pilot flyir	ng had inadverte	ntly knocked	the p	rop stop ha	andle	when	n reduc	ing the	throt	tle to idle d	uring	
taxying, which caused the the stop to extend and contact the rotating propeller.												

Date	4-Jun-2017	Regior	n	VSA	SOAR Report Nbr				S-0993		
Level 1	Operational	Level 2		I 2 Corr	cations Lev			3	Other Communication		
										Issues	
A/C Mod	el 1		HI	K 36 R		A/C Model		2			
Injury	Nil	Dam	age	Nil	Pha	ise	Landi	ng		PIC Age	55

Upon returning to the airport in Class D airspace following a local flight, the pilot proceeded to fly the standard CTA entry procedure. The circuit was very busy and an unexpected and unfamiliar instruction was received from the Air Traffic Controller. The pilot read back the instruction incorrectly but the error was not noticed by the controller until the glider was observed descending in the wrong direction. Upon recognising the situation, the controller directed the pilot to climb and re-enter the and the light proceeded uneventfully under ATC instructions. Misunderstanding is not uncommon and the potential for misunderstanding increases when an ATC clearance contains more than two instructions. Pilots should always seek confirmation or clarification if they do not understand a procedure rather than proceed. Similarly, any readback by the pilot requires a hearback by the controller in order to close the communication loop. Most pilots perceive the absence of an acknowledgement or correction following a clearance readback as an implicit confirmation of the readback. The lack of acknowledgement by the controller usually is the result of frequency congestion, requiring the controller to issue clearances and instructions to several aircraft. Uncorrected erroneous readback can lead to breakdown in separation. The following points will assist achieve n effective pilot / controller communications:

- Understanding of pilots and controllers respective working environments and constraints;
- Disciplined use of standard phraseology;
- Strict adherence to the pilot / controller communication loop (i.e., confirmation / correction process);



Accident and Incident Summaries

- Alertness to request clarification or confirmation, when in doubt;
- Readiness to question an incorrect clearance or an inadequate instruction; and
- Preventing simultaneous transmissions.

Date	7-Jun-2017	Region SAGA				SOAR Report Nbr				S-0997		
Level 1	Operational		Level 2 Communications					Level	3	Other Com	Other Communications	
										Issues		
A/C Mod	odel 1 Discus b A/C Model 2 Piper PA-25-235										5	
Injury	Nil	Damage Nil Phase Launch PIC Age 64							64			
The tow p	pilot lost sight of	the glide	er in the	mirror and,	assum	ning t	he glid	er had i	releas	sed, comme	nced its	
descent v	vhile the glider v	vas still a	ttached	The glider j	oilot re	eleas	ed befc	re an u	ipset	developed.	The tow	
pilot stat	ed: <i>"When…we</i> w	vere app	roachin <u>e</u>	3,000ft, I t	hough	t tha	t I hear	d a brie	ef trai	nsmission fro	om (the	
glider pilo	ot) to indicate th	at he wa	s off ton	. I checked i	the mi	rrors,	saw n	othing (and c	ommenced	decent. I	
definitely	definitely felt the release moments after." The Club's The tugmaster is having wider mirrors fitted to replace											
the curre	nt round ones.											

Date	10-Jun-2017	Regior	n	WAGA			SOAR Report Nbr			S-0996	
Level 1	Consequential	Events	Level	2 Lo	ow Cir	cuit		Level	3	Low Circui	t
A/C Mod	el 1		DG-	1000S		A/C	Mode	2			
Injury	Nil	Dama	age	Nil	Pha	ise	In-Flig	ght		PIC Age	67

This investigation involves a claim that a pilot, practicing a low-level finish manoeuvre at a Regional airfield, flew contrary to the Rules and Regulations. It was reported that, *"Following an evaluation flight the PIC joined a crosswind leg at a normal height but then, without any prior low-level finish warning calls, proceeded to descend at high speed to join the downwind leg at approx. 200ft AGL and then descended further to approx. 100ft AGL on the base leg before landing normally."* It was later alleged the pilot was showboating; i.e. acting in a manner to attract attention or admiration because the manoeuvre is very skilful. A key component of any investigation is to maintain objectivity, for otherwise it is merely just another person's opinion. Subjectivity is a viewpoint, or possibly a bias, regardless of the information it provides, and subjective opinions are ephemeral and influenced by any number of factors that can include a mix of facts and emotions. Consequently, the following is based on factual information, including interviews and written communications.

Scope of Investigation

This investigation considered:

- whether the pilot breached the rules and regulations and, if so, were they wilful violations:
- the intent of the rules around Low-Level Finishes; and
- whether the rules need to be amended to provide clarification.

Regulatory Requirements

- Civil Aviation Regulations 166A General requirements for aircraft on the manoeuvring area or in the vicinity of a non-controlled aerodrome.
- Civil Aviation Order (CAO) 95.4, paragraph 3(j)
- GFA Operational Regulation 6.5
- GFA Manual of Standard Procedures, Part 2, Section 10.8.3

Analysis of the Flight

The purpose of the flight was to undertake a performance evaluation following annual maintenance. The pilot in-command was experienced, with over 10,000 hours aeronautical experience on fixed-wing, including gliders, and rotary wing. The pilot holds an ATPL and was previously a Level 2 Gliding instructor and a former CFI. The other seat in the glider was occupied by an experienced glider pilot. The following information was taken from the flight log provided.



Accident and Incident Summaries

Note: Times are UTC +8 hours. As the glider did not thermal during the flight, the logger did not calculate a wind component. Consequently, only ground speed was recorded. Wind speed was advised as 10 knots from 030 degrees.

The glider was launched at 11:52 and released eight minutes later at 4,700 ft (QNH) about 3.5kms to the North-East of the operational runway. A few minutes after release and at about 4,100ft, the pilot incommand commenced a high-speed (near Vne) run to the South-West. The aircraft descended to about 2,700 ft, whereupon the pilot slowed down by climbing back to 3,200 ft. The aircraft then crossed the operational runway at about 3,100 ft and flew about 3kms to the South-West. Upon return to the airfield the pilot positioned to join for a right-hand circuit onto the duty runway 34. The pilot commenced a mid-field join a few hundred meters to the left of the runway intersection and crossed the operational runway at about 300ft AGL. The pilot then, while progressively increasing the glider's speed, turned onto a downwind leg at about 300ft AGL. The pilot continued the downwind leg at high speed to a low point of about 100ft AGL about 750 meters from the runway threshold, whereupon the pilot slowly climbed to about 150ft AGL for the turn onto final approach. Safe airspeed was maintained throughout the base and final legs. The glider touched down about 12:09. The flight track is below at Figure 1. Data points are at Table 1.







Figure 3 – Flight track (looking North-West from 2,000ft).





Photo of glider turning onto downwind.



Accident and Incident Summaries

Position	Time	AGL	GSp
LH into wind abeam end RWY 34	12:07:13	839	52
	12:07:17	814	50
	12:07:21	800	51
	12:07:25	770	55
Turning onto crosswind for RH downwind join	12:07:33	646	72
	12:07:37	492	84
	12:07:41	492	84
	12:07:45	438	91
	12:07:49	393	91
	12:07:53	351	90
	12:07:57	325	88
Turn onto downwind	12:08:01	303	94
	12:08:05	279	102
	12:08:09	245	108
	12:08:13	205	111
	12:08:17	168	110
	12:08:21	139	109
Turning onto base leg	12:08:25	117	103
During pullup on turn onto base leg	12:08:29	105	87
Base leg	12:08:33	128	72
	12:08:37	157	66
Turn onto final	12:08:41	169	55
	12:08:45	153	47
	12:08:49	119	47
	12:08:53	89	46
	12:08:57	59	45
Touchdown	12:09:01		
	12:09:05	20	36
	12:09:09		
End of roll	12:09:13	0	28

Table 1. Data points from logger. Note: Indicated Airspeed was not recorded.

Additional Information

The pilot reported: "...I was to fly a high visibility LLF that provided lateral and height de-confliction with any possible 'unknown' traffic and allowed ideal general and targeted scan opportunities throughout. The continuous radio listening watch and thorough close in observation afforded by the five legs of a standard laterally spaced circuit made it obvious that I was the only aircraft airborne and that no one was about to launch from the landing airfield (Remaining Tug and glider were both side-lined at the launch point). There was simply no conflicting pilot to be 'surprised' by my LLF but the track and energy profile flown also allowed for other safe options should the unexpected occur." The pilot advised in an interview that he made an 'all stations' broadcast of his intention to conduct a low-level finish. The reporter who observed the flight from the ground stated no call was made.



Accident and Incident Summaries

Analysis and Findings

1. After careful review of the flight parameters and the regulations, it is not evident that the pilot has breached any rules and regulations. The provisions of CAR 166A (as amended by CAO 95,4, Section 3(j)), to avoid a collision, were met. Furthermore, the glider's circuit did not conflict with the guidance detailed at paragraph 5.3.1 of Civil Aviation Advisory Publication (CAAP) 166-1(4.1) as the pilot has permission to descend below 500ft as per the CASA approved GFA Operational Regulation 6.5(b)(iii). However, the question of whether the pilot communicated his intentions in accordance with the rules in 10.8.3 in MOSP Part 2 Operations cannot be determined.

2. Track analysis shows that the high speed, low level finish phase of flight was conducted within the circuit area, not during the approach to the aerodrome from the SW. A safe speed was maintained during flight in the circuit area.

3. Assessment of whether the flight was conducted within the rules requires analysis of both the letter and the intent of those rules. Communications exchanged during the investigation highlighted some divergent interpretations of the rules and their intent.

Some witnesses expressed views that the low-level finish flown by the pilot was outside the intent of the rules:

(a) One witness stated: "The MOSP intention is clearly that a Low-Level finish should be planned and executed from a point outside the 5 km area not from well inside any 3 km finish circle and certainly not within 1 km of the airfield."

(b) Another witness stated: "The definition in MOSP states that the pilot must descend "with sufficient kinetic energy to enable the pilot to convert energy into height and recover adequate height to enable a safe circuit and landing to be performed". It seems clear from this that the intent is for the low-level portion of the flight to be completed before the circuit is commenced and for the circuit itself to be conducted at a normal height. A minimum circuit height is unfortunately not defined and so it is (apparently) open to interpretation. I certainly don't believe that the intention is to endorse the conversion of height to speed in order to do complete circuit as low & as fast as possible - which is exactly what I observed."

The above comments are the witnesses' interpretation of the rules. When interpreting the rules we should consider 'intent' in its widest sense to include such things as what the rule was intending to achieve and the mischief the rule was intended to remedy. Prior to 2006 "low-level finishes" could only be conducted at approved Competitions (State, National and International only) and required CASA approval. GFA was concerned about that process as it excluded any legitimate means of safely practicing or training for a procedure that clearly requires a high level of skill and judgement. It was also noted that the CASA approval only authorised the event at which the low-level finish procedure could take place but not the pilots, leaving control in the hands of the competition organisers, who may at times have little knowledge of the pilots that are performing them. After lobbying by GFA, CASA agreed to remove their approval requirement and hand over approval to GFA subject to GFA introducing acceptable pilot endorsement and low-level finish procedural requirements. The change was promulgated on 30 March 2006 via Civil Aviation Order 95.4 Amendment Order (No. 1) 2006. When this procedure was developed competition finish lines were usually set as some point on or near the aerodrome, and was usually an extended line from a runway or airfield boundary fence. It was only in more recent times that remote finishes were introduced, thereby displacing the finish point up to 3 kms from the aerodrome reference point. For example, WAGA Local Rules for Beverley 2011, para 15, define a finish circle 2km from the aerodrome reference point and a minimum finish altitude of 500ft. Original guidance in pilot's notes accompanying the original Operations Directive 01/06 stated: "It goes without saying that a safe landing is planned to follow the finish and pull-up. The circuit that follows the pull-up should ideally contain 3 legs, however, safety is the prime consideration. A circuit following a low-level high energy finish might be best likened to a modified circuit following a low-level winch launch cable break, but with a much higher pilot workload. As always, a pre-landing check is part of the circuit procedures. Pilots unable to safely perform such a circuit under these circumstances should never attempt (or be allowed to attempt) a low level high energy finish." The guidance closed with the comment that: "Low level glider finishes are spectacular and exhilarating events when conducted safely. However, they are skilled undertakings that require great care and planning." The intent of the rule was to train pilots



Accident and Incident Summaries

how to safely manage a low-level finish and allow pilots the opportunity to practice the manoeuvre to maintain proficiency. It is left to the pilot's discretion to manage the entry to the manoeuvre and the only requirement is that they do it safely and with prior permission where possible. The statements by witnesses (a) and (b) draw on the opening statement at paragraph 10.8 of MOSP Part 2 Operations: "A pilot holding a Low-Level Finish Endorsement may conduct low level finishes, which are defined as an approved circuit entry and landing technique where a glider descends below 500ft AGL within 5km of an airfield with sufficient kinetic energy to enable the pilot to convert "energy into height" and recover adequate height to enable a safe circuit and landing to be performed." The witnesses contend that the conversion of energy into height must be done at circuit entry. However, this is a very narrow reading of the statement and does not reflect the dynamics of a low-level finish manoeuvre or the variations to circuits that are actually flown in competitions and XC regattas. This should NOT be read as the pull-up must be done at circuit joining. It merely requires that a safe circuit and landing be performed., It is improbable for most gliders to gain 800-1,000ft required to join a standard circuit, more likely in the range 250-500ft. There are also many variations to circuits, such as straight-in approaches and joining from base leg, often preferred in competitions.

4. Based on 3 above, it is not intended to make any significant amendment to the rules. GFA MOSP Part 2 Operations Section 10.8.3 contains required procedures to achieve safety outcomes.

5. The GFA Operations Department will consult with the GFA Sports Committee to review whether any change to guidance in the GFA Competition Safety Pack or pilot's notes might be published. Guidance around training and practicing low-level finish manoeuvres will form part of this review.

6. GFA also recognises the obligations of Club CFIs and Operations and Training Panels, defined in MOSP Part 2 Operations Section 9.1, in maintaining operations and safety standards, maintaining compliance with rules, and pilot discipline. GFA recognises that clubs have the right to develop and publish local rules, competition rules and local operations supplements. Where restrictions are applied, consideration must also be given to providing opportunities and areas for safe training and practice.

Date	11-Jun-2017	Region	VSA SOAR Report Nbr				S-	0994			
Level 1	Operational	Le	vel 2	Fu	el Rela	ated		Level	3	Starvation	
A/C Mod	el 1	HC	RNET	STOL		A/C	Model	2			
Iniurv	Nil	Damage		Nil	Pha	se	In-Flig	t		PIC Age	65

While preparing to conduct endurance trials of a new tow plane type, the pilot dipped the tanks to measure fuel quantity. To prevent cross-feeding during the measuring process, the pilot closed the wing fuel tank shut off taps. Unfortunately, the pilot forgot to open the taps and did not check them during the pre-flight checklist. Shortly after settling into the cruise the engine stopped and the pilot safely conducted an off-field landing about five miles from the airfield. Investigation revealed that, just after the fuel quantity was measured, the pilot and maintenance crew observed an accumulation of carbon inside the exhaust pipe and briefly discussed the matter agreeing that the mixture was obviously too rich. The pilot agreed to adjust the air/fuel mixture control on the flight to lean the engine. The aircraft was then pushed to a grassed area where the pilot could carry out the daily inspection. The pilot completed the fuel drain tests along with the rest of the outside checks, and then boarded the aircraft. The pilot started the engine and allowed it to warm while carrying out the usual cockpit checks. The pilot then taxied to the operational runway and took off. The pilot stated: "All went exceptionally well as I climbed on departure upwind to my decided upon altitude of 3500' AMSL. At top of climb, I levelled the plane out and spent about a minute or so setting the plane up to cruise at 4800 RPM with an in IAS of 75kts. A check of all instruments indicated that all was well. Shortly after... I noticed the mixture indicator starting to fluctuate and, as I had adjusted it on a number of occasions previously, I thought that it just needed adjustment for cruise altitude. After several attempts to rectify the now roughly running engine I decided it best to turn back towards (the airfield) ... and try to ascertain the problem. The engine picked up again, but I realise that I was losing power and I carried out the 'Forced Landing' checks ... without checking that the fuel was turned on; presumably because I don't normally turn it off and by now I was looking at a stationary propeller!" With a forced landing inevitable, the pilot gave a 'Mayday' broadcast on the CTAF and headed for landable terrain. The pilot completed a safe



Accident and Incident Summaries

landing and made a telephone call back to base. The pilot then proceeded to troubleshoot the loss of power and discovered the fuel had not been turned on. The pilot noted that *"previously when I have on the rare occasion turned the fuel valves off, I have turned them on again shortly after as when in the cockpit, they are up behind me and I (have now) decided that it was best to leave them on at all times."* With the assistance of the local farmer, the aircraft was towed to a more suitable paddock and the pilot flew the aircraft back to the airfield. Investigation revealed that shortly after assessing the fuel quantity the pilot was distracted by discussion about the fuel/air mixture and forgot to open the fuel taps. Although this should have been checked during the pre-flight checklist, the pilot overlooked the main fuel taps as they are usually left on permanently. The aircraft is also fitted with a 10-litre header tank under the pilot's seat, which held sufficient fuel to get the pilot airborne and away from the airfield. Fuel management is a perennial cause of accidents and incidents, particularly in general aviation. Flight Safety Australia has covered the topic regularly, most recently in 2016. CASA's Civil Aviation Advisory Publication 234-1: '<u>Guidelines for aircraft fuel</u> requirements' covers methods for cross-checking fuel on board before flight. And the ATSB has published a selection of harrowing and embarrassing case studies of fuel management related accidents in Avoidable Accidents No. 5—'<u>Starved and exhausted: Fuel management aviation accidents</u>'.



Date	23-Jun-2017	Region NSW			NSWGA	GA SOAR Repo			ort Nbr		S-0999	
Level 1	Operational	Level 2			Airfrar	ne		Level	3	Landing gear/Indic	ation	
A/C Model 1 Piper I					iper PA-25-235/A1			Model	2			
Injury	Nil	Dama	age		Minor	Pha	ise	Landi	ng		PIC Age	65
After con tow plane	After completing a normal landing the tail spring failed at the wheel fixing bolts. The wheel came off and the tow plane came to a halt. The spring was found to have fatigued and was replacd.											



Date	25-Jun-2017	Region GQ SOAR Report Nbr S-0998						0998				
Level 1	Operational		Level 2	Grour	nd Ope	eratio	ns	Level	З	Ground ha	ndling	
A/C Mod	el 1		ASK-2	21		A/C	Model	2				
Injury	Nil	Dama	ge	Minor	Pha	ise	Grour	nd Ops		PIC Age	61	
The towi	ng bar for this air	craft, whi	ch attacl	nes to a mo	otor ve	ehicle	e, is of t	he exte	endab	ole type with	n a self	
locking p	in which maintai	ns the tow	ving bar i	n either th	e colla	apsec	d or the	extend	ded p	osition. The	usual	
practice f	or connection of	this towi	ng bar is	to attach i	t to th	e tail	dolly c	of the a	ircraf	t while it is i	n the	
collapsed	position, release	e the locki	ing pin, e	extend the	towin	g bar	(allowi	ing the	lockiı	ng pin to loc	ate itself	
into the h	into the hole further along the towing bar), connect towing bar to motor vehicle. Any attempt to connect											
the towir	he towing bar to the motor vehicle with the towing bar in the collapsed position would bring the rudder of											
the aircra	the aircraft within very close proximity of the motor vehicle and would be a visual indicator that the towing											
bar shou	d be extended b	efore con	tinuing w	ith the co	nnecti	on to	the m	otor ve	hicle.	In this case	, the aircraft	
and the r	notor vehicle we	re not alig	gned, wh	ich allowe	d the t	owin	g bar to	o be co	nnect	ted to the ve	ehicle	
without t	he usual visual ir	ndicator b	eing app	arent due	to the	angle	e of the	e aircrat	ft rela	tive to the i	notor	
vehicle. A	dditionally, the t	owing ba	r is offse	t to the po	rt side	e of th	ne aircr	aft whi	ch pla	aced the ruc	lder further	
away froi	away from the vehicle when connected at this angle, thereby reducing the indication of there being a closer											
than usua	al proximity of th	e rudder t	to the ve	hicle (with	the to	owing	g bar no	ot exter	nded)	. In transit (taxiing) from	
the flight	line to the hanga	ar there w	as no ind	dication of	any p	roble	m and	no unu	sual r	noises were		
heard. U	pon reaching the	e hangar t	he moto	r vehicle w	as ste	ered	to the l	eft, it v	vas at	this time th	nat a noise	
was hear	d. The vehicle wa	as stopped	d and the	e damage t	o the	aircra	aft rudo	ler was	obse	rved.		

Date	30-Jun-2017 Region NSWGA						AR Repo	ort Nbr		S-1000	
Level 1	Operational		Level 2	Grour	nd Ope	eratio	ons	Level	3	Taxiing collision/near	
										collision	
A/C Mod	el 1		DG-10	00S		A/C	Model	2			
Injury	Nil	Dama	age	Minor	Pha	ase	Grour	nd Ops		PIC Age	
At the er rather th walker to instructo overseas took care the other corner of or hanga remain s to avoid	d of the day the an adhering to th o steer the glider r was walking the school students to keep clear of side, nor did the one of the T har r. At all times wh tuationally awar	glider wa ne establi clear of a e wing clo was walk the club e monito ngars at s en towin e, keep t	as being to ished club any obsta- osest to th king next t hangar b ring instru- low speed g or othe heir mind	owed back practice c cles should ne club har to the othe ut did not uctor or vis d, fortunat rwise man s on the jo	to the of towing l the d ngar we r wing appre- itor al ely ca oeuvri b and	e han ing ba Iriver /hilst g. Driv ciate ert th using a be re	gar usin ack by a not ma a teena ving at the pro- ne drive only m glider o eady to	ng its ri a rope o aintain age me slow sp oximity er. The inimal on the g call "S ⁻	gid to on the suffic mber peed i of the glider dama groun TOP!"	w-out bar c e nose to all ient clearan of a visiting nto the sun e row of T h wingtip str age to either d, all partici sooner rath	on the tail ow the wing ce. An group of , the driver angars on uck the the glider pants must her than later

Date	30-Jun-2017	Regior)	NSWGA		SOA	R Repo	ort Nbr		S-1012		
Level 1	Technical		Level 2 Powerplan				lsion	Level	3	Engine failure or malfunction		
A/C Mod	el 1	H 36 Dimona						2				
Injury	Nil	Dama	age	Nil	Pha	hase Launch				PIC Age	69	
During th	e climb-out and	at about	2000' A	AGL the moto	or com	men	ced to I	run ver	y rou	gh. The com	imand pilot	
immediat and the p	tely operated the propeller feather	e electric ed. A nor	fuel pu mal ciro	mp but there cuit and land	e was ing wa	no im as ma	nprover Ide on t	nent, s he rec	o the iproca	engine was al runway. A	s shut down .fter	



Accident and Incident Summaries

exhaustive examination of the aircraft's fuel and electrical systems, it was determined that the magneto capacitor had completely failed. The magneto, including capacitor, had been checked and passed as serviceable less than ten hours prior the incident.

Date	1-Jul-2017	Region G		GQ	S	SOAR Report Nbr			S-1017				
Level 1	Operational		Level 2	Airc	raft Cont	rol	Level 3	••	Control issues				
A/C Mod	el 1		Twin A	stir	А	/C Model	2						
Injury	Nil	Dama	ge	Nil	Phase	In-Flig	ght		PIC Age	51			
The comr	nand pilot was to	o conduct	: a short f	light to re	position	he aircra	ft follow	ing a	a runway ch	ange, and			
offered t	he front seat to a	low-hou	rs studer	it. After re	leasing fi	om an ur	neventfu	l aer	otow the co	ommand			
pilot han	ilot handed over to the student pilot, who immediately advised that the front rudder pedals were difficult												
to operat	o operate. The command pilot assumed control and safely conducted a circuit and landing. Subsequent												
inspectio	o operate. The command pilot assumed control and safely conducted a circuit and landing. Subsequent nspection of the front rudder pedals revealed the left-hand front pedal the return spring had detached.												
Investiga	tion revealed that	it the Dail	y Inspect	or had not	ticed the	detached	spring	but v	was called a	way to			
attend a	briefing before r	ectifying t	he probl	em. After t	he briefi	ng the ins	spector,	havi	ng forgotte	n the			
detached	detached spring, completed the Daily Inspections and signed out the Maintenance Release. As the inspector												
subseque	subsequently stated: "I was interrupted doing the DI and didn't re-commence the DI from the start. I												
should ho	should have either completed the DI and insisted on a Sterile Environment, or started again from the												
beginning	iouia have either completed the DI and insisted on a Sterile Environment, or started again from the eginning."												

Date	2-Jul-2017	Region NSWGA				SOAR Report Nbr				S-1006		
Level 1	Operational		Level 2 Aircra			ontro		Level	3	Incorrect configuration		
A/C Mod	el 1	ASK-21Mi			A/C Model 2							
Injury	Nil	Damage Nil			Pha	Phase In-Flight				PIC Age	75	
On reach	On reaching to close the throttle for engine shut-down, the PIC inadvertently operated the prop stop handle.											
The rotat	The rotating propeller contacted the prop stop and damaged it.											

Date	8-Jul-2017	Region			SOA	R Repo	ort Nbr		S-1007			
Level 1	Operational		Level 2 Fuel R			ated	ated Level 3			Exhaustion		
A/C Mod	el 1	F	Piper PA	25-235		A/C Model 2		2				
Injury	Nil	Dama	ge	Nil Ph		ise In-Flight		ght		PIC Age	41	

RAAF Field Investigation.

1. INTRODUCTION

A Piper Pawnee was conducting glider towing operations in support of an AAFC gliding activity at Bathurst airfield. Shortly after releasing a glider at the completion of a tow, the Piper Pawnee experienced a significant reduction in power, forcing the aircraft to land immediately, without normal engine power.

2. SEQUENCE OF EVENTS

Refuelling issue

Two days earlier the tow plane was taxied to the refuel point at the end of the day's flying in order to complete a refuel. At the refuel point the pilot was unable to access fuel, as a swipe-card issue prevented fuel delivery. The pilot had not experienced this issue previously and, unable to refuel, stored the aircraft in the hanger without refuelling.

Daily Inspection and Pre-Flight checks

On the morning of the incident flight another pilot was rostered as tow pilot. This pilot carried out the Daily Inspection and Pre-Flight checks. The pilot stated that the aircraft's fuel level would usually be checked whilst in the hangar (level ground), but on this day it was not checked until the aircraft was outside on a ramp (Figure 3). To allow another aircraft to exit the hangar, the pilot had moved the tow plane onto the



Accident and Incident Summaries

ramp outside the hangar prior to checking the fuel level. The angle of the ramp was approximately 3 degrees, with the aircraft positioned 'nose-high'. The pilot checked the fuel level by removing the fuel tank filler cap and determined visually that the tank was full, describing the fuel level as 'just under the filler cap'. Operational runway change

On the day of the incident, the Chief Flying Instructor (CFI) was on duty. Due to a shifting wind direction, the CFI planned to move operations from RWY 35 grass left to RWY 26. Ground-handling gliders to the new operational runway was considered undesirable due to the time taken to complete the process. To expedite the runway change, the CFI planned to launch the remaining gliders from RWY 35 and recover them post-flight to RWY 26. Three launches would be required to achieve the planned runway change. Mid-Operation refuel discussion

The tow pilot had been operating for approximately 90 minutes, at which point the fuel gauge was noted as 'a little bit above' the level at which they would normally refuel. Returning to land, the tow pilot radioed to the Operations Base the intention to refuel after one more glider launch. The CFI, an experienced tow pilot, overheard the radio call regarding the tow pilot's intention to refuel. The CFI was curious as to why the aircraft had not been able to operate for longer (The normal duration between refuels was 120 mins, rather than the elapsed time of approximately 90 mins). Over the radio the CFI stated they had three more launches before the change to RWY 26, then asked the tow pilot 'how do you feel about doing three more launches?' The tow pilot responded: 'not too sure about my fuel state'. After landing the CFI and Tow Pilot conferred at the aircraft, during which time the tow pilot remained strapped-in at the controls. The CFI confirmed with the tow pilot that the aircraft had started the day with a full fuel tank. The CFI opened the fuel tank filler cap and visually assessed fuel quantity, informing the tow pilot that the fuel level was approximately 30 – 40 millimetres (mm) below the filler cap. Based on the elapsed operating time and the visually assessed fuel quantity, the tow pilot and the CFI agreed that three more glider launches could be achieved. They planned to conduct the refuel after the third launch when ground personnel were relocating to the new operational runway. The CFI then transferred the Duty Instructor role to another Instructor in order to leave the airfield to conduct a noise assessment.

Engine loss of power and recovery.

The tow pilot conducted the three glider launches as planned. After releasing the third glider at the top of the third launch, the tow pilot closed the cowl flap, lowered the aircraft nose to commence the descent, and began to retard the throttle. The tow pilot felt the aircraft shudder and engine power reduced rapidly to idle. The tow pilot responded by selecting carburettor heat to full, cycling the fuel mixture control and throttle. However, these actions did not result in the recovery of engine power. The tow pilot continued the glider separation turn to track direct to the airfield, while assessing the arc under the wingspan for potential landing fields; the departure airfield fell within the arc. The tow pilot configured the aircraft at best glide speed and continued with the forced landing checklist, initially tracking for downwind RWY 35. A PAN was declared with the intention to land on RWY 35 grass left. Assessing the descent rate, the tow pilot realised that the aircraft was undershooting RWY 35, and changed intentions to track for a straight-in approach and landing on RWY 17 grass right. The engine was secured by isolating the magnetos and shutting off fuel. Recognising the aircraft was undershooting RWY 17 grass right, the tow pilot then moved the approach path east over main RWY 17, in order to make use of the longer undershoot area.

During the final stages of the approach, the tow pilot attempted to extend the glide by raising the aircraft's nose, to clear a drainage ditch running parallel with the main runway. The pilot successfully cleared the drainage ditch but airspeed had decayed, resulting in a hard landing and impact with a frangible runway gable marker. The gable marker was destroyed, and the aircraft's wing narrowly missed an airfield bird-scaring gas gun. It is likely that the aircraft missed the gas gun as a result of the aircraft bouncing due to the hard landing. The ground roll was short and the aircraft came to rest at the intersection of RWY 17/35 and RWY 08/26.



Accident and Incident Summaries



Missed drainage ditch and aircraft wheel marks

Post Incident Actions. The tow pilot was not injured during the hard landing. The Pilot exited the aircraft and was able to move it off the runway. The CFI and Duty Instructor attended the scene and directed that the aircraft was to be quarantined. The CFI opened up the filler cap and visually inspected the fuel tank – it appeared to be empty. The CFI contacted the Licenced Aircraft Maintenance Engineer (LAME), who was not located in the area at the time. The CFI and the LAME discussed the incident, detailing the troubleshooting required to identify the cause of the incident. This included filling the aircraft to check for leaks and inspection of the refuelling paperwork. Using a jerry-can, the CFI put a small quantity of fuel into the aircraft. The aircraft started immediately and was then taxied to the refuel point where the aircraft accepted 151.5 Litres of fuel



Accident and Incident Summaries

(including the fuel from the jerry-can). The CFI and LAME discussed the hard landing. The LAME advised an inspection of the undercarriage bungy cords for signs of damage or disturbance; no damage was found. The CFI scrutinised the refuelling paperwork and found evidence that the fuel tank had not been full at the start of the day. Based upon this information, the LAME assessed there was no requirement for maintenance. The LAME reasoned that the fuel system on the Pawnee (not fuel-injected) was not susceptible to air-locks, and therefore did not require bleeding. The LAME advised that the quarantine and flight restrictions could be lifted following successful engine runs.

Engine runs and next flight.

The following day, prolonged engine ground runs were successfully conducted. The aircraft was then operated without incident. As a precaution, the aircraft was refuelled at shorter operating intervals to assess and monitor the fuel burn rate.

3. DAMAGE TO AIRCRAFT

The right main undercarriage tyre suffered minor scuff marks as a result of the impact with the runway gable marker. The CFI assessed the damage as superficial only. No rectifications were required or performed.

4. METEOROLOGICAL INFORMATION

At the time of the incident the weather was reported as 'cloud and visibility okay' (CAVOK). Wind and sun position were assessed as not contributing to the incident.

5. SIMILAR OCCURRENCES

The Gliding Federation of Australia's (GFA's) database was queried to determine whether similar occurrences had occurred in the past. The GFA database for fuel-related occurrences returned 11 reports, with the oldest dated 19 November 2011. Figure 9 illustrated the breakdown of occurrences between fuel exhaustion, starvation and maintenance/materiel causes.



GFA database occurrences for fuel exhaustion/starvation

Of the 11 reports, seven were found to be dissimilar (i.e. fuel starvation, fuel system maintenance or material issues). Four were found to be similar (i.e. fuel exhaustion). The dataset suggests that on average there is a fuel exhaustion occurrence approximately every 20 months. Of the similar reports, three were very similar:

• 19 Nov 11, PA-25-235 Piper Pawnee. The aircraft ran out of fuel during a glider launch. The pilot safely executed an off-field landing. The pilot reported misreading the fuel tank quantity when checking the tanks before flight.



Accident and Incident Summaries

- 18 May 14, PA-25 Piper Pawnee. The aircraft ran out of fuel during a glider launch. The pilot did not notice a low fuel light. The pilot was forced to land, and a heavy off-field landing with significant aircraft damage resulted.
- 23 May 15, Cessna 150E. The aircraft momentarily lost power due to near- fuel-exhaustion. The pilot was able to land safely under power.

6. ANALYSIS

Applicable Fuel-related Regulation, Policy and Procedures

Gliding operations (including aerotowing in support of gliding operations) are by definition a private operation under CAR 1988. Civil Aviation Regulations 1988 (CAR) 209 (1) states that '[t]he operator and the pilot in command of an aircraft engaged in private operations shall comply with the provisions of these Regulations and such additional conditions as CASA from time to time directs in the interest of safety'. Regulation 234 requires the pilot-in-command of an aircraft to take reasonable steps to ensure that the aircraft carries sufficient quantities of fuel and oil for the proposed flight to be undertaken safely. The regulation also requires the operator of an aircraft to take reasonable steps to ensure that an aircraft does not begin a flight unless it is carrying sufficient fuel and oil to allow the flight to be conducted safely. The GFA Aerotow Manual, which is a CASA approved, recommends a fixed fuel reserve of **at least 30 minutes** is appropriate for normal aerotow operations (not involving cross-country transit). It is a condition of the tow pilot's Glider Towing Certificate that they comply with the GFA Aerotowing Manual. The GFA Aerotowing Manual has this to say:

"Tow pilots should start the day's towing with full tanks, keep a record of the number of tows and time flown, and refuel early rather than late. GFA recommends pilots carry no less than 30 minutes reserve fuel. On aircraft which have recording tachometers, or an engine hour meter connected to an air pressure sensor and switch, keeping track of tacho or meter time is a useful aid to fuel management. Fuel exhaustion incidents are most likely after a change in pilot, where the relief pilot has taken over an almost empty aircraft. In aircraft such as the Piper Pawnee it is difficult to determine the remaining fuel level by visually inspecting the fuel tank. Therefore, it is good airmanship to check the fuel state by reference to at least two separate methods of fuel management upon changing pilots."

The AAFC's policy for 'Fixed Fuel Reserves' is 45 minutes. It is also practice of AAFC clubs to completely fill the tow plane in the evening and during the day as required. AAFC guidance on this subject states: "A good method to monitor the fuel state is to use a combination of the following 3 methods. Items a & b should be rigidly observed, while some latitude is allowed with item c.

a) Watch fuel contents gauge (it is red lined – under no circumstances should the tug launch with a reading below the red line).

b) Record Tacho Time at each refuel and limit time to a maximum of 2 Tacho hours.

c) Usually in the region of 15 x 2000ft tows can be carried out on a full tank of fuel.

Do not be bullied into a launch if you are concerned about the fuel status. This usually happens about the last flight of the day when the tanks are low. Remember that there never has and never will be a suitable reason for fuel exhaustion. It is entirely your responsibility."

Piper Pawnee Pa-25-235 Fuel System

The Piper Pawnee PA-25-235 involved in this incident has a simple fuel system which transfers fuel using gravity from a single tank to a carburetted engine. Aspects of the fuel system, relevant to the incident are as follows:

a) **Pump and feed.** To start the engine, an engine primer pump moves fuel from the fuel strainer to the engine's cylinders. During normal operation, fuel flows under gravity through the strainer and into the carburettor.

b) **Tank**. The aircraft is fitted with a single fuel tank, aft of the engine and forward of the hopper. The tank can accept 159 L of fuel, of which 148 L is useable. The tank geometry is such that the tank is wider at its top than at its bottom.

c) *Gauge*. Fuel quantity can be determined by a float gauge. The float moves up and down depending on the fuel level, which in turn moves an indicator in the sight glass. The effect of the fuel tank geometry is that the rate of movement of the float gauge is slowest for a full tank and becomes progressively faster as the tank



Accident and Incident Summaries

empties. The gauge's sight glass is located on top of the fuel tank, within the pilot's line of sight from the cockpit. The sight glass on the incident aircraft was marked with a red line.



Fuel tank quantity gauge, seen from (L) cockpit and (R) side

Methods for determining fuel quantity

The extant methods for determining fuel quantity are:

a) visual inspection via the fuel filler cap;

b) fuel gauge; and

c) fuel burn rate.

Visual inspection via the fuel filler cap.

Direct visual inspection of the fuel level is possible by looking through the filler port (after removal of the filler cap). However, the accuracy of this method is problematic for the following reasons:

1. *Tank geometry.* The shape of the fuel tank means that the relationship between fuel level and fuel quantity is not constant. For the upper-portion of the tank, a small change in fuel level means a relatively large difference in fuel quantity. The tank is normally concealed from view by the aircraft fuselage. Figure 13 is a simplified representation of the fuel tank, compared to a regular geometry.



For the first 50 mm of the tank, the cross-sectional area is approximately constant. The Figure demonstrates the effect on available aircraft operating time for every 10 mm of error when measuring the fuel level.



Accident and Incident Summaries





Accident and Incident Summaries

c) the gauge sits on the fuel tank, external to the cockpit. Pilots must determine the position of the indicator within the gauge by viewing it through the windshield at a distance; and

d) the gauge has a prominent red line marked on it, but the meaning is not defined. The following was found:

- 1. The red line was applied locally by the LAME;
- 2. It was commonly understood that the red line indicated the fixed fuel reserve. However, there was no formal process for defining the meaning of the red line.
- 3. A red line on the gauge indicating fixed fuel reserve must be set based on an assumed average fuel burn rate. It was unclear how this assumed average had been decided and by whom.For the reasons described the gauge has limited accuracy. Its capability is limited to a rough indication of fuel quantity only. Typically, pilots are able to use the gauge to tell whether they are above, approaching or underneath the red line.

5. Fuel burn rate. Due to the limitations of the fuel gauge, operators of the Piper Pawnee determine their approximate fuel remaining, indirectly through measurement of operating time - using the Tachometer Clock ("tacho time"). The Tachometer Clock measures the duration of engine operation. When the initial fuel state (i.e. full) is known, the pilot can apply an estimate of fuel burn rate, and thus determine the time when re-fuel is required (i.e. when the non-reserve fuel has been consumed). Tow pilots at the Club generally used a tacho time of 2 hours (hrs) as the maximum operating time. This was based on a fuel burn rate approximation of 50 L/hr. Analysis of 30 days of glider-tug operations determined that the average, actual fuel burn rate for the incident tow plane was 47 L/hr. Therefore, the fuel burn rate used by the Club is appropriate for this tow plane's operating from the home airfield. Useable fuel capacity on the subject tow plane is 148 L - therefore after 120 mins operation, roughly 48 L remains. This remaining fuel gives approximately 57 mins of operating time, which comfortably accounts for 45 mins of fuel reserve. Effective fuel planning and fuel management rely on the accuracy of the predicted fuel consumption rate. The accuracy of the fuel consumption data used for the planning and decision making depends on the source of that data. During the interviews a number of figures were mentioned, however there was no common source quoted. Further, there was no promulgated fuel burn rate for the subject tow plane. Retro-fit devices are available to assist with fuel management (fuel flow meters, low fuel lights, etc.). The availability of such devices during the incident may have alerted the pilot to the low fuel state before the fuel ran-out.

7. HUMAN FACTORS

Pre-flight fuel quantity check

The tow pilot carried out a pre-flight fuel quantity check before the incident flight. However, this check was ineffective due to a combination of expectancy bias, knowledge based deficiencies and a decision error; outlined as follows:

a) *Expectancy bias.* It is standard GFA and Club practice to refuel tug aircraft at the completion of the day's flying. The tow pilot and others have come to expect the aircraft to be full when checked pre-flight. An expectancy bias is induced, whereby the tow pilot expected to see a full tank of fuel, via a visual assessment, during the aircraft pre-flight. Additionally, the tow pilot had no metrics or measurement devices available that would help define whether the tank was full or not, further compounding this bias.

b) *Knowledge based deficiencies.* The tow pilot was unaware of the fuel tank geometry and hence did not realise that a small fuel level discrepancy at the top of the tank meant a significant amount of missing fuel. During the conduct of the investigation, it was assessed that a number of current tow pilots were deficient in a working knowledge and understanding of the Piper Pawnee's fuel system design and operation. The tow pilot stated that, had the geometric shape of the fuel tank been known, it is likely that would have strengthened the decision to refuel at the time. It is considered good airmanship for an Aircraft Captain to have proficient knowledge of the aircraft systems. This knowledge is gained from ground school notes, system briefs, and hands on maintenance of the aircraft types flown. The training should be provided during aircraft type endorsement by appropriately trained persons. Systems knowledge allows pilots to diagnose problems and make informed decisions during operations and in emergency situations. Aircraft systems knowledge should be covered and assessed by the authorised tow pilot delegate.



Accident and Incident Summaries

c) **Decision error.** The tow pilot, lacking effective systems knowledge, combined with an interrupted preflight habit pattern, knowingly conducted the fuel check on sloping ground. This resulted in the fuel angling towards the fuel filler cap, giving the perception that it contained more fuel than it actually did. Re-creation of the scenario showed that the fuel tank angle of the incident aircraft changed by approximately 3 degrees (nose high) when compared to level ground. This could have raised the perceived fuel level by approximately 30 mm. The tow pilot did not understand the geometric shape of the fuel tank and the corresponding effect of sloping ground on the fuel level in the tank. Performing the fuel check on sloping ground was a result of a decision error stemming from knowledge based deficiencies. The knowledge based deficiencies were likely masked by engrained pre-flight habit patterns formed during training. The tow pilot, by moving the aircraft to the sloping ramp during the pre- flight checks, effectively broke a well engrained habit pattern which leads to the decision error of checking fuel on sloping ground.

Refuel Decision-Making process

The tow pilot had the intention to refuel, triggered by a fuel level indication approaching the red line on the fuel gauge. The intention was radioed through to glider operations; however, a combination of confirmation bias and experience/authority gradient resulted in a deferred decision and Pilot 2 continued flying without refuelling.

Confirmation bias. Confirmation bias involves favouring information that confirms previously held or existing beliefs. Confirmation bias can impact how people gather information and influence how they interpret information and make decisions. Starting with a based-lined full tank, towing operations would usually operate for two hours tacho time or until the red line was reached, at which point a refuel would take place. The basis of the Decision-Making process that occurred on the ground, between the CFI and tow pilot, assumed that the aircraft had a full fuel tank at the start of flying that day. This assumption of a full fuel tank was established by the CFI at the aircraft. Once the initial fuel state was established the following confirmations were sought to support the decision to continue for three more launches:

a) an observation of the fuel gauge on the ground

b) a visual inspection of the fuel tank contents, and

c) confirmation of tacho time flown.

Three methods existed for determining fuel quantity though no clear guidance exists for a case where the refuel line is reached prior to two hours tacho. During this incident a fuel gauge approaching the refuel line was likely dismissed because a visual inspection of the fuel tank on the ground and tachometer clock suggested there was sufficient fuel on the aircraft. A more appropriate course of action would be to refuel whenever any of the methods indicated a refuel was required.

Authority gradient. Authority Gradient refers to the established, and/or perceived, command and decisionmaking power hierarchy in a Team, Crew or Group situation, and also how balanced the distribution of this power is experienced within the Team, Crew or Group. Concentration of power in one person leads to a steep gradient, while more democratic and inclusive involvement of others results in a shallow gradient. Through interviews, it was established that the interaction between the CFI and tow pilot was professional and intended to be 'pilot to pilot' in nature. This intention aside, a subtle underlying authority/experience gradient was still likely present in the sub-conscience of the tow pilot. The CFI, a very experienced tow pilot, acting as Duty Instructor at the time did not make the decision for the tow pilot, though it is highly likely the tow pilot's decision-making process was influenced by the abovementioned confirmation bias and a perception of the CFI having greater knowledge due to the authority/experience gradient. Fuel indication post decision to continue

The tow pilot likely noticed the decreasing fuel gauge indication and disregarded its meaning in order to execute the planned course of action and the distrust of general aviation fuel gauges. The fuel gauge is situated along the line of sight of the pilot looking out the windscreen while flying. Based on the fuel tank design, the fuel level indication during the final launches would have been reducing at a high rate. The tow pilot likely disbelieved, discarded, or downgraded the significance of the fuel indication below the red line, as it appeared to conflict with the expectations of the decided course of action. Additionally, the tendency to disbelieve, discard or downgrade the fuel indications were likely strengthened by the tow pilot's significant



Accident and Incident Summaries

distrust of General Aviation fuel gauges, which was cemented during the conduct of his Private Pilot's Licence (PPL) training.

Pilot recovery actions.

The tow pilot safely recovered the aircraft to the airfield. Troubleshooting actions were attempted; however, these actions proved unsuccessful and were discontinued at an appropriate time and altitude, to focus on the imminent forced landing. Tracking for the take-off runway (RWY 35 Grass left) was initiated, however the tow pilot, using good judgement assessed a significant undershoot and amended the tracking for RWY 17 Grass right. Further adjustments were made as the tow plane's glide performance became evident. The forced landing checks were appropriately conducted, and a PAN was declared, which appropriately informed other airfield users. The situation warranted an upgrade to a MAY DAY. However, the workload on the approach was high and the tow Pilot effectively prioritised flying over communication. The tow pilot is to be commended for his recovery actions.

8. ACTION ALREADY TAKEN

The AAFC implemented the following Aviation Safety Alerts:

a) Pilots will check fuel level, on a level surface, before commencing flying operations. If the fuel level is not within 1 cm of the fuel filler neck the aircraft shall be refuelled before commencing operations.
b) If the pilot has any doubt as to the quantity of fuel in the aircraft and/or remaining time available before fuel is required, the aircraft is to be refuelled immediately in order to positively establish a fuel baseline.
c) When the aircraft is refuelled, the pilot shall note the tacho time, as of the time of refuelling, on the laminated card attached to the instrument panel. This shall be updated before the aircraft is moved from the

bowser to ensure that the number is accurate and not forgotten.

d) The pilot shall take care to accurately and promptly update the fuel log; and

e) Pilots of the Piper Pawnee shall not exceed 90 minutes Tacho time before conducting a full refuel.

9. CONCLUSION

The investigation identified the following organisational influences which aided the establishment of preconditions for this incident:

a) inconsistent regulation covering fuel measurement, fuel reserves and refuel procedures

b) informal fuel policies

c) ineffective communication, and

d) aircraft system knowledge deficiencies.

During the conduct of the Daily Inspection and Pre-Flight checks, knowledge deficiencies and expectation bias established the pre-conditions for the decision error of checking the fuel on sloping ground. This then led to an incorrect assessment of a full fuel tank at start of flying that day. Once this assessment was made there were no effective controls in place to prevent the sequence from continuing through to fuel exhaustion. The incident pilot recognised a recovery point to refuel, however once challenged, this recovery point was eroded through confirmation bias based upon the initial assessment of a full fuel tank at the start of flying. The decision to continue without refuelling was effectively deferred to experience based on a perceived experience/authority gradient. Once the decision was made the incident pilot then executed the course of action with effective task focus, likely discarding evidence of a reducing fuel gauge due to it not fitting the planned course of action. At the point of fuel exhaustion, a safe and effective forced landing to the departure airfield was conducted. The incident pilot is to be commended for his recovery actions and prioritisation whilst executing the forced landing. Whilst the above does not relinquish the responsibility of a pilot in command to conduct a thorough pre-flight recommendations made herein, when implemented, will reduce the likelihood of a similar occurrence. Since the incident a number of short term task specific actions have been implemented to allow for continued operations until full rectification of the identified deficiencies takes place.

Date	9-Jul-2017	Region		VSA	SOAR Repo	ort Nbr		S-1003
Level 1	Operational		Level 2	Runway E	vents	Level	3	Runway excursion
A/C Mod	el 1		Twin /	Astir	A/C Mode	2		



Accident and Incident Summaries

InjuryNilDamageNilPhaseLandingPIC Age62Following landing the command pilot taxied the aircraft off the runway towards the hangar and a group of
people. The pilot was counselled about the hazards of such a manoeuvre.62

Date	10-Jul-2017	Region		NSWGA		SOAR Report Nbr		S-1024				
Level 1	Operational		Leve	12	Com	munic	atior	IS	Level	3	Other Com	nmunications
											Issues	
A/C Mod	el 1		DG	6-100	00S		A/C	Model	2	N/A		
Injury	Nil	Dama	age		Nil	Pha	ise	In-Flig	ght		PIC Age	65
During a	period of extend	ed radio	transr	nissi	ions, the ir	nstruc	tor tı	urned t	he volu	ime d	own on the	radio in
order to	order to clearly communicate with the student but failed to readjust the volume control afterwards. The											
comman	command pilot later flew the circuit making standard radio transmissions but was effectively transmitting											
blind. For	rtunately there w	/as no tra	affic or	r bre	eakdown ir	n sepa	ratio	n and t	he glid	er lan	ded withou	t incident.
With glid	ers, where head	sets and	interco	om s	systems ar	e usua	ally al	bsent, i	radio cl	natter	[.] can be a di	straction.
Notwiths	Notwithstanding, the radio is an important tool for situational awareness and collision avoidance, and must											
be used p	be used properly to be effective. To this end the volume and squelch should always be adjusted to provide											
the best	reception and he	aring qu	ality. Iı	nstr	uctors sho	uld av	oid t	urning	down t	he vo	lume unless	absolutely
necessary	y for flight safety											

Date	12-Jul-2017	Regior	า	SAGA		SOAR Report Nbr				S-1008		
Level 1	Airspace		Level	2 Aircra	aft Sep	arati	on	Level	3	Near collis	ion	
A/C Mod	el 1		DG-	-1000S		A/C	Model	2	Jabi	ru		
Injury	Injury Nil Damage Nil Phase In-Flight PIC Age 67											
During a	During a check flight (Annual Flight Review) the pilot under check flew into the downwind leg to join circuit.											
The glide	r's flight path wa	s head-o	n to a .	Jabiru aircraf	t estak	olishe	d on th	ie dowi	nwinc	l leg. Althou	gh a collision	
was avoid	ded the glider pil	ots were	counse	elled. When f	lying a	at und	control	led airp	orts,	pilots rely o	n each other	
to help avoid midair collisions by following the recommended procedures and communicating intentions on												
the comr	non traffic advise	ory frequ	ency (C	CTAF). The ris	ks of f	lying	against	the cir	cuit t	raffic are ob	ovious.	

Date	15-Jul-2017	7 Region VSA SOAR Report Nbr						S-:	1009		
Level 1	Airspace		Level 2	Aircra	ift Sep	arati	on	Level	3	Near collis	ion
A/C Mod	el 1		Twin	Astir		A/C	Model	2	Unk	nown	
Injury	Nil	Dama	age	Nil	Pha	ase	Landi	ng		PIC Age	19
During th area with manoeuw powered nearby ce horizon a collision a heading. that the c vineyards had the b certified a	e course of an a the view to con ring to join circu aircraft flying ov ertified aerodror nd climbing stra and simultaneou The aircraft pas overcast conditions, scrubby terrair pase radio alert r aerodrome saw	nnual flig ducting a lit, a radio verhead t ne. The p ight towa isly made sed withi ons made not been i the aircra depart di	ht revie frunnin call wa he airfie ilot und ards the a radio n 200 m sighting gs and si made. Ti ft depai rectly ov	w the instru g out of heig s heard fror ld at about er check spo glider. The p broadcast to etres lateral aircraft bel wamps", and he powered t the runwa er the nearl	ctor m ght' ex n the s 700ft a bilot u bilot u o alert lly at t ow th d that aircra by glic by glic	hanoe xercis glidin AGL, a low- nder the p the sa e hor the p aft wa ontra	euvred euvred g opera climbin -wing p check r powere in hei izon dif powere is not ic ventior vinch si	the glic ne pilot ations t g out fi owered manoeu d aircra ght. Th fficult, o d aircra dentifie n to put te.	ler to unde pase a rom t d aircr uvred aft to e pilo espec aft ma d but plishe	wards the ci er check was lerting the p he direction raft just belo the glider to maintain its of under che ially against y not have b witnesses a d procedure	pilots to a of the ow the o avoid a ck reported <i>"a variety of</i> been sighted at the nearby es designed



Date	15-Jul-2017	Region NSWGA				SOAR Report Nbr				S-1013		
Level 1	Operational		Level 2	Mis	cellar	eous		Level 3		Other Miscellaneous		
A/C Mod	el 1	SZ	ZD-50-3	'Puchacz"		A/C	Model	2	Paw	nee		
Injury	njury Nil Damage Nil Phase Launch PIC Age 55									55		
The tow	he tow pilot was given the 'all-out' signal before the slack was fully out of the rope. The rope had											
momenta	momentarily become caught on a tussock of grass, which caused the glider to be catapulted forward and											
overrun t	he rope. The rop	e again d	came un	der tension	as the	tug	acceler	ated ar	id the	glider was	again	
catapulte	catapulted forward. At this point the glider pilot released. While this incident was consequent of an											
erroneou	erroneous signal by forward signaller, a slower application of power by the tow pilot may have pulled the											
rope clea	r of the tussock o	of grass.										

Date	15-Jul-2017	Regior	egion VSA			SOAR Report Nbr				S-1014	
Level 1	Airspace		Level 2 Aircraft S			arati	on	Level	3	Aircraft Separation	
										Issues	
A/C Mod	el 1	Duo Discus A/C Model 2									
Injury	Nil	Dama	Damage Nil Phase In-Fl					ght		PIC Age	64
The glide	r was observed o	on the ac	tive sid	le of the circ	uit con	ducti	ng som	e therr	nallin	g turns and	travelling
upwind a	upwind against the circuit pattern at a height below 1500' AGL. The aerodrome is a busy site and the										
conduct	of the flight was	contrary	to Club	o rules. The p	ilot wa	as cou	unselled	d.			

Date	16-Jul-2017	Regior	n l	GQ		SOA	AR Repo	rt Nbr		S-1019		
Level 1	Operational		Level	2 Airc	raft C	ontrol Leve			3	Wheels up landing		
A/C Mod	el 1		Disc	us CS		A/C	Model	2				
Injury	Nil	Dama	age	Minor	Pha	ase	Landi	ng		PIC Age	54	
The pilot had returned to the airfield after a 3-hour local soaring flight in hot and blustery conditions. The										ions. The		
pilot's CF	pilot's CFI commented that "the flying (because of turbulence and unrelenting sun) was tiring (though with											
some spectacular streeted thermals in the blue)". The pilot arrived over the airfield at 2,000ft AGL in order to												
properly assess the wind direction by reference to the windsock. The wind speed at that height was 23									was 23			
knots. After joining downwind, the pilot commenced the pre-landing checks but, due to concentrating on									rating on			
speed an	speed and trim in the blustery conditions, forgot to lower the undercarriage. The pilot noted: "I didn't											
verbalise	the FUST as I no	rmally do	o. My wo	orkload was	high c	is the	downv	vind le <u>e</u>	g was	fast and I n	eglected to	
lock the u	undercarriage do	wn, and j	followin	g base and f	final la	inded	wheel	up. The	e high	wind speed	l on the	
ground n	nade the landing	quite sho	ort and	nitigated fui	rther d	lama	ge to tl	he unde	erbelly	<i>y."</i> The pilot	's CFI noted	
"The con	ditions were cert	ainly liab	le to inv	vite heat exh	austic	n/de	hydrati	on and	the k	ind of fatigu	ie that	
allows ch	ecklist items to f	all throu	gh the c	racks. I can i	magir	ie hoi	w (the p	oilot's)	atter	ntion would	have been	
drawn in	to the immediate	e challen <u>e</u>	ge of the	e circuit: mai	naging	g spee	ed and	space i	n turk	oulent high-	wind	
condition	s. And that after	a long fl	ight in t	he bumpy, h	ot blu	e. I de	o know	(the pi	lot) h	nad drinking	water with	
him, as I	saw him put it in	the glide	er." Land	ling mishaps	comr	nonly	occur/	when p	oilots	become ove	erloaded	
close to t	he ground. Work	cload ma	nageme	nt can be ea	ised b	y pro	per flig	ht man	agem	ent which i	ncludes	
attending	close to the ground. Workload management can be eased by proper flight management which includes attending to pre-landing tasks (like lowering the undercarriage) early rather than later in the circuit. Refer											
also OSB	01/14 'Circuit an	d Landin	g Advice	<u>e'</u> .								

Date	21-Jul-2017	Regior	Region		SAGA S			SOAR Report Nbr			S-1025		
Level 1	Airspace		Level 2		2 Aircraft Sepa			Level 3		Aircraft Separation			
									Issues				
A/C Model 1		DG-1000S			A/C Mode		I 2 Jab		ru J170-C				
Injury	Nil	Dam	age	Nil	Pha	ase Launo		aunch		PIC Age	55		



Accident and Incident Summaries

The pilot of a powered aircraft conducted a low overflight of a glider, which was positioned behind the displaced threshold awaiting a launch, to land on the bitumen glider strip directly ahead rather than on the main gravel runway alongside. The crew of the glider estimated the powered aircraft overflew at a height of less than 30 feet. Aerodrome operating procedures require that powered aircraft pilots must use the main gravel runway for landing when gliding operations are in progress and not to overfly the gliding operation. Investigation revealed the powered aircraft was being flown on a training flight. The student overshot the turn onto final and lined up on the glider strip. The instructor, although aware of the requirement to land alongside the glider runway neglected to correct the student and allowed the approach to continue. While a good instructor recognises that a student must have opportunities to make and correct errors, when close to the ground there is less opportunity for correction and instructors must take control to ensure the safety of the flight. In this case the instructor should have recognised the danger of approaching low over aircraft and people, and taken control to realign the aircraft clear of obstacles. The incident was raised with the instructor and their CFI, and the need to set appropriate safety limits and comply with the aerodrome operating procedures was reinforced.

Date	26-Jul-2017	6-Jul-2017 Region		NSWGA		SOAR Report Nbr				S-1010		
Level 1	Airspace	Airspace L			ft Sep	paration Level			3 Near collision		ion	
A/C Model 1			JS1 B				A/C Model 2 Unk			nown		
Injury	ijury Nil Damage			Nil	Pha	ase In-Flig		ght		PIC Age	76	
A glider w airfield w avail. The way. The	vas returning to l vithin 500 feet. Th e aircraft, a blue a aircraft was sigh	and whe ne duty in and white ted by th	n an un hstructo e colour he glider	identified po or made two red low wing r pilot.	attem monc	d airc ipts t iplan	craft fle o conta e with	w betw act the a retracta	veen t aircra able g	the glider an ft on the CT gear, continu	nd the TAF to no ued on its	

Date	29-Jul-2017	Region		GQ	SOAR Report Nbr				S-1011		
Level 1	Operational		Level 2		Terrain Colli		lisions		3	Controlled flight into terrain	
A/C Mod	el 1	N	MDM-1P "FOX-P"			A/C Model 2					
Injury	Minor	Dama	age Substantial		Pha	ise	Landi	ng		PIC Age	60

1. FACTUAL INFORMATION (GFA Field Investigation)

1.1 History of flight

On 29 July 2017, the pilot flew the glider from Boonah, Qld on tow to Lismore airfield, NSW (YLIS) behind a Piper PA-25-235 Pawnee. The pilot arrived on tow over YLIS at 5,500 feet in order to have time and space to merge with other traffic. He landed at Lismore at 10:30 am (all times are local) on 29 July 2017, the day of the Lismore Aviation Expo. Air displays that day had been approved by CASA, to be conducted by Paul Bennet Airshows (the approved organisation). The glider pilot and tow pilot attended a private briefing session by the organiser's delegate at the Lismore Aeroclub, consistent with the Lismore Display Instructions from the organiser. The glider pilot and the tow pilot then both signed the participant signature sheet as per the conditions for the air display approval that day. The scheduled time for the glider display was 2:40 pm. At approximately 3 pm, the glider was towed to 3,500 ft. AGL by the Piper Pawnee and released over the display area (see section 1.10 Aerodrome information). Weather at the time was CAVOK with light winds. Altitude was used up as the glider performed its planned aerobatic manoeuvres inside the designated display box. At approximately 100ft AGL, a wing-over was initiated which brought the glider onto an ESE track inside the display zone. As planned, the pilot then initiated the final manoeuvre, a four-point roll. After this roll, another wingover was planned, followed by a landing on runway 33. The four-point roll was initiated at approximately 50ft AGL. Halfway through the manoeuvre, the glider appeared to be running out of energy, according to witnesses. While inverted, the pilot lowered the nose somewhat to increase airspeed, then pushed away from the horizon and levelled the wings to the upright position. The glider then impacted the ground near the runway, but outside the gable markers (see figure 1).



Accident and Incident Summaries



Figure 1: Impact point and glider resting position

According to witnesses, the wingtips both briefly contacted the ground on initial impact. The undercarriage separated from the glider, and the impact left an indentation of approximately 30-40cm in the soft grass. The glider slid to a stop and came to rest about 100m beyond the point of first ground contact. Given that it was outside the gable markers and not on the runway, the pilot remained in the aircraft until help arrived. No evacuation was needed. The pilot was assessed by local first responders, removed from the glider and taken to Lismore hospital, and later to the Gold Coast University hospital.

1.2. Injuries to persons

The pilot suffered a fractured T12 vertebra (The T12 vertebra is located in the last position of the thoracic section of the spine, and sits just above the lumbar section) as well as some minor lacerations. No other injuries. No long-term consequences of injury sustained.

1.3. Damage to aircraft

- Undercarriage and wheel fairing separated from airframe on first impact.
- Several tears and fractures of the seat pan and other inside cockpit side-wall structures.
- Skid marks along fuselage aft of the wheel well.
- No skid marks under the nose or forward of the wheel well.

1.4. Other damage

Nil

1.5. Personnel information

- Pilot total flying hours: 7000+
- Hours on type: 170+
- Licences held: Private Pilot Licence, Glider Pilot Certificate
- Valid Medical
- CASA Low level aerobatics endorsement held.
- The pilot has considerable aerobatic and display experience, both in powered aircraft and gliders.

1.6. Aircraft information

- Manufacturer: MDM Marganski & Myslowski
- Type: Fox-P



Accident and Incident Summaries

- Country of manufacture: Poland
- Year of manufacture: 2001
- Engines: None
- Total airframe hours: 180
- Certificate of Airworthiness: Yes, perpetual
- Maintenance Release Yes, until end 2017
- Max allowable take-off mass: 535kg
- Max allowable landing mass: 535kg
- Stall speed (all-up mass) : 45 knots
- Stall speed (one pilot onboard): about 40 knots.

1.7. Meteorological information

CAVOK, light to zero wind.

Time	Wind dir	Wind spd km/h	Wind gust km/h	Tmp. °C	Dew pt °C	Feels like °C	rh %	Fire	Rain mm	Rain 10' mm	Pres hPa
Sat 15:30 EST	-	0	4	22.3	4.4	22.3	31	9	0	0	1019
Sat 15:23 EST	NNW	2	5	22.4	1.4	22.4	25	12	0	0	1019
Sat 15:20 EST	-	0	0	22.2	2.3	22.2	27	10	0	2	1019

Table 1. Data from Lismore Airport AWS.

1.8. Aids to navigation

Not applicable

1.9. Communication

A dedicated display frequency was in use, in addition to the normal airfield CTAF for YLIS.

1.10 Aerodrome information

The runway at YLIS is sealed and oriented 15/33 and 1647m long (see figure 2). The air display line was offset from the runway by 65 degree (see figure 3). Displays were to be orientated south of an imaginary display axis line between the 1000ft RWY marker on RWY 15 and the NW corner of the large shed located on the eastern side of the field. Displays were to be conducted with all turns to the south (away from the spectators). Top side passes were permitted as long as the aircraft was not projected to be inside 200m from the spectator line (see figure 3).



Accident and Incident Summaries



Figure 3: YLIS display zone for the Aviation Expo

1.11 Flight Recorders

The glider was not equipped with FLARM or another data logger device (Typically, these devices only record position and altitude at pre-selectable intervals down to one second.) at the time of the incident. Hence it was not possible to download a trace of the flight to aid the investigation. However, limitations on the resolution of the FLARM or logger data is likely to be too coarse to derive useful datapoints (e.g. descent rate) in the last second(s) of the flight. Also, such traces do not reveal rolling manoeuvres per se, and thus do not offer an authentic reflection of aerobatic flight.

1.12. Place of incident



Accident and Incident Summaries

The glider impacted and came to rest outside runway gable markers in grass next to the runway at Lismore airport, NSW.

1.13. Medical and pathological information

Not applicable.

1.14. Fire

None.

1.15. Survival aspects

The grassy ground where the glider impacted was muddy and relatively soft. The indentation in the soil made by the glider on first ground contact was about 30-40cm deep, absorbing a good part of the impact energy. The pilot was in the front cockpit sitting directly on the seat pan of the glider, with no cushion. The seat cushion (of dense foam) had been removed that morning for reasons of comfort and better glider controllability. The pilot was wearing a backpack type parachute that does not extend below the back to form a seat cushion for the pilot.

1.16. Tests and research

None conducted.

1.17. Organisational and management information

Air displays that day had been approved by CASA, to be conducted by Paul Bennet Airshows (the approved organisation). Ground and flight operational procedures had been established and clearly communicated to pilots both in the briefing and documentation sent out beforehand. A ringmaster had been appointed with the authority to run the day. Display abort procedures, diversion airfields, weather contingency plans and emergency response plans were all in place for the day and publicised beforehand, as well as briefed in detail on the day, to all participating pilots. A display schedule had been drawn up and was followed as closely as possible throughout the day.

1.18. Additional information

None.

1.19 Useful or effective investigation techniques

The glider pilot, tow plane pilot and airshow organiser were interviewed for this report.

2. ANALYSIS

2.1. Flight preparation

Before the display flight this day, the pilot elected to remove the seat cushion to change his seating position, as he was unable to get comfortable with the cushion on this day. Normally, the glider pilot sets his altimeter to QFE minus 200ft. This has been his practice for years to ensure that there is always adequate margin in the low-level manoeuvres. On this day, his altimeter was unintentionally left at zero feet (QFE). Investigators examined the situation around the glider's take-off in an attempt to understand the circumstances that may have led to this inadvertent altimeter setting. The glider pilot boarded the cockpit about 10 minutes before the actual take-off. With the help of a groundcrew, the glider was then pushed along the taxiway toward runway 15. The tow plane had taxied out in advance and was waiting with the rope on the runway. The glider was positioned behind the tow plane by the ground crew, but slightly off to the side in order to leave space for the preceding display—a helicopter demonstrating water bombing procedures. The tow pilot was communicating with the ringmaster on the display frequency, and directed a request at the helicopter to take off with the glider. The helicopter crew replied negatively, and the tow plane and glider—hooked up and ready to go—waited on the runway for another 4 minutes. They were then cleared for take-off once the helicopter was well out of the way. When the ringmaster called to clear the glider for its display, they had just climbed through 2,000 feet. A group of NASA researchers investigated the phenomenon of unintentionally not doing something that one had planned to do, which they referred to as an issue of prospective memory [Dismukes, R. K. (2006). Concurrent task management and prospective memory: Pilot error as a model for the vulnerability of experts. Human Factors and Ergonomics Society 50th Annual Meeting, San Francisco, CA, HFES. And see also: Loukopoulos, L. D., et al. (2009). The multitasking myth: Handling complexity in real-world operations. Farnham, England; Burlington, VT, Ashgate Pub. Ltd.]. Remembering to set the altimeter to minus 200ft AGL after landing in the morning and before the aerobatic


display flight in the afternoon is a prospective memory task. NASA research established that the conditions under which prospective memory works most reliably are:

- 1. a linear environment where each step follows in a fixed sequence on the previous one;
- 2. a predictable environment where tasks and events can be exactly anticipated;
- 3. a controllable environment in which the pilot determines exactly what is going on around him or her.

In the situation on the ground at YLIS at the time, these three conditions were not or only partially met. The order in which the display flight pre-take-off checks could be accomplished was not fixed because of various parallel task demands. Pre-flight checks somehow assume that pilots are in control over the timing, pacing and manner of execution of their tasks. But the environment on the ground at an airshow is difficult to control for individual pilots because of other traffic, space constraints, and exact time allocations associated with the published display schedule. In addition, a glider cannot taxi under its own power, which means it is dependent on ground crew to manually manoeuvre it into position for take-off. The unplanned waiting time for the helicopter to pass and make room for the glider's take-off may have contributed to the sense that all pre-flight checks had been amply completed and obviated the need for another double-check of the cockpit setup. In addition, the negotiations with the helicopter, coupled with the time pressure that was building for the glider to take off so it could commence its display on time (as evidenced from the ringmaster's clearance which was received about halfway its climb), may have directed the glider pilot's attention and cognitive resources outside the cockpit rather than back inside.

2.2. Currency before the flight

The pilot commented that it is difficult to build up and maintain adequate proficiency for the kinds of flights done in displays. There is a general lack of possibilities for safe, and legal, practice for the kinds of aerobatic manoeuvres at low level that get displayed during airshows like the one at Lismore. There are very few areas in which low-flying is allowed, and very few airports at which the regulator has approved low-level aerobatic flying as a legal possibility. This lack of proficiency and currency mean that when it comes to flight preparation for an airshow, there is no authentic practice until the real event. This puts display pilots in a position where the manoeuvres are executed when (1) recovery margins are slim, where (2) visual cues are different from what was practiced at higher altitudes before, and where (3) diversion opportunities are few (because of tight display area limits).

2.3. Flight execution

When the pilot came out of a wing-over to begin the last run, which was to include a fast 4-point roll from level flight, then another wingover and then landing on RWY 33, he noticed that the altimeter showed over 400ft. He decided this was 'very good,' as he'd normally expect it to show about 200-250ft (given the -200 correction he normally puts in before the flight). When coming out of the wing-over, he saw a fence ahead which appeared surprisingly close, in a way that was inconsistent with the altitude he had just read off his altimeter. As a result, he was not able to generate quite as much airspeed for the 4-point aileron roll as he had liked. When entering the first quarter of the roll, airspeed was 80-85 knots, rather than the desired 90 knots. When inverted, the pilot noticed that the picture 'didn't look right,' and decided to abort the manoeuvre. The roll rate of the Fox glider is about 360 degrees/4 seconds, so this was literally a 'split-second' decision. From here on, all pilot actions were focused on mitigation and recovery. While completing the last part of the roll, the pilot used his knife-edge position to move the glider away from the display area and spectators and bring it over an empty, clear area of the airfield instead. As he was doing so, the nose was dropping and the descent rate was increasing. Not long after the pilot had levelled the wings, the glider contacted the soft grassy ground outside the gable markers on the western side of the airfield.

2.4. Ground contact

The skid marks on the fuselage, the damage sustained by the undercarriage, the 100 metre ground run through soft grass, witness statements, the fact that the ailerons and other control surfaces were responding accurately to pilot inputs during the last roll to level flight, and interviews with the pilot all suggest that the glider was not stalled when it contacted the ground, or that it had stalled at a higher speed because of additional wing loading in the recovery attempt close to the ground. The pilot recalled the glider flying about 60 knots when it made ground contact.



Accident and Incident Summaries

2.5. Plan continuation

The sequence of events fits a well-known pattern in human factors, called 'plan continuation.' The pattern has been studied extensively by another group of researchers at NASA Ames Research Center (*See: Orasanu, J. M., et al. (1996). Cognitive and contextual factors in aviation accidents: Decision errors. Applications of naturalistic decision making. E. Salas and G. A. Klein. Mahwah, NJ, Lawrence Erlbaum Associates*). From a number of incidents, they concluded that:

In plan continuation, early and strong cues suggest that sticking with the original plan is a good, and safe, idea. Only later, and weaker cues suggest that abandoning the plan would be better, but they are not as convincing as the early cues that encouraged continuation. By the time later cues come in, margins for recovery and safe plan abandonment may have shrunk. In hindsight, outside observers may forget to see the cues from the point of view of pilot at the time, and when and how persuasively those cues appeared. NASA researchers pointed out that decision-making in complex, dynamic settings such as the last part of an aerobatic display is not an activity that involves a weighty comparison of options against pre-specified criteria. Rather, such decision-making is "front-loaded:" this means that most human cognitive resources are spent on assessing the situation and then re-assessing it for its continued do-ability. In other words, decision-making in a dynamic situation is hardly about making decisions, but rather about continually sizing up the situation. The 'decision' is often simply the outcome, the automatic by-product of the situation assessment. This is what turns a decision on whether to continue with a plan into a constantly (re-)negotiable issue: even if the decision is not made on the basis of an assessment of the situation now, it can be pushed ahead and be made a few or more seconds later when new assessments of the situation have come in. The order in which cues about the developing situation come in, and their relative persuasiveness, are two key determinants for plan continuation. Conditions often deteriorate gradually and ambiguously, not precipitously and unequivocally. In such a gradual deterioration, there are almost always strong initial cues that suggest that the situation is under control and can be continued without increased risk. This sets a pilot on the path to plan continuation. Weaker and later cues that suggest that another course of action could be safer have a hard time dislodging the original plan. In summary, plan continuation means sticking to an original plan in rapidly evolving situations, while the changing situation actually calls for a different plan:

- Early cues that suggest the initial plan is correct are usually very strong and unambiguous. This helps lock people into a continuation of their plan. The persuasive early cue here would have been an indicated height of over 400ft AGL when coming out of the wing-over.
- Later cues that suggest the plan should be abandoned are typically more ambiguous and not as strong. These cues, even while pilots see them and acknowledge them, often do not succeed in pulling pilots away from the plan. In this case, later cues would have been the fence, and the inability to get the desired airspeed for the final 4-point roll. Neither cue made the roll manoeuvre impossible, however, and were not as convincing as the early height cue. When the plan was abandoned, there was still sufficient margin to steer the glider away from risk at the airfield and then level the wings, but there was insufficient height and/or energy for a landing with a slower descent rate.

3. CONCLUSION

3.1. Findings

- 1. Both glider and pilot were appropriately certified and approved for the display at Lismore on 29 July 2017, including low-level aerobatic manoeuvres.
- 2. The airshow was appropriately planned and approved.
- 3. The seat cushion was taken out before the display flight to achieve a better seating position.
- 4. The altimeter was set at Oft AGL, and not at minus 200ft AGL, as is the pilot's usual practice for display flying.
- 5. In the wingover before the last planned 4-point roll, the pilot noticed indicated altitude to be around 400ft, whereas normally (with the altimeter adjustment) it would be around 250ft.



Accident and Incident Summaries

- 6. The sequence of events fits the pattern of plan continuation in which early, strong cues suggested the plan could be safely continued, and only later, less persuasive clues suggested the plan might need to be changed or abandoned.
- 7. The glider was flying at about 60 knots when it impacted the grass.

3.2. Causal factors

- There is a structural lack of legal possibilities for the safe and approved practice of low-level aerobatic manoeuvres in Australia, both for powered aircraft and gliders.
- The sequence of events in the glider incident at YLIS fits the pattern of plan continuation. In plan continuation, early and strong cues suggest that sticking with the original plan is a good, and safe, idea. Only later, weaker cues suggest that abandoning the plan would be better, but they are not as convincing as the early cues that encouraged continuation.
- The altimeter setting of Zero feet AGL, rather than the pilot's customary minus 200ft AGL, contributed to the strong height cue at the beginning of the last manoeuvre that suggested that continuing with the planned manoeuvre was safe.
- The pre-flight removal of the seat cushion may have contributed to the injuries sustained, but that is not certain: the seat cushion that was removed was made of dense foam but not designed to a specific G-rating.

4. RECOMMENDATIONS

- 1. GFA and appropriate bodies in General Aviation are recommended to work with stakeholders to create possibilities for the safe and legal practice of low-level aerobatic manoeuvres outside of airshow days and locations.
- 2. Pilots, whether before aerobatic display flights or any other flights, might be encouraged to take steps to ensure as 'sterile' a cockpit environment as possible as they are preparing their aircraft for departure. This ensures a micro-environment that is as controlled and predictable as possible, so that necessary preparatory steps are taken in a fixed order, and prospective memory problems are minimised.

Date	6-Aug-2017	Region		WAGA		SOA	AR Repo	ort Nbr		S-1015		
Level 1	Operational		Level 2	Airc	raft Co	t Control Level 3		Control iss	ues			
A/C Mod	el 1	Glas	sfugel Lib	elle 201B		A/C Model 2						
Injury	Nil	Dama	ge	Nil	Pha	ase In-Flight		PIC Age				

This incident occurred during a test flight following the completion of the glider's annual Form 2 Inspection. Weather conditions at the time the test flight was undertaken were benign and the pilot considered conditions were suitable to carry out a VNE run. After releasing from aerotow at 3500' AGL and following initial control checks and clearing turns, straight and level flight was assumed at a speed of 50 knots. From this starting point speed was increased in 10 knot increments with control checks carried out at each speed. This progressed normally with no adverse reaction to control inputs noted. Just as the speed reached VNE (135 knots) the pilot felt an upward surge of the aircraft as would normally be felt passing through a bubble of lift. The pilot did not feel this through the controls but rather through the "seat "and is convinced it was external to the aircraft. Immediately following the vertical surge the aircraft started to vibrate. The pilot stated: "I can best describe the sensation felt as a "shimmy" coming from behind me, it as if the tail section was oscillating and shaking the rest of the aircraft. It was not a very high frequency shake, I would estimate the oscillations at 3-4 per second but the frequency may have been increasing before corrective action was taken." Although the event happened quite suddenly, the strength of the oscillations was mild initially but increased in magnitude rapidly. As soon as the oscillations began the pilot gently reduced speed. As the speed bled off the magnitude of the oscillations initially seemed to increase in intensity but then gradually subsided and finally stopped completely when the speed dropped below 100 knots. As the pilot was preoccupied with getting the glider under control, observation of the wings and tailplane, which can be partially seen from the cockpit of the glider, was not undertaken. After resuming a stable attitude, the pilot



Accident and Incident Summaries

assessed the glider's handling and structure to be normal, so the flight was abandoned. The landing was uneventful and a visual inspection of the airframe did not reveal any damage. A detailed inspection of the aircraft identified excessive free-play in the rudder gimbal drive had led to a flutter event. The free-play was removed and the aircraft returnd to service.

				60						6 4 9 4 6		
Date	8-Aug-2017	Region		GQ			AR Repo	ort Nbr		S-	1016	
Level 1	Operational		Level 2	Airc	Aircraft Control Level 3		Hard landi	ng				
A/C Mod	el 1		Twin A	Astir		A/C Model 2						
Iniurv	Nil	Dama	ige Su	ubstantial	Pha	hase Landin		ng		PIC Age	60	

While demonstrating a simulated launch failure to the student, the instructor misjudged the round-out from a very steep approach and the aircraft landed heavily with some sideways drift. The tail boom broke off just behind the wings. The tow was taken to the usual 2000ft AGL on a day with little thermal activity. The decent was used for training sequences, such as control co-ordination, and a high approach was made to the operational runway (RWY 21) with the intention of demonstrating a simulated launch failure from about 500ft AGL at the far end of the runway. The instructor conducted a 270 degree turn to the right followed by a 90 degree turn to the left to align with runway 03. Unfortunately, the instructor had not identified that the wind speed had increased since launch and the glider drifted further downwind than anticipated during the turn. This placed the glider in a very steep approach to the remaining 350 metres of runway. The instructor used full airbrake and sideslip to increase the descent rate. Unfortunately, the instructor did not close the airbrakes in time to prevent the glider from landing heavily with some sideways drift. The instructor stated that prior to the flight they believed the wind was abating and was surprised to find the wind had increased.





Accident and Incident Summaries



Date	12-Aug-2017	Regior	ion SAGA				AR Repo	ort Nbr		S-1018		
Level 1	Operational		Level 2	Grour	nd Ope	eratic	ons	Level	3	Taxiing collision/near		
										collision		
A/C Model 1 Grob G 109 A/C Model 2												
Injury Nil Damage Minor Phase Ground Ops PIC Age 67												
As the air	As the aircraft was being taxied from the hangar apron to the aircraft parking area adjacent to the											
operatior	operational runway by an experienced pilot, the port wingtip contacted vegetation at the side of the runway											
resulting	in minor damage	e. The tax	kiway is r	arrow, with	n mini	mal c	learan	ce for g	liders	due to con	stantly	
growings	mall gums. The	club usua	ally emplo	oys a perso	n to g	uide 1	the airc	raft do	wn th	ne taxiway d	uring	
crosswind condition but one was not employed on this occasion as the wind was light. It is believed the pilot												
may have	e been momenta	rily distra	acted by	a cut on his	finge	r that	was b	leeding	. The	Club will ap	proach the	
airfield ov	wner to reduce t	he encro	aching v	egetation.								

Date	12-Aug-2017	Regior	n NSWGA				SOAR Report Nbr				S-1054		
Level 1	Operational		Leve	Level 2 Airfra			ne		Level	3	Landing		
											gear/Indic	ation	
A/C Mod	el 1		SZD-55-1				A/C	Model	2				
Injury	Nil	Dama	age Minor Pł			Pha	ase Landing				PIC Age	70	
The pilot	lowered the un	dercarria	ge fo	r lan	ding but th	ne lock	king n	nechan	ism dic	not e	engage. Upo	on	
touchdown the undercarriage retracted resulting in some minor scratching of the fuselage. The wheel													
retraction	n and lowering n	nechanisr	n for	this	aircraft is v	via a n	necha	anism o	n the r	ight-ł	nand side of	the cockpit.	



Accident and Incident Summaries

With the handle forward, the wheel is down; and with the handle rearward, the wheel is up. A small red trigger like device is fitted to the front of the handle, which must be depressed to retract the undercarriage. When the undercarriage is lowered the lock should automatically engage and the red trigger should need to be depressed if the wheel is to be retracted again. Although the pilot can see that the wheel is down there is no indent or visual way of verifying that the wheel is locked. The pilot noted that after lowering the wheel it is their practice to confirm the lever is locked by trying to retract it without depressing the red trigger. The pilot has a clear recollection of doing this on the day but noted that considerable force is required to retract the undercarriage, even when the trigger is depressed and the mechanism is unlocked. The pilot suspects on this flight that insufficient force was applied to the gear retraction mechanism to confirm it was locked.

Date	19-Aug-2017	Regior	1	SAGA		SOAR Report Nbr			S-1022		
Level 1	Operational		Level 2		Airfrar	ne		Level 3 Fuselage/		Wings/Empe	
										nnage	
A/C Mod	el 1		AS-K	13		A/C	Model	2			
Injury	Nil	Damage Minor Phase In-Flight PIC Age 67									67
The purp	The purpose of the flight was to undertake a performance evaluation following annual maintenance. The										
comman	command pilot flew the aircraft to Vne and, as the glider was slowed, some fabric separated from the top										
surface o	f the starboard v	ving imm	ediately b	pehind the	airbra	ake b	ox. Whi	ile the a	aircra	ft felt heavy	, the pilot
was unav	vare of the prob	lem until	after land	ling. Invest	igatio	n det	termine	ed that	when	the wing w	as recovered
some yea	ars earlier, the fa	bric had	been cut i	flush with a	airbra	ke cu	t-out ir	stead o	of bei	ng lapped ir	nto airbrake
box. This	box. This error was masked by paint and was not picked-up at subsequent inspections. Gradual degradation										
of the pa	int and UV dama	ige over t	ime led to	o the leadi	ng edg	ge of	the fab	ric losi	ng ad	hesion, thei	reby allowing
the airflo	the airflow to lift the fabric to the point that it tore off.										

Date	19-Aug-2017	Region VSA SOAR Report Nbr S-1026 Lovel 2 Aircreft Separation Lovel 2 Near callision						1026			
Level 1	Airspace		Level 2	Aircra	aft Sep	barati	on	Level	3	Near collis	ion
A/C Mod	el 1		PW	·6U		A/C	: Model	2	DG-	400	
Injury	Nil	Dama	age	Nil	Pha	ase	Laund	h		PIC Age	
It was reported that a glider/tug combination climbing for height passed less than 100ft over a thermalling									hermalling		
motor gli	motor glider. Investigation revealed that the towing combination commenced take-off from operational										
runway 1	runway 18 at 13:36, and almost one minute later, when the combination was just upwind of the runway										
perimete	perimeter, the DG-400 pilot commenced take-off. At 13:38, while at a height of about 800ft AGL, the towing										
combinat	combination commenced a procedural turn to the left. Approximately 30 seconds later and around 800ft										
AGL the I	DG-400 pilot tur	ned to the	e right. A	minute lat	er the	towi	ng com	binatio	n wa	s on a West	erly heading
just upwi	ind and to the Ea	ast of the	operatio	nal runway	wher	the g	glider p	ilot rec	eivec	l a collision	alert from
the Flarm	n. At the same ti	me, the D	G-400 h	ad complet	ed 270	0 deg	rees of	a turn	and v	vas heading	in a
Southerly direction when the pilot suddenly noticed the towing combination at a similar height closing from											
the left.	The DG-400 pilo	t took av	oiding ac	tion by tigh	tenin	g the	turn as	the to	wing	combinatio	n passed
within 10	0ft. It is possible	e the tow	pilot did	not identif	y the I	DG-40	00 as it	was sli	ghtly	lower and r	nay have
been obscured by the nose of the tow plane.											



Accident and Incident Summaries



Date	20-Aug-2017	Regior	۱	VSA		SOA	AR Repo	ort Nbr		S-	1021
Level 1	Airspace		Level 2	Aircra	aft Sep	arati	on	Level	3	Near collis	ion
A/C Mod	el 1		DG-1	000S		A/C	Mode	2	Pipe	er Cub/Pace	r
Injury	Nil	Dam	age	Nil	Pha	ase	Landi	ng		PIC Age	54
On early	downwind the co	ommand	pilot ide	ntified a po	wered	d airc	raft clir	nbing f	rom t	he left on a	collision
course ar	nd took avoiding	action to	prevent	a collision.	The p	ilot o	of the p	owered	l airci	raft also too	k avoiding
action an	d passed about !	50-100m	in front	of glider. Th	ne glid	er wa	as on ar	n instru	ction	al flight and	returning to
the airfie	ld to join circuit.	It was la	te aftern	oon, and lig	ghting	cond	itions v	vere du	ıll due	e to an over	cast sky. Just
after the	decision to brea	k-off the	flight, th	e crew of t	he glid	ler he	eard a c	lepartu	re ca	ll over the C	TAF from the
pilot of a	visiting Piper Tri	pacer. Th	ne gliding	instructor	visual	ly acc	quired t	he Trip	acer	lifting off ab	out two
thirds do	thirds down the operational runway. Nearing the circuit joining area the gliding instructor scanned the										
airspace	irspace for the departing Tripacer but did not see it. As glider became established on the downwind leg										
and at ab	oout 900ft AGL th	ne glider i	instructo	r saw Tripa	cer in	in the	e 10 o'o	clock po	ositio	n climbing o	n its
crosswin	d track on a path	that wo	uld confl	ct with the	glider	. The	gliding	g Instru	ctor a	issumed cor	trol of the
glider an	d rolled left to pa	ass behin	d the Tri	bacer. Shor	tly aft	er the	e glider	rolled,	the T	Tripacer pilo	t also turned
left to av	oid the glider. At	the clos	est point	, the two ai	rcraft	were	estima	ated to	be 50) to 100 met	res apart. It
is conside	ered that had ne	ither pilo	t taken a	voiding act	ion a d	collisi	on was	likely.	No ra	adio commu	inications
followed	the incident, and	d the Trip	acer dep	arted to th	e sout	h. Tl	ne glide	er instru	uctor	suspects the	e Tripacer
may have	e been obscured	from vie	w by the	Clear Visio	n Pane	el on t	the left	-hand s	side o	of the glider'	s canopy.
Investiga	tion revealed the	e Student	: pilot, w	no is not so	lo star	ndard	l, did no	ot sight	the 1	Tripacer as t	heir
attention	was directed at	flying th	e glider. /	An inbound	l call w	as no	ot made	e by the	e glide	er pilots as t	hey had
been ope	erating within glio	de range	of the ae	rodrome. 1	Гhe gli	der p	ilots als	so did r	not giv	ve a positior	nal broadcast
upon joir	ning the circuit be	ut this wa	as consid	ered a timi	ng issu	ie rat	her tha	in an ov	versig	ht as the in	cident
occurred	around the time	e a call wa	as due to	be made b	y the	stude	ent.				

Date	20-Aug-2017	Region	1	VSA	SOAR Rep	ort Nbr		S-1023
Level 1	Operational		Level 2	Airfrai	me Level 3			Doors/Canopies
A/C Mod	el 1		Vent	tus c	A/C Model 2			



Accident and Incident Summaries

Injury	Nil	Damage	Minor	Phase	In-Flight	PIC Age	69						
The purpose	of the flight v	vas to underta	ike a performa	ince evalua	tion following annu	ual maintena	ance. As the						
command pi	lot flew the ai	rcraft to Vne t	he canopy ope	ened. The p	oilot immediately sl	owed the ai	rcraft and						
pulled the ca	anopy down b	ut could not cl	ose it fully so l	held it in po	osition. The pilot no	oted that the	e canopy						
showed no i	showed no inclination to lift open once the speed had decreased. The plot completed a successful landing												
without furt	her incident. 1	he pilot recall	ed noticing the	e canopy a	ppeared not to be p	properly clos	sed while						
conducting 1	he pre-launch	checks, so the	e canopy was o	opened and	d closed again. The	pilot believe	es, with						
hindsight, th	at the canopy	locking lever	was not pushe	d sufficient	tly forward to prop	erly engage	the locking						
pins, and the pilot did not attempt to lift the canopy to ensure the lock was engaged. A witness to the launch													
believed the	canopy was n	ot properly cl	osed but did n	ot have acc	ess to a radio to al	ert the pilot	. The pilot						
also noted t	hat operations	were being co	onducted on t	he main bit	umen runway as th	ne grass strip	os were						
unserviceab	le due to rain.	Consequently	, the take-off	was smootl	n and the canopy d	id not move	(movement						
over rough §	round may ha	ve altered the	pilot to the ca	anopy bein	g unlocked). Inspec	tion of the l	ocking						
mechanism	, revealed it to	be stiff, which	was alleviated	to some e	xtent by lubrication	n. While 'car	10py closed						
and locked'	is part of the r	ore-launch che	cklist. all too c	often a pilo	, t will take off with t	the canopy o	losed but						
not locked.	Fo prevent this	s, pilots should	d be in the hab	it of verifvi	ng the canopy is lo	cked. This ca	an be done						
by gently pu	shing up on th	e frame of the	e canopy, not t	, the Perspex	. Also, the comma	nd pilot is re	esponsible						
for each can	for each canopy being closed, locked and verified and not just their own.												

Date	27-Aug-2017	Region VSA SOAR Repo				ort Nbr		S-	1027		
Level 1	Operational		Level 2	2 Airc	raft C	ontro	ol –	Level	З	Wheels up landing	
A/C Model 1 Twin Astir A/C Model 2											
Injury Nil Damage Nil Phase Landing PIC Age 73											
During a instructo undergoi pre-landi	training flight the r did not normall ng type conversion ng checklist and	e glider w y retract on, raised failed to	vas land the und d the ur check t	led with the dercarriage a ndercarriage he correct se	under and go in flig ense a	carria t cau ht. Bo nd po	ge retr ght out oth pilo	acted. when ts did r of the u	Inves the st not pr inder	tigation rev tudent, who operly com carriage lev	ealed the was plete their er. A
debriefed	debriefed by their CFI.										

Date	8-Sep-2017	Regior	n WAGA			SOAR Report Nbr				S-1033		
Level 1	Technical	cal		el 2		Syster	ns		Level 3		Flight controls	
A/C Mod	el 1	SZD-4	SZD-48-3 Jantar Standard 3					Model	2			
Injury	Nil	age	Sul	bstantial	Pha	ase	In-Flig	ght		PIC Age	69	
During the post-maintenance test flight the elevator pushrod disconnected. The pilot was able to land the									o land the			
glider usi	glider using weight-shift techniques to dampen the phugoid oscillations. The pilot was uninjured, but the											
glider wa	s substantially d	amaged.										



Accident and Incident Summaries



It was determined that the elevator coupling had not been secured during rigging and the dual check did not identify the problem. Inspectors must ensure the release button is securely locked during rigging, and should use a mirror and torch if necessary.



Accident and Incident Summaries



Date	9-Sep-2017	Regior	n	VSA			AR Repo	ort Nbr		S-1032		
Level 1	Technical		Level	2	Syster	ns		Level	3	Flight cont	rols	
A/C Mod	el 1		ASK	21Mi		A/C	Model	2				
Injury	Nil	Damage Nil		Pha	ase	Grour	nd Ops		PIC Age	68		
During the Daily Inspection the starboard wing airbrake pushrod was found disconnected from the l'Hotellier												
coupling	coupling in the fuselage. It is thought the diconnect occurred during landing on the prevous flight.											
Investiga	Investigation evealed the L'Hotellier was functioning correctly, leading to the conclusion that it was not											
properly	connected at tim	e of rigg	ing. Thi	s aircraft use	es sprii	ng-loa	aded W	edekin/	d safe	ety sleeves a	and the	
manufact	turer is unaware	of simila	r occuri	ences on th	is mod	lel. Tł	ney not	ed that	а сон	rectly fitted	d Wedekind	
sleeve wi	ll prevent an uni	ntention	al disco	nnection as	long a	s the	ball dia	meter	is wit	hin specifica	ation and the	
wedge is not unduly worn. The Aircraft Flight Manual states: "During assembly of the quick-release												
connecto	rs either the alur	ninium se	afety sle	eve is pushe	ed bac	k unti	il the w	edge m	ay be	e pushed in a	entirely, or	
the sprin	the spring is removed from the check hole of the wedge. After the careful assembly of the quick-release											



Accident and Incident Summaries

connectors check that the spring-loaded safety sleeve secures the wedge again completely. All quick-release connectors must be tested by pulling the pushrods - socket ends off the ball heads -, applying a force of not less than 5 daN (10 lb), and it must be checked that the safety elements are in their correct position." It is suggested that inspectors check the correct fitment visually, using a torch if necessary. The Wedekind sleeve also has a notch and pin arrangement that can be felt to conform it is correctly engaged. [Refer also to SOAR Report S-0765].

Date	10-Sep-2017	Regior	n	VSA		SOA	AR Repo	ort Nbr		S-	1084
Level 1	Airspace		Level	2 Aircr	aft Sep	oarati	on	Level	3	Near collis	ion
A/C Mod	el 1		ASł	K-21Mi		A/C	Mode	2	Ces	sna 172	
Injury	Nil	Dama	Damage Nil Phase In-Flight PIC Age 51							51	
After con	npleting some tra	aining ma	anoeuv	res the glide	r instr	uctor	notice	d a Ces	na air	craft in clos	e proximity
(60 metre	es laterally) and t	turning away from the potential conflict. The identity of the other aircraft was not									

established.

Date	10-Sep-2017	Region	1		VSA		SOA	AR Repo	ort Nbr		S-	1085
Level 1	Airspace		Level	2	Aircra	ift Sep	arati	on	Level	3	Near collis	ion
A/C Mod	el 1		ASK	(-211	Иi		A/C	Model	2	Cess	sna 172	
Injury	Nil	Dama	age		Nil	Pha	ise	In-Flig	ght		PIC Age	23
The self-l	aunching sailplai	ne was op	peratin	g fro	om Runw	ay 17	on a	training	g sortie	. Follo	owing a nori	mal launch,
and as the sailplane was climbing through 1200ft, the command pilot heard a radio call from the pilot of a												
Cessna ai	Cessna aircraft reporting entering the CTAF at 10NMs. The sailplane pilot made a position report that was											
acknowle	edged by the Ces	sna pilot.	Shortl	y aft	erwards,	and a	t a h	eight o	f 2,000	ft, the	e student pil	ot in the
sailplane	alerted the com	mand pile	ot of th	ne pr	esence o	f a Ce	ssna	ahead a	and slig	htly t	o starboard	. The
comman	command pilot executed a clearing turn and the Cessna passed about 200ft laterally. The command pilot											
was unable to identify the Cessna and believes its pilot had not sighted the sailplane.												

Date	15-Sep-2017	Region		GQ		SOA	AR Repo	ort Nbr		S-	1034
Level 1	Technical		Level 2 Syst		Syster	ns		Level	3	Flight cont	rols
A/C Mod	el 1		Twin Astir			A/C Mode		2			
Injury	Nil	Dama	age	Nil	Pha	se	Grour	nd Ops		PIC Age	66

While conducting the Daily Inspection, the inspector identified that mandatory maintenance based on 'time in service', i.e. the lubrication of L'Hotellier couplings, was not undertaken and the aircraft had flown on at least four occasions beyond the service due date. The outstanding maintenance was performed and the aircraft was returned to service. Before starting a Daily Inspection, it is essential to check that the Maintenance Release is valid, and no Major Defects are recorded which prevent flight. The inspector must also check the details of any scheduled maintenance as listed. If the Maintenance Release is not valid, there is no point in continuing to inspect the glider because it will be illegal if it is flown. The GFA Daily inspector's Handbook requires the following points to be checked:-

- 1. Registration to correspond with glider registration, i.e. booklet is in the correct glider. The booklets are numbered and are specific to each glider registration. It is not permitted to swap booklets between gliders.
- 2. The date of expiry. The glider must not be flown if the document has expired.
- 3. The document is signed.
- 4. That the post-inspection evaluation flight has been signed off.
- 5. That any scheduled maintenance (recurring maintenance) due for completion by date or time is recorded as completed or, if the maintenance is now due but not completed, organise the



Accident and Incident Summaries

maintenance to be carried out this day, if possible, by an appropriate person & certified before final DI signature and release for flying.

Date	16-Sep-2017	Regior	1		VSA		SOA	AR Repo	ort Nbr		S-	1035
Level 1	Operational		Level	2	Run	way E	vent	S	Level	3	Runway ex	cursion
A/C Mod	el 1		Ke	estro	el		A/C	Model	2			
Injury	Nil	Dama	age		Nil	Pha	ise	Landi	ng		PIC Age	78
The pilot	lost control whil	e landing	; in a st	tron	ıg crosswii	nd and	d a gr	ound lo	oop ens	sued.	The pilot re	ported flying
a high cir	cuit due to the s	trong and	d gusty	/ wir	nd conditi	ons, a	nd th	e final a	approa	ch wa	is made witl	h half
landing flap. The pilot noticed significant drift just before touch-down but was able to counter this with												
rudder in	rudder inputs. Just after touchdown the port wing contacted high grass at the edge of the runway resulting											
in the glio	der rotating thro	ugh 120 (degree	es. T	here was	no dai	mage	or inju	ry. The	pilot	attributed t	he ground:
loop to a	combination of	pilot erro	r, wind	d gu	sts and th	e den	senes	ss of th	e grass	. One	of the Club'	's instructors
advised t	hat, just prior to	launch, t	he pilo	ot w	as inform	ed tha	t the	tail do	lly was	still fi	tted, and he	e had to get
out of the	out of the glider to take it off. The pilot's CFI noted that while the pilot has been able to pass their annual											
flight rev	flight review, some age-related issues are beginning to manifest.											

Date	16-Sep-2017	Regior	า		VSA		SOA	R Repo	ort Nbr		S-	1041
Level 1	Airspace		Leve	el 2	Aircra	ift Sep	arati	on	Level	3	Aircraft Se	paration
											Issues	
A/C Mod	el 1		Beech	craft	t Baron		A/C	Mode	2			
Injury	Nil	Dam	age		Nil	Pha	ise	In-Flig	ght		PIC Age	
A powere	ed aircraft enrou	ite to a Re	egiona	al Air	port overf	lew th	ne loc	al glide:	er airfie	ld at l	low level, de	espite being
alerted b	alerted by radio that gliding operations were in progress. The gliding airfield is situated 2NM SSW of the Regional Airport and is mentioned in FRSA entry for the Airport. The gliding club launches by winch. About											
Regional Airport and is mentioned in ERSA entry for the Airport. The gliding club launches by winch. About												
1322 the	ground operation	ons heard	a rad	io ca	all from the	e pilot	of a	Beecho	raft Ba	ron e	ntering the	CTAF from
the South	n-West. The Dut	y Pilot ma	ide a i	radio	call to th	e Pilot	of th	ne Beed	hcraft	to adv	vise that glio	ding
operation	ns were in progr	ess and re	eceive	d an	acknowle	dgem	ent. ⁻	The CFI	, who \	was at	bout to fly w	/ith a
student,	decided to delay	/ the laun	ch. Sh	ortly	y afterwar	ds the	Beed	chcraft	flew ad	cross t	the operatio	onal runway
at circuit	at circuit height. The CFI made a call to the pilot of the Baron but did not receive a reply. The matter was											
referred	referred to the ATSB, who alerted the Beechcraft pilot to the issues.											

Date	17-Sep-2017	Regior	1		GQ		SOA	R Repo	ort Nbr		S-	1083
Level 1	Operational		Leve	el 2	Terra	ain Col	lisior	IS	Level	3	Ground st	rike
A/C Mod	el 1		AS	K-21	lMi		A/C	Model	2	N/A		
Injury	Nil	Dama	age		Minor	Pha	ise	Landi	ng		PIC Age	70
The com	mand pilot was c	onductin	g an a	ir ex	kperience t	flight.	After	landin	g on ru	nway	06 the airc	raft had
sufficient forward speed for the command pilot to taxi the aircraft clear of the runway with the aim of												
stopping on the apron outside the aerodrome terminal building. As ground speed reduced, the command												
pilot beg	an to lower port	wing ont	o the '	taxiv	way in ord	er to l	keep '	the sta	rboard	wing	well clear o	f the taxiway
lights. A	sudden gust of w	ind rolle	d the	wing	gs, and de	spite t	he in	put of t	full opp	osite	aileron con	trol, the
starboard	wing contacted	the grou	ind an	nd st	ruck a taxi	way li	ght. [Due to t	the slov	w forv	ward speed,	the aircraft
suffered	suffered only superficial damage. The Club CFI has banned taxying unless the aircraft is under power with											
one wing	one wing firmly down.											

Date 19-Sep-2017 Region GQ SOAR Report Nbr S-1047		Date	19-Sep-2017	Region	GQ	SOAR Report Nbr	S-1047
---	--	------	-------------	--------	----	-----------------	--------



Accident and Incident Summaries

Level 1	Operational		Level 2	Terra	ain Col	lisior	าร	Level	3	Controlled	l flight into
										terrain	
A/C Mod	el 1		ASK-21		-21		A/C Model		N/A		
Injury	Fatal	Dama	Damage Write-o		Pha	se Landir		ng		PIC Age	62

GFA Field Investigation

1. FACTUAL INFORMATION

At 0933 hours on 19 September 2017 an ASK-21 two-place glider launched behind a Piper Pawnee tow plane from the Jondaryan airstrip in Queensland, and released at a height of about 2,400 ft above ground level (AGL) at 0937 hours. After a short flight the command pilot joined the downwind leg of the circuit for landing. During the final approach to the operational runway and at a height of between 50 and 30 feet AGL, the glider suddenly and unexpectedly nosed steeply towards the ground and impacted the surface of a ploughed paddock approximately 30 metres short of the runway. The accident was witnessed by the tow pilot, who was also a gliding instructor and the wife of the command pilot, and another trainee pilot. The two witnesses rushed to the accident site in a vehicle. Upon reaching the site they noted significant damage to the aircraft and that the flight crew had been seriously injured (refer figure 1). The trainee pilot telephoned emergency services and, together with the tow pilot, removed the flight crew from the aircraft and commenced CPR. Police and emergency services attended the scene shortly afterwards and confirmed the pilots were deceased. The Australian Transport Safety Bureau (ATSB) was notified of the accident but declined to investigater. The Gliding Federation of Australia (GFA) dispatched a Technical Advisor, who is an experienced investigator, to the site to assist the Queensland Police.



Figure 1: Glider resting position

1.1 History of flight



Accident and Incident Summaries

The command pilot and his wife, who are both flying instructors and tow pilots, were running a week-long ab-initio gliding course for two student pilots. They were alternating between flying the glider and flying the tow plane each day. The accident occurred on the third day of the course and was the second flight of the day; the first flight had been conducted without incident by the same instructor and same student, and in the same aircraft. The student pilot was occupying the front seat, and the instructor was seated in the rear of the cockpit. This was the student pilot's 8th training flight. The glider was observed by the witnesses towards the end of the flight just after it entered the circuit for a landing. The witnesses watched the glider flying the downwind leg for runway 31 and then observed the glider as it was turned onto the base leg slightly closer than on the previous flight. Both the tow pilot and trainee pilot were interviewed separately by the GFA's investigator, who recorded their conversations. The tow pilot later provided a written statement, which was similar to their recorded statement. In their written statement, the tow pilot noted that the "Downwind leg looked well placed and at the right height; the base leg was similarly good height and distance away. The glider appeared to modify the base leg slightly towards the field as the wind was quite strong. No Airbrake seemed to be applied in this leg." When the glider was approaching abeam the extended runway centreline, it was observed to turn onto the final approach. The flight log indicates this was at a height of about 700ft AGL. On final approach the glider appeared, to the witnesses, to be flying at normal speed, with airbrakes half extended. The flight log reports a ground speed of between 50 to 56 knots, which would be the normal approach speed into a reported 10 to 15 knot headwind. The tow pilot reported in their witness statement: "The final leg looked well placed and at a good height for the wind on the day. I estimate it turned final at about 4-500 ft (but it can be checked on the GPS trace). Initially there was no airbrake applied. Then some airbrake came out for several seconds; then the airbrakes went away for several seconds; then airbrake deployed again. I thought that [the command pilot] was demonstrating the moving of the aiming point. Full airbrake was not deployed on either action. It then looked like the glider was on the stabilised approach with maybe one-third to one-half airbrake. It all looked entirely normal at this point." On short final, at a height of between 30 and 50 feet above the ground, the glider was observed to make a sudden, very steep, nosedive. Coincident with the glider nosing over, the airbrakes were observed to became fully extended. The glider impacted the ground at an angle of about 65 degrees to the horizontal plane immediately after, with no evidence of any attempt by the flight crew to recover (refer Figure 2). The glider came to rest in an empty cotton field just short of the runway. The tow pilot wrote: "When approaching about what I think was 30-50 ft the airbrake came out full and at the same time, the glider pitched violently forward to the near vertical position and within a second or not much more, hit the ground vertically. The glider landed about 10-15m short of the runway in the ploughed field." In a recorded interview with the GFA's investigator, the trainee pilot said: "The transition was very quick - from everything looking fine and from what you'd expect to be the final approach to everything obviously just being not good and it was over in like what was a second if that. There was obviously no time for the pilots or [the command pilot] to recover the aircraft, if say the student was in command or, I'm not sure." He also stated: "It wasn't a full 90 degree straight-in, it was more like 60 to 65 degrees; it was definitely quite steep."



Accident and Incident Summaries



Figure 2: Impact profile

The tow pilot wrote: "[The Trainee pilot] and I jumped in my car and we drove very fast to the crash site. I was horrified at the damage and as we approached the cockpit, it was apparent that there was catastrophic damage and the pilots were in bad shape, [the command pilot] (was) slumped in his seat and [the Student Pilot] (was) hanging out of his cockpit." The trainee pilot told the GFA Investigator: "We drove over there and as soon as we got to the wreckage it was definitely something that was pretty gnarly. After getting hold of emergency services, I managed to pull both occupants out of the cockpit and I began CPR on both – I started on [the student pilot], ended up pulling out [the command pilot] and continued on him until the emergency services took over." Shortly after attending the scene, paramedics attempted resuscitation, but their attempts were unsuccessful and both men were pronounced deceased.

1.2. Injuries to persons

A full post-mortem examination demonstrated severe injuries in both flight crew, sufficient to cause death. The injury pattern is consistent with having been sustained during the impact of the glider with the ground.

1.3. Damage to aircraft

- An impact angle of about 65 degrees nose-down, was derived from a combination of damage to the underside of aircraft, wings and the indentation made in the field.
- Substantial damage was caused to the entire airframe consistent with high-speed steep-angle impact with ground. The nose cone, cockpit canopies and seat pans were shattered. Both control sticks were bent flat forward. The instrument panels were dislodged but largely intact themselves and still loosely held. Most of the instruments were still intact. The cockpit frame was bent and shorn in multiple places. The seat harnesses were intact but suspended from the cockpit frame, which itself was damaged substantially.



Accident and Incident Summaries

There was no evidence of a ground run after impact. The aircraft came to rest about 1 metre from where it impacted, twisting up to 30 degrees to the left between the initial impact and final resting place (refer Figure 3).

Figure 3: Impact crater behind the main wheel.



Accident and Incident Summaries



Figure 4: Left wing displacement

- Evidence of impact (as marked by dust/sand imprinted from the field into the airframe) was visible on both wings, up to half the length of each wing from the tips inward. The outboard halves of both wings thus hit the ground on impact, likely (almost) simultaneously.
- The right wing was still in place. The left wing was mostly in place but torqued slightly forward and upward (refer Figure 4).



Accident and Incident Summaries



Figure 5: Tail boom, rudder and elevator.

- The tail boom had broken off approximately 1.5m inboard from rudder. It had cocked forward by almost 180 degrees, connected to the fin and empennage by only by the rudder cables and a severely deformed elevator pushrod control rod (refer Figure 5).
- The elevator circuit and trim system were both found to be intact (refer Figure 5).
- The airbrakes were unlocked and partially extended.
- All parts of the airframe suffered damage consistent with a high 'g' impact.

1.4. Other damage

Nil. The aircraft impacted on vacant rural land.

1.5. Personnel information

1.5.1 Flight Experience

Command Pilot

The command pilot held a GFA Glider Pilot Certificate with a Level 3 Instructor endorsement, and held the position of Chief Flying Instructor of the Darling Downs Soaring Club. He also held Commercial and Private pilot licences issued by the Civil Aviation Safety Authority (CASA). Logbook records show the command pilot commenced gliding in 1968, and at the time of the accident had flown 3,228 glider flights for a total of 1,933 hours; over 680 hours of which were as an instructor. The command pilot had an additional 2,960+ hours in General Aviation powered aircraft.

Student Pilot

Logbook and training records reveal the student pilot commenced their flight training two days earlier on 17 September 2017 and had accumulated just under 3½ hours flight time. The accident occurred on the student pilot's eighth flight. The tow pilot, who had flown with the student the day before, advised the GFA Investigator in a recorded interview that the student pilot had no prior aviation experience: *"I did make the*



Accident and Incident Summaries

comment to him and said you fly quite well have you got any prior experience and he said no, I ride a motorbike, and maybe that's it. No hang gliding or nothing."

1.5.2 Medical Information

Command Pilot (Instructor)

The command pilot had been examined by a Designated Aviation Medical Examiner on 19 August 2017 and was issued with a CASA Class II Medical Certificate valid to 9 August 2019.

Student Pilot

The student pilot was not required to hold a medical certificate but had informed the club that they were not suffering from any physical condition that would preclude them from operating a glider.

1.6. Aircraft information

The ASK 21 is a two-seat, mid-wing glider with 17m span. It has docile flight characteristics that makes it ideal for flight training, combined with easy handling – both on the ground and in the air. The two-part double-tapered wing is built as a fiberglass sandwich with hard foam core, and the wing spars use a conventional tongue and fork extensions to ensure a straight-forward wing assembly. There are very effective large dive brakes on the wing upper surface which give very good manoeuvrability, even in the case of a steep landing approach. Aileron, elevator and airbrakes are actuated via pushrods, and the rudder is actuated by stainless steel cables. The tailplane is fitted with an automatic elevator connection which, on rigging8, ensures that the stabilizer can be assembled only when the elevator control is correctly connected.

1.7. Meteorological information

The wind was about 320 degrees at about 10 -15 kts. No cloud was visible.

1.8 Aerodrome information

McCaffrey Field is uncertified Aeroplane Landing Area (ALA) operated by the Darling Downs Soaring Club and situated approximately 4.5 NM WNW of Jondaryan Qld. It has a single grass runway (12/30) of 1200 metres length. The airfield is 1,215 ft above mean sea level. The Common Traffic Advisory Frequency is 126.7 MHz. The terrain around the airfield is flat with few trees, and there are no obstacles, hills or mountains of any influence in the vicinity.



1.9 Flight Recorders

Figure 6: McCaffrey's Field (Google Maps)



Accident and Incident Summaries

The Gliding Club has fitted 'dittolog' to their aircraft, which is a system that captures pertinent flight data from the aircraft's FLARM device and automatically uploads this data to a wireless base station connected to the internet. A data file providing fight parameters for the accident flight was obtained from the base station.

1.10. Wreckage and impact information

The aircraft impacted wings level in a steep nose down attitude. The aircraft came to rest upright, about 1 metre from the point of impact in the direction of flight (030 Magnetic). The underside of the nose took the initial impact, forward of the nose wheel. The main wheel did not contact the ground during the initial impact, as the fibreglass wheel fairing showed only pre-existing damage. Both wing leading edges contacted the ground during the initial impact. The fin and horizontal stabiliser separated from the fuselage at the base of the fin (refer Figure 5). There was other damage to the fuselage aft of the wings indicating large compressive forces had been applied to the top of the fuselage. The left wing rotated forward far enough to tear the drag pin fitting from the root rib, crushing the left side of the fuselage into the rear cockpit in the process. Damage to the front of the aircraft, including the front cockpit was catastrophic, and the rear cockpit was also heavily damaged. In both cockpits the survival space had been severely compromised. Initial examination of the wreckage showed that all extremities of the aircraft were present at the crash site, as were all control surfaces. The control surfaces were not able to be moved with the aircraft assembled. 1.10.1 Elevator Control System

The separation of the fin and horizontal stabiliser had severely bent the elevator pushrod, but it was confirmed as intact, and connected to the elevator bellcrank at the base of the fin. When the fin was separated from the remainer of the wreckage by cutting the pushrod, the elevator system in the fin was found to be complete and operating smoothly. The elevator was still correctly engaged with the fitting at the top of the pushrod in the fin. The horizontal stabiliser was still connected to the top of the fin by the bolt, which was locked and taped. The bolt was easily removed using a standard Allen Key. The horizontal stabilizer mountings did not appear damaged. The forward end of the elevator pushrod still ran through all the fairleads but the aft-most fairlead had been torn from its mounting by impact forces. The pushrod could not be moved in a forward/aft direction and was intact and still connected to the lever on the aft end of the aileron/elevator torque tube. Detailed examination of the control system showed that both control sticks remained connected to the torque tube, although the front control stick was bent forward by impact forces, and the torque tube itself was bent and flattened. The supports at each end of the torque tube had separated from the structure as a result of impact forces, but all fasteners were present and correct. The aileron/elevator rocking arm was still properly attached to the rear control stick, and the pushrods to the elevator were intact and working. The elevator control system was intact at impact. 1.10.2 Elevator Trim Controls

The elevator trim system in the ASK-21 is a spring bias system. A trim lever is located to the left at the base of each control stick, and these are joined at the bottom by a pushrod. This pushrod is connected to the aileron/elevator torque tube between the two cockpits by two springs, one at each end of an adjuster plate, the centre position of which is changed by moving either trim lever. This entire mechanism is located in the forward fuselage, under the front seat and aft instrument panel. Examination of the trim system showed that both trim springs were intact, and still connected to the aileron/elevator torque tube at one end and to the adjuster plate at the other. The adjuster plate was still correctly attached to the trim pushrod. However, the forward end of the trim pushrod was broken off at the weld at the base of the forward trim lever. Crushing and bending of the pushrod adjacent to the failure, as well as buckling at the after end of the pushrod, indicated that the pushrod had been subjected to substantial longitudinal forces at impact. There was no evidence of any pre-existing defect.



Accident and Incident Summaries



Figure 7: Trim Pushrod Forward end showing failure



Accident and Incident Summaries



Figure 8: Trim Pushrod rear end



Accident and Incident Summaries



Figure 9: Trim System showing Trim Springs and Trim Pushrod

1.10.3 Aileron Control System

Both ailerons were immoveable with the aircraft rigged, and both aileron l'hotellier fittings in the fuselage centre section were found properly connected and locked by their locking sleeves. Once the wings were removed, both ailerons moved normally. The pushrods within the fuselage remained connected to the aileron/elevator rocking arm, which was still connected correctly to the rear control stick and moving freely. All aileron control system fasteners in the fuselage were present and correct. The aileron control system was intact at impact.

1.10.4 Rudder Control System

The fin and horizontal stabiliser separated from the fuselage at the base of the fin, and one rudder cable had snapped as a result. The aft end of both cables were still attached to the rudder horns by their respective bolts and 'nyloc' nuts. Despite the disruption of the forward fuselage, and the broken rudder cable, it was evident that the rudder control circuit was intact until impact.

1.10.5 Airbrake Control System

The airbrakes were found closed but not locked. Neither the airbrake lever nor the airbrakes could be moved as a result of the damage to the forward fuselage and the dislocation of the left wing. Both airbrake l'hotellier fittings in the fuselage centre section were found properly connected and locked by their locking sleeves. The disruption to the forward fuselage, and the displacement of the wings during impact prevented determination of the airbrake position at impact. There were no witness marks. The left airbrake had been forcefully driven out beyond normal full travel as a result of the left wing's displacement under impact forces. The inboard airbrake arm had crushed the inboard end of the airbrake box, but there was no such damage on the right airbrake indicating that the damage was asymmetric and the result of the impact. The airbrake pushrod in the cockpits was severely bent as a result of impact forces, but all connections were in place and once the wings were removed, movement of the airbrake handles produced motion in the bellcranks holding the l'hotellier fittings. The airbrake control system was intact at impact. 1.10.6 Front Cockpit



Accident and Incident Summaries

Virtually no intact structure remained of the front cockpit. The whole nose structure, including canopy, canopy frame, instrument panel and fuselage side and floor were reduced to fragments. As result, the survivable space in the front cockpit was severely compromised during the accident sequence. The aircraft was equipped with five-point harnesses. As a result of the fragmentation, the anchorages for the crotch strap and for both ends of the lap belt had become detached from the structure. The two shoulder belts were intact and attached to front cross-bar, but the bar was severely bent and detached from the cockpit walls on both sides. Impact damage was consistent with high 'g' deceleration and a steep nose down attitude at impact.

1.10.7 Rear Cockpit

The rear cockpit was severely damaged, mostly forward of the front of the rear seat, but deformation of the forward fuselage, and possible intrusion of the leading edge of the left wing into the rear seat, together with much of the forward fuselage and front cockpit meant that the survivable space in the rear seat was severely compromised during the accident sequence. The rear seat lap belts had torn their anchorages from the structure, as had the crotch strap. The two shoulder straps remained intact and attached to the after cross-bar.

1.10.8 Harnesses

The aircraft was equipped with two ETSO C114 five-point harnesses. As mentioned above, the anchorages of the crotch and lap straps of both harnesses were torn out during the crash sequence by failure of the associated structure. However, the harnesses remained effective up to that point, indicated by the fracture of the tang of the crotch strap on both harnesses. Both tangs appear to have failed by bending. The buckle from the rear harness appears to have sustained internal damage. The pin for the crotch strap was not moving freely and was not extending as far as the other pins in the buckle, or the pins in the buckle from the forward harness. This damage would have resulted from the same forces that caused the failure of the rear seat crotch strap tang. These forces had to have been considerable and applied before the strap anchors failed. The peak longitudinal acceleration during the crash sequence would have been in the order of 50 to 60g10, and with each harness restraining a mass of 80 to 100 kg, extreme loads would have been imposed on the harnesses and buckles. Both harnesses were manufactured by Schroth and fitted with buckles Part Number SL 10.02 manufactured in week 40 of 2014. According to Schroth Service Information Letter SIL SSP-00711 these harnesses may be used for aerobatics with a maximum life of five years. These buckles are not affected by EASA AD 2017-022512 that was issued on 17 November 2017. As the glider was less than 3 years old, the buckles were serviceable.



Accident and Incident Summaries





Accident and Incident Summaries



Figure 11: Rear Harness with failed crotch strap tang

1.11. Medical and pathological information

Autopsies were performed on both the instructor and the student. Within the limits of the autopsy, no natural disease which could have caused or contributed to the accident was positively identified. Post mortem examination of the:

- command pilot identified marked atherosclerotic narrowing of one of three main coronary arteries, but there was no associated luminal thrombosis or myocardial infarction.
- student pilot identified severe coronary atherosclerosis, but there was no associated luminal thrombosis or myocardial infarction. The medical Examiner noted that "severe stenosis of the coronary arteries may be asymptomatic but may also cause sudden incapacitating arrhythmia and even death. The contribution of this finding to the events leading to the glider collision cannot be determined."

The toxicological examination did not reveal any factors which might have influenced the performance of the flight crew.

1.12. Survival aspects

Because of the angle and severity of impact, damage to the front of the aircraft, including the front cockpit, was catastrophic, and the rear cockpit was severely damaged. In both cockpits the survivable space had been severely compromised during the accident sequence. The accident was not survivable. Both pilots were removed from their respective seats by witnesses who arrived at the scene of the crash shortly after it had occurred and were laid next to the cockpit. Resuscitation attempts were initiated but then abandoned.



Accident and Incident Summaries

Both pilots were subsequently pronounced dead by ambulance personnel. Based on height, airspeed and impact angle, the time from normal flight on final approach to impact was calculated to have been between 0.36 and 0.54 seconds. The impact force was calculated to have been between 11g and 12g. Harnesses in both the front and back seats had held, but the structures from which they are suspended had shorn in various places. Both control sticks had been bent flat forward, presumably by the impact of the respective bodies, likely resulting in substantial soft-tissue and internal damage.

1.13. Tests and research

An extensive program of test-flying the ASK-21 was initiated by the GFA, with the help of German colleagues near Heidelberg, the Beverley Soaring Society in WA and the Gliding Club of Victoria in Vic. Instructor and student weights were matched as closely as possible, and the glider was instrumented with cameras (where possible to the side and to the front) to record flight angle, height and airspeed information. The purpose of the tests and research was twofold:

- Establish whether the ASK-21 could have entered a dive with the steepness and suddenness of VH-GVJ without active pilot control. These tests were mostly conducted in Germany shortly after the accident. They were meant to examine (and possibly rule out) incapacitation on either or both of the pilots.
- Establish the angle and speed that can be obtained within 50ft of height from flight at approach speed with half airbrakes, into a sudden bunt with full airbrakes. These tests were performed in Victoria and WA. The results of these tests and the research were as follows:
- It is impossible to make the ASK-21 dive into a downward angle of 650 by itself, independent of front-seat pilot weight, trim setting or airbrake manipulation or height available. The maximum downward angle achieved during 50 ft of height loss in the German tests was about 400 when pilot incapacitation was simulated.
- The airbrakes on the ASK-21 used in these tests did not move noticeably when the handle was released and the glider was nosed over.
- The impact angle cannot have resulted from a stall at 50ft.
- When bunted deliberately (taking the glider from flight at approach speed of 62 kts with airbrakes half out, and then nose fully forward and airbrakes fully out), the ASK-21 will achieve a downward angle of about 800 and an airspeed of about 70 kts within the first 50ft of height lost. Results were consistent in repeated tests. As this was done, the pilot-not-flying, who had been cradling the controls loosely (like an instructor might), reported his hands flying involuntarily upwards to the canopy due to the negative 'g' of the bunt. The half-second of the manoeuvre under negative 'g' proved insufficient to regain a grasp of the controls. Although a flight log was retrieved from the Dittolog system, the low sampling rate of 5 seconds did not allow for any meaningful conclusions to be drawn about the last seconds of the flight.

1.14 Useful or effective investigation techniques

Two witnesses were interviewed. They were the instructor pilot's business partner/wife and another student pilot. Both witnesses had deliberately been visually following the flight, circuit and approach of the glider from the ground, verbalising and discussing what they saw as a way of instructing the student on the ground. The witnesses were placed down the runway, some 600m from the crash site. Height and flight path information (apart from the impact angle, for which the wreckage and the disturbed ground was used) relied on by this investigation come largely from these witness statements, and in part from normal procedures used at this field. One of the witnesses reported that the student had been learning about the interaction between the airbrakes and control stick on his last flight on the day before, and that he could have *"a death grip"* on the control stick; indicative of higher student tension at this stage of flight. A tight grip on the control stick is usually accompanied by coarser control movements using arm muscles, in contrast to finer control movements using wrist and fingers with a more relaxed grip. Other than that, this student was said to have a relatively good aptitude for flying, particularly given his age. The instructor was known as being both prudent and careful.

2. ANALYSIS



Accident and Incident Summaries

2.1. General

The command pilot held appropriate flight and medical certificates, and was trained and qualified for the flight. The aircraft was properly certificated, and there was no evidence that aircraft maintenance was a factor in the accident. Flight tests were conducted in aircraft of the same type to investigate aircraft behaviour when the controls were released, and also to determine the level of human intervention in order to replicate the flight path as described by the two witnesses. Weather was not considered to be a factor in this accident.

2.2 Flight operations

The glider was launched by a Piper PA-25-235 Pawnee at 0933 hours from runway 30 into the North-West. About five minutes later the combination was flying on a North-Easterly heading when, at a height of about 2,300 ft AGL, the command pilot released from tow. The glider then turned to the right about 90 degrees and then was established on a South-Easterly heading. After about 30 seconds the glider turned onto a North-westerly heading. At 0941 hours, when at about 1,700ft AGL and about 4.3 NMs (8kms) from the runway threshold, the glider was turned through 180 degrees and flown on an extended downwind leg back towards the airfield. Base leg was joined at 0945 hours at a height of about 1,000ft AGL, and was flown on a slight angle away from the runway. At 0946 the glider was turned onto final approach at a height of about 700ft AGL and about 1,600 metres from the runway threshold. Barograph records indicate the approach was steepened at least twice, which is in line with the tow pilot's observations: "Initially there was no airbrake applied. Then some airbrake came out for several seconds; then airbrakes went away for several seconds; then airbrake deployed again." Refer figures 12 to 14 following.





Accident and Incident Summaries



Figure 13: Flight path showing height above ground (max. 2,300 ft).



Accident and Incident Summaries



the manner witnessed. In fact, these tests confirmed that it is impossible to make the ASK-21 pitch down 60 to 65 degrees as was observed without one of the crew members actively and deliberately manipulating its controls. The possibility of an inadvertent stall was also ruled out, as it is impossible for an ASK-21 to achieve



Accident and Incident Summaries

an angle of 65 degrees within a height of 50ft, even with airbrakes fully extended. Furthermore, both witness observations about the final approach are inconsistent with a stall. The student pilot's instructor on the previous day was the tow pilot for the accident flight. In their recorded interview with the GFA's accident investigation, the tow pilot stated: "So, I flew with him the previous day – four flights making reasonable progress, but we weren't up to doing anywhere near landings or anything. I was talking him down and he could hold speed control and all that sort of thing and good coordinated turns. So yesterday when I flew with him I had him down to lining up on final and then I was taking over from final onwards, so he wasn't really up to landings, as of yesterday afternoon." "One comment I wanted to make which may be relevant is when I did the take-offs with him yesterday, I said I just want you to come on the controls and feel the controls but be loose on the controls just because we had done – [the Trainee pilot] was much more advanced with his flying and we were doing briefings for [the Trainee pilot] so [the Student pilot] was listening to the briefings – so I said I'm happy for you to come on the controls, feel the controls as I'm doing the take-off but don't impede my control inputs, and all I can say is when he got on the controls he was solid as a rock. He's a big man and really firm and I had to prompt him to get off the controls, and when I was doing aero-tow training with him yesterday, he had a little bit of trouble with that and I told him to fly with a finger and a thumb because he was flying too rigidly, so I don't know if there was a bearing if he was on the controls whether something..." The GFA's investigator asked whether it was likely that the command pilot would have been similarly coaching the student, to which they responded: "He may have been, similar to me, just saying stay on the controls with me while I do this. He certainly, [the instructor] had done previous flights, so he would have made an assessment of his skills at that point. So, it is quite possible he was on the controls, but I don't know." Later in the interview the tow pilot stated: "What else can I add in there. He was just an average student. A 60-year-old student doing better than your average 60-year-old who have heaps of trouble even getting coordinated but he was doing – well you can have a look at his flight card if you like. But yesterday we did stalls, we had a lot of thermals, we had an opportunity to cover lots, so we did stalls and use of airbrakes, so he did quite a bit of exercise using the airbrakes, putting them away and adjusting." When prompted for more detail by the GFA's investigator, the tow pilot explained: "When I was doing the airbrake exercise, which is a standard thing, you know, you say now I want you to fly 60 knots and you pull the airbrake out and there's an adjustment on the nose to keep it at 60 knots - I wonder whether he's exaggeratedly...." The tow pilot was suggesting the student may have forcefully lowered the nose in response to the airbrakes coming open. Review of the Student pilot's 'Glider Pilot Certificate Pre-Solo Training Card' revealed they had been assessed as competent in the following relevant exercises after 6 flights:

- Primary and secondary effects of the controls;
- Straight flight at various speeds and trim;
- Use of airbrakes;
- Low speed handling; and
- Stall recognition and recovery. The description of the student pilot being *"solid as a rock"* on the controls, using excessive force, and *"flying too rigidly"*, is normally associated with student tension. This often manifests with an overly firm clamping grasp on the control stick with all fingers and thumb, a rigid wrist and coarse movements of stronger arm muscles. This can be exacerbated by excessive force on rudder pedals and use of upper leg muscles, tensing up the entire body. It can be difficult to overcome such forces used by a big, strong pilot. Students often need to be instructed on using a more relaxed grip, with greater 'feel' of controls, using wrist muscles and finger pressure for finer control movements.

The transition from a stabilised approach (with airbrakes half open) into the flare, requires a gradual backward pressure on the elevator to arrest the rate of descent. If airbrakes are extended during the approach, then a light forward pressure on elevator might be required to retain a safe approach speed until beginning the transition into the flare. These movements require fine motor control of elevator, not coarse movements with massive pitch angle changes. The observed sudden change in pitch angle close to the ground indicates that the pilot on the controls was probably the student pilot, with an excessively coarse



Accident and Incident Summaries

forward push on the elevator. Due to inexperience, the student pilot may also have not recognised that at about 50ft, they should be preparing to initiate transition into the flare. The student pilot was also aware of the concept of maintaining a 'Safe Speed Near the Ground' and had been introduced to turns and aerotowing. When training students in the use of the airbrakes, the GFA Instructor's Handbook states (page 60): "In the early stages it may be helpful for the student to fly the approach using the primary flight controls while the instructor controls the airbrakes/spoilers. It is not necessary with all pilots, but some students respond very positively to this technique, which significantly reduces their workload in the early days of learning landings." Consistent with the information obtained from witnesses, tests and research, as well as wreckage analysis, the accident may have resulted from an instructional sequence in which the student was allowed to handle the control stick on final approach, while the instructor manipulated the airbrakes. As per the tow pilot's comments, it is evident the student had been allowed to fly the circuit down to the final approach the day prior, and that the student was cognisant of the need to maintain safe speed near the ground and of the need to lower the nose of the glider to maintain airspeed when the airbrakes were opened. It is likely the command pilot was continuing the theme established by the earlier instructor and was allowing the student pilot to fly the circuit and approach while they manipulated the airbrakes. 2.3. Aircraft

Mechanical failure on either the elevator control, airbrake or trim system was ruled out.



Figure 15: Three-view drawing of ASK-21

2.3.1 Aircraft maintenance

The Schleicher ASK-21 glider was purchased new by the Gliding Club and delivered in April 2015. Its first maintenance Release was issued on 22 April 2015. The aircraft was maintained in accordance with GFA requirements, using GFA Form 2 and the ASK-21 Maintenance Manual. The last annual inspection was completed on 23 April 2017. At the time of this inspection the aircraft had flown 577 hours over 1,288 flights. There were no open minor defects in the Maintenance Release and only one that had been closed off. The Maintenance Release had no entries for major defects. The command pilot conducted the Daily Inspection and certified the aircraft fit for flight by signing the Maintenance Release at 0900 hours. 2.3.2 Post-accident analysis



Accident and Incident Summaries

While the forward fuselage of the glider was damaged severely, examination of the control systems showed that all flight controls circuits except the elevator trim and the rudder were intact and connected to their respective control surfaces. Failure of one rudder control cable was the result of impact forces and the separation of the fin and horizontal stabiliser during the crash sequence. Damage to the inboard end of the left airbrake box was the result of the violent deployment of the left airbrake as the left wing swivelled forward during the crash sequence. Failure of the crotch straps on both harnesses was the result of extreme loads imposed during the crash sequence, and before the structure to which the crotch straps were anchored failed as a result of structural disintegration.

2.2.2.1 Failure of the Elevator Trim Pushrod

The elevator trim system in the ASK-21 is a spring bias system. A trim lever is located to the left at the base of each control stick, and these are joined by a pushrod. This pushrod is connected to the elevator/aileron torque tube between the two cockpits by two springs, one at each end of an adjuster plate, the centre position of which is changed by moving either trim lever. Once the trim has been set, the elevator trim pushrod only carries the loads imposed by the trim springs, and when the aircraft is flying at the trimmed speed, the loads imposed by the two springs cancel each other out; there are no net loads on the ends of the trim pushrod. Loads are only imposed as the trim levers are moved, or if the control sticks are moved significantly away from the trimmed position. The trim levers are connected to the base of the control sticks by a friction brake at each end, and these are set to share the task of preventing the trim pushrod from moving except when a trim lever is moved. Hence, even if the trim pushrod were to fail at one end, the friction brake at the other end would preclude free movement of the trim pushrod, although it would not necessarily prevent it entirely. The elevator trim pushrod was broken at the weld near its connection to the forward trim lever. Crushing and bending of the pushrod adjacent to the failure, as well as buckling at the after end of the pushrod, indicated that the pushrod had been subjected to substantial longitudinal forces. These cannot have been imposed by control forces as the only connection to the trim pushrod is through the two trim springs. The trim pushrod runs parallel to the elevator/aileron torque tube and is the same length. During the crash sequence, the elevator/aileron torque tube was bent and buckled, as was the trim pushrod. Examination of the wreckage showed that the resultant, damaged lengths of the two pushrods were almost identical (See Figures 7 to 9). Therefore, it is most likely that the trim pushrod and the elevator/aileron torque tube remained connected during the crash sequence, and the trim pushrod failed as a result of impact forces.

2.3.3 Mass and balance

The structural strength of an aircraft places upper limits on the weights it can support. The wings are selfsupporting but the fuselage and its attachments (tailplane, pilot, luggage, etc.) are suspended from the wings or spar. The designer of the aircraft has placed an upper limit on the weight in the fuselage (or nonlifting parts) which must never be exceeded. However other more critical issues arise when it is realised that the aircraft may not even fly if it is too 'nose heavy 'or too 'tail heavy', that is, if the centre of the mass (centre of gravity (CG)) is too far forward or too far aft. The consequences of too little weight at the nose, resulting in a CG aft of the aft limit, are that the aircraft may pitch up, be unstable, even uncontrollable, impossible to trim, and impossible to recover from a stall or spin. Too much weight in the cockpit will result in a forward out-of-range CG, making the pilot use full back stick/elevator (beyond trim range) to maintain speed, leaving no capacity to flare the glider on landing. The aircraft's weight and balance were last calculated on 25 April 2015. Assessment of the weight of the flight determined the aircraft was flown well within the prescribed centre of gravity limits.

2.4. Human Factors

The judgment of whether and when to allow a student to manipulate the controls close(r) to the ground is known to be a difficult one. In this case it was distributed across a husband-and-wife team who were alternating the days they were teaching this student during the ab-initio course. On the day before the accident flight, the student had been taught by the other instructor about the workings of the airbrakes and had also been taught how to recover from a stall, which involves a resolute forward movement of the control stick. The accident flight was the student's second on that day. Both flights had been short, and stall practice would not have been included, so the instructor this day may not have experienced the stick-



Accident and Incident Summaries

forward response from this student. The student had not yet developed fine motor skills in his flying and was known to be somewhat heavy-handed. When on short final, either in response to instructions or on the basis of what he had learned about airbrakes and nose attitude the day before, he may have applied a version of his freshly learned stall-recovery stick-forward response. Instructors often loosely cradle or 'shadow' the control stick when students fly closer to the ground. Instructors are trained to adopt a "defensive posture"; and to have appropriate "thresholds of intervention" for particular flight sequences. Put simply, a minor variance from intent may result in the instructor asking a question, or making a verbal command, whilst a major variance would result in a physical intervention such as taking over control. All of this assumes there is time to react, so as the time available reduces, the demands on the instructor increase. It is possible for the instructor to prevent the control stick from moving backward or sideways by blocking its path, but this is much harder for forward movements, particularly if the instructor was holding the airbrake handle in his left hand, in which case only his right hand would have shadowed the stick. A sudden forward movement would have forced his hand forward with the stick, or for the stick to be forced past his fingers with relative ease. In addition, the instructor's hand may well have flown upward from the control stick because of negative 'g' forces (see section 1.14). Even if the control stick was within the grasp of the instructor, human reaction time (also known as response latency) in cases such as this one vary between 200 and 400 milliseconds, which would have been barely (or simply not) enough to safely intervene. Once established in the observed steep nose down attitude, the height required to recover to a normal landing attitude was far more than the height available.

2.5 Survivability

The crash was nonsurvivable and the deceleration forces exceeded those of human tolerance.

3. CONCLUSION

The accident was almost certainly the result of controlled flight into terrain, that is, an airworthy aircraft under the control of the flight crew was flown unintentionally into terrain.

3.1. Findings

- 1. The command pilot was certified and qualified for the flight in accordance with existing regulations.
- 2. The maintenance records indicated that the aircraft was equipped and maintained in accordance with existing regulations and approved procedures.
- 3. The aircraft was airworthy when dispatched for the flight.
- 4. All flight controls were operating correctly at impact and suffered damage due to the forces of impact with terrain.
- 5. No other defects were found that would have adversely affected the airworthiness of the aircraft.
- 6. The mass and centre of gravity of the aircraft were within the prescribed limits.
- 7. There was no evidence of a stall before impact.
- 8. There was no evidence that either of the flight crew suffered any sudden illness or incapacity which might have affected their ability to control the aircraft.
- 9. Toxicological tests were negative.
- 10. The accident was not survivable due to the magnitude of the deceleration forces.

3.2. Causal factors

The accident most likely resulted from an instructional sequence in which the student handled the control stick on final approach while the instructor manipulated the airbrakes. The student pilot's likely coarse elevator control inputs were inconsistent with a safe transition from a stabilised approach into the flare and landing, instead resulting in a sudden and unrecoverable steep dive into the ground. This sudden manoeuvre, initiated at very low level, was beyond the limits of instructor intervention and safe recovery.

4. SAFETY RECOMMENDATIONS

There is no single error or latent factor that can be addressed to prevent an accident of this kind. The following recommendations are made, to reduce the likelihood of such circumstances in the future:

1. GFA provide further educative material to instructors, in the form of an Operational Safety Bulletin, and in the GFA Training Manual under development, on safe instructing sequence, instructor



Accident and Incident Summaries

defensive posture, thresholds of intervention, reaction time (response latency) and cognitive biases regarding student performance.

- 2. GFA develop and publish educative material for widest distribution online, in Gliding Australia and through clubs, on the effects of pilot tension on muscular movements and glider control, more effective fine control methods, relaxation techniques and pilot self-awareness.
- 3. GFA reinforce the importance of progression through the GPC training syllabus and reinforcement of key concepts of control and energy management.
- 4. GFA might also encourage sharing of "I learned about gliding instructing from that" case studies, for use in Flight Instructor Refresher Courses and Instructor Training, drawing upon accidents and near miss occurrences related to instructor assumptions, biases, interventions, unplanned events and student behaviours outside expectations.

Date	22-Sep-2017	Region		NSWGA		SOA	R Repo	ort Nbr		S-	1043
Level 1	Operational		Level 2	Airc	raft Co	ontro		Level	3	Hard landi	ng
A/C Mod	el 1		DG-1	000S		A/C	Model	2			
Injury	Minor	Dama	age S	Substantial	Pha	ise	Landi	ng		PIC Age	21
The glide	r was establishe	d on a sta	ble fina	l approach,	but th	e flar	e was e	execute	ed hig	her than no	rmal
followed	by a rapid rate o	of descent	and a h	neavy landin	g caus	sing tl	he maii	n unde	rcarria	age to colla	ose. There
were only	y very minor inju	ries to th	e stude	nt, and no ir	njuries	to th	e Instr	uctor.	The in	structor sta	ted that the
student v	vas struggling to	maintain	circuit	speed on th	e base	e leg c	of the c	ircuit a	nd th	is continued	onto the
final app	roach. The stude	nt was al	so havin	g difficulty ı	mainta	aining	direct	ional co	ontro	l on final ap	proach and
the instru	ictor was promp	ting the s	tudent	to maintain	the ru	nway	centre	eline. O	n late	e final appro	ach the
instructo	r noticed the airs	speed wa	s decayi	ng as the ai	rbrake	e was	being o	deploye	ed. Th	e instructor	assumed
control a	nd applied forwa	ard pressu	ure on t	ne control c	olumn	to lo	wer th	e nose	and r	egain airspe	ed. The
aircraft ir	npacted the grou	und direc	tly on th	ie main geai	r, follo	wed	by the	nose ge	ear ar	nd tail whee	. The main
undercar	riage collapsed c	on impact	. The In	structor app	lied fu	ill bao	ck stick	and fu	ll airb	rakes and t	ne airframe
came to i	est approximate	ely 95 me	tres froi	n the initial	main	gear v	witness	s mark.	Inves	tigation rev	ealed the
student p	oilot was on their	eleventh	n flight i	n a glider an	d had	not f	lown fo	or 5 mo	onths.	Although th	ne Instructor
was awar	e the student ha	not flo	wn for a	n extended	perio	d, the	stude	nt's tra	ining	records sho	wed they
had prev	ously demonstra	ated satis	factory	approaches	and la	indin	gs, so t	he insti	ructor	chose to di	rect and
monitor	he approach and	d landing	rather t	han demon	strate	. The	investi	gation	also io	dentified the	at the
instructo	r had not mainta	ined a de	efensive	stance with	their	hand	s near t	the rele	evant	controls in o	order to
react qui	ckly during the a	pproach	and land	ling. The cau	usal fa	ctors	include	ed a lat	e and	l inappropri	ate
intervent	ion by the instru	ctor to re	egain air	speed on sh	ort fir	ial. Tł	ne nose	attitu	de wa	is abruptly l	owered
resulting	in an excessively	steep de	escent fr	om which a	norm	al flai	re and	landing	was	improbable	. Witness
accounts	suggest the airb	rake rem	ained d	eployed thro	bugho	ut ins	tead of	fbeing	close	d to arrest t	he rate of
descent.	The instructor u	ndertook	remedia	al training fo	ocusse	d on	studen	t plann	ing ar	nd managen	nent,
instructo	r intervention an	d correct	metho	ds for rectify	ing in	corre	ct and	mishar	ndled	student app	roaches and
landings.											



Accident and Incident Summaries



Date	23-Sep-2017	Regior	า 🗌	NSWGA		SOA	AR Repo	ort Nbr		S-	1046
Level 1	Operational		Level	I 2 Mis	scellar	eous		Level	3	Rope/Ring Strike	s Airframe
A/C Mad	ol 1		L Trah C	102 Turin II		A/C	Madal	2		otine	
A/C IVIOU	erit	Ċ.	100 G	103 I WIII II		A/C	Nouei	Z			
Injury	Nil	Dam	age	Minor	Pha	ise	Launo	h		PIC Age	41
						1	1 1 0		1.11	· ·	

Just as the slack was taken up in the aerotow rope, the glider lurched forward and the tension on the rope relaxed. The wingtip signaller, who did not notice the glider had overrun the rope and that the tension had come off the rope, gave the 'all out' signal. The tow pilot accelerated rapidly, causing the rope to snatch. The weak link broke and the rope sprang back, with the weak link striking the fuselage in front of the canopy on the starboard side. Investigation revealed a number of contributing factors:

- 1. The runway sloped downhill in the direction of launch, making it easy for the glider to roll forward.
- 2. The wingtip runner was a new student pilot who had only been at the club for two weeks. Although briefed on the duties of a wingtip runner, the student did not fully appreciate the effect of a slack rope at launch.
- 3. The two pilots in the glider did not release the rope, despite being aware that the glider had significantly overrun it. The Club CFI has reminded pilots to release immediately in the event of a suspected overrun.

Date	23-Sep-2017	Regior	1 I	GQ		SOA	AR Repo	ort Nbr		S-	1042
Level 1	Operational		Level 2	Airc	raft C	ontro		Level	3	Control iss	ues
A/C Mod	el 1		ASK	-21		A/C	Mode	2	Ces	sna 150E	
Injury	Nil	Dama	age	Nil	Pha	ase	Launo	h		PIC Age	68
Just after becoming airborne, and at a safe height, the instructor commanded the student pilot to descend											
into the l	into the low tow position. As English is the student's second language, the command was misunderstood										
and the s	tudent climber h	nigher an	d the tov	v plane disa	ppear	ed fr	om vie	w. The	instr	uctor took c	ontrol
quickly a	quickly and restored the glider to the normal low tow position and the rest of the flight was conducted										
uneventfully. The student pilot had power flying experience but was on their 11th flight in a glider. The											


Accident and Incident Summaries

instructor reported that they were surprised just how quickly the glider got out of station. If the glider is allowed to climb rapidly behind the tug, it can very quickly become impossible to prevent it accelerating upwards in a slingshot action (rather like a winch launch), and tipping the tug over into a vertical dive. Once that has happened only height can save the tug pilot from disaster. Downward displacement of the glider to a position below the slipstream is quite acceptable, but upward displacements are much more critical. The glider pilot must release immediately if the glider is going high and the tendency cannot be controlled, or the pilot loses sight of the tug. The trainee should not attempt the take-off and early part of the launch until he can maintain position successfully during the latter part of the tow. The demonstrations and the trainee's early attempts shouldn't begin until the tow reaches a height and position from which landing back on the airfield poses no problems.

Date	30-Sep-2017	Region	1		VSA		SOA	AR Repo	ort Nbr		S-:	1049
Level 1	Operational		Leve	<u>2</u> او	Airc	raft Co	ontro	Ĩ	Level	3	Loss of cor	ntrol
A/C Mod	el 1		Ľ	S 8-1	18		A/C	Model	2			
Injury	Fatal	Dama	age	W	/rite-off	Pha	ise	Outla	nding		PIC Age	

GFA Field Investigation

INTRODUCTION

On 30 September 2017, at 1352 Australian Eastern Standard Time, and while flying in the vicinity of Benalla Victoria, a Rolladen Schneider Flugzeugbau GmbH, LS8-18 glider departed controlled flight following a low-level right-hand turn and impacted the ground. The aircraft rebounded approximately 8 metres from the impact point and came to rest upright. The aircraft was substantially damaged and the pilot suffered fatal injuries. The aircraft crashed onto a rural property approximately 230 metres South-South-West of Murray Road Benalla, between the Midland Highway and the Benalla-Yarrawonga Road. The accident site was approximately 3 kilometres north of the Benalla Aerodrome. The accident was witnessed by a passing motorist, who saw the aircraft low in the sky and coming in at a steep descent angle just before it struck the ground. The witness arranged for the emergency services to be contacted and waited for them to arrive at the entrance to the accident site. Police and emergency services attended the scene and confirmed the pilot was deceased. The Australian Transport Safety Bureau (ATSB) was notified of the accident shortly thereafter but declined to investigate. The Gliding Federation of Australia (GFA) provided technical assistance to the Victoria Police.

FACTUAL INFORMATION

History of the flight

This was the pilot's first flight in the aircraft, having purchased it in April 2017. It was also the pilot's first flight on type, although he had flown earlier model gliders from this manufacturer. It is believed the pilot's intentions were to conduct the post-maintenance assessment flight and explore the handling qualities of the aircraft. It is unlikely the pilot intended to fly a cross-country task as the conditions on the day were not conducive to such, and he did not record the flight in the Search and Rescue Register as is required by the gliding club for all cross-country flights. The pilot arrived at the glider launch point on glider runway 26 around 13:30 and positioned the aircraft at the front of the launch grid as directed by the Duty Instructor. Another club member assisted the pilot with the launch and observed the pilot conduct a *"measured and methodical pre-flight"*. The tow plane was positioned in front of the aircraft, and the tow rope was then attached to the aircraft. Data from the pilot's portable flight logger recorded the take-off time to be 13:43:51. The flight logger showed the tow plane and glider combination turned onto a northerly heading around 400ft AGL and then turned on a north-easterly heading when at about 1,000ft AGL.



Accident and Incident Summaries



The tow pilot recalled towing the glider towards the nearest clouds indicating lift, and that it was a "bumpy tow". Data from flight logger disclosed the pilot released from the tow at a height of 1,563ft AGL at 13:46:25.



Accident and Incident Summaries



Figure 2: GPS Altitude Record

The data indicates the glider and tug combination flew into rising air but when the glider pilot released and turned to the right, the glider encountered descending air. The tow pilot was surprised by the "very early" release from tow by the glider pilot as they had not yet reached the clouds. Immediately upon release the glider pilot completed a 360 degree turn to the right and then resumed the north-easterly heading, continuing towards the clouds. The pilot flew for three kilometres and then, at a height of about 1,000 ft AGL at time 13:48:28, turned through 180 degrees and headed back along the track previously flown. Approximately 30 seconds later, and at a height of about 880ft AGL, the pilot turned right 90 degrees and then back onto track where the aircraft encountered an area of reduced sinking air. These two turns suggest the pilot was heading towards potential sources of rising air to keep the aircraft airborne. The pilot was unsuccessful in finding rising air and at about 700ft AGL the aircraft turned onto a southerly heading directly towards the aerodrome. At 13:51:15 the aircraft was approximately 3kms north of the aerodrome at a height of about 450ft AGL. In response to an indication of rising air, the pilot conducted a 360 degree turn to the right but was unsuccessful in establishing a climb. Upon completion of the turn the pilot resumed a heading towards the aerodrome. At 13:52:28, after travelling approximately 600 metres in a south-westerly direction, and at a height of about 130ft AGL, the aircraft commenced a right-hand turn. This was the last recorded data point of the flight.



Accident and Incident Summaries



Figure 3: 3D representation of the flight track (Google Earth)

The aircraft was observed by a witness who was driving their car in a south-westerly direction along Murray Road. The witness: "...noticed a white glider flying very low to the ground. The glider was travelling towards me from the West. I looked at it and I thought it was going to land as it was that low. Suddenly it appeared that the wind flipped his right wing and then the glider went straight towards the ground. I believe the glider was about 20 metres off the ground when it flipped." In a subsequent telephone interview with the witness, the GFA's investigator was informed that the aircraft was flying towards the witness and parallel to the road. The witness saw the aircraft's "right wing go up and the left wing go down". The witness stated the aircraft "spiralled to the left into the ground". The aircraft impacted the ground about 150 metres and 90 degrees to the right of the last recorded data point.

Injuries to persons

The pilot sustained multiple injuries consistent with a rapid deceleration leading to death.

Damage to aircraft

The aircraft impacted the ground almost vertically, with the nose and left wing forming deep depressions in the ground. The cockpit area was severely compromised, and the remains of the canopy were scattered at the impact site. The rear fuselage split about 40cms behind the trailing edge of the wings and lay parallel to the left wing. The leading edge of the left wing suffered multiple breaks consistent with initial ground impact left wing down.



Accident and Incident Summaries



Pilot information

At the time of the accident the pilot had accumulated 661 flights for a total of 1,167 hours. This was the pilot's first flight in this aircraft and first on type. However, the pilot did have considerable experience in earlier model Rolladen Schneider 'LS' sailplanes, with many similarities in cockpit design and handling characteristics. His last annual revalidation flight had been satisfactorily completed on 10 September 2017, prior to which the pilot last flew on 20 August 2017 at Warkworth, NSW with Hunter Valley Gliding Club (Annual revalidation check flights include demonstrating correct spin recovery technique). The pilot was a member of the Gliding Club of Victoria and usually operated from Benalla, Vic aerodrome. The pilot's logbook revealed he was an experienced cross-country pilot, and during the previous year had flown 15 cross-country flights for a total of 5,240 kms.

Aircraft information

The LS8 sailplane was approved by the German Federal Aviation Office, Luftfahrt-Bundesamt (LBA), in accordance with Joint Aviation Requirements for Sailplanes and Powered Sailplanes (JAR-22) dated 28 October 1985. The LBA-Type Certificate2 No. 402 for the LS8-18 was issued on 20 January 2000. The LS8-18 is a single-seat sailplane with carbon fibre wing shell, winglets, T-tail, wing and vertical tail fin water ballast systems, retractable and sprung landing gear, and upper wing surface air brakes. The LS8-18 may be operated in 15m or 18m span and winglets in both versions. It is designed for competition flights - high performance combined with excellent handling. The aircraft was flown on this occasion in 15-metre configuration. The controls of the aircraft are of conventional layout as shown below:



Accident and Incident Summaries





Accident and Incident Summaries

Control Column

The ailerons and elevator are operated from the cockpit by means of the 'control column'. The control column is located between the pilot's legs and just in front of the instrument panel. Movement from side to side operates the ailerons, while movement backward and forward operates the elevators. The Ailerons bank the aircraft in the direction they are moved and are used to initiate a turn. The elevator controls the pitch of the aircraft; forward movement lowers the nose of the aircraft, while rearward movement raises the nose.

Rudder Pedals

The rudder pedals are located forward of the cockpit and are operated by the pilot's feet. Forward pressure with one foot or the other operates the rudder. The rudder pedals cause the aircraft to yaw in the direction of the pedal being depressed and are used in conjunction with the ailerons to turn the aircraft. Yawing motion may also have an additional effect of causing roll in the direction of yaw, due to more lift being generated by the faster moving wing. At low energy, excess yaw may cause the slower moving inside wing to stall.

Airbrakes

Airbrakes are used to control the rate of descent and angle of glide when approaching to land, thus making it easier to land safely in small spaces. They increase the drag, and hence steepen the angle of glide (a steeper angle of glide is necessary to maintain the same airspeed). The airbrake lever is situated against the left-hand cockpit wall and is operated by the pilot's left-hand.

Landing Gear

The retractable landing gear is operated by a push-pull rod with a handle at the right-hand side of the cockpit. The handle is pushed forward to retract the undercarriage and pulled backward to extend the undercarriage. The handle is pushed/pulled through a guide slot with two locking recesses. To retract the undercarriage, the handle is swung out of the rear locking recess and pushed forward through the slot and engaged into the forward locking recess. To extend the undercarriage, the handle is swung out of the rear locking recess and pushed forward through the slot and engaged into the forward locking recess. To extend the undercarriage, the handle is swung out of the forward locking recess and pulled backward through the slot into the rear locking recess. In order to manipulate the undercarriage lever the pilot must fly left-handed whilst activating the landing gear handle.

Stalling Characteristics

Stalls from straight flight will result in the nose dropping. The amount the nose drops depends on how steeply the aircraft entered the stall; the steeper the entry, the lower the nose drops. The impending stall is usually signalled by slight oscillation of the horizontal tail plane and the aileron controls becoming sloppy and can be prevented by the pilot easing the control column forward. A stall in flight with accompanying yaw usually results in the aircraft pitching down steeply in the direction of the lower wing. The downward pitching is usually greater than that experienced in level flight, accentuated at higher bank angles. The Pilot Operating Handbook notes the stalling speed for straight and level flight, air brakes retracted and without water ballast to be 37-38 knots in 15-metre configuration. Stalling speed will be slightly higher in a turn. **Spinning**

The flight manual notes that if the angle of incidence is increased considerably by further "pulling" on the control column during an asymmetric stall, spinning may result, especially with an aft Centre of Gravity (CG) position. No spin check was performed when the aircraft entered Australia as it is not approved for spinning. Notwithstanding, aircraft designed to JAR-22 requirements are capable of being recovered from a spin if the standard spin recovery technique is applied. Note: GFA Annual Revalidation Checks flown by pilots include a mandatory demonstration of correct spin recovery technique in a suitable two-seater glider.

Weight and Balance

The last Weight and Balance calculation was completed on 26 September 2014. The maximum pilot weight (with parachute) was 108 kgs. At the time of the accident a battery was fitted to the tail (fin) of the glider. The Medical Examiner noted the pilot's weight to be 80 kgs. The pilot was wearing a parachute that weighed 7 kgs, and the aircraft was fitted with one ballast weight in the cockpit that was equivalent to 5kg on the front pilot seat. At 92kgs pilot weight and with a tail battery installed, the aircraft was being flown within the normal flight envelope.

Meteorological information



Accident and Incident Summaries

Weather conditions observed on Benalla aerodrome3 around the time of the accident were:

- Wind speed: 5 to 10 Knots, gusting to 15 knots.
- Wind Direction: South westerly.
- Cloud: 4/8 Cumulus at 4,000ft AMSL. The Bureau of Meteorology data collected by the weather station at Benalla Aerodrome does not cover the time period of the accident. However, observations at Wangaratta were similar, viz.:
- 1:30PM: Wind Speed 21 kph/11 Knots, gusting to 28 kph/15 Knots.
- 2:00PM: Wind Speed 22 kph/12 Knots, gusting to 30 kph/16 Knots.



Accident and Incident Summaries

Wind direction 200 degrees to 210 degrees. Benalla Airport (Site No. 82170)																					
Benalla Airport (Site No. 82170) Date Time Rain since QC Air QC Rel QC Wind QC Visibility QC Total QC Present QC Past QC																					
Date	Time (LCT)	Rain since last obs	QC.	Air Temp	QC	Dwpt Temp	QC	Rel Hum	QC	Wind Speed	QC	Wind Direction	QC.	Visibility (m)	QC	Total Cloud	QC	Present Weather	QC	Past Weather	90
30/09/2017	06:00 AM	(mm) 0.2	N	9.0	N	6.9	N	87	N	00m/10 17	N	(degrees) 270	N	30000	N	(oktas) 7	N	Fine	N	Fine	N
30/09/2017	09:00 AM	0.0	N	11.5	N	6.4	Ν	71	N	9	Ν	270	N	35000	Ν	5	N	Fine	N	Fine	N

Observations from Benalla Airport (BoM Site No. 82170)

							urbay or weldorolog	là nara nochu	ges mayness	A040-1
				Wangaratta Aero	(Site No. 82138))				
Date	Time (LCT)	Rain since 9am (mm)	Air Temp ("C)	Dewpoint Temp (°C)	Relative Humidity (%)	Wind Speed (km/h)	Wind Direction (degrees)	Wind Gust (8m/h)	MSL Pres (hPa)	ure
30/09/2017	10:30 AM	0.0	13.4	6.5	63	30	250	39	1019.1	1
30/09/2017	11:00 AM	0.0	14.2	7.0	62	21	280	30	1018.5	
30/09/2017	11:30 AM	0.0	14.3	4.9	53	26	250	37	1018.8	
30/09/2017	12:00 PM	0.0	11.3	7.6	78	28	200	41	1019.4	
30/09/2017	12:30 PM	0.0	14.0	7.8	66	15	180	21	1019.6	
30/09/2017	01:00 PM	0.0	15.4	5.9	53	18	230	28	1019.1	
30/09/2017	01:30 PM	0.0	16.0	6.2	52	21	200	28	1018.8	
30/09/2017	02:00 PM	0.2	15.9	5.2	49	22	210	30	1018.6	
30/09/2017	02:30 PM	0.2	16.1	6.0	51	22	210	30	1018.3	
30/09/2017	03:00 PM	0.2	14.7	5.2	53	21	230	30	1018.3	5
30/09/2017	03:30 PM	0.2	15.9	6.1	52	24	240	35	1018.4	
30/09/2017	04:00 PM	0.2	14,9	6.2	58	17	240	22	1018.8	
30/09/2017	04:30 PM	0.2	15.5	3.9	46	21	250	31	1019.1	
30/09/2017	05:00 PM	0.2	15.2	5.1	51	15	200	21	1019.3	5
30/09/2017	05:30 PM	0.2	13.6	3.9	52	15	250	21	1019.6	5
30/09/2017	06:00 PM	0.2	12.5	4.5	58	13	230	17	1019.6	
30/09/2017	06:30 PM	0.2	10.7	4.2	64	11	220	15	1020.1	1
30/09/2017	07:00 PM	0.2	10.4	4.1	65	2	230	5	1020.3	1
30/09/2017	07:30 PM	0.2	9.6	5.4	75	0	000	0	1020.6	1
30/09/2017	08:00 PM	0.2	8.0	4.8	80	0	000	0	1021.0	1
30/09/2017	08:30 PM	0.2	7.1	4.2	82	0	000	0	1021.5	
30/09/2017	09:00 PM	0.2	6.1	3.8	85	0	000	0	1021.7	1
30/09/2017	09:30 PM	0.2	5.4	4,1	91	0	000	0	1022.0	
30/09/2017	10:00 PM	0.2	5.7	4.8	94	5	190	8	1021.9	
30/09/2017	10:30 PM	0.2	5.2	4.5	95	0	000	0	1022.0	1
30/09/2017	11:00 PM	0.2	4.7	3.5	92	0	000	0	1022.2	

Observations from Wangaratta Aero (BoM Site No. 82138)

									\$	Strath	bogie (Site	No. 82042)									
D	ate	Time	Rain since	QC	Air	QC	Dwpt	QC	Rel	QC	Wind	0C	Wind	QC	Visibility	QC	Total	QC	Present	QC	Past	QC
		(LCT)	last obs		Temp		Temp		Hum		Speed		Direction		(m)		Cloud		Weather		Weather	
			(mm)		("C)		(°C)		(%)		(km/h)		(degrees)				(oktas)					
30/09	/2017	09:00 AM	0.8	Ν	8.9	Ν	7.9	N	93	N	4	Ν	270	Ν	10000	Ν	7	Ν	Drizzle	N	Rain	N

Observations from Strathbogie (BoM Site No. 82042)

									Edi U	lpper (S	ite N	io. 83083)									
Date	Time (LCT)	Rain since last obs (mm)	QC	Air Temp (°C)	QC	Dwpt Temp (°C)	QC	Rel Hum (%)	QC.	Wind Speed (km/h)	oc	Wind Direction (degrees)	oc	Visibility (m)	QC	Total Cloud (oktas)	QC	Present Weather	QC	Past Weather	QC
30/09/2017	09:00 AM	1.3	Ν	10.4	Ν	9.6	Ν	95	N	9	N	310	Ν	5000	Ν	7	Ν	Drizzle	N	Rain	N

Observations from Edi Upper (BoM Site No. 83083)

Figure 6: Synoptic Observations

Flight recorder

The pilot carried a portable 'NANO' flight recorder manufactured by Slovenian company LXNAV. This flight recorder features an integrated 66-channel GPS receiver, built-in antenna and built-in battery. Flight data, such as time, position and altitude, are stored directly in IGC format and are downloadable through a USB connection. The unit was set to record data points at two-second intervals.



Accident and Incident Summaries

Wreckage and impact information

Examination of the occurrence site and wreckage indicated that the aircraft was in a left-hand spiral when it struck the ground in a left-wing-low, very steep nose-down attitude. After the initial impact the aircraft rebounded rearwards approximately eight metres. The aircraft came to rest right side up on a Westerly heading, with the right-hand wingtip passing through a post and wire fence. The nose of the aircraft left a single conical impact point some 75mm deep and 100mm in diameter. The impact point was about 8.1 metres from the final resting place of the fuselage. The tail boom broke behind the wings, with the tailplane tucked under the left-hand wing.





Accident and Incident Summaries



The left wing contacted the ground almost simultaneously with the nose along its full length, leaving a welldefined depression in the ground. The left-hand wing suffered significant damage.



Accident and Incident Summaries



The aircraft was equipped with four-point lap and shoulder restraints, which was worn by the pilot. The harness remained intact during the accident. Gliding club personnel noted all flight control surfaces were accounted for at the accident site. While there were multiple overload failures of the flight control system in



Accident and Incident Summaries

the fuselage and cockpit areas, control continuity was established. The hand grip from the control column was rotated about 45 degrees to the right, i.e. clockwise.





Accident and Incident Summaries

The undercarriage was found to be collapsed and the tyre deflated. The undercarriage lever was noted in the 'down and locked' position, and the guide rod immediately forward of the handle was bent upwards by impact forces. Dirt and debris accumulated between the tire and wheel confirmed the undercarriage was down and locked at the moment of impact. It was also noted that the left and right airbrakes were unlocked but a lack of damage to the airbrake mechanism in the wings is indicative of them being in the closed position prior to impact. The airbrake lever was in the locked position in the cockpit. The airbrakes most likely become unlocked when control circuit integrity was lost. The instrument cluster suffered substantial damage. The electrical system master switch toggle was broken and the number 2 circuit breaker to the electric Variometer had popped. The needle electric Variometer (top right in the instrument cluster) was indicating a rate of descent of 600ft per minute. The needle on the Air Speed Indicator (top left in the instrument cluster) was stuck on 70 knots, and the needle on the altimeter (bottom left in the instrument cluster) was indicating 160 feet.



Accident and Incident Summaries



The pilot held a GFA Medical Practitioner's Certificate of Fitness dated 28 October 2015. The medical standards applicable for the issuing of this Certificate are the Austroads standards for the issue of a driver's



Accident and Incident Summaries

licence medical certificate for a private motor vehicle. The issuing Medical Practitioner signed the Certificate and attested: *"I hereby certify that I have examined the applicant and to the best of my knowledge he is not suffering from a medical condition which would preclude him from flying a sailplane as pilot in command."* Medical notes obtained by the pathologist from the pilot's Medical Practitioner revealed his past medical history included:

- Cerebrovascular incident (2015, no residual neurological deficit).
- Coronary angiography no significant obstruction (2015).
- Gastro-oesophageal reflux disease.
- Cataract surgery (bilateral).

The Pathologist noted that there was "...significant narrowing of the carotid sinuses which are capable of causing transient ischaemic attacks (mini strokes) and the possibility of one causing loss of consciousness and/or coordination should be considered as one possible causal or contributing factor for this crash."

Survival aspects

The forward cockpit was severely compromised upon impact with the ground. The pilot was found reclined in the seat and still restrained by the aircraft harness. The impact forces were not survivable. **ANALYSIS**

Pilot qualifications

The pilot was appropriately qualified for the flight but was lacking currency, having flown only two flights since 1 March 2017. The flight immediately preceding the accident flight was a 10-minute check flight with his Chief Flying instructor (CFI) on 10 September 2017. The CFI noted that *"[The pilot] recently hasn't been flying much and he was a little rusty"*. The flight covered emergency procedures and upper air stalling exercises. The pilot flew a normal circuit and landing, with the CFI commenting: *"Beside a better lookout there was nothing I could fault him. We debriefed, and both came to the conclusion that more time on the stick would benefit [the pilot]. I signed his logbook confidently."* Although the accident flight was the pilot's first in an LS8 sailplane, the pilot had considerable experience in flying earlier model LS gliders, with many similarities in cockpit design, controls and in-flight handling characteristics. He also had much experience flying cross-country in other high-performance glider types. He had a Glider Pilots Certificate and Independent Operator Rating, qualifying him for independent unsupervised flight.

Weather

The weather was generally fine, but other pilots who flew that day noted there was moderate turbulence at lower levels. Turbulence is usually present in two forms; mechanical and thermal. Mechanical turbulence is a product of wind strength and variation in the terrain (trees, buildings, ridges, etc.). It can extend up to 500ft above terrain and is more pronounced the lower the pilot flies. Thermal turbulence is caused by variations in ground heating of the air, creating buoyancy. Thermals can be quite broken and turbulent below 1,000ft above ground.

Flight Recorder

A GFA technical expert attended the Benalla Police station at 9.00am on the 1 October 2017 and recovered a data file from the Nano data recorder. The flight recorder recorded altitude and position data for the flight up until approximately two seconds prior to impact with terrain. It is believed power to the unit was lost at impact that prevented the unit from continuing to record GPS data. The data obtained allowed a reconstruction of the flight as detailed earlier under the heading 'History of the Flight'. An overlay of the flight on a 'Google Earth' satellite image provides a reasonably accurate track of the aircraft over the ground and through the air.



Accident and Incident Summaries



Figure 12: Flight Track

While GPS and pressure altitude and GPS track data cannot be relied upon with absolute accuracy due to horizontal and vertical resolution errors, and the two-second sampling rate, in this case the heights and track data recorded are consistent with the statements of the tow pilot and the sole witness to the accident. Using the last recorded data point and the position of the aircraft wreckage, it was possible to extrapolate the flight path and identify the probable landing point.





Accident and Incident Summaries

A post-crash inspection of the wreckage was undertaken by a GFA Airworthiness Inspector. As far as could be determined, inspection of the aircraft did not identify any defects which might have affected the pilot's ability to control the aircraft in flight.

Aircraft maintenance

The aircraft was maintained by the pilot, who held GFA authorisation to conduct annual inspections. Prior to purchase, the aircraft was maintained by the owner. The current inspection schedule confirmed compliance with GFA and the Manufacturer's requirements. The aircraft was certified airworthy and fit for an evaluation flight. The schedule also confirms that a dual inspection of the control safety locking was undertaken prior to closing all access panels, and an independent control check was conducted by another person following assembly of the aircraft on 9 September 2017. At the time of this inspection the aircraft had flown 1,418 hours over 438 flights. The current Maintenance Release was issued by the pilot on 30 September 2017 with an expiry date of 29 September 2018. The maintenance release evidences the pilot undertook a Daily Inspection in accordance with GFA operational procedures at 12:40 and prior to the first flight of the day. No defects had been recorded.

Mass and balance

As previously noted, the aircraft was flying within its weight and balance envelope.

Aircraft instrumentation

The aircraft carried basic instruments. Due to the effect of impact forces on the Altimeter, it is not possible to determine whether the pilot set the altimeter to record QNH (height of the airfield above sea level - 569 feet) or whether it was set to record QFE (altitude relative to an airfield - 0 feet). The Airspeed Indicator (ASI) was stuck on 70 knots. This most likely indicates the aircraft's indicated airspeed at impact.

Analysis of injuries and fatalities

It is sometimes possible to determine which hand the pilot had on the control column at the time of the accident from injuries sustained to the hand and fingers. The control column of most gliders is situated between the pilot's legs and very close to the instrument panel. During a crash of this nature it is common for the fingers of the hand holding the control column to impact the instrument panel and leave contusions. In the case of this accident, the Injuries to the pilot's left hand and arm are consistent with pilot flying left-handed. This is further supported by the position of the control column hand grip, which was found to be rotated 45 degrees clockwise, to the right.

General

Review of the flight trace suggests the pilot was in control of the aircraft up until the point of departure from controlled flight into a low-level spin, leading to collision with terrain.

The pilot's decision-making processes during the course of the flight warrant consideration:

1. This was the post-maintenance flight of the aircraft, so it would be usual for the pilot to take a much higher tow to, say, 3,000 ft, in order to confirm the aircraft was airworthy and provide sufficient altitude to abandon the aircraft should a serious technical problem be identified. Furthermore, it would be usual for a pilot to exercise a degree of caution on their first flight on type. Notwithstanding, it is possible, at the moment of release, the pilot believed he was in sufficient lift to climb to height without the tow plane. Unfamiliarity with the differences in LS8 aircraft feel from other type and functioning of the Variometer may have been a contributing factor. Another potential factor that may have contributed to the pilot's decision to release from tow was misreading the altimeter. The pilot's previous glider was fitted with a metric-style 2-hand altimeter showing 3,000ft per revolution (refer Figure 14: Altimeters). In this case, misinterpretation by the pilot could have resulted from the difference between the conventional altimeter and the 3000ft-per-revolution altimeter. When the conventional 1000ft-per-revolution altimeter reads 700ft, the hands of a metric altimeter in the same spatial position would read about 2000ft. A misinterpretation of altimeter height is possible even in the face of contradictory cues (short time on tow, external visual cues) in what the human factors literature refers to this as a 'capture error.' In this, people follow a similar but unwanted and unintended line of action because it is triggered by a strong contextual cue (in this case the altimeter hands), which eclipses other cues. External visual cues may have been less persuasive because of attentional narrowing under the stress of the



Accident and Incident Summaries

upcoming flight, and the time spent on tow would have similarly been less obvious because of the common distortion of time perception under these circumstances.

- 2. It is evident the pilot headed downwind, away from the airfield, for a total distance in excess of seven (7) kilometres in search of rising air (refer Figure 11: Measured Maximum Distance from Benalla Aerodrome). Pilots will usually remain within glide range of the airfield until they have sufficient height to fly further away, and they will usually not fly far downwind. A pilot will assess glide range visually, taking onto account the angle down to the destination, which is a function of the aircraft's height above ground and distance to run, and the effect of any wind. It is likely the pilot's decision was influenced by the presence of cumulus clouds, which form at the top of thermal convection.
- 3. The pilot made a very late decision to break-off the flight and conduct a landing. The flight trace suggests the pilot made the decision to break-off the flight immediately following the last attempt at contacting a thermal and at a height below 500ft AGL (refer Figure 15: Estimated Break-off Point). Breaking off the flight at this height is contrary to GFA training and safe practice. Glider Pilots are trained that when below 2,000 ft AGL, searching for lift and other upper air activities should normally be conducted upwind of the intended circuit joining area, and that the glider should be flown so as to ensure it can always join circuit at a safe height and commence a normal downwind leg. The normal height for joining circuit in a high-performance glider like the LS8 would be around 800ft AGL or higher. Sufficient height is especially important when landing in a paddock of which the pilot has no knowledge, as it enables the pilot to properly check for any hazards and allow for safe flight to an alternative landing area should the first option prove unsuitable.



Accident and Incident Summaries





Accident and Incident Summaries



Figure 15: Estimated Break-off Point

Reconstruction of the flight trace, which did not record the last seconds before impact, and review of the statement of a witness suggests the pilot was attempting to conduct a downwind landing in a paddock parallel to Murray Road. The aircraft appears to have departed controlled flight after rolling out of the right-hand turn to wings level while on final approach to the paddock. As previously mentioned, the nature of injuries to the pilot's left hand and left forearm, plus the orientation of the control column grip, suggest he was holding the control column with his left hand at the time of impact with terrain. It is unusual for a pilot, at such a late stage of the circuit and final approach, to be flying left-handed. This is because the airbrake controls used to manage the final approach are manipulated by the pilot's left hand and are usually held for the duration of the approach and landing. It is therefore probable the pilot was flying left-handed because he changed hands to lower the undercarriage, the lever for which is on the right-hand side of the cockpit. If this was the case, then the pilot had not configured the aircraft for landing prior to turning onto final approach, which is indicative of workload management being affected by increased stress. The ergonomics of this control activation sequence are relevant to possible contribution to low level loss of control leading to



Accident and Incident Summaries

a collision with terrain. To lower the undercarriage, the pilot must use his right hand to disengage the undercarriage lever from the 'UP' locking recess and pull it back into the DOWN' locking recess. The act of pulling backwards with the right hand can lead to the pilot also moving the left hand and possibly applying pressure to one of the rudder pedals if the undercarriage lever is somewhat difficult to engage into the retaining slot. Such action could cause the aircraft to pitch and yaw, which coupled with low-level turbulence may have led to the aircraft departing controlled flight and entering a spin. **Human Factors** From an aviation operations and safety management perspective, accidents may be analysed in terms of active errors ("unsafe acts") and latent (systems, organisational) conditions. In this case there appears to be some active errors and failed defences that have combined in the accident causation chain, with fatal result. These include:

Active errors:

- The pilot headed too far downwind for the conditions, having released from aerotow at a lower altitude than is normal for post-maintenance evaluation flights and first flight in a new type.
- The pilot did not break-off the flight and commit to a landing at a safe height; and
- It is likely the pilot had not configured the aircraft for landing at a safe altitude prior to final approach.

Failed Defences:

• Non-adherence to standard operating procedures for safe circuit and landing, possibly due to high workload and stress.

The effect of age

Due to the nature of a pilot's work and the demands that are placed on an individual's abilities, the process of aging is of importance to a pilot. The natural and expected process is that as one becomes older, there is a gradual deterioration of some of the body's physical components and sensory functions, although the degree of deterioration varies greatly from person to person. The first change to manifest is certain bodily stresses, especially fatigue, becoming more difficult to handle as a pilot ages. The body's reaction time, efficiency, and recovery from climatic extremes slows down as it gets older. Quickness of response begins to decline with maturity, so an older person will be slower to respond to urgent situations than a younger person, and a slower reaction time may be more significant in landing procedures in which many actions must be carried out rapidly. Due to the gradual loss of elasticity, the lens of the eye may be unable to focus properly on near objects, making it more difficult to read instruments, charts, or radio controls. To better cope with age-related factors, pilots need to ensure:

- 1. they are physically fit, not just at the time of their medical exams but in the two years between them' and
- fly more, not less, to keep skills current—and every so often go out and practice manoeuvres such as stalls, slow flight, approaches, take-offs and landings, in order to maintain their flying skills.CONCLUSIONS

While it is not possible to determine the cause of this accident with certainty, review of the evidence suggests the aircraft most likely departed controlled flight when the pilot initiated crossed control inputs while lowering the undercarriage when flying with his non-preferred left hand, while on final approach into an unplanned off-aerodrome landing. Low-level turbulence may also have been a contributing factor. It is also possible that the pilot's decision making identified in this report was affected by a transient ischaemic attack prior to, or during flight.

Findings

- 1. The pilot was qualified for the flight in accordance with existing regulations.
- 2. The pilot lacked recent flying practice and had no prior experience on type.
- 3. The aircraft's maintenance records indicated that it was equipped and maintained in accordance with existing regulations and approved procedures.
- 4. All control surfaces were accounted for, and all damage to the aircraft was attributable to the severe impact forces.



Accident and Incident Summaries

- 5. There was no evidence of any defect or malfunction in the aircraft that could have contributed to the accident.
- 6. The aircraft appeared capable of normal operation up to the moment of impact.
- 7. Weather conditions were generally favourable, although increased thermal turbulence could have been experienced close to the ground.
- 8. The pilot's previous glider was fitted with a metric-style 2-hand altimeter showing 3,000ft per revolution. An altimeter misinterpretation (capture error) may have suggested to the pilot that he was significantly higher than he actually was when releasing from tow.
- 9. The pilot made a number of decisions and interpretations during the flight that led to an attempted off-aerodrome landing.
- 10. During final approach for a paddock landing, the aircraft inadvertently stalled and departed controlled flight at a height too low for the pilot to recover before ground impact. **SAFETY RECOMMENDATIONS**
- 11. Given the possibility that 'metric' style altimeters can be misread, GFA will recommend to new owners of gliders fitted with a 'metric' style altimeter that they consider replacing them with standard altimeters.
- 12. The GFA include advice regarding conversion of pilots to high wingspan, high inertia gliders, and controllability considerations in its current update of the GFA Training Manual.
- 13. The GFA Operations Department review, and update as required, guidance to instructors and pilots on safety implications of low recency and currency, especially in regard to older pilots.

REFERENCES

1 ATSB. Human Factors in Fatal Aircraft Accidents. Canberra, ACT: Australian Transportation Safety Bureau (formerly BASI), 1996.

2 Norman DA. Categorization of action slips. Psychological review 1981;88(1):1-15.

3 Reason JT, Mycielska K. Absent-minded? The psychology of mental lapses and everyday errors. Englewood Cliffs, N.J.: Prentice-Hall 1982.

4 Wickens CD, Hollands JG. Engineering psychology and human performance. 3rd ed. Upper Saddle River, NJ: Prentice Hall 2000.

5 Wiener EL, Nagel DC, editors. Human factors in aviation. San Diego, CA: Academic Press, 1988.

6 Nagel DC. Human error in aviation operations. In: Wiener EL, Nagel DC, eds. Human factors in aviation. San Diego: Academic Press 1988:263-303.

7 Hancock PA, Weaver JL. On time distortion under stress. Theoretical Issues in Ergonomics Science 2005;6(2):193-211.

8 The "Swiss Cheese" model of accident causation developed by James Reason (Human Error (1990) and Managing the Risks of Organisational Accidents (1997)) is the accepted model for investigation used by the International Civil Aviation Organisation and Australian Transport Safety Bureau. Risks may be realised if hazard defences fail, particularly if active errors occur and are combined with latent conditions including human, operational and organisational factors.

9 The Ageing Pilot, New Zealand Civil Aviation Authority, Vector Magazine March/April 2010

Date	30-Sep-2017	Regior	۱ I	VSA		SOA	AR Repo	ort Nbr		S-	1050	
Level 1	Airspace		Level 2	2 Aircra	ift Sep	arati	on	Level	3	Near collis	ion	
A/C Mod	el 1		hacz		A/C	Model	2	PIK				
Injury	jury Nil Damage Nil Phase									PIC Age	51	
During ar	During an aerotow launch and about 800' AGL, the attention of the pilot of the glider under tow was caught											
by a shad	low passing ove	r the glide	er. The p	ilot looked u	up to s	see ar	nother	glider (PIK 2	0) approxim	ately 400'	
directly a	irectly above heading to join circuit. The pilot of the tow plane and the pilot of the PIK 20 were both											
unaware	of the potential	conflict.	Investig	ation reveal	ed the	pilot	of the	PIK 20	pilot	had earlier s	sighted the	



Accident and Incident Summaries

towing combination on the ground but did not hear the tow pilot's radio calls that would have alerted them to the take-off. As the pilot of the PIK turned onto downwind, the tow plane was almost directly underneath. It is possible neither the PIK pilot nor the tow pilot sighted each other due to blind arcs. When operating at uncontrolled airspace, it is the pilot's responsibility to maintain separation with other aircraft. For this, it is important that pilots utilise both alerted and unalerted see-and-avoid principles. Pilots should never assume that an absence of traffic broadcasts means an absence of traffic. Unalerted see-and-avoid relies entirely on the ability of the pilot to sight other aircraft. A traffic search in the absence of traffic information is less likely to be successful than a search where traffic information has been provided because knowing where to look greatly increases the chance of sighting the traffic. This incident highlights the importance of broadcasting radio calls to alert pilots and assist in see-and-avoid practices. It also serves as a reminder to keep a good lookout for other aircraft, particularly around noncontrolled aerodromes.



Date	4-Oct-2017	Region	NSWGA	SOAR Report Nbr	S-1051



Accident and Incident Summaries

Level 1	Environment		Level 2		Wildli	fe		Level	3	Birdstrike	
A/C Mod	el 1		DG-200	/17 C		A/C	Model	2			
Injury	Nil	Damage Minor Phase In						ght		PIC Age	
While in	the cruise on a c	a cross-country flight the pilot spotted an eagle approximately 1,000 fe								1,000 feet	higher. The
eagle div	ed towards the \mathfrak{g}	cowards the glider head first and wings folded, leading with its talons. The eagle passed over the									
canopy and wing but struck the fin. The pilot conducted a control check and found it to be normal, so flew											al, so flew
back to t	he home airfield	. Subsequ	ient inspe	ction reve	aled o	nly m	ninor da	amage,	comp	orising a ber	nt TE probe
and a scr	atch down the fi	n and rud	lder. Bree	eding Wedg	ge-tail	ed Ea	agles ar	e parti	cularly	/ sensitive t	o aircraft
approaching the nest, even if the aircraft remains many hundreds of metres away. To avoid collisions when											sions when
flying ove	er nesting habita	t during t	he breed	ing season	(betw	/een /	August	and Ja	nuary), pilots mus	st learn to
recognise	e aggressive beh	aviour an	d be on tl	ne lookout	for w	arnin	g signs	while f	lying.		

Date	5-Oct-2017	Region		NSWGA		SOA	AR Repo	ort Nbr		S-	1052
Level 1	Airspace	Le	evel 2	Airspac	e Infri	ingen	nent	Level	3	Airspace In	nfringement
A/C Mod	el 1	J	JS1 C 18	3/21		A/C	Mode	2			
Injury	Nil	Damage	`	Nil	Dha		In-Elic	tht			/1

Damage Nil Phase In-Flight injury NII PIC Age The pilot was flying in the 2017 Queensland State Gliding Competition. On day 2, the pilot was flying a 2.5hour AAT task of up to 353kms. During the course of this flight the pilot briefly violated restricted airspace for 1min 38 seconds and a distance of not more than 1km. The pilot reported no relevant airspace warnings of any kind were received from the flight computer, despite being correctly configured and using the competition airspace file. Post-flight analysis determined that the airspace file had been corrupted during conversion to a format used by the flight computer. This was a latent threat, not presenting itself until it had become an error, as the lateral limits of the airspace types were shown correctly, and the flight computer was generating warnings for Danger areas and CTAF's that were coded correctly. The pilot also noted that they missed the day briefing and presented to the CD afterwards for a makeup briefing. The pilot suspects that had they been present in the tasking instruction, it is doubted the error would have been made. When flying near airspace boundaries pilots must ensure they use sensible tolerances to airspace. AIP ENR 1.1, paragraph 19.12 states: "For aircraft operating in close proximity to an airspace boundary where there is a risk of an airspace infringement, the pilot in command should consider obtaining a clearance to enter the airspace or altering track to remain well clear." Pilots should always navigate using CASA approved data and charts. Airspace files provided by competition organisers or downloadable from the internet are unapproved and should not be relied upon.

Date	6-Oct-2017	Regior	ı	SAGA		SOA	AR Repo	ort Nbr		S-	1059
Level 1	Operational		Level 2		Airfrar	ne		Level	3	Fuselage/\	Vings/Empe
										nnage	
A/C Mod	el 1		ASK-2	21Mi		A/C	Model	2	N/A		
Injury	Nil	Dam	age	Nil	Pha	ise	In-Flig	ght		PIC Age	
The aircra	aft had been flov	vn for a v	veek wit	n the port d	lrag pi	n unl	atched	. At the	conc	lusion of fly	ing
operation	ns, the aircraft w	as de-rig	ged. Dur	ng the deri	g it wa	as no	ted tha	t the po	ort wi	ng drag spa	r pin, which
had been	had been covered with tape, was not secured by the safety latch. The safety latch had been compressed by										
the pin. I	t is likely the pin	was not	properly	secured du	ring ri	gging	g the w	eek ear	lier, a	nd that sub	sequent
Daily Insp	ectors failed to	notice th	is due to	the tape co	overing	g.					

Date	7-Oct-2017	Region		VSA	SOAR Repo	ort Nbr		S-1053
Level 1	Operational	L	evel 2	Runway E	vents	Level 3	;	Runway excursion
A/C Mod	el 1	Pi	per PA 2	25-260	A/C Mode	2		



Accident and Incident Summaries

Injury	Nil	Damage	Minor	Phase	Landing	PIC Age	80
Following a s	successful glid	er launch, the	tow pilot retu	rned to the	e aerodrome and es	tablished th	ie tow plane
on a stable f	inal approach	for the operat	ional runway	01. The run	way strip comprise	s a bitumen	surface with
wide grass v	erges either si	de for the use	of gliders, tov	v planes an	d vintage aircraft. A	A permanen	tly displaced
threshold ex	ists to allow th	ne gliding oper	rations to be c	onducted v	vithout occupying t	he runway p	proper.
Weather cor	nditions on the	e day were fine	e, with a preva	ailing NNE v	vind of between 5 t	o 10 knots.	The tow
plane was al	igned with the	e runway centi	reline, as both	the left an	d right-hand verges	behind the	threshold
were occupi	ed by gliders.	The tow plane	touched dow	n on the m	ainwheels and bour	nced slightly	. While still
airborne the	tow plane wa	s struck by a v	wind gust or th	nermal from	n the west that resu	Ited in the t	ow plane
yawing to th	e left. The tov	/ plane touche	ed down again	slightly sid	eways as the aircra	ft weatherc	ocked to the
left. The por	t wingtip lifted	l in the gust, r	esulting in the	starboard	wingtip contacting	the ground.	The tow
plane turned	through 180	degrees and s	topped facing	the opposi	te direction to trave	el. During t	his excursion
the pilot swi	tched off the e	engine. The air	rcraft was mar	nhandled of	ff the runway and s	ome minor	damage to
the starboar	d wingtip was	identified. A f	ew pilots witn	essed the a	accident and confirm	med the airc	raft was
struck by a s	udden wind g	ust from the V	Vest. Tailwhee	l aircraft ar	e particularly susce	ptible to gro	ound-
looping, whi	ch occurs whe	n directional o	control is lost l	by the pilot	and the tail passes	outside the	centre of
gravity, spin	ning the aircra	ft. Although t	he pilot condu	ucted a whe	eel landing, which is	s preferred i	n higher
wind conditi	ons because t	he aircraft is t	hen less susce	ptible to th	e yaw generated fr	om wind gu	sts, the gust
struck just as	s the aircraft v	vas approachi	ng the stall and	d the pilot v	was unable to corre	ect the ensui	ing swing.

Date	9-Oct-2017	Region		VSA			SOAR Report Nbr				S-1055	
Level 1	Operational		Level 2 A		Airc	craft Control		Level 3		Loss of control		
A/C Mod	JS1 C 18/21					A/C Model 2 N			N/A			
Injury	Fatal	Dama	age	Write-off		Pha	Phase In-Flig		ght		PIC Age	75

GFA Field Investigation

SYNOPSIS

On 9 October 2017, at about 1314 hours Eastern Standard time, a Jonker Sailplanes Pty Ltd JS1C, registered VH-IBS (IBS), was towed into the air from Goondiwindi Aerodrome Queensland by a Piper PA25-235 Pawnee tow plane registered VH-TOJ. The pilot intended to fly a practice task in preparation for participation in the National Gliding Competition that was scheduled to start the following day. At about 1320 hours the glider pilot released from tow at a height of about 2,000ft above ground level (AGL) just north-west of the airfield. Several minutes later the glider was observed by a number of other pilots in a steep nose-down attitude spiralling towards the ground at a position approximately 4 kms south-west of the airfield along the extended centreline of Runway 22. The glider did not recover from the dive and impacted the ground in a steep nose-down attitude at high speed and was destroyed. The pilot, who was the sole occupant, was fatally injured. The accident was notified to the Gliding Federation of Australia by the competition Director shortly after it occurred. The GFA, operating under a deed of agreement with the Civil Aviation Safety Authority, is the organisation responsible for the administration of gliding activities in Australia. A GFA field investigation was commenced immediately to support the NSW Police investigation pursuant to a Deed of Agreement between the GFA and The Crown in Right of The State of New South Wales, for and on behalf of the NSW Police Force.

1. FACTUAL INFORMATION

1.1 History of flight

The pilot was competing in the 37th Australian Club and Sports Class National gliding championships being held at Goondiwindi (Qld) Aerodrome during the period 9 to 18 October 2017. At around 0900 hours on Monday 9 October 2017 the pilot, together with other competitors, attended a morning briefing at which weather conditions, tasks, gridding order on the airstrip and operational instructions were provided. The day was to be practice before the competition commenced the following day. The pilot was flying the glider in 'Open Class', where there are no restrictions except a limit of 850 kg to the maximum all-up mass. At briefing the pilots of Open Class were informed they would fly an Assigned Area Task of between 249.66 kms and



Accident and Incident Summaries

474.77 kms, with a task duration of three hours. The pilot was assisted just prior to launch by crew member. In a statement to NSW Police dated 21 November 2017, the crew member stated "[The pilot] was flying that day at about mid-morning, it was a practice day for the competition. I had seen [the pilot] at the morning briefing prior to his flight. I next saw [the pilot] on the flight line and he was standing at the side of the glider and I made it obvious to him that I would run his wing. I watched him get into the glider cockpit and I think he made a comment like "this will take a minute." I noticed that he was wearing a parachute. When [the pilot] was in the cockpit I helped him strap in, which is putting on the harness. I do not recall where the harness buckle was in relation to his torso.... At [the pilot's] request I helped him close the canopy. I did this by reaching in to put pressure on the canopy sill. [The pilot] assisted with his hands to put pressure on the sill, so he appeared to have arms movement." Flight sheets maintained by the competition organisers record the glider was aerotow launched from Goondiwindi aerodrome at 1314 hours by a Piper PA25-235 Pawnee tow plane registered VH-TOJ. The tow pilot provided the flight track in a diagram at Figure 1. The tow pilot advised that he followed the runway heading towards the south-west and, after crossing the railway, turned about 90 degrees to the right and flew parallel to the railway line. Just after crossing Brennan's Road at a silo complex, the tow pilot then turned 90 degrees to the right on a north-easterly heading and parallel to the operational runway. The tow pilot advised that approximately five minutes into the launch and at a height of about 2,000 feet AGL, the glider pilot released from the tow. The tow pilot turned slightly to the left and observed the glider in a right-hand turn. The tow pilot estimates the glider pilot released at a position approximately 100 metres east of the point where Polo Road crosses a creek. The release position was about 4.75 kms from the crash site. The tow pilot then flew a curved path towards the east, before heading south to align with the extended centreline of runway 30.



Figure 1: Aerodrome environs showing take-off path of the towing combination (yellow) and the path of the tow plane after the glider pilot released from tow (orange).

A few minutes after release, the glider was observed by a number of other pilots in a steep nose-down attitude spiralling towards the ground approximately 4 kms south-west of the airfield along the extended centreline of Runway 22.

1. A glider pilot flying a JS-1B glider noted in their statement to NSW Police dated 9 October 2017 that, while they were on tow they noticed a glider in their *"10 o'clock position, slightly higher"*. They stated *"Initially I thought the glider might have been in a stall, but it wasn't a developed spin and*



Accident and Incident Summaries

there was very little rotation. I thought there was time to recover but the glider didn't seem to be recovering. The speed was building up and the nose was towards the ground, very close to vertical. ...The glider moved to my 9 o'clock position as we (glider-tug combination) continued the turn to the right. The glider was below at this stage in a fast (and) vertical dive. I didn't think there was sufficient height to recover at this stage. I watched until almost impact but didn't see impact. The glider remained vertical the whole way down. The wings were flexed up but, as I have a JS1-18, I was familiar with the upsweep of the wings. I didn't have the impression the glider was under any 'g' loading."

- 2. Another glider pilot, flying an ASW 19-B glider, noted in their statement to NSW Police dated 18 October 2017 that "I had been up for approximately 10 to 15 minutes, still in the thermal, when I saw [a glider] straight in front of me on the NSW side of the Boarder. I saw [the glider] was in a very nose down attitude rotating, I think to the right. It was very nose down and quicker than a spin. I would say it looked to be in a spiral dive and, in my opinion at that time and at that particular height, it looked like he had time to recover. ... [the glider] had done a number of rotations at this point and I was concerned that [its pilot] hadn't followed procedure for corrective action at this time. I still thought [the glider] had height to do that. My initial thought was if [the pilot] put a corrective action in, he was going to be too low to make it back to the field but he could have made it into a cultivated field which was straight ahead of him. A routine call in this situation would have been a mayday call. At no time did I hear [the pilot] make a call. It is not common for glider pilots to make calls during competition except in emergency situations or to communicate with other glider pilots. In saying that, [the pilot] would have been under enormous mental pressure and may not have had the presence of mind to make the call. When I saw [the glider] get to a height of between 500 to 300 feet I knew [the pilot] was not going to be able to put corrective action in and outland safely. [The glider] was still in a very nose down attitude and still rotating. I saw [the glider] go behind a line of trees at very high velocity and [it] would have impacted virtually nose first. I did not see the impact."
- 3. The tow pilot flying Piper Pawnee VH-SWR, was towing a JS-1B. The pilot of VH-SWR noted in his statement to NSW Police dated 18 October 2017 that when the towing combination was in a right-hand turn at about 700 feet near the Macintyre River he *"became aware of a glider in a steep descending turn having all the appearances of a spiral dive. In layman's terms, a spiral dive is a descending turn in a steep, nose down attitude with a steep angle of bank but rotating slowly, unlike a spin. The glider had a steep nose down attitude, at least 60 degrees down and a steep angle of bank, at least 60 degrees. The glider was higher than the tug, approximately 1000 feet AGL and in my 10 o'clock high position relative to me. The glider was less than one kilometre away from me. I observed the wing tips appeared deflected up, approximately three metres from normal flight. There was a very pronounced curve in the wings. That Jonker has a lot of flex in the wings due to their length and thinness. The flex indicates how much load the wings are under, so I could see the glider was under a lot of load. As I had a glider on tow it wasn't possible to manoeuvre the tug to keep the glider in sight. The glider was moving below and behind the left wing of the tug as I continued the turn. At this point the glider disappeared from my sight. My last observation of the glider was it appeared intact although under load. The canopy was still on."*

The glider did not recover from the dive and impacted the ground in a steep nose-down attitude at high speed and was destroyed. The pilot, who was the sole occupant, was fatally injured. In a statement to NSW Police dated 6 March 2018, the pilot who towed VH-IBS mentioned: *"I was on the ground taxying back to the launch point for the next glider and departure, and that's when I became aware that something was going wrong in the sky, but I still didn't know who it was."* The tow pilot advised the total flight time was about 8 minutes, and it was while he was taxying the tow plane on the runway that he heard radio chatter advising of a mishap. An experienced competition Pilot, in a statement to NSW Police dated 15 April 2018 noted: *"About 7 or 8 minutes after [the pilot] had taken off, I was still on the ground waiting to take off when I heard a "mayday" call on the radio in my aircraft on the CTAF frequency that was being used by the*



Accident and Incident Summaries

competition. The call was made by the Tug pilot (of VH-SWR) and he indicated that a glider was going in." The accident occurred in daylight, at approximately 1325 hours AEST.

1.1.2 Location

The aircraft crashed onto a rural property located on the NSW side of the Qld/NSW border. The crash site was situated east of an unnamed road immediately opposite Uathery Lagoon and approximately 500 metres to the south of the intersection with Kentucky Lane, Boggabilla, NSW. This position was approximately 4 kms south-west of the Goondiwindi (Qld) Aerodrome along the extended centreline of Runway 22 at co-ordinates 28°33'15" S 150°17'33" S. The site elevation is 710ft above mean sea level (AMSL).

1.2. Injuries to persons

The pilot, who is an Australian national, suffered a catastrophic pattern of injuries in the accident, involving the commingling of the limbs, head and torso that would have led immediately to death.

1.3. Damage to aircraft

The aircraft was seriously damaged. The wings, rear fuselage and empennage were damaged but identifiable, and the cockpit area forward of the wings was destroyed. All aircraft wreckage was confined to the accident site.

1.4. Other damage

Nil. The aircraft impacted on vacant land.

1.5. Personnel information

1.5.1 Flight Experience

The pilot had been flying gliders since about 1995 and held a GFA Glider Pilot Certificate, endorsed with Carriage of Private Passengers and Independent Operator Level 1. The Certificate was valid to 30 September 2018, aligned with the pilot's GFA membership expiry date. According to the competition entry form, the pilot's last Annual Flight Review was conducted on 16 April 2017. Flight records from the pilot's primary club (the Gliding club of Victoria), evidence that the pilot flew with the Club's Chief Flying Instructor (CFI) on that day. In an email to the GFA's Technical Advisor dated 20 November 2017, the CFI stated: *"For an annual flight review we use our AFR template and we include recover from a fully developed spin and the differences to a spiral dive. We did not do any spin training; also with him flying in the rear seat, I could not check on lookout. ...I can't recall any unsatisfactory flying or errors in his skills, decision making process and situational awareness." Flight records reveal the pilot to be very experienced, with over 2,026 hours and 2170 flights. However, the pilot's experience on type prior to the accident was modest; comprising 80 hours in 35 flights. The pilot was not in current flying practice, having last flown in a glider on the day of his alleged Annual Flight Review almost 6 months earlier. The pilot's penultimate flight in the accident aircraft was on 8 February 2017.*

1.5.2 Medical Information

The pilot's treating cardiologist, in a statement to NSW Police dated 14 December 2017, noted that the pilot had had a history of hypertension, obesity, smoking, dyslipidaemia, sleep apnoea, moderate alcohol intake, type II diabetes mellitus and left ventricular hypertrophy but had no symptoms of heart failure or coronary artery disease. The GFA medical standards are explained in GFA Operational Regulations at subparagraph 3.2. Pilots who do not suffer from any of the listed disqualifying medical conditions, and who do not hold instructor or charter pilot qualifications, are eligible to self-declare their medical fitness. In all other cases, the pilot is required to submit to a medical examination and hold a valid medical certificate. Pilots who do not hold a valid CASA Civil Aviation Medical Certificate are required to be assessed by a legally qualified Australian registered medical practitioner and found fit to fly in accordance with the 'Austroads' standards for the issue of a private motor vehicle driver's licence medical certificate. The 'Austroads' standards are contained in their publication 'Assessing fitness to drive for commercial and private vehicle drivers: medical standards for licensing and clinical management guidelines, March 2012', or a later version as is in force from time to time. On 12 September 2017, as part of his annual online membership renewal, the pilot declared that he was not suffering from any physical condition that would preclude him from operating a glider as pilot in command. In the aforementioned statement to Police, the pilot's treating cardiologist stated: "According to the 'Austroads' standards (current) regarding cardiac issues, he (sic) had no reason to limit or deny him a licence for a private motor vehicle. His LVH (Left Ventricular Hypertrophy) on echo had not



Accident and Incident Summaries

caused any clinical or echocardiographic heart failure." Several witnesses observed that the pilot was overweight and occasionally breathless, but on the day of the accident he was variously described as his 'normal' or 'jovial' self.

1.6. Aircraft information

- Manufacturer: Jonker Sailplanes Pty Ltd
- Type: JS1C 18/21
- Country of manufacture: South Africa
- Year of manufacture: 2013
- Serial Number: 1C-055
- Engines: 1 x Turbine Jet Engine MD-TJ42
- Total airframe hours: 279.37 (90 Flights)
- Total engine hours: Zero
- Certificate of Airworthiness: Experimental
- Maintenance Release: No. P1687, until 21 September 2018
- Max allowable take-off mass: 720kg (21 Metre configuration)
- Max cockpit load: 115 kgs
- Stall speed (all-up mass): 56 knots at maximum weight

1.7. Meteorological information

The weather at the time of the accident was good. The weather observation by the contest organisers at the time of the accident was:

- Surface wind WNW at 5 to 7 kts;
- Outside Air Temperature of 31°C; and
- Sea level pressure of 1010 hPa.

1.8. Communication

Goondiwindi (Qld) aerodrome is situated in non-controlled Class G airspace. As it is a registered aerodrome the carriage of radio is mandatory for aircraft operating within its vicinity. An aircraft is in the vicinity of a non-controlled aerodrome if it is within:

- airspace other than controlled airspace;
- a horizontal distance of 10 NM from the aerodrome (reference point); and
- a height above the aerodrome (reference point) that could result in conflict with operations at the aerodrome. Consequently, all aircraft flying in the competition were radio equipped. The primary frequencies authorised for use by competitors were:
- CTAF: 126.70
- Safety: 122.025
- Aerotow Retrieves: 122.5
- Finish: 126.70 (CTAF)

1.9 Aerodrome information

The Goondiwindi Airport is a CASA registered airport under the Civil Aviation Safety Regulation Part 139 for Aerodromes. The airport site lies approximately 3km north of the town of Goondiwindi on the western side of the Cunningham Highway. The airport provides a limited scale of commercial air charter services and serves an important function for private aviation access to Goondiwindi for residents in the region. The aerodrome operator is the Goondiwindi Regional Council. On the day of the accident, gliding operations were being conducted on the left-hand (grass) side of runway 22. Gliders were gridded in two rows.



Accident and Incident Summaries



Figure 2: Goondiwindi Aerodrome (Google Maps)

Airstrip details:

- Aerodrome Reference Point 28° 31.6' S 150° 19.5' E
- Aerodrome Elevation 714ft above mean sea level

Runway Information for RWY 04/22:

- Runway Bearing 033 degrees magnetic
- Length 1340m x 30 m wide
- Slope 0.1% down to NE
- Length of Clearway 60m each end
- Dimension of Runway Strip Length 1460m, width 50m (graded 90m)
- Surface sealed bitumen
- Runway Information for RWY 12/30:
 - Runway Bearing 123 degrees magnetic
 - Length 795m x 30m wide
 - Slope 0.1% down to SE
 - Length of Clearway 60m each end
 - Dimension of Runway Strip Length 915m, width 90m
 - Surface grey clay

1.10 Flight Recorders

The aircraft was equipped with an LXNAV LX9000 avionics system, with serial number 09924. According to the manufacturer's website the device contained various sensors to provide inertial, variometer, attitude and heading reference system, and wind information. It was also equipped with an engine noise level sensor and had a flight recording function.



Accident and Incident Summaries



buttons, and internal electronic components (refer Figure



Accident and Incident Summaries



Figure 4: The damaged LXNAV LX 9000 taken from VH-IBS

The Gliding Federation of Australia is not equipped to forensically examine damaged electronic components. The assistance of the ATSB was sought to download information from the avionics unit, and the GFA arranged for the NSW Police to send the unit to the ATSB facilities in Canberra. The ATSB contacted the manufacturer of the device for information regarding the physical location of data recorded on the device. The manufacturer advised that the flight data was stored on a micro-SD card located on the rear of the main circuit board. Examination of the micro-SD card holder found it to be damaged. The ATSB removed the micro-SD card from the holder (refer Figure 5). The micro-SD card was SanDisk 16GB card. It was found to contain a crack in the middle of the card, consistent with the damaged area on the holder (refer Figure



Accident and Incident Summaries





Accident and Incident Summaries

Figure 6: Micro-SD card from the unit, damage to the micro-SD card is marked in the red box The ATSB subsequently had the card x-rayed to determine the extent of the damage (Figure 7). The damage found during the examination made it unlikely that the device would function correctly, however there did not appear to be any short circuits. The device was connected to a forensic read-only card reader; however, it did not respond correctly and was unable to be downloaded. Micro-SD cards are entirely encapsulated devices. No internal parts are removable or replaceable. Recovery of the device may be possible by exposing memory chip interconnects and connecting these to an identical micro-SD card controller. This process would involve significant resources. The ATSB currently does not have the hardware or resources to carry out such a task. No analysis was undertaken.



*Figure 7: X-ray of micro-SD card*The following conclusions were made with respect to the examination of the avionics unit provided to the ATSB:

- The device exhibited signs of damage both internally and externally.
- The flight data was stored on a micro-SD card located on the main circuit board.
- The micro-SD card containing the flight was damaged and unreadable.
- The ATSB was unable to determine the state of the memory integrated circuit.
- The ATSB does not have the hardware or resources required to attempt recovery on the memory IC encapsulated within the device.

1.11. Wreckage and impact information

Examination of the occurrence site and wreckage indicated that the glider struck the ground in a very steep nose-down attitude. The GFA's Regional Manager Operations (RMO) assisted the Police at the scene. In his report emailed to the GFA's Technical Advisor on 1 October 2017, the RMO noted: "Approaching the scene, I could only see the wings, fin, tailplane, and aft fuselage boom. From closer-up it became evident that the rest of the aircraft was reduced to debris and largely obscured in the impact hole in the black soil. The wings were level and ground impacts indicated the wings struck more or less simultaneously. The wings were still attached together by the two main pins with the 21 m tips lying alongside. The fuselage forward of the wings



Accident and Incident Summaries

trailing edge was utterly destroyed. The aft fuselage was lying beside the wings, split down the boom, broken through in front of the fin, and the tailplane (less elevators) was still properly rigged to the fin."




Accident and Incident Summaries



Figure 9: Aerial photograph of crash site showing the ground scar left by the wing (yellow)

All flight control surfaces were accounted for at the accident site and were separated from their normal locations by the impact. Due to the extent of the damage, it was not possible for the RMO to identify much of the debris in the cockpit and forward fuselage area. Examination of debris excavated from the impact hole was inconclusive, and much cockpit equipment could not be found or identified; some items had been removed with the body of the pilot. Consequently, it was not possible to determine the airworthiness status of the glider prior to impact. Scars in the ground left by the wing (refer yellow line in Figure 9) suggest the aircraft was under load and travelling at a very high speed; likely in excess of 130 knots (240 kph). The RMO noted: *"From examination of the wreckage and the ground impact hole, it was evident that:*

- The glider did not break up in mid-air;
- It struck the ground with huge energy;
- It struck in a steep nose down attitude;
- The wings struck the ground more or less simultaneously;
- There was no tail compartment battery and a tiny amount of water drained from the tail when it was moved; and
- There was no other sign of water draining from the wreck and the water ballast compartments were empty."The RMO located and identified the aircraft Maintenance Release, the LNAV avionics unit, the radio, the FLARM display and the altimeter face.



Accident and Incident Summaries



Figure 10: collection of instruments recovered from the accident site.

In respect to the Maintenance Release, the RMO noted in his report that "...the daily inspection had been signed the previous morning by the pilot." The RMO further stated that the "... accident flight was the first since the annual inspection and GFA Form 2 Maintenance Release issue on 18 September 2017, so technically this was the 'evaluation flight'."**1.12.** Medical and pathological information

A post-mortem examination revealed that the pilot had died of severe multiple injuries, all of which were consistent with the impact. In the autopsy report dated 20 November 2017, the pathologist noted:

- 1. The CT report showed catastrophic injuries involving comingling of all soft tissues, internal organs and the entire appendicular and axial skeleton. There was complex comminution of all long bones, multiple separations of the spine, fragmentation of the cranial and facial bones, comminution of the mandible, a complex pelvic fracture and multiple rib fractures.
- 2. The deceased had a history of heart disease, however, at autopsy examination the heart could not be identified (The pilot's treating cardiologist would clarify, in a statement to NSW police dated 14 December 2017, the pilot had no symptoms of heart failure or coronary artery disease.).
- 3. Toxicology showed a low liver alcohol level of 0.022g/100mL, most probably decomposition alcohol and not relevant.
- 4. Histology was non-contributory.

1.13. Survival aspects

The impact was not survivable. The cockpit structure was destroyed by impact so that no liveable space remained, and the deceleration forces exceeded those of human tolerance.

2. ANALYSIS

2.1. General

The aircraft had a current Maintenance Release and was properly maintained. No evidence was found of any defect that could have caused or contributed to the accident. The pilot was properly certified and authorised to fly the aircraft in competition. The weather was good, and the pilot was in good spirits. Thermal turbulence was weak, with one pilot reporting a climb rate of about 1.5 knots or 150ft per minute.



Accident and Incident Summaries

2.2. Aircraft

The Jonker Sailplanes JS-1C Revelation is a high performance single-seat sailplane. It has shoulder wing with flaperons, conventional T-type tailplane, with triple blade airbrakes on the wing upper surface, water ballast tanks in the wings and fin, a retractable main landing gear with brakes, and 18m or 21m span wings including winglets (refer figure 11). It is constructed from glass-fibre, carbon fibre and Kevlar. The manufacturer is Jonker Sailplanes of Potchefstroom, South Africa. The accident aircraft, VH-IBS, is a JS1-C 18 model with the 21m tips fitted. It was also fitted with a turbo jet engine (refer Figure 12) for sustaining height and self-retrieve. It was constructed in 2013 to the Certification Specifications for Sailplanes and Powered Sailplanes as described in EASA document CS-22, issued 14 November 2003. Although the aircraft met the South African type certification requirements as stated in their Civil Aviation Regulations Part 21 Subpart 2, Australia does not recognise the South African type acceptance system. Consequently, the aircraft was issued with an Experimental Certificate of Airworthiness on 12 March 2014 by the Gliding Federation of Australia under delegation from CASA.



Accident and Incident Summaries





Accident and Incident Summaries

Gliders are stowed and transported in disassembled configuration, with the wings and horizontal stabiliser being detached. To minimise the possibility of incorrect assembly in this model glider, the designers included automatic connection of the controls during rigging.



Figure 12: Jet system illustration

2.2.1 Aircraft maintenance

The airframe was maintained in accordance with the GFA system of maintenance, and the engine was maintained in accordance with the manufacturer's requirements. In addition, the aircraft operator was also required to comply with all special Inspections and lifed component changes which are listed in:

- 1. A schedule of Airworthiness Limitations contained in the Maintenance Manual applicable to the aircraft;
- 2. Approved data relating to modifications incorporated in components in the aircraft; and

3. Approved data relating to modifications incorporated in components installed in the aircraft. The aircraft was purchased new from the factory in 2013 and the initial Maintenance Release was issued on 3 March 2014 by a GFA Approved Maintenance Organisation (AMO) in Qld. The most recent annual inspection was undertaken in September 2017 by the pilot. A Victorian-based AMO oversaw the pilot's maintenance and issued the Maintenance Release on 22 September 2017. The authorising engineer and principal of the AMO is a CASA Licensed Aircraft Maintenance Engineer with over 30 years' experience. He also holds GFA maintenance qualifications enabling him to maintain gliders. In a statement to NSW Police dated 15 May 2015, the AMO principal advised: *"[The pilot] completed the work. I conducted the final inspection of what had been done; no flight controls were removed during the entire process, and during the inspection the flight control system was inspected, including gap seals. No defects were noted. After the inspection was completed, [the pilot] and I rigged the glider and I carried out all flight control deflections and wing frequency checks. The aircraft was in an airworthy state when it left [my company]." 2.2.2 Aircraft performance*

The aircraft flight manual notes, at Section 1.1, that "The JS1 Revelation is a high-performance sailplane and not a trainer. Even though it possesses excellent performance and handling qualities, it can only be flown by a skilled pilot who complies with the limitations and recommendations set out in this manual." The aircraft had a maximum speed never to be exceeded of 146 knots when flown in 21-metre configuration. The flight



Accident and Incident Summaries

manual advises "Do not exceed this speed in any operation and do not use more than 1/3 of control deflection." Operating above this speed is prohibited as it may result in damage or structural failure. Theoretical performance in 21-metre configuration gives a claimed best glide of around 1:60 at 65 knots and maximum weight (refer figure 13).



VH-IBS had been flown on a number of occasions by an experienced glider pilot and a commercial pilot flying for a major international airline. In a statement to NSW Police dated 15 April 2018, this pilot advised: *"I had previously flown [the Pilot's] glider on a number of occasions, it was a fantastic glider. It was a big glider when configured with the 21-metre wing. The handling characteristics changed with the 21-metre wing with a slower roll rate and needing more rudder to aileron to co-ordinate the aircraft. If in 18-metre wing configuration it was a lot easier to handle." This aircraft is certified in the Utility category, and some basic aerobatic manoeuvres (e.g. spins, stall turns, positive loops, chandelle) are permitted in 18-metre configuration only. Aerobatic manoeuvres are not permitted when flying with water ballast. As previously mentioned, three pilots observed the glider heading earthward in a steep nose-down position. In view of these observations, the spinning and spiral dive characteristics of the glider are reviewed hereunder. A graphical depiction of the spin and spiral dive is at Figure 14.*



Accident and Incident Summaries





Accident and Incident Summaries

A stall with wing drop can result in a spin if the glider remains stalled, or a spiral dive if it unstalls. The characteristic symptoms of the spin (i.e. those which are obvious without input from the pilot) are:

- a usually nose-down and rapid rotation of the glider (if the spin is unstable the rate of rotation and the pitch attitude may change periodically);
- low or flickering indicated airspeed;
- very high rate of descent; and
- no increase in 'g' force.
- The characteristic symptoms of a spiral dive are:
- the speed increases rapidly;
- 'g' force increases if the stick is held back or moved back;
- the rate of rotation is markedly slower than most spins; and
- the controls feel heavy but are effective.

2.2.2.1 Spin recovery

The aircraft flight manual notes that spin recovery is performed using the standard recovery procedures. Intentional spins with water ballast or in 21-metre configuration are prohibited. The standard recovery procedure is:

- full opposite rudder to reduce the amount of yaw, and indirectly (as a result of roll coupling) to help pitch the nose down.
- centralise the ailerons to reduce the down going wing's Angle of Attack.
- move the stick progressively forwards until the rotation stops to unstall the glider, even though the nose is already pointing steeply downwards. In powered aircraft it is usual to pause between applying opposite rudder and moving the stick forward. In gliders this isn't necessary.
- centralise the rudder when the rotation stops to prevent a spin in the other direction, and also to prevent high sideways loads on the fin as the speed increases.
- recover from the ensuing dive.

Altitude loss during recovery from a spin is between 100m and 150m (330 ft to 500ft) without water ballast and up to 220m (720 ft) at maximum weight. The spin rotation speed is relatively low, typically five to six seconds per rotation. The flight manual notes that if the spin is entered with a high incident angle, the nose will oscillate in pitch during the first two rotations. After approximately one rotation, the nose will (with very aft CG positions) rise above the horizon before stabilizing in a nose down spin attitude. Pitch oscillation may continue during the spin, especially with aft CG positions. In an email to the GFA's Technical Advisor dated 16 October 2017, the manufacturer advised that, according to certification spin test results, the aircraft is unlikely to enter a spin with the CG so far forward (as with the accident aircraft), and recovery is usually automatic after 1 turn even if pro-spin control input is maintained.

2.2.2.2 Spiral dive recovery

The aircraft flight manual states that a spiral dive may occur when:

- 1. The aircraft terminates spinning automatically should the pilot continue applying into-spin control inputs.
- 2. During excessive slip angles with full rudder deflection.

Indications of a spiral dive are high bank angle, increasing airspeed and a high G-loading. Spiral dive recovery is performed by:

- 1. Apply aileron, co-ordinated with rudder, gently against the direction of the turn until the wings are level with the horizon.
- 2. When the wings are level, neutralize both aileron and rudder.
- 3. Gently pulling out of the resulting dive.

During the resulting dive the pilot must take care not to exceed VNE. With water ballast in the wingtips a glider has substantially more roll-wise inertia and will not respond as quickly to aileron deflection. Consequently, the aforementioned spiral dive recovery technique will take longer to occur, thereby increasing the height loss during recovery. The recovery techniques from a spin and a spiral dive aren't the



Accident and Incident Summaries

same since in the spin the object is to break the stall by reducing angle of attack and increasing airspeed and in the spiral dive the goal is to reduce speed.

2.2.2.3 Excessive sideslip recovery

The aircraft flight manual also notes that an excessive sideslip may occur when the pilot applies full cross control input. At a slip angle exceeding 20° rudder control forces reverse as the rudder is sucked into the wake of the stalled fin. The pilot's control inputs to recover from an excessive slip are:

- 1. Apply opposite rudder against the direction of the yaw.
- 2. When balanced flight is restored, neutralize both aileron and rudder.

The flight manual notes that if an excessive slip angle is not corrected with opposite rudder input, the secondary effect of yaw may cause the sailplane to roll and enter a spiral dive. It is not possible to prevent roll by applying full opposite aileron during excessive sideslip.

The flight manual cautions that the rudder control input force to recover from a side slip exceeding 20° is high (approximately 20daN) and increases if the speed is allowed to build up during the resulting spiral dive. The pilot must apply sufficient rudder input to recover from the sideslip to prevent spiral dive. 2.2.3 Mass and balance

The structural strength of an aircraft places upper limits on the weights it can support. The wings are selfsupporting but the fuselage and its attachments (tailplane, pilot, luggage, etc.) are suspended from the wings or spar. The designer of the aircraft has placed an upper limit on the weight in the fuselage (or nonlifting parts) which must never be exceeded. However other more critical issues arise when it is realised that the aircraft may not even fly if it is too 'nose heavy 'or too 'tail heavy', that is, if the centre of the mass (centre of gravity (CG)) is too far forward or too far aft. The consequences of too little weight at the nose, resulting in a CG aft of the aft limit, are that the aircraft may pitch up, be unstable, even uncontrollable, impossible to trim, and impossible to recover from a stall or spin. Too much weight in the cockpit will result in a forward out-of-range CG, making the pilot use full back stick/elevator (beyond trim range) to maintain speed, leaving no capacity to flare the glider on landing. Advanced gliders carry additional weight (as water) in the load bearing parts (wings). This water ballast can enhance performance but also affects the weight and balance of the glider. Water ballast is generally quite close to the spar (0.15m say), but can still introduce a forward movement of CG, requiring back trim. Some gliders are fitted with an auxiliary tank in the tail to permit a counter balance. The safe limits for water are recorded in the flight manual. The manufacturer of the JS-1C provides the pilot with an 'Excel' spreadsheet specific to the glider to enable the pilot to calculate the CG at various loading configurations. Note: While the JS-1C was designed for a maximum all up weight of 720kgs in 21-metre configuration, the factory only demonstrated the glider to 600 kg.

2.2.3.1 Water Ballast

The water ballast system allows the weight of the aircraft to be increased to achieve higher wing loadings. The water ballast system consists of two main tanks, each integral to a wing and holding approximately 90 litres of water, and two trim tanks in the vertical fin. The tail ballast tanks consist of an expendable tank of approximately 7.5 litres and a non-expendable tank of approximately 5 litres. The 21 m wing tips also feature integral tanks, with a capacity of approximately 17 litres (17kgs) each.

2.2.3.2 Weight & Balance Calculations

On 8 October 2017 the pilot ballasted the glider to the weight he intended to fly during the competition. The aircraft was then weighed by the competition organisers to obtain a reference weight, which would be checked each day before flight. The aircraft are weighed in their flying configuration, including the pilot and parachute. The aircraft is initially positioned so that its mainwheel and tailwheel are each resting on a scale, and the weights at both locations are recorded. The aircraft is then connected to the pilot's towing vehicle (car) with the glider's mainwheel positioned on the scale, and the (tow out) weight is recorded. The glider's reference weight (usually the maximum all up weight) is recorded and the variation between actual weight and reference weight is recorded. A table of weights recorded for VH-IBS follows:



Accident and Incident Summaries

Rego	Main wheel	Tail wheel	Total	Tow out	Ref WT	Variance		
IBS	590	39	629	456	720	-91		
The tow pilot wi the glider was b unusual at all. V to the smaller gu looks perfectly n manufacturer's	ho launched th allasted on the Vhen towing th liders. I know it normal." The co principal enter lider's Contro s	e glider, in his s day of the acciv is type of glider, was ballasted l ompetition weig ed this data in t	tatement to NS dent: <i>"Upon co</i> , <i>it feels heavy</i> <i>because of the</i> hing data was the weight & ba	SW Police dated mmencing to to for four to five s usual accelerat forwarded to th alance calculato	27 November ow out, nothing seconds as it is ion and weight. ne Manufacture or for this specif (refer Figure 15	2017, confirme appeared heavy compare The JS-1 sits au for analysis. T ic aircraft to		



Flight date	e:	Flight number:			
	Enter load	ling only in this co	olumn		
	Loading points:	Max allowed (kg)	Actual Loading (kg)	Mass (kg)	Moment (kg.m)
Tot	Empty aircraft	400.0	361.0	361.0	212.5
Pilot	Pilot + Parachute	115.0	135.0	135.0	-77.6
NoseB	Nose ballast	11.0	4.0	4.0	-7.2
H2O Main	Water ballast main	180.0	44.0	44.0	8.8
H2O Tips	Water ballast tips	34.0	34.0	34.0	16.3
Tail1	Expendable tail tank	7.5	7.5	7.5	34.3
Tail2	Non-expendable tail tank	4.5	0.0	0.0	0.0
TailW	Brass Tail wheel (additional)	2.0	0.0	2.0	9.1
TailB	Tail battery	2.6	2.0	2.0	9.0
Bag	Baggage compartment	15.0	2.0	2.0	0.3
02	O2 bottle	2.0	2.0	2.0	0.0
Jet	Jet engine	3.5	0.0	0.0	0.0
JetS	Jet System	4.2	0.0	0.0	0.0
Fpanel	Jet Fuel panel	1.6	0.0	0.0	0.0
ECU	Jet Electronic Control Unit	1.2	0.0	0.0	0.0
Ftank	Jet Top Tank	1.2	0.0	0.0	0.0
Rtank	Jet Rear Tanks	2.8	0.0	0.0	0.0
FF	Jet Fuel Front (with water 11kg)	8.8	8.8	8.8	3.8
FR	Jet Fuel Rear (with water 33kg)	26.4	26.4	26.4	19.9
51 	8		Totals	628.7	229.2

Figure 15: VH-IBS Weight & Balance calculation based on competition weights.

628.7

543.2

51.2

44.3

364.6

312.6

Using known information (empty weight and balance, pilot weight with parachute, maximum weight during flight, and that the aircraft did not have the tail battery fitted or carried ballast in the nose and non-expendable tail tank), and assuming the pilot loaded the 21m tips first in accordance with manual and had about 2kg of luggage (water or similar) on board, the manufacturer arrived at two scenarios:

- Scenario 1 Expendable tail tank full In this case the aircraft was on a CG position of 352mm, well in front of the aft CG range.
- Scenario 2 Expendable tail tank empty In this case the aircraft was on a CG position of 300mm, well behind the most forward CG range.

With water ballast

Expendable water ballast dumped

229.2

169.8



According to the manufacturer's calculations and scenario interpretations it is highly unlikely that the aircraft was flown outside its CG range (refer Figure 16).



Figure 16: VH-IBS Calculated CG envelope.

The manufacturer also stated that, according to certification spin test results, the aircraft is unlikely to enter a spin with the CG so far forward, and recovery is usually automatic after 1 turn even if pro-spin control input is maintained. **NOTE**: Notwithstanding the manufacturer's comment about spinning, it is still possible for the aircraft to enter a spiral dive from a loss of control event, including excessive sideslip (as described in 2.2.2.3).2.2.3.3 Flight Crew

The minimum and maximum pilot mass is indicated on the cockpit placard.

- Minimum cockpit load: 70 kg (154.3 lbs)
- Maximum cockpit load: 115 kg (253.5 lbs)

Nose ballast may be added to enable lighter pilots to meet the minimum cockpit load. The nose ballast weights for VH-IBS were located in the glider's trailer parked at the aerodrome. The weight and balance calculator for VH-IBS, which is a factory supplied computer spreadsheet with data specific to that airframe, was obtained from the pilot's laptop computer. This spreadsheet recorded the weight of the pilot and



Accident and Incident Summaries

parachute at 130 kgs. This weight is consistent with observations made by some of the witnesses. At 135 kgs, the pilot was flying the glider outside the maximum cockpit load. This was in breach of GFA Operational Regulation 4.1.3, which states: "A pilot shall at all times operate a sailplane within the limits of its cockpit placards and shall not exceed the privileges of their authorisation(s)." In the case of the JS-1C glider, the maximum cockpit load is limited by the seat harness and not the glider's structure. As the weight & balance calculations demonstrate, the aircraft was being flown within the designed flight envelope. By exceeding the harness load of 115 kgs, the pilot assumed the risk that in a serious accident the harness was unlikely to restrain him, and he could suffer serious injury. In the case of this accident this is a moot point, as the accident was not survivable. The pilot was described as having a large build and was 6' 2" tall. The crew member noted, in his statement to NSW Police dated 21 November 2017, that the pilot "physically filled the cockpit and it was a very close fit due to his size. He had really big thighs so there was not a lot of spare room left in the cockpit." Another witness, in their statement to NSW Police dated 21 February 2018, stated "The cockpits of the gliders are inherently small and [the pilot] was a big man. I recall [the pilot] appeared comfortable in his glider, however it was a tight fit." The experienced competition pilot, in their statement to NSW Police dated 15 April 2018, stated "Although I did not see [the pilot] prepare or get into his glider prior to the flight on 9th October 2017 I have seen him prepare and get into the glider on previous occasions. Although he was a big guy, he did not have much difficulty fitting into the cockpit of the glider. Coordination in flying the glider that [the pilot] owned, in particular in 21 metre configuration, could be demanding but there would have needed to have been a significant issue for the glider to have entered the dive before the accident." The crew member and the experienced competition pilot both commented that they believed the pilot could adequately manipulate the flight controls surfaces (elevator, ailerons and rudder).

- Crew member: "I do not recall seeing [the pilot] exercise full and free movement of the controls. There is such a thing as a Chaotic Check27 but I did not see [the pilot] undertake this bit I noticed control deflection such as movement of the flight control system, it appeared that [the pilot] had movement of the controls."
- Experienced competition pilot: "I also believe that [the pilot] had full control movement of the glider whilst he was flying as he had been flying the glider for a couple of years without issues."

2.2.4 Aircraft instrumentation

The aircraft was equipped with a Pitot-static type airspeed indicator, an altimeter, a magnetic compass, a variometer and a LXNAV LX9000 avionics system providing navigation display. On the left of the instrument panel was mounted the Jet Display Unit (refer figure 17).



Figure 17: Left - Instrument panel layout (Note: the centre screen was replaced with the LX9000) and Right -Jet Display unit with Information displayed.

<u>2.2.5</u> <u>Aircraft systems</u> The aircraft ancillary controls of airbrakes, flaps, trim and landing gear are of conventional layout, with the airbrakes, flaps and trim located on the left-hand side of the cockpit, and the landing gear on the right-hand side of the cockpit.



Accident and Incident Summaries

2.2.5.1 Landing Gear Operation

The landing gear handle is located on the right-hand side of the cockpit and labelled as illustrated in Figure 18.



Figure 18: Landing gear handle.

Pulling the handle backwards retracts the wheel into the fuselage and pushing it forward extends the wheel. The handle is rotated firmly towards the cockpit side to lock in the extended and retracted position. The Aircraft Flight Manual does not recommend retracting the landing gear on aerotow. As previously stated, the pilot was a person of large stature. When the GFA's Technical Advisor sat in the cockpit of a similar JS1 glider he identified that raising the landing gear would have been difficult in flight for a larger person. This was because the pilot's arms would be constricted when placed between the side of cockpit and torso. It is considered unlikely the pilot would have had the room to move the right arm sufficiently backward to fully retract and lock the landing gear, and the use of both hands may have been needed. Other JS-1 pilots, of smaller stature, advised the GFA's Technical Advisor that it was difficult get the leverage needed to engage the rearward locking mechanism and needed exertion of force. One pilot said that he 'bunted' the aircraft to get the landing gear locked up. If the pilot was flying left-handed because he changed hands to raise the landing gear, the act of pulling backwards with the right hand may have led to the pilot also moving the left hand and possibly applying pressure to one of the rudder pedals. Such action could cause the aircraft to pitch and yaw, which coupled with a forward Centre of Gravity could lead to the aircraft departing controlled flight and entering a spiral dive. A spiral dive may also occur if depression of the rudder only resulted in a sideslip as described at 2.2.2.3 above.

2.2.5.2 Personal Egress Device

The pilot was using an egress device known as a *"Whoopsie Cushion"* that was designed and manufactured by another glider pilot. The device is intended to be used to assist the pilot quickly get out of the cockpit following a mid-air collision and parachute to safety. The system's main element is an air cushion that is inflated by pressurised gas (CO2). It is not dissimilar to a car's airbag, except that it is manually operated (refer Figure



Accident and Incident Summaries



Figure 19: Left - Deflated cushion and pouch. Right - Inflated cushion.

The pilot places the deflated cushion on the seat pan of the glider and sits on it. The system is designed such that the pilot then places a pouch containing the pressurised gas cylinders onto a thigh strap in easy reach. In the case of an emergency requiring the pilot to abandon the aircraft, the pilot would:

- 1. jettison the glider's canopy;
- 2. undo the seat harness;
- 3. open the flap of the pouch to reveal a lanyard attached to the actuators; and
- 4. pull the lanyard to activate the flow of gas.

When the lanyard is pulled, compressed gas flows from the cylinders and inflates the cushion. The inflating cushion pushes the pilot upwards and above the cockpit side, enabling them to roll out of the aircraft. The device was designed to be used as personal apparel at the pilot's own risk. It was not designed to be fixed to the aircraft structure; consequently, it did not need to meet any certification requirements. The investigation examined whether inadvertent activation of the egress device led to the pilot losing control of the glider. The designer and manufacturer was interviewed by NSW Police on 18 January 2018. In their witness statement they advised that it was not possible to accidentally or inadvertently activate the device as supplied, because it requires at least two deliberate, considered actions – opening the Velcro sealed pouch, and pulling the lanyard. Nevertheless, and in response to feedback from prospective users, the manufacturer also supplied a small disposable knife with the pouch to deflate the cushion if needed.



Accident and Incident Summaries



Figure 20: Cushion and gas cylinders at the accident site.

The manufacturer's review of the cushion in the wreckage (refer Figure 20) revealed that the gas cylinders had been affixed to the cockpit structure, possibly at the base of the instrument panel. It appears the cylinders were not contained in the pouch, so it is possible the actuating lanyard was within the pilot's reach. If so, the safeguards against inadvertent activation would not have been present. The manufacturer was provided with copies of photographs taken of the cushion at the accident site. According to him the cushion did not display the tell-tale signs of activation (split seams and deformation). The designer and manufacturer concluded they were "...of the opinion that the cushion has not inflated. I can see two tears in the cushion, but they are not ruptures due to pressure because my experiments during development showed that the weak points were the seams of the cushion."2.3. Human Factors

Several human factors related to this incident have been discussed in previous sections, among them the pilot's lack of flying currency, large stature, and possible excessive control inputs when retracting the landing gear.

2.4 Survivability

2.4.1 Rescue fire service response

The accident occurred at around 1326 hours and emergency services were called immediately thereafter. The emergency services responded quickly. The Queensland Fire and Emergency Services received notification of the accident at about 1329 hours, and their first unit arrived at the accident site at 1351 hours. On arrival they observed that Police and QLD Ambulance officers were already in attendance, those having arrived at around 1346 hours. NSW Rural brigades also attended the incident scene however their approximate arrival time was not recorded.

2.4.2 Analysis of injuries and fatalities

The crash was nonsurvivable and, within the limits of the autopsy, no natural disease which could have caused or contributed to the accident was identified. The toxicological examination did not reveal any factors which might have influenced the performance of the pilot. The medical pathologist noted: "It is not possible to comment on whether this accident was the result of pilot error, an aircraft fault or a natural disease event."

2.5.3 Survival aspects

The cockpit structure was destroyed by impact so that no liveable space remained, and the deceleration forces exceeded those of human tolerance. The impact was not survivable.

3. CONCLUSION

Witness reports evidence the glider departed controlled flight at a height between 2,000 ft and 1,000 ft AGL. Witness observations of the glider pointing steeply earthwards, rotating at a high bank angle with the wings under load is indicative of the aircraft being in a spiral dive. This is also supported by the ground scars at the



Accident and Incident Summaries

impact site. Given the high mass of the glider and water ballast in the wingtips, it is likely the glider did not have sufficient height for the pilot to recover, presuming the pilot was not otherwise incapacitated. **3.1. Findings**

- 1. The pilot was certified and qualified for the flight in accordance with existing regulations.
- 2. The pilot lacked recent flying practice and only had modest experience on type.
- 3. The pilot had not completed an Annual Flight Review.
- 4. The maintenance records indicated that the aircraft was equipped and maintained in accordance with existing regulations and approved procedures.
- 5. The aircraft was airworthy when dispatched for the flight.
- 6. Due to the destruction of the aircraft by the impact, it could not be determined whether any preimpact failure or system malfunction contributed to this accident.
- 7. The pilot was flying the glider outside the maximum permitted cockpit load.
- 8. The mass and centre of gravity of the aircraft were within the prescribed limits.
- 9. The glider departed controlled flight and entered a spiral dive, from which there was insufficient height available to effect a recovery.
- 10. The lack of a data from the avionics unit covering the period of the incident prevented some details of the events from being resolved.
- 11. There was no evidence that the pilot suffered any sudden illness or incapacity which might have affected his ability to control the aircraft.
- 12. Toxicological tests were negative.
- 13. The accident was not survivable due to the magnitude of the deceleration forces.**3.2.** Causal factors

Due to the extent of damage to the glider and the injuries sustained by the pilot, it was not possible to determine the cause of this accident with any certainty.

- The pilot may have suffered a catastrophic medical event. This cannot be discounted as the autopsy was inconclusive.
- A maintenance error may have left the aircraft unairworthy resulting in the pilot's loss of control. This is considered unlikely given: 1. a post-maintenance dual inspection of the aircraft was undertaken that confirmed the functioning and security of the controls; 2. the aircraft controls automatically engage during assembly; 3. the pilot conducted a pre-flight inspection the previous day and certified the aircraft as airworthy in the aircraft Maintenance Release; and 4. The airframe and all control surfaces were accounted for at the crash site.
- The pilot may have contributed to the loss of control. The accident occurred shortly after release from tow and during the period the pilot would be conducting the post-release configuration, which includes raising the landing gear. As outlined earlier, the pilot may have experienced difficulty retracting the landing gear. Due to cockpit ergonomics, the pilot could have inadvertently applied control inputs through the control column and/or rudder pedals while in the course of manipulation of the landing gear lever leading to the aircraft departing controlled flight.

4. SAFETY RECOMMENDATIONS

- 1. The GFA to develop and disseminate pilot education material regarding minimum impediments to operation of controls, controllability and other safety considerations for large pilots.
- 2. The GFA to include advice regarding conversion of pilots to high wingspan, high inertia gliders, and controllability considerations in its current update of the GFA Training Manual.
- 3. The GFA Operations Department to review, and update as required, its guidance to instructors and pilots on safety implications of low recency and currency, especially in regard to older pilots and pilots entering competitions.

Date 9-Oct-2017 Region SAGA SOAR Report Nbr S-1056
--



Accident and Incident Summaries

Level 1	Technical	Lev	el 2	Powerp	lant/P	ropu	lsion	Level	3	Abnormal Engine	
										Indication	s
A/C Mod	el 1	Sup	er Di	mona		A/C	Model	2			
Injury	Nil	Damage		Nil	Pha	ase	In-Flig	ght		PIC Age	71
The pilot	was conducting	a positioning	VFR 1	flight from	Darw	in NT	to Para	afield S	A. Ab	out 45 NM	north of Alice
Springs a	t 9,500ft AMSL,	the motor glic	ler's	engine beg	gan su	rging	and ru	nning r	ough	ly. The pilot	was unable
to increa	se power by mo	re than 45% b	ut wa	as able to r	nainta	in he	eight. Tl	he pilot	cont	acted Air Tr	affic Control
(ATC) to a	advise of the eng	gine problems	and	declare an	emer	gency	y. The p	oilot red	quest	ed a diversi	on to the
gliding ai	rfield at Bond Sp	rings airfield,	inclu	ding perm	ission	to er	nter Cla	ss C co	ntroll	ed airspace	so as to
maintain	glide slope for a	landing at th	e dive	ersion airfi	eld. A	TC co	ordinat	ted witl	h the	Alice Spring	s tower, and
the aircra	aft was cleared t	o proceed as i	eque	ested with	no res	tricti	ons or	require	ment	s. The Aircr	aft safely
landed at	t the diversion ai	rfield and the	eme	rgency pha	ase wa	as car	ncelled.	Subse	quent	: investigation	on, including
a check o	of the fuel systen	n and carbure	ttors,	, did not id	entify	the s	ource	of the t	roubl	e but the ov	wner
suspects it may have been due to fuel contamination.											

Date	9-Oct-2017	Regior	Region SAGA SOAR Report Nbr S-1060							1060	
Level 1	Airspace	1 0 -	Level 2	Airspac	e Infri	ingen	nent	Level	3	Airspace In	nfringement
A/C Mod	el 1		HK 3	5 TTC		A/C	Mode	2			5
Injury	Nil	Dama	age	Nil	Pha	ase	In-Fli	ght		PIC Age	71
The pilot	inadvertently er	ntered Ali	ce Sprin	gs controlle	d airs	pace	while a	waiting	g a cle	earance. The	e pilot was
navigatir	g using AvPlan, v	which is a	in appro	ved applicat	tion, b	ut th	e airsp	ace rad	ials n	orth of Alice	e springs
were not	displayed on the	e 'MegaV	FR' char	t being view	ed by	the p	oilot. Th	ne mati	ter wa	as raised wit	h Airservices
Australia	who advised the	e followin	ig:								
1.	MegaVFR chart (Alice spr	ings) – V	/AC chart or	nly vie	w at	the zoo	om sele	cted.	No airspace	e boundaries
	visible.										
2.	MegaVFR chart (Alice spr	ings) - W	AC automa	tically	over	laid wit	h Alice	Sprir	igs VTC. At h	nigher levels
	of zoom the VTC	is display	yed to p	rovide great	er det	tail. A	irspace	e bound	laries	only display	yed as on
	VTC chart.										
3.	MegaVFR chart (Alice Spr	ings) - W	AC overlaid	l with	Alice	Spring	s VTC a	nd "A	irspace ena	bled in
	AvPlan". Same zo	oom leve	l as 2, bi	it AvPlan is	supple	emen	ting th	e missi	ng air	space boun	daries in this
	instance.						_				
4.	Alice Springs onl	y VIC cha	art – Cor	nplete VIC (overla	id on	Open	Street r	nap. /	Airspace bo	undaries are
	visible as per the	e area cov	ered by	VIC. The ma	apping	g syst	em wo	rks by I	ayerii	ng maps tha	t display the
	displayed will sh	ivaliable i	for the a	rea currenti	iy in vi om /fi	ew. L	Jepend	ling on	the zo	oom level tri	ie map
	highost zoom/cl	ow the w	icolov T	ho usor has	tho	ntion	ofona	lispiay bling th		tom to chevi	c at the
	fill in the missing	bounda	rips (as r	or 3) If flyi	ng wit	h inst	naner	version	ne sys	the WAC and	d VTC the
	same issue woul	d have he	en enco	untered In	sumn	narv t	he Δir	Service	s man	nroducts h	ave the
	required level of	detail w	hich ann	ears to be r	eflecte	ed in	the thi	rd nart	v AvP	lan product	when
	"zoomed" to the	requirec	level. A	vPlan users	need	to be	aware	that i	n cert	ain configur	rations and
	zoom levels, not	all inforr	nation is	displayed.							

Date	13-Oct-2017	Regior	egion NSWGA			SOA	R Repo	ort Nbr		S-1070		
Level 1	Technical		Level	2	Syster			Level	3	Other Syst	ems Issues	
A/C Mod	el 1	DG-1000S					A/C Model 2					
Injury	Nil	Dama	age	Nil	Phase In-			ght		PIC Age	58	
Prior to a	3.3 hour local so	paring flig	ght, the	e integral tail	ballas	t box	locate	d in the	e fin w	/as loaded w	vith five	
factory-supplied 2.4kg and 1.2kg brass weights. The glider was within its C of G limits for the two persons												



Accident and Incident Summaries

carried on the flight. After the flight the glider was not used again and was returned to the hangar. The ballast box is secured by a perspex cover incorporating a fixed pin which locates into a fitting in the bottom of the opening and a sliding plunger which must be pushed slightly inwards then fully up into a locating hole at the top. Additionally there is a manufacturer's requirement for the edges of the cover to be secured to the fin on all four sides with tape having a minimum width of 19mm. At the next daily inspection it was found that:

- the top plunger had not been pushed up into its locating hole, and was barely resting with a light spring pressure against the top of the ballast box,
- the top of the cover had moved outwards about 5 mm from the surface of the fin, and
- there was only one piece of tape present, that being on the vertical front edge of the cover, but it
 had been progressively peeling off from the top so that less than the bottom 15cm was still
 attached.Had the flight continued much longer, it is likely that the perspex cover would have
 completely detached from the ballast box, potentially allowing the weights to depart from the
 glider. The serious ramification of the five brass weights falling onto persons or property on the
 ground needs no further explanation.



Care must always be taken in properly securing any type of ballast, as failure to do so can lead to serious or fatal consequences.

Date	14-Oct-2017	Region		VSA			AR Repo	ort Nbr		S-1057		
Level 1	Operational		Level 2	el 2 Aircraft Cor			bl Level 3			Wheels up landing		
A/C Mod	el 1	ASW 20C		20C	A/C Mode		Model	2				
Injury	Nil	Dama	age	Nil	Pha	Phase Landing			PIC Age			



Accident and Incident Summaries

The pilot did not properly conduct the pre-landing check and landed with the undercarriage retracted. The pilot had launched to 2600ft AGL and joined two other gliders in a weak thermal. The pilot could not connect with the thermal and kept searching for lift while gradually losing height. At 1100ft AGL the pilot gave up searching for lift and headed to the circuit joining area. On downwind leg the pilot verbalised the pre-landing check list and confirmed the flap setting and trimmed for safe speed near the ground but did not check the undercarriage. The pilot noted that, while not current on type, "...I am relatively current, having flown passengers, instructed and done some aero(batic)s during the winter months. All of this was of course in the K21 where flaps and undercarriage get a mention during FUST but are never actioned." This is not an uncommon occurrence for pilots who are accustomed to flying gliders with a fixed undercarriage, where not having a lever to operate leads to familiarity and 'habit' such that the inaction becomes the normal routine. This 'normalisation of deviance' is easier to prevent than to correct, so pilots should always aim to do their checks diligently at all times and not be complacent.

Date	15-Oct-2017	Regior	n	VSA		SOA	AR Repo	ort Nbr		S-	1061
Level 1	Operational		Level 2 Aircraft Control Level 3 Hard lar					Hard landi	ng		
A/C Mod	el 1		DG-1	L000S		A/C	Model	2			
Injury	Nil	Damage Minor Phase Landing PIC Age						70			
The elder	rly pilot, who was in current practice, was attempting to land short rather than fly between two										
gliders or	n either side of th	ne runwa	y. Howe	ever, the pilo	ot misj	udge	d the a	pproac	h and	l landed lon	ger than
intended	. While focussin	g on land	ling bet	ween the glio	ders, t	he pi	lot mis	judged	the la	anding flare	and the
glider tou	uched down heav	ily and r	ebound	ed into the a	ir. The	e pilo	t pitche	ed forw	ard o	n the contr	ol column
and the r	nosewheel impac	ted the g	ground i	esulting in d	amag	e to t	he fairi	ng. Dui	ring tł	ne bounced	landing the
plastic handgrip on the airbrake lever came off in the pilot's hand. Investigation revealed that the pilot is									e pilot is		
prone to	prone to task saturation as workload levels increase, and they are now flying with a safety pilot.									safety pilot.	

Date	20-Oct-2017	Regior	า	VSA			SOA	AR Repo	ort Nbr		S-	1071
Level 1	Consequential	Events	Leve	el 2 Low Circuit Level 3 Lov				Low Circui	t			
A/C Mod	el 1	C	Grob G 103 Twin II A/C Model 2									
Injury	Nil	Damage Nil Phase Landing PIC Age							73			
The command pilot was conducting a right-hand (modified) circuit onto the operational runway when he									when he			
heard a C	Cessna aircraft jo	in a norn	nal left	t-har	nd circuit.	In ord	er to	avoida	a head-	on sit	tuation duri	ng the base
leg, the c	ommand pilot of	f the glid	er opei	ned	the airbra	kes ar	nd fle	w a no	n-stand	lard c	urved base	turn to land
well ahea	d of the Cessna.	The com	nmand	pilo	t misjudge	ed the	rate	of des	cent an	d cros	ssed the aer	odrome
boundary	/ fence at such a	low heig	ht that	t the	aircraft t	ouche	d dov	wn bef	ore it h	ad ali	gned with tl	ne runway
centrelin	centreline. The command pilot was counselled by their CFI who witnessed the incident.								ncide	ent.		

Date	21-Oct-2017	Region	1	SAGA SOAR Report Nbr						S-	1064
Level 1	Airspace		Level 2	Aircra	aft Sep	arati	on	Level	3	Near collis	ion
A/C Mod	el 1	D	G-500 Ela	n Orion		A/C	Model	2	Jabi	ru	
Injury	Nil	Dama	age	ge Nil Phase In-Flight PIC Age					49		
A Glider a conduction operation down the potential pilot that	and Jabiru got clo ng a midfield joir nal runway and v e crosswind leg t for both aircraft the glider will b	ose durin n of the ci was maint he pilot c to arrive e joining	g the dow rcuit, the taining th all enterin at the sa downwin	vnwind leg command e runway h ng downwi me point s d shortly a	of the pilot neadin nd. Th simulta head	e circu obsen ng. Th ne cor aneor of the	uit. Wh rved a J e Jabiru mmand usly and 2 Jabiru	ile the abiru h u then pilot in d md a . The so	glider nad ju turne n the radio econc	was over the st taken off d crosswind glider recog call advising pilot who	he cross-strip from the and halfway nised the g the Jabiru was flying
the glider, then gave a radio call on joining downwind. The command pilot noted the Jabiru pilot "still well											



Accident and Incident Summaries

behind us in what appears to be a climbing turn onto downwind". The glider was slightly high and wider than normal, so the pilot flying used some airbrake to descend 200ft. The command pilot then looks back over the right wing to the rear to get a visual on the Jabiru and noticed the Jabiru about 50ft lower and about 50 metres behind taken avoiding action by turning to the right. It is unclear why the Jabiru pilot did not sight the glider. The command pilot of the glider later reflected: *"I should have continued to assume we were unseen and/or the Jabiru pilot was unaware of us being there and used our extra height to extend further into the joining area and ensure we were behind the Jabiru."* By itself, the concept of 'see-and-avoid' is far from reliable. It is important that pilots apply the principles of 'see-and-avoid' in conjunction with an active listening watch. Research has shown the effectiveness of a search for other traffic is eight times greater under alerted circumstances than when un-alerted. Pilots should be mindful that transmission of information by radio does not guarantee receipt and complete understanding of the information. Without understanding and confirmation of un-alerted see-and-avoid. The club is looking at fitting Flarms to their light sport aircraft.

Date	22-Oct-2017	Regior	۱		NSWGA		SOA	AR Repo	ort Nbr		S-	1063
Level 1	Airspace		Leve	12	Aircra	ift Sep	arati	on	Level	3	Aircraft Separation	
											Issues	
A/C Mod	el 1		Piper I	PA-2	5-235		A/C	Model	2	RPA	S (Drone)	
Injury	Nil	Dam	age		Nil	Pha	ase	Landi	ng		PIC Age	61
Gliding o	perations were b	peing con	ducted	d on	runway 2	7 with	n land	lings lo	ng on r	unwa	y 15. Follow	/ing the first
launch of	f the day, a mem	ber decio	led to	drive	e to the th	nresho	old of	runwa	y 15 to	look	for a ruddei	r chock that
had gone	had gone missing earlier. While in transit the member saw two vehicles parked in the sealed parking area on											
the side o	of the highway a	djacent t	o the a	airfie	ld. After o	confirr	ning	the rud	lder ch	ock w	as not there	e, the
member	drove back to th	e operati	ional ri	unw	ay, during	g whic	h tim	e they	noticed	l a dro	one at abou	t 50ft AGL
flying no	rth, abeam the r	unway 15	5 thres	hold	l and insid	le the	airfie	ld bour	ndary; a	about	50 meters	to the east
side of ru	inway 15. The m	ember ol	oserve	d thi	ree or fou	r peop	ole be	eside tv	vo vehi	cles i	n the highw	ay parking
bay, one	of whom was in	control c	of the c	dron	e. The me	mber	drov	e out o	f the ai	rfield	to speak wi	ith the drone
operator	, but the two vel	nicles had	l depai	rted	north. Me	odel a	ircraf	t and d	lrones i	nust	not be flow	n within 5.5
kilometre	es of a non-contr	olled aer	odrom	ne if	there is a	mann	ed ai	rcraft c	peratir	ng to,	or from, the	e
aerodrome. The provisions of AC 101-3(0): 'Unmanned aircraft and rockets: Model aircraft' also apply.								apply.				

Date	23-Oct-2017	Region		SAGA		SOAR Report Nbr				S-1077	
Level 1	Operational		Level 2	ŀ	Airfrar	ne		Level	3	Doors/Car	iopies
A/C Mod	el 1		Discus	-2cT		A/C	Model	2			
Injury	Nil	Damag	ge	Nil	Pha	ise	In-Flig	ght		PIC Age	73
Shortly a	fter launch the pilot deployed and started the sustainer engine to confirm it was in order. The								er. The		
engine w	engine was run for two minutes and then stowed. This is the pilot's usual practice, as the engine cannot be										
started on the ground. The pilot then headed off on a cross-country task. About one hour into the flight the											
aircraft flew into some turbulence and the pilot heard a loud noise and whistling sound. The pilot identified											
the whist	ling was being c	aused by a	ir flowin	g through	a sma	ll gap	betwe	en the	cano	py and fuse	lage on the
starboard	d side. The pilot	returned fo	or home	and lande	d une	ventf	ully abo	out half	f an h	our later. Th	ne pilot
discovere	ed the canopy hi	nges were	not eng	aged in the	e locki	ng me	echanis	m but	was a	ble to open	the canopy
on the gr	ound with the h	elp of two	other pi	lots. Invest	tigatio	n rev	ealed r	no dam	age to	o the canop	y or hinges,
and it wa	s determined th	at the pilot	t inadvei	rtently pull	led the	e can	opy rel	ease le	ver, n	nistaking it f	or the fuel
open/ clo	ose valve lever th	nat was fou	ind in th	e 'open' po	osiitor	n. In t	his airc	raft the	e fuel	lever is loca	ited
immedia	tely below the ri	ght-hand c	anopy h	inge releas	se leve	er, an	d both	levers,	altho	ugh differe	nt sizes, are
painted b	olack. The Regist	ration Hold	ler advis	ed: <i>"The D</i>	Discus	C has	a diffe	rent ca	nopy	jettison sys	tem to
earlier models. The flight manual is quite clear that only the left-hand lever should be pulled in a canopy											



Accident and Incident Summaries

jettison situation, hence it's a requirement that ONLY the left lever is painted red, which it clearly is (actually red/white as it's also the main canopy opening lever). The hinges on the right-hand side of the C model are sacrificial and break away under load. That lever (actually a sliding knob) on the right is purely for removing the canopy on the ground and should expressly not be operated in a canopy jettison (i.e. emergency) situation. Hence, it's not painted red. It's poor design that this lever is situated adjacent to the fuel valve and is the same colour." This incident highlights the importance of the adage **'Locate, Identify and Operate'**. The fuel lever was permanently marked with a thin white stripe to aid differentiating it from the on-ground canopy detachment lever.

Data	20.0+2017	Desta				604	DD	a sate A Lla sa		6	1005
Date	28-Oct-2017	Regior	1	VSA		SOF	чк керс	ort NDr		5-	1065
Level 1	Operational		Level 2	Grour	aO br	eratio	ons	Level	3	Taxiing co	llision/near
										aalliaian	,
									-	consion	
A/C Mod	el 1		Disc	us CS		A/C	Mode	2			
Injury	Nil	Dam	age	Minor	Pha	ase	Grou	nd Ops		PIC Age	
While be	ing towed back t	o hangar	, the wii	ng walker w	heel st	truck	runwa	y gable	mark	er, causing	the aircraft
to separa	ite from tow bar	and colli	de with	back of tow	vehic	le. Or	n the m	orning	of thi	s incident tl	ne pilot was
to rig the	glider with the	intention	of carry	ing out the	post-n	naint	enance	assess	ment	flight. Whi	le rigging the
glider it v	vas noticed that	the wing	pin was	missing, so	the pi	lot ha	ad to m	nake a t	wo-h	our round-t	rip home to
retrieve i	t. The Glider wa	s then rig	ged, ins	pected and	signed	off.	The pilo	ot arriv	ed at	the flight lir	ne mid-
afternoo	n and eventually	complet	ed the a	ssessment f	light v	vitho	ut incid	lent. Th	e acc	ident occur	red due to a
lapse in c	oncentration af	ter a long	and stre	essful day.							

Date	28-Oct-2017	Region		VSA		SOA	AR Repo	ort Nbr		S-	1080
Level 1	Operational		Level 2	Run	way E	vent	S	Level	3	Runway ex	cursion
A/C Mod	el 1	0	SZD-51-1	Junior		A/C	Model	2			
Injury	Nil	Dama	ige	Nil	Pha	ise	Landi	ng		PIC Age	
,	1		0-					0		0-	

During flight the wind picked up in intensity and changed direction, and the gliding operation moved to the more into wind runway. The low-hours pilot had not identified the change of wind direction or operational runway and joined circuit for the runway they had launched from. The pilot only became aware of the wind direction and speed during the final approach but was committed to a landing. The pilot flew a crabbed approach but did not apply enough correction to prevent the aircraft from drifting towards the runway boundary. As a consequence, the glider touched down close the airfield boundary and the pilot had to initiate a ground-loop to avoid colliding with the boundary fence. The pilot was uninjured and the aircraft undamaged. Weather conditions can quickly change, so it is important that pilots monitor the windsock when entering the circuit. Pilots also need to remain aware of the crosswind components of their aircraft and land as near as possible into wind.

Date	29-Oct-2017	Regior	۱		GQ		SOA	AR Repo	ort Nbr		S-	1066
Level 1	Airspace		Leve	el 2	Aircra	ift Sep	arati	on	Level	3	Near collis	ion
A/C Mod	el 1		Α	ASK-2	21		A/C	Model	2	Cess	sna 172 R	
Injury	Nil	Dama	age		Nil	Pha	se	Thern	nalling		PIC Age	58
At this Re	gional aerodrom	ne, glider	s and	pow	vered aircr	aft fly	cont	ra circu	its as a	dvise	d in the ERS	A. This
incident i	nvolved a power	ed aircra	ıft flyi	ng tl	hrough the	e glide	r circ	uit. The	e stude	nt pilo	ot in the pov	wered
aircraft w	as performing a	n overhe	ad mi	d-fie	eld departu	ire an	d per	formed	l a clim	bing o	circuit to 20	00ft AGL in
close pro	ximity to a glider	. Had the	e stud	ent	pilot cond	ucted	a nor	mal cir	cuit the	e prox	imity event	would not
have occ	urred. The Club S	afety Of	ficer c	onta	acted the C	Chief P	ilot c	of the a	ircraft o	opera	tor, who ad	vised the
student p	student pilot was undertaking their first solo cross country and did not report the incident. The Chief Pilot											



Accident and Incident Summaries

undertook to debrief the student and ensure other students flying in the vicinity of the gliding operations were briefed on the ERSA requirements.

Date	30-Oct-2017	Regior	n	NSWGA	S	OAR Repo	ort Nbr		S-:	1072
Level 1	Operational		Level 2		Flight		Level	3	Aircraft pr	eparation
				Prepara	tion/Nav	/igation				
A/C Mod	el 1		LS 7	-WL	А	/C Model	2			
Injury	Nil	Dama	age	Nil	Phase	Laund	:h		PIC Age	
The pilot	forgot to lock th	e airbrak	es, whic	h came ope	n during	aerotow	launch.	The	pilot is expe	rienced
across a i	ange of flight dis	sciplines,	includir	ig general a	viation a	nd hang/p	oara glio	ding,	but has limit	ted
experien	ce in sailplanes (52 hours)	. This w	as the pilot'	s first flig	ght on typ	e and v	vas to	be the pilo	t's first
attempt	at a 300km cross	-country	flight. A	t about 300	ft AGL or	n aerotow	, the pi	ilot he	eard a bang.	The pilot
"…immed	diately checked t	ow rope	and nor	nal control j	functiond	ality. All a	ppeare	d nor	mal. While r	naintaining
the tow,	I checked all inst	ruments	and not	ced the radi	o was of	f and assu	umed th	he ba	ng was relat	ed to an
electrical	(possibly fuse) p	opping."	The tov	/ pilot recog	nised the	e airbrake	s had c	leploy	ed and sign	alled the
pilot, wh	o then realised tl	neir erroi	r and loo	ked the airk	orakes. Tl	he pilot d	ecided	to rel	ease from to	ow to land
and chec	k the problem w	ith the ra	dio. A i	ormal landi	ng ensue	ed. The pi	lot recc	gnise	d that they	were in a
hurry to	get away on time	and had	l rushed	the pre-tak	e-off che	eck list. As	a cons	eque	nce, the pilo	ot did not
recognise	e that the airbrak	es, while	closed,	were not lo	cked. As	for the ra	dio, th	e pilo	t believes th	ney knocked
the on/o	ff switch to off at	some st	age on t	ow. The pilo	ot took ai	nother lau	unch an	d suc	cessfully co	mpleted a
200km cr	oss-country fligh	it. The pi	lot was	debriefed by	their CF	ч.				•

Date	4-Nov-2017	Regior	n	SAGA		SOA	R Repo	ort Nbr		S-	1073
Level 1	Operational		Level	2	Fligh	t		Level	3	Other Flig	nt Prep/Nav
				Prepara	tion/N	laviga	ation			Issues	
A/C Mod	el 1		Dis	cus b		A/C	Model	2			
Injury	Nil	Dama	age	Nil	Pha	ise	Grour	nd Ops		PIC Age	55
During th and out a recorded recorded pre-boar	e Daily Inspectio and decided to no the entry in the in the Maintena ding check of the	n the ins ote this a Major De nce Rele Mainter	pector s a Min efect se ase. As nance R	noted the au or Defect in t ction. The air the inspecto elease, inclue	dio va the M rcraft r was ding D	ainte ainte was t the fi V vali	eter so nance l hen cle rst pers dity, wa	und wa Release eared fo son the as not u	is inte e. The or flig fly th under	ermittently of inspector method in the method of the metho	cutting in histakenly ajor defect n that day, a

Date	4-Nov-2017	Regior	۱		SAGA		SOA	AR Repo	ort Nbr		S-	1074
Level 1	Operational		Leve	el 2		Fligh	t		Level	3	Other Flig	ht Prep/Nav
					Preparat	tion/N	laviga	ation			Issues	
A/C Mod	el 1	DG-1000S A/C Model 2										
Injury	Nil	Dam	age		Nil	Pha	ise	Grour	nd Ops		PIC Age	69
During th	e daily inspectio	n it was i	notice	d the l	Mainten	ance l	Relea	se had	not be	en sig	ned on the	day the
aircraft la	ast flew. Investiga	ation rev	ealed	that o	on the da	y the	aircra	aft prev	iously 1	flew,	a Daily Insp	ection was
conducte	d but the inspec	tor got d	istract	ted red	ctifying t	he fla	t tailv	wheel a	nd forg	got to	sign the Ma	aintenance
Release.	As the inspector	was the	only p	berson	the fly t	he air	craft	on that	: day, a	pre-b	boarding ch	eck of the
Maintenance Release, including DI validity, was not undertaken.												

Date 4-Nov-2017 Region SAGA SOAR Report Nbr S-1076
--



Accident and Incident Summaries

Level 1	Operational		Level 2		Fligh	t		Level	3	Other Flig	nt Prep/Nav
				Prepara	tion/N	laviga	ation			Issues	
A/C Mod	el 1		Discus	s b		A/C	Mode	2			
Injury	Nil	Damag	ge	Nil	Pha	ise	In-Flig	ght		PIC Age	67
The aircra	aft was flown wi	th a major	defect r	ecorded in	the N	laint	enance	Releas	e. Th	e experienc	ed pilot did
not notic	e a Major Defec	r Defect was recorded in the Maintenance Release during the Pre-boarding Inspection.									
Fortunate	ely, the defect w	as only mi	nor and	did not aff	ect th	e safe	ety of f	light. Tł	ne pilo	ot advised t	hat they
checked	that the correct	Maintenan	nce Relea	ise was in t	the aiı	rcraft	, and tl	hat a Da	aily In	spection ha	id been
complete	ed by an authoris	sed inspect	or. The p	oilot did no	ot und	ersta	nd the	y also n	eede	d to check f	or defects
and othe	r issues. The pilo	ot noted that	at in futu	ure they wi	ill carr	y out	additi	onal ch	ecks d	of the Main	tenance
Release a	as follows:-										

- Check that the aircraft is still inside the Maintenance Release validity period;
- Check that there are no current Major Defects;
- Check the Minor Defects and ensure they are no worse; and
- Check that the aircraft still has the required hours left for my flight and at least one launch left before a scheduled maintenance item is due.

Date	5-Nov-2017	Region		GQ		SOA	AR Repo	ort Nbr		S-	1098
Level 1	Operational		Level 2	Airc	raft Lo	badin	g	Level	3	Loading re	lated
A/C Mod	el 1		Blanik I	.13 A1		A/C	Model	2			
Injury	Nil	Dama	Damage Nil Phase In-Flight PIC Age						PIC Age		
While co	nducting the pre-	boarding	g checklis	t the stude	ent pile	ot cor	nfirmed	l there	was r	no ballast in	the aircraft
but did n	ot consider the w	eights of	f the pilc	ts. The inst	ructo	r also	did not	t consid	der th	e weights o	f the pilots
and the a	aircraft subseque	ntly flow	15 Kgs c	ver the ma	vimur	n coc	knit loa	d and	with a	forward ce	ontre of

and the aircraft subsequently flew 15 Kgs over the maximum cockpit load and with a forward centre of gravity (CoG). All gliders must be flown within carefully defined CoG limits. To achieve this, the pilot weights must lie within the margins specified on cockpit weight and balance placards. Pilots must know how much they weigh to ensure that the weight requirements are met. In some cases, it is necessary to carry extra weight (ballast) to ensure the aircraft is within the CoG limits. A 'ballast' check is part of the pre-boarding checklist and must be completed before the pilots enter the aircraft to confirm that the cockpit loading is within the placarded limitations. Ballast will be added or removed as necessary. Checklists are an essential part of aviation and are used prior to all critical aspects of flight, such as take-off and landing, to ensure that the aircraft is correctly configured for the next phase of the flight. They serve as a formal reminder to help prevent errors of omission and contribute to a safer flying environment. Instructors must ensure their student's complete the checklists diligently, and be satisfied they have been completed correctly. NOTE: It is not uncommon for pilots to conduct successive flights without the need to alight from the glider. In such circumstances the pilot may assume that the pre-boarding ABCD components of the checks conducted before the previous flight (or first flight) remain valid, if it is considered there is no likelihood that any changes will have occurred. In respect of two-seater successive flights, it is not uncommon for the pilot combination to change and if so the pilot in command must consider the cockpit loading requirements and must be satisfied that cockpit loading compliance remains valid.

Date	5-Nov-2017	Regior	۱		GQ		SOA	AR Repo	ort Nbr		S-:	1099
Level 1	Operational		Leve	el 2	Crew ar	nd Cab	oin Sa	ifety	Level	3	Inter-crew communic	ations
A/C Mod	el 1		Blanik L13 A1					Model	2			
Injury	Nil	Dam	age		Nil	Pha	ise	Landi	ng		PIC Age	
On final a	pproach and at	low level	(100	ft AG	iL) the inst	ructo	. advi	sed the	e stude	nt, wł	no was flying	g the
approach	, to ease off the	e airbrakes a little to avoid an undershoot. As the student moved the airbrake leve						brake lever				



Accident and Incident Summaries

forward they unconsciously pulled back on the stick and the aircraft quickly lost airspeed. With the aircraft close to the stall, the Instructor took over control and was able to regains airspeed and conduct a safe landing. The instructor noted that they *"were not as quick to the controls as* (they) *should have been"*. Up until that point the student had displayed good flying skills and the instructor was quite relaxed. This is not an uncommon occurrence and even experienced instructors can be lulled into a false sense of security. Notwithstanding the experience level of the student, Instructors must always guard themselves against unexpected reactions during the critical stages of flight by adopting a defensive posture (i.e. having their hands and feet ready to take control), and taking over quickly. Students should not be on the controls at low levels until competence in smooth and reasonably accurate co-ordination has been acquired, and the student should have some idea of anticipation in the use of the controls.

Date	5-Nov-2017	Region	1 I	VSA		SOA	AR Repo	ort Nbr		S-	1075
Level 1	Airspace		Level 2	Aircra	aft Sep	arati	on	Level	3	Aircraft Se	paration
										Issues	
A/C Mod	el 1		DG-5	D0 M		A/C	Model	2	Pipe	er PA-25-23	5
Injury	Nil	Dama	age	Nil	Pha	se	Launo	h		PIC Age	73
A self-lau	nching glider en	tered the	runway	and comm	enced	its ta	ke-off	run wh	ile a F	Pawnee tow	plane was
on base l	eg. The Pawnee	tow plane	e landed	alongside a	and ah	ead o	of the g	lider ta	king	off. The pilo	t in
comman	d of the glider he	eard the F	Pawnee p	oilot make a	a call c	n joi	ning the	e base l	leg an	id, believing	they had
sufficient	: time, made a ra	dio call a	dvising o	of their inte	ntion	to en	ter the	runway	y for t	ake-off. The	e pilot in a
Eurofox t	ow plane that w	as positic	oning to	aunch anot	her gl	ider a	at the la	aunch p	oint,	saw the Pav	wnee turn
onto fina	I approach and id	dentified	the pote	ential for a r	mishap	o. The	e Eurof	ox pilot	mad	e a radio ca	ll advising
the taxiir	ng glider pilot to s	stop but i	it was no	t heard. Th	e glide	er pilo	ot did s	ee a sto	op sig	nal given by	the crew at
the laund	h point but thou	ght the s	ignal wa	s for the Eu	rofox	pilot.	The po	wered	sailp	lane continu	ued its take-
off run, v	while the pilot of	the Pawr	nee man	peuvered to	o land	on th	ne runw	ay ahe	ad of	the Eurofox	. The
Eurofox p	oilot, who was als	so the Tu	gmaster	debriefed	the Pa	wne	e pilot a	and sug	geste	ed that a 'go	around'
would ha	ve been a better	option t	han con	ducting the	modif	ied la	anding.	The Tu	gmas	ter also deb	riefed the
glider pile	ot, who recognise	ed they s	hould no	t have ente	ered th	ne rui	nway w	hile the	e tow	plane was o	on the latter
stages of	its circuit.										

Date	6-Nov-2017	Region		GQ		SOA	R Repo	ort Nbr		S-	1105
Level 1	Operational		Level 2	Airc	raft Co	ontro	Ē	Level	3	Hard landi	ng
A/C Mod	el 1		Twin A	stir		A/C	Model	2			
Injury	Nil	Dama	ge	Nil	Pha	se	Landi	ng		PIC Age	69
This early	v solo pilot was o	n their firs	st solo fli	ght from t	his site	e, hav	/ing jus	t comp	leted	a check flig	ht with an
instructo	r. The pilot relea	sed from a	aerotow	into what	they tl	houg	ht was	a thern	nal ar	nd, after spe	nding some
time and	height trying to	find it, the	e pilot ch	ose to retu	irn to t	the a	irport a	and ent	er the	e circuit. On	release
from tow	the pilot did not	orient th	emselve	s and it too	ok som	ne ad	ditiona	l time a	and he	eight to loca	ite the
airport. T	airport. The pilot entered circuit at low altitude and became fixated on reaching the launch point, but during										
the dowr	wind leg recogn	ised they	were nov	w very low	and th	nat a	modifi	ed circu	uit wa	is necessary	. The pilot
conducte	d a low-level tur	n from mi	id downv	vind direct	ly onto	o fina	l. After	a shor	t and	unstable ap	proach, the
aircraft to	ouched down ha	rd and the	e glider b	ounced tw	ice. Th	ne glio	der wa	s not da	amag	ed in the inc	cident and
the pilot	underwent furth	er check f	lights wi	th a local ii	nstruct	tor to	o orient	and fa	milia	rise themsel	lves with
local land	lmarks, and to w	ork on the	eir circuit	: planning.	Goal f	ixatio	on ofte	n manif	fests i	n times of s	tress, which
coupled v	with site unfamil	arity and	a lack of	currency r	esults	in a f	failure	of the p	oilot t	o analyse in	formation
appropria	ately leading to a	loss of sit	tuational	awarenes	s. Situ	ation	al awa	reness	must	precede de	cision-
making b	ecause the pilot	must perc	ceive a si	tuation in o	order 1	to ha	ve an o	utcom	e. Situ	uational awa	areness also
allows th	e pilot to stay ah	ead of the	e aircraft	. To prever	nt the	loss c	of situa	tional a	aware	ness, imple	ment proven



Accident and Incident Summaries

best practices, such as orienting oneself post release (post-release checklist), remaining current, and breaking of the flight at an appropriate height.

Date	9-Nov-2017	Region		WAGA		SOA	R Repo	ort Nbr		S-	1078
Level 1	Airspace		Level 2	Aircra	ift Sep	aratio	on	Level	З	Near collis	ion
A/C Mod	el 1		Astir C	S77		A/C	Model	2	Cess	sna 172	
Injury	Nil	Dama	ge	Nil	Pha	se	Landi	ng		PIC Age	69
While tur	ile turning onto final for the operational runway the pilot of the single-seat glider saw a Cessna 172 under										
their righ	heir right wing. The Cessna was turning to the right and away from the glider as its pilot made a radio call										
that they	hat they were "going around". The glider landed safely. The incident was observed by the club tow pilot and										
two mem	wo members at the control van. Investigation revealed that the Cessna pilot made an inbound call at										
10Nms a	ONms and was conducting a 'straight-in' approach. Sometime later the glider pilot made a radio call on										
joining do	joining downwind for a conventional circuit. Just prior turning onto the base leg, the glider pilot heard a										
radio trai	adio transmission from the Cessna pilot, who asked the glider pilot if he would have room to land behind										
the Cessr	na if it did a full s	top landin	ng. The gl	ider pilot r	nisuno	dersto	ood the	e transr	nissio	on and thoug	ght the
Cessna pi	lot has advised t	hey were	landing l	pehind the	glider	[.] Alth	nough t	he glid	er pilo	ot had not s	ighted the
Cessna, t	hey acknowledge	ed in the a	affirmativ	e and ther	n turne	ed on	to the	base le	g of t	he circuit. Ir	ו the
meantim	e, the tow pilot h	nad been o	observing	g the situat	tion ar	nd ide	entified	that a	risk c	of Collison w	as
developir	developing. Fearing that the glider would collide with the Cessna during the final approach, the tow pilot										
made a r	adio call advising	the Cessr	na pilot t	hat there w	was a g	glider	to the	ir left. 1	The C	essna pilot i	mmediately
altered co	ourse about 20 d	egrees to	the right	t and ackno	owledg	ged tl	hat the	y had t	he gli	der in sight.	The
following	causal factors w	vere identi	ified:								
•	There were no radio calls heard from the pilot of the Cessna advising of the intention to conduct a										

- There were no radio calls heard from the pilot of the Cessna advising of the intention to conduct a straight-in approach.
- The glider pilot misinterpreted the radio call from the Cessna pilot, and did not sight the Cessna on final approach.Straight-in approaches to non-controlled aerodromes are not a recommended standard procedure. However, Regulation 166B of the Civil Aviation Regulations does not preclude pilots from conducting straight-in approaches provided certain conditions are met. Pilots who choose to adopt a straight-in approach should only do so when it does not disrupt, or conflict with, the flow of circuit traffic. Paragraph 166 (2) (b) of the Civil Aviation Regulations requires a pilot conducting a straight-in approach to give way to any other aircraft established and flying in the circuit pattern. Nonetheless, pilots conforming to the circuit pattern particularly on the base leg should continue to check for traffic entering along the final approach path.

Date	12-Nov-2017	Regior	1		NSWGA SO			SOAR Report Nbr			S-	1086
Level 1	Operational	Level 2				Airfrar	ne		Level	3	Landing	
											gear/Indic	ation
A/C Mod	′C Model 1				LS 6-c				2			
Injury	Nil	Dama	Damage Minor				hase Outlanding				PIC Age	
The unde	The undercarriage collapsed during an outlanding in a rough cattle grazing paddock. The owner has had the											
indent fo	indent for the undercarriage locking lever increased in size to make it less prone to unlocking during landing.											

Date	12-Nov-2017	Region		VSA		SOA	AR Repo	ort Nbr		S-	1091
Level 1	Operational		Level 2		Flight		Level 3		3	Aircraft preparation	
				Preparation/Na		lavig	ation				
A/C Mod	el 1	SZD-48	-1 "Janta	Jantar Standard 2"		A/C Model		2			
Injury	Nil	Dama	ige	Nil	Pha	ise	Laund	h		PIC Age	56



Accident and Incident Summaries

Launching was being conducted on runway 19 with a crosswind component from the east of between 5 & 8 knots. During the initial ground roll the glider's left wing dropped to the ground, causing the glider to veer away from the runway. As the experienced pilot reached for the release, the wing came up and the pilot elected to continue the launch. Once the tow plane and glider were airborne and climbing away, the glider pilot identified that the climb rate was lower than expected but rationalised that the combination was flying through strong sink. When the climb rate did not improve for about another 1 to 2 mins and at about 800ft AGL, the pilot decided to raise the undercarriage, at which time the undercarriage warning horn sounded alerting the pilot to the airbrakes being open. The glider pilot closed the airbrakes, and the launch continued normally with a much-improved climb rate. On the other end of the rope the tow pilot, flying a 260 Hp Pawnee, had noticed the airbrakes were out and initially thought the glider pilot had used the airbrakes to increase aileron control on take-off and had not put them away. The tow pilot elected not to signal with a rudder waggle at this time as the climb rate, while less than usual, was acceptable, and he did not wish to risk an inadvertent release by the glider pilot until better landing options were available to the glider pilot. The tow pilot became engaged in lookout while negotiating turns, and when he again checked the mirror, the brakes were away and the climb rate improved. The glider pilot was adamant that the airbrakes were closed and locked prior to launch, and believes they dislodged from the over-centre lock position during the rough ground roll. The over-centre locking mechanism was inspected after the incident and found to be in satisfactory working order. The pilot's CFI noted that the high workload associated with the early stages of a launch and the need to focus on flying the glider at a critical time, made it difficult for the pilot to consider airbrakes, even though the pilot was aware that the climb rate was not what it should be. Also, the pilot was unlikely to associate the reduced climb performance with the airbrakes being unlocked because they believed they had closed and locked the airbrakes during the pre-take off check and had previously experienced reduced climb performance during aerotow launch.

Date	12-Nov-2017	Region	1	SAGA			SOA	AR Repo	ort Nbr		S-	1107
Level 1	Airspace		Leve	el 2	Aircra	Aircraft Separation Level 3		Near collis	ion			
A/C Mod	el 1		A	SK-2	1		A/C	Model	2	LS 4		
Injury	Nil	Dama	age		Nil	Pha	se	Landi	ng		PIC Age	20

At around 1700 hours an ASK 21 on a training flight joined a right-hand circuit for a landing on the operational runway (RWY 36). At the same time, an LS4 returning form a cross-country flight joined a left-hand circuit for a landing on the operational runway. Both pilots assert that radio calls were made during the downwind leg but neither pilot heard the transmissions. Neither pilot had the other sighted as they turned onto base leg on a heading towards each. The Flarm in the ASK21 gave an audible alert and the command pilot, a new Level 1 instructor, turned onto final early to avoid a potential conflict. The pilot of the LS4 turned onto final at the same time and then got an alert on their Flarm. The command pilot of the ASK21 then observed the LS4 abut 50ft below and to the left, and so immediately turned away to the right to provide more separation. The LS4 pilot continued the approach and landed safely on the operational runway. The command pilot of the ASK21 conducted a low-level manoeuvre to divert to runway 31 and conducted a safe landing. Potential causal factors identified included:

- contra circuit operations were being used;
- the position of the sun, and cloud cover on the horizon may have made sighting of the LS4 difficult; and



Accident and Incident Summaries



Date	12-Nov-2017	Regior	1 I	SAGA			AR Repo	ort Nbr		S-1082	
Level 1	Consequential I	Events	Level 2	Lo Lo	ow Cir	cuit		Level	3	Low Circui	t
A/C Mod	el 1		ASK-21 A/C Mode								
Injury	Nil	Dama	Damage Nil Phase Landing PIC Age 26								
While ap	Nhile approaching the airfield during a low-level finish manoeuvre to runway 34, the pilot noticed gliding										
operation	operations had changed to runway 16. The pilot then conducted a very low modified circuit to the new										
runway v	runway with low energy. The final turn onto the approach was conducted extremely low to the ground;										
estimated at no more than 25 ft with around 30 degrees of bank. The aircraft landed safely. Investigation											
revealed the pilot:											
•	did not recognise	e the win	d had cl	nanged dired	ction a	s the	'sea br	eeze' o	ame	inland and t	hat the

- did not recognise the wind had changed direction as the 'sea breeze' came inland and that the glider had to penetrate the wind to get back to the aerodrome;
- had not identified the change to runway 16, possibly due to the presence of two gliders at the end
 of runway 34 that were due to be towed to the operational end of the runway;
- underestimated the sink rate of the glider at the speed being flown;
- flew the low-level finish manoeuvre at too low a speed resulting in only a moderate gain of height during the pull-up to join the circuit.

The pilot was counselled and underwent remedial training with their CFI.



Accident and Incident Summaries



Date	13-Nov-2017	Regior	n	NSWGA			SOAR Report Nbr			S-1081		
Level 1	Operational		Leve	2	Groun	id Ope	eratio	ons	Level 3		Taxiing collision/near	
											collision	
A/C Mod	el 1		LS	S10-	st		A/C	Model	2			
Injury	Nil	Dama	age	Su	bstantial	Pha	ise	Grour	nd Ops		PIC Age	
While to	ving the glider to	the fligh	nt line,	, a n	ortherly w	ind gu	ıst lif	ted the	port w	ing a	nd wing-wal	ker off the
ground re	esulting in the sta	arboard v	wingtip	р со	ntacting th	ne gro	und.	As the	pilot sl	owed	to a stop th	e towing-bar
disconne	cted from the tai	l dolly. T	he glid	der c	continued	towar	ds th	e car ai	nd the	trailin	g edge of th	e port-wing
aileron co	ollided with the v	ehicle. T	he aile	eron	was dama	aged c	over a	total l	ength o	of 600	mm and ful	l chord
width in p	olaces.											



Accident and Incident Summaries



Date	15-Nov-2017	Region NSWGA				SOA	R Repo	ort Nbr		S-:	1087
Level 1	Operational		Level 2	Airc	raft Co	ontro	I	Level	3	Hard landi	ng
A/C Mod	el 1		AS-K	13		A/C	Model	2			
Injury	Nil	Dama	ge	Nil	Pha	ise	Landii	ng		PIC Age	75
During ar	ring an instructional flight the student pilot mishandled the approach and the instructor failed to correct										
the situat	situation before the aircraft touched down heavily. The instructor noted that they had omitted to										
accuratel	urately ascertain the pupil's previous experience before flight, and allowed the student, who was										
undertak	undertaking their fourth flight in a glider, on the controls too early in the training. During the course of the										
flight the	flight the student displayed reasonable handling skills and the instructor was comfortable allowing the										
student t	udent to fly the approach. Unfortunately, the student did not have the skill or experience to land the glider										
and the i	nstructor was ca	ught unaw	vare. Altl	hough the i	instru	ctor b	oriefed	the stu	dent	on the land	ing exercise
before th	e flight, they had	l not revie	ewed the	student p	ilot's t	rainir	ng reco	rd or lo	ogboo	k. Had they	/ done so, it
would ha	would have been obvious that the student was not at that stage of their training. This incident highlights the										
importan	importance of instructors ensuring their students are not on the controls at low levels until competence in										
smooth a	nd reasonably a	ccurate co	o-ordinat	ion has bee	en acc	quired	d, and t	hat the	e stud	ent has som	e idea of
anticipati	on in the use of	the contro	ols.								

Date	17-Nov-2017	Regior	า	SAGA	SOAR Repo	SOAR Report Nbr		S-1126
Level 1	Operational		Level 2	Fligh	nt	Level	3	Other Flight Prep/Nav
				Preparation/	Navigation			Issues
A/C Mod	el 1		DG	400	A/C Mode	A/C Model 2		



Accident and Incident Summaries

Injury Nil Damage Nil Phase In-Flight PIC Age 44 The pilot flew with a lapsed Annual Flight Review. Discussion with the pilots' CFI revealed the pilot had not flown in a two-seater for three years. The pilot was grounded pending a satisfactory flight review. While pilots need to have a valid flight review if they want to exercise the privileges of command flying, it is important to consider that the annual flight review is the only regular proficiency training experienced by many pilots. Consequently, the review should not be viewed as a check ride but rather the opportunity for an independent assessment of a pilot's knowledge and ability to perform safe flight operations, and to correct those areas in which a deficiency is identified. The Annual Flight Review should be considered as the aeronautical equivalent of a regular medical check-up and ongoing health improvement program.

Date	18-Nov-2017	Regior	Region GQ			SOA	AR Repo	ort Nbr		S-	1088	
Level 1	Operational		Level 2 Ground C			eratio	ons	Level	3 Taxiing collis		llision/near	
										collision		
A/C Mod	1odel 1		ASK-2		A/C Model 2			N/A				
Injury	Nil	Dam	age	Minor	Pha	ise	Landi	ng		PIC Age	49	
The com	The command pilot was conducting a flight with another instructor as passenger. After landing on runway 06											
the comm	he command pilot taxied the aircraft onto the apron outside the aerodrome terminal building. As the											
comman	d pilot began to	lower the	e port win	g onto the	taxiw	ay, a	gust of	^f wind f	orced	l the starboa	ard wing	
down. Th	down. The command pilot applied correcting control inputs to no avail and the starboard wing leading edge											
struck one of the taxiway lights. The taxiway light separated from its base and a small section of Gel Coat												
was remo	was removed from the leading edge of the wing. The CFI immediately suspended the practice of taxying											
onto the	Apron area.											

Date	18-Nov-2017	Regior	Region VSA				SOAR Report Nbr				S-1089	
Level 1	Operational		Level 2 Ground Or			nd Ope	perations Level 3			3	Ground ha	andling
A/C Model 1 ASK				SK-21Mi			A/C Model 2			Ces	Cessna 172	
Injury	Nil	Damage Minor P			Pha	ase Ground Ops				PIC Age	51	
While being manhandled into the hangar, the nose of the glider struck a bolt in the hangar floor causing												
minor da	minor damage.											

Date	18-Nov-2017	Regior	1	SAGA			AR Repo	ort Nbr		S-1094	
Level 1	Consequential	Events	Level 2	Lo	ow Cir	cuit		Level	3	Low Circui	t
A/C Mod	el 1		Asti	CS		A/C	Model	2			
Injury	Nil	Dama	age	Nil Phas			Landi	ng		PIC Age	69
The expe	rienced pilot was	s observe	oserved to pull up over a line of trees and then a fence on final approach and								
landed ju	landed just inside the airfield boundary. Review of the flight trace revealed the pilot joined the circuit in the										
usual position but much lower at around 570ft AGL. Heavy sink was encountered at the end of the											
downwin	d legs and on the	e base leg	g. The pil	ot appears	not ha	ave n	oticed	the wo	rsenir	ng situation	as no
attempt	was made to mo	dify the c	ircuit. U	on turning	final	the p	ilot dive	ed the a	aircra	ft down to a	around tree-
top height, presumably to keep speed and to lessen the time spent in the sink. The pilot's CFI noted the pilot											
did not p	roperly monitor	the flight	-path th	oughout th	ne circ	uit, a	nd may	not ha	ive se	t the altime	ter correctly
prior to la	aunch, leading th	e pilot to	believe	they were	higher	thar	n they v	vere.			

Date	18-Nov-2017	Region		VSA	SOAR Repo	ort Nbr	S-1096
Level 1	Operational		Level 2	Ground Ope	erations	Level 3	Taxiing collision/near collision



Accident and Incident Summaries

A/C Model 1		Duc	o Discus	A/C	Model 2			
Injury	Nil	Damage	Substantial	Phase	Ground Ops		PIC Age	69
A squall line	with thunder	storms and hea	avy rain was a	pproaching	g the airfield, a	nd fly	ing operatio	ons had
ceased. The glider betwe	glider was be en the aerod	ing towed back rome access ga	to the hangai te and the hai	r by vehicle ngar, the le	e. As the vehicl eft wing struck	e driv a sta	ver was nego r picket. Thi	otiating the s caused the
was substan	tially damage	d.	ining cup resu	iting in the	e rudder impac	ung i	.ne venicie.	ine rudder

Date	19-Nov-2017	Region		WAGA		SOA	AR Repo	ort Nbr		S-	1093
Level 1	Operational		Level 2	Terra	ain Co	llisior	าร	Level	3	Ground sti	rike
A/C Mod	el 1	Ja	antar Stai	ndard 2		A/C	Model	2			
Injury	Nil	Dama	ige	Minor	Pha	ise	Outla	nding		PIC Age	42
The pilot	had just returne	d to flying	g cross-co	ountry afte	r a lor	ng ab:	sence, a	and wa	s atte	mpting a 30	00km flight
when an	outlanding beca	me inevita	able. Wit	h most of t	he pa:	ddoc	ks cont	aining	unhai	vested crop	s or stock,
the pilot	elected to land i	n the clea	r side of a	a paddock	conta	ining	sheep.	Just af	ter ro	ounding out	the pilot
noticed t	wo lambs 10 me	tres ahea	d. The pil	ot raised t	he nos	se of	the glid	ler and	clear	ed the lamb	s, but as the
airbrakes	were not reduc	ed or clos	ed, the ai	irspeed de	cayed	rapio	dly. The	pilot lo	owere	ed the nose	attitude to
regain a s	suitable speed b	ut over pit	tched, an	d the nose	ofthe	e airc	raft str	uck the	grou	nd followed	l but the
mainwhe	el and the tailwl	neel. The a	aircraft ro	olled to a s	top ar	nd sul	bseque	nt insp	ectior	n revealed o	nly
superficia	al damage to the	bottom c	of the fus	elage. A po	otentia	al cor	ntributin	ng facto	or is t	he effect of	startle on
the pilot.	Where people a	re startle	d, and a t	hreat pers	ists, tl	hen t	he star	tle refle	ex is li	kely to tran	sition into a
full surpr	ise or a startle re	eaction. Th	he pilot w	/ill react to	the t	hreat	, but co	ognitive	e proc	esses may b	e impaired.
In this ca	se the pilot react	ted imme	diately by	/ climbing	the aiı	rcraft	but did	d not co	onside	er the additi	onal
safeguar	ds of closing the	airbrakes	and reco	vering to a	norm	nal lai	nding a	ttitude			

Date	20-Nov-2017	Region	1		VSA		SOA	AR Repo	ort Nbr		S-	1090
Level 1	Airspace		Level	12	Aircra	ft Sep	arati	on	Level	3	Near collis	ion
A/C Mod	el 1		Twi	'in Asti	r		A/C	Model	2	Arcı	us M	
Injury	Nil	Dama	age	1	Nil	Pha	se	Landi	ng		PIC Age	67

The powered sailplane had been towed with a vehicle to the operational runway (RWY 08) with the intention of taking off on a cross-country flight. Upon arrival at the launch point it was noted that there was no gliding activity being conducted and the wind was favouring the reciprocal runway (RWY 26). After consulting with a tow pilot and other members, the powered sailplane pilot towed the glider to RWY 26. However, by the time the powered sailplane pilot was ready to launch, the wind had swung around and was now favouring RWY 08. Shortly afterwards the pilot flying a two-seat glider returning from a short crosscountry coaching flight entered the circuit area. The command pilot of the two-seat glider noted that the windsock closest to the runway intersection was uninformative, however the windsock on the eastern end of the airfield indicated a wind speed of about 5-7 knots with a direction from 120 degrees. The decision was made to land on RWY 08 and a radio call was made on entering the downwind leg. About the time the glider turned onto the base leg, the pilot of the powered sailplane started their take-off run. No radio call was heard from the powered sailplane pilot, and it was later determined that the radio was set to another frequency. The tow pilot on RWY 08 heard the engine of the powered sailplane as it started its take-off run and saw the glider on base leg. Identifying the risk of a collision between the powered sailplane and glider, the tow pilot made a radio call to the glider pilot alerting them to the powered sailplane taking off on the reciprocal runway. Just after turning final, the command pilot of the glider sighted the powered sailplane climbing towards them directly in front. The command pilot assumed control and took avoiding action by opening the airbrakes and diving to the right. The two aircraft passed within 30 meters. Causal factors include:



- variable wind conditions made identification of the operational runway problematic;
- normal "alerted see and avoid" processes used to achieve situational awareness were degraded by the radio in the powered sailplane being set to the wrong frequency;
- the powered sailplane pilot did not identify the radio was set to the wrong frequency;
- the powered sailplane pilot did not sight the glider in circuit;
- the glider pilots did not sight the powered sailplane until a collision was imminent.

When operating outside controlled airspace, it is the pilot's responsibility to maintain separation with other aircraft. For this, it is important that pilots utilise both alerted and unalerted see-and- avoid principles. Pilots should never assume that an absence of traffic broadcasts means an absence of traffic. The pilot of the powered sailplane was counselled.

Date	21-Nov-2017	Region		VSA		SOA	AR Repo	ort Nbr		S-	1092
Level 1	Operational		Level	2 Ter	ain Co	llisior	าร	Level	3	Collision w	ith terrain
A/C Mod	el 1		Dis	scus 2c		A/C	: Model	2	N/A		
Injury	Fatal	Dama	ge	Write-off	Pha	se	In-Flig	ght		PIC Age	78
Injury	Fatal	Dama	ige	write-off	Pha	ise	IN-FIIE	gnt		PIC Age	/8

The following is an extract from the New Zealand Civil Aviation Authority Investigation Report. The original report can be downloaded from this link: <u>https://www.aviation.govt.nz/assets/publications/fatal-accident-reports/zk-gxg-fatal.pdf</u>

EXECUTIVE SUMMARY

A Schempp-Hirth Discus-2c glider was being flown by a visiting overseas pilot as part of the South Island Regional Gliding Championship (the Championship) on the afternoon of 21 November 2017. The pilot had achieved the first two points of the set racing task and was thermalling (Thermalling is the process of circling within columns of rising air to gain lift) close to terrain below the Hunter Ridge in the Huxley Range, Central Otago. Following a series of right hand turns the aircraft made a left turn, the airspeed rapidly reduced, followed by an aerodynamic stall (Aerodynamic stall is a condition where the wing's angle of attack increases beyond a certain point such that lift begins to decrease. The angle at which this occurs is called the critical angle of attack). There was insufficient height to recover from the stall and the glider impacted the terrain. Competitors in the Championship saw the glider on the hillside and raised the alarm. One of these gliders flew lower and the pilots observed the pilot motionless in the glider. A search and rescue helicopter arrived on scene and medics confirmed the pilot had received fatal injuries. The Transport Accident Investigation Commission was notified of the accident and elected not to open an inquiry. Accordingly, a Civil Aviation Authority safety investigation commenced. The safety investigation identified the following contextual factors:

- Wreckage signatures and track data indicated an unrecovered aerodynamic stall
- Though an experienced glider pilot, they had minimal experience gliding in the South Island mountainous environment
- The pilot made an error in judgement by delaying a decision to stop circling.
- It was possible the pilot's performance had degraded after a period of challenging flying
- Flying in the Championship may have influenced the pilot's decision-making
- The South Island mountainous area is regarded by pilots as one of the world's most challenging gliding environments and the soaring conditions were challenging that day.

SAFETY MESSAGES AND RECOMMENDATIONS

Pilots new to flying in the South Island mountains need to be cognisant of the challenges this environment poses and consider the risks of flying solo. Pilots are reminded that the South Island mountainous environment is particularly challenging, even for those experienced in the area. Anything that affects their fitness to fly or decision-making will increase the risk of something going wrong. Pilots are advised to:

- gain knowledge and skills from experienced local pilots
- undergo instruction, or at least fly with another experienced local pilot until familiar with the environment



Accident and Incident Summaries

• fly with caution and within their own limitations

• always have an escape route when circling below a ridge and make the decision to turn away early. A safety recommendation has been made for Gliding New Zealand Incorporated (GNZ) to consider the appropriateness of visiting pilots flying as solo competitors if they are new to the New Zealand South Island mountainous area and have limited recent experience in similar environments. GNZ accepted this recommendation and has provided further guidance in GNZ <u>Advisory Circular 2-13 Mountain & Ridge Soaring Safety Principles</u>, Section 7 Competitions.

INCIDENT TIMELINE

- 11 Nov 2017 The pilot and a friend arrive at Omarama to attend a week-long mountain soaring course with a gliding training organisation (the organisation), followed by the South Island Regional Glider Championship (the Championship)
- 12 to 16 Nov The pilot completes the course and passes a biennial flight review (BFR). A current BFR flight check is required by GNZ before any pilot can take part in the Gliding Championship. The pilot decides to enter the Racing Class of the Championship with his friend acting as crew.
- 17 to 18 Nov Two practice flights are flown by the pilot in a single seat Discus-2c, ZK-GXG, rented from the organisation.
- 19 Nov First day of the Championship. The pilot completes the Racing Class task, placing 10th.
- 20 Nov All Championship flying tasks are cancelled due to the weather.
- 21 Nov Morning The pilot attends the morning briefings and conducts pre-flight planning and the daily inspection. By 1300 NZDT5 The pilot and his friend are on the grid ready for launch for the Racing Class
- 1347 ZK-GXG is launched by aero tow
- 1535 ZK-GXG achieves the first racing point, Stewarts (Refer to Figure 1: Racing Class Task A), at 7125 feet (ft) and soars to the next task point, Makarora East.
- 1616 ZK-GXG enters the eastern edge of the Makarora East point at 6030 ft then soars across the Hunter Valley towards the Hunter Ridge (The Hunter Ridge refers to the ridges above the Hunter River and are part of the Huxley Ranges) for the next task point, Morven.
- 1625 ZK-GXG arrives on the western side of the Hunter Ridge at 4500 ft and completes six right turns attempting to gain altitude from thermal uplift (refer to Figure 3). The wind averages 182°Magnetic and 8-10 knots (kt) and the glider's indicated airspeed (IAS)10 ranges between 49 and 68 kt in the turns.
- 1629:11 No lift is gained and ZK-GXG stops circling and tracks close to rising terrain on a northeasterly heading (refer to Figures 3 and 4)
- Next 6 seconds ZK-GXG's IAS progressively reduces (refer to Figure 3 and 4)
- 1629:17 The IAS reduces to 41kt, ZK-GXG enters a left turn, rapidly loses height and strikes terrain two seconds later (refer to Figures 4 and 5)
- 1658 Passing Championship pilots observe the damaged glider below the ridge and see no sign of movement. They make a MAYDAY call "glider down on the Hunter Ridge" to the Championship operations base. Championship emergency response procedures commence
- 1709 Rescue Coordination Centre of New Zealand (RCCNZ) is alerted and a rescue helicopter is dispatched. RCCNZ notifies the CAA
- 1725 The tow plane from Omarama flies to the accident site to act as a marker for the helicopter, and relays information to base
- 1742 Rescue helicopter arrives on site. The pilot is confirmed as deceased
- 1801 The Transport Accident Investigation Commission elects not to open an inquiry. Accordingly, a CAA safety investigation commences

INCIDENT MAPS AND PHOTOGRAPHS



Accident and Incident Summaries

Task II	normatio	n	Reg 201	7 Day 2 (21/11/.	17) Racing	 Task
Type: Ass Task dista	igned area ta ince: 144.3kn	sk with 3 areas n/314.5km (225.9km)	61.25	Reg 2017 Day 2 (21)	/11/17) Racin	g - Task
Style	Code	Points	Latitude	Longitude	Dis.	Crs.
Start	1	303-Horrible	\$44°32.000'	E170°00.000'		
1.Point		099-Stewarts	\$43°57.000'	E169°58.000'	64.9km	358°
2.Point		L305 Makarora East	S44°16.400'	E169°12.100'	71.0km	239°
3.Point		064-Morven	S44°38.500'	E169°30.400'	47.6km	149°
Finish		305-OM Finish	\$44°28,800'	E169°59.433'	42.4km	65°
E168°34 \$43°45,000'	1.000° E168°45.1	000' E169200.000' E169215	E169930.000	E169945.4007 E170/00.00	E170º15.000	E170
			498	2 104	Stewarts	
				CON NO	-Stewarts	
544*00,000		212 202			-Stewarts	
544*00,000		212			o o	
544*100,000	. 19	1			-stewarts	
544100,000					-stewarts	
544100,000	05 Malarete East				-Stewarts	
514*00,000 2,13 244*15,000'	105 Makaroto East				-Stewarts	
544*00,000 2,1,3 2,44*15,000'	105 Makarona East				-Stewarts	
544*00,000 2,1.3 544*15,000	105 Malancina East				-Stewarts	
544900,000 2.L3 \$44°15,000	105 Malanona East				-Stewarts	
544*100,000 2.L 2.d*15,000	10'S Materiana Eest				-Stewarts	
544*100,000 2.1. 2.44*15,000	105 Materians East				-Stewarts	
544*100,000 2.L 344*15,000*	05 Materials East				-Stewarts	
544*10(,100) 2,1 3,44*25,000* 2,4 4*30,000*	05 Mataretia East				-Stewarts	
544*10(,100) 2,1 2,1 2,1 2,1 2,1 2,1 2,1 2,1 2,1 2,1	05 Malaretto East				I-Stewarts	
544°10(,000 2,13 2,44°25,000' 2,44°31(,000')	05 Malaretto East				I-Stewarts	
544101,000 2,13 344725,000' 544930,070'	05 Malarcito East				I-Stewarts	
544°10(,000) 2,13 344°15,000' 344°30,070'	IOS Makareno East				I-Stewarts	
544°10', (100' 2,11 344°15, 000' 544°31,000'	IOS Makarono East				-Stewarts	
544900,000 2,1 344725,000 344730,000	IOS Makareno East				I-Stewarts	



Accident and Incident Summaries




Accident and Incident Summaries



Figure 3: ZK-GXG's track below the Hunter Ridge showing spot speeds up to 26 seconds before the stall. Refer also to Figure 4. (Source: ZK-GXG LX9000)

Screenshots for the 26 seconds prior to ZK-GXG stall

On the following page(s), Figure 4 shows a series of See You[™] screenshots of the last 26 seconds of ZK-GXG's flight before the aerodynamic stall. These screenshots were created by GNZ using data from the LX9000 installed on ZK-GXG. Use the mouse scroll wheel, or arrow keys, to animate these eight images. Note: The white dot at the end of the ground trace in each screenshot indicates the ground clearance directly below the glider.

26sec IAS 64kt



















Accident and Incident Summaries



investigation 0810 23/11/17 NZDT



Accident and Incident Summaries



Figure 6: ZK-GXG on a 30° slope facing south. The Hunter River valley is to the right and Dingleburn Station airstrip is further south. (Source: CAA field investigation 0839 23/11/17 NZDT)

FINDINGS AND CONCLUSIONS FROM THE INVESTIGATION

The safety investigation covered human factors, equipment factors, and environmental factors. The key findings are listed below and are then described in more detail.

Equipment factors

- No pre-accident defects were found with the glider
- Wreckage signatures and track data indicated an unrecovered aerodynamic stall

Human factors

- Though an experienced glider pilot, he was not experienced at gliding in the South Island mountainous environment.
- The pilot made an error in judgement by delaying a decision to stop circling
- It was possible the pilot's performance had degraded after a period of challenging flying
- Flying in the Championship may have influenced the pilot's decision-making.

Environmental factors

- The soaring conditions were challenging that day
- The South Island mountainous area is regarded as one of the world's most challenging gliding environments
- The Championship operated in accordance with Gliding New Zealand procedures and Civil Aviation Rules.

Equipment factors

Aircraft information



Accident and Incident Summaries

ZK-GXG was a Discus-2c, single seat, high-performance glider constructed from fibre-reinforced plastic. It had a swept-back wing with winglets and airbrakes on the upper surface and was flown in the 18-metre configuration for the Championship. It was fitted with an LxNav LX9000 Vario Navigation system (LX9000) from which Global Positioning System (GPS) data pertaining to the flight was accessed. The pilot's portable NavITer Oudie Navigation system also tracked the flight.



Figure: 7. Example of Discus-2c (Schempp-Hirth brochure)

No pre-accident defects were found with the glider

ZK-GXG was built in Germany in October 2007 and registered as D-6111. It was imported into New Zealand in November 2009 and a certificate of airworthiness in the standard category was issued by the CAA. The annual review of airworthiness was completed on 11 October 2017 with no defects or discrepancies. There was no recorded maintenance carried out on the glider after that. At the time of the accident the glider had accrued 1840 hours total flight time. On the day of the accident, the organisation's ground crew and the pilot both completed the daily inspection. Thirty litres of water ballast were added to each wing and approximately five litres to the tail.11 Other Championship competitors reported dumping some of their water in flight. The safety investigation was unable to determine if ZK-GXG's pilot did the same, or by how much, as any remaining water was lost during the accident sequence. It was calculated that the glider was within weight and balance limitations. During the site examination, no mechanical defects which may have contributed to the accident were identified.

Wreckage signatures and track data indicated an unrecovered aerodynamic stall

Following what appears to be an uneventful flight, ZK-GXG achieved the Makarora East point and soared towards the Huxley Range and the next task point, Morven (refer to Figures 1 and 2). Near the accident location, six right turns were completed close to the Hunter Ridge at between 300 to 1200 ft agl at an average IAS of 54 kt. After rolling out of the last right-hand turn, the glider progressively slowed as a left turn was initiated at around 4500 ft. The IAS reduced to 41 kt followed by a 30° bank left turn away from the ridge at 100 ft agl (refer to Figures 3 and 4). The glider descended rapidly, and the left wing impacted the terrain, followed shortly by the fuselage and right wing. After the initial impact, the glider slid forward on a westerly heading then rotated left to slide down the slope and come to rest approximately 25 metres from the initial impact point (refer to Figures 5 and 6). The wreckage signatures and the track data indicated that the glider's critical angle of attack was exceeded, with a loss of lift, typical of an aerodynamic stall. There was insufficient height above terrain for the pilot to recover control. **Human factors**



Accident and Incident Summaries

Though an experienced glider pilot, he was not experienced at gliding in the South Island mountainous environment.

The pilot was considered an experienced pilot and instructor, having accrued 4682 hours of flight time in gliders. He met the GNZ requirements for entry into the Championship which included completing the mountain soaring course and passing the GNZ BFR. The pilot had limited gliding experince in New Zealand prior to this visit. He was reported to have had considerable (hundreds of hours) flying and instructing in the Australian mountains of Victoria where he was based. He had gained some mountain soaring experience in the USA and more recently in the French Alps in 2012. Pilots experienced in both the South Island and Australian environments reported the South Island flying conditions are quite different to Australia and, in their opinion, would have been challenging for the pilot, despite his experience in USA and France. The pilot was cognisant of his lack of local experience and completed the mountain soaring course and conducted solo flights prior to the Championship. The organisation's owner stated that given the pilot's age and lack of New Zealand mountain flying experience, he reviewed the tracks from every flight the pilot completed and discussed these with him. He stated that the pilot had flown appropriately and in accordance with "what he had been told" in the first Championship task. The owner reviewed ZK-GXG's track leading up to the accident. He noted that the pilot had flown well with a steady pattern of climbing and soaring and had achieved the first point, Stewarts, well into the circle. He stated the pilot "clearly had a plan for the task" and "appeared to have easily achieved Makarora". The owner, and experienced local pilots all stated that the pilot's actions close to the Hunter Ridge were contrary to gliding best practice. Several stated they felt the conditions were "stretching [the pilot's] ability". In 2016 the CAA investigated an accident that occurred during the South Island Regional Gliding Championship. During a reversal turn, away from a ridge, the right wing of the glider G-OJTA struck terrain, the glider was destroyed, fatally injuring both occupants. The CAA Accident Report, G-OJTA Section 4.115 made a recommendation to GNZ that they: "encourage gliding clubs to mentor visiting pilots, and pilots with limited experience on gliding in the New Zealand Southern Alps during a contest environment". It appears that the pilot in ZK-GXG did receive mentorship from:

- the organisation -both during the course and during the Championship
- the Championship itself, via daily briefings and a competitor mentorship programme
- fellow competitors and local pilots on an informal basis.

However, a safety recommendation has been made to GNZ to consider the appropriateness of visiting pilots flying as solo competitors if they are new to the New Zealand Southern Alps and have limited recent experience in similar mountainous environments. GNZ has accepted this recommendation and has provided further guidance in GNZ Advisory Circular 2-13 Mountain & Ridge Soaring Safety Principles Section 7 Competitions.

The pilot made an error in judgement by delaying a decision to stop circling

It appears the pilot made a late decision to stop circling below the ridge, leaving no escape option. The series of right turns plus the effect of the south-westerly tail wind (12 kt average) took the glider progressively closer to the side of the Hunter Ridge. The general south-easterly airflow over the Hunter Ridge created pockets of sinking air which reduced the thermal lift. Any remaining water ballast would have increased the stall speed and adversely affected the handling of the glider close to the stall but was unlikely to be a contributory cause of the stall. GNZ Advisory Circular AC2-13 Mountain & Ridge Soaring Safety Principles provides advice on circling near a hill which states: "It is vitally important when considering circling near a hill that you consider the risk of sudden loss of height if sink is encountered. Many mountain flying accidents have occurred due to insufficient margin when circling near the hill. Both horizontal and vertical separation needs to be considered along with drift due to wind. Circling against slopes (as opposed to figure of eights) is potentially hazardous, particularly in weak climbs. In these conditions, there is a constant need to closely monitor drift and push out from the slope for a few seconds on each turn. Figure of eights should be used if you have any doubt, carefully watching your drift and always turning away from the hill." The pilot had been taught to perform figures of eights in the mountain soaring course. His instructor commented that he demonstrated proficiency in conducting the figure of eight. This was confirmed by the investigation review of the tracks from the training flights. It is likely due to the weak thermal conditions that the pilot opted to use the circling technique instead of the figures of eight. During the circles the glider had drifted



Accident and Incident Summaries

progressively closer to the ridge. Following the sixth circle the glider flew parallel to the ridge and commenced the left turn. It takes some time to reverse a turn and, in this case, this was compounded by the tailwind and loss of thermal lift. The glider covered significant ground in this time. With the spur in front of him and little clearance from the terrain, the pilot had no escape options remaining. <u>Gerrard G Dale</u> explains the importance of making early decisions when circling below hill tops.

If continuing the turn into a circle, make the decision early

When the wind on the ridge is very light and there are thermals mixed into the flow, you may climb better by circling. It takes a long time to reverse a turn from one direction to the other and in that time a glider will travel quite a long way over the ground. By circling you can keep the glider in a smaller area of lift. However, if you want to continue a turn and fly a full circle near or below the hill top then you must make the decision very early, when you are flying parallel to the ridge. If you try to change your mind later on you may find that you are already committed - you are pointing towards the hill and cannot turn away if you suddenly realise you are too close.

A late decision may lead to an inevitable crash



This is a trap for newcomers to ridge soaring and one of the reasons you should not circle beneath the hill top until you are experienced in this type of flying. Even then you should think carefully about the situation before you decide to circle. If you are not absolutely sure, without any doubt, that there is room to circle plus a big safety margin - don't! Fly a figure-eight instead.

The Soaring Engine, Volume 1, page 19.

Source: Dale, G.



Accident and Incident Summaries

There is a wealth of information and advice for pilots flying in mountainous areas including flying in proximity to ridge lines. Below is a short summary on threats from experienced glider pilot, Arthur Gatland (Gliding Threat and Error Management. Soaring, August 2010).

Threats	Possible Strategies
Irregular ridge lines	Be aware of the probability of unexpected ridges and spurs appearing in front of you. Irregular ridges are guaranteed to produce strange wind effects. Always have a safety margin in distance from the ridge, and always fly at a minimum of your "safe speed near the ground." Trim for this speed and always have an escape route away from terrain.
Inconsistent winds, giving	There will be instances of loss of airspeed, one wing lifting unexpectedly,
stronger and weaker lift,	possibility of stall. Expect this to happen and allow safety margins.
windshear, turbulence	Remember, unlike the car ads – in gliding it is Lack Of Speed that Kills!
Stronger winds due to	Recognise this as a serious threat! Often you will find yourself closing
funnelling etc	with the ridge faster than expected. Never fly directly towards the ridge,
	but close on it obliquely so you can always turn away when required.
Difficulty in depth	Ridges – particularly in the South Island – that do not have vegetation
perception	(trees) make it difficult to assess how far away you are. The rock you can
	see might be 5 metres wide or the size of a house – you really can't be
	sure. This has probably resulted in several pilots flying too close and
	dying as a result. Allow more margin than you think necessary!
Any nagging doubts or	Get out of there – pronto!
uncertainty about what	
you are doing	
Over-confidence	Every pilot must acknowledge that we are all human and we do all make
(This includes a level of	mistakes. Ridge
confidence higher than	flying is very unforgiving and over-confidence has proven repeatedly to
your level of experience.)	be fatal.

Table 1: Ridge Soaring -Threats and Strategies (source Arthur Gatland)

Previous CAA accident investigation reports describe the causes of gliding accidents in mountainous terrain. Pilots are reminded of the recommendation made in the CAA <u>Accident Report ZK-GZV</u>: "When operating in close proximity to high or mountainous terrain, it is vitally important that sufficient distance from the terrain is maintained to allow for any sudden height loss due to unexpected changing environmental conditions. Glider pilots need to be aware of not falling into the trap of continued flight close to terrain while leaving themselves with no other options for a safe flight path away from the terrain." Pilots are encouraged to:

- gain knowledge and skills from experienced local pilots
- undergo instruction or at least fly with another experienced local pilot until familiar with the environment
- always have an escape route when circling below a ridge and make the decision to turn away early
- be cautious to fly within their own limitations.

It was possible the pilot's performance had degraded after a period of challenging flying Championship competitors stated the gliding conditions were "difficult" and "challenging" that day. At the time of the accident the pilot had already flown 2 hr 42 minutes and had been preparing for the flight all morning. It is possible that the combined effects of a prolonged period of physical and mental demands on the pilot may have reduced his performance when he encountered the area of poor thermal lift below the ridge. *Hydration and nutrition*

It had been several hours since the pilot had eaten or drunk anything. Though he carried one water bottle and snacks in the glider only a few sips of water and a few nuts had been consumed. Interviews with other witnesses stated they would normally drink one to three litres of water in a three-hour flight. Family



Accident and Incident Summaries

members and gliding colleagues stated that the pilot usually drank water from a Camelback™ type system or bottles during flights. He was an experienced instructor pilot and aware of the need to maintain blood sugar and hydration. However, his instructor stated he had to remind the pilot about maintaining hydration during the mountain soaring course. The Championship daily briefings included reminders about the importance of inflight hydration and nutrition. A level of mild dehydration or low blood sugar may have affected the pilot's physiological wellbeing and performance, but it cannot be concluded as a definitive causal factor. All pilots are reminded of the importance to maintain hydration and blood sugar during flight.

Medical fitness

The pilot held a Civil Aviation Safety Authority (CASA), Australia Class 2 medical which was valid to 02 August 2018. He had a current Gliding Federation of Australia Medical Practitioner's Certificate of Fitness stating that he had a chronic condition that was "under control and does not impact his ability to fly". His family reported that he was fit and well. Concerns were expressed by the course instructor and other Championship competitors that the pilot appeared "frail", "physically and mentally tired". Some made comments relating to the pilot's age (78 years). The owner stated he reviewed the pilot's performance during the mountain soaring course and after all solo flights. He said had there been any concerns he would not have authorised the pilot to enter the Racing Class solo. The pilot was aware of the effects of ageing on pilot physical and cognitive performance and had written an article titled 'Ageing Pilots', for his local gliding club. The pilot's friend stated that the pilot had a good night's sleep the day prior to the accident. He had taken his prescribed medications, was in good spirits, and appeared fit to fly. The autopsy report determined that the pilot died of injuries sustained in the accident and not from any pre-existing medical condition.

Physical and cognitive demands

The pilot was an experienced instructor and competition pilot. He had, however, been exposed to an intense period of mental and physical exertion; the week's mountain soaring course followed by the Championship. This was in a new and challenging environment flying a glider different to his own. The instructor stated that the pilot "wasn't used to putting in the effort required [for the environment] he could fly okay, but performance dropped at the end". He passed the course, but the instructor cautioned the pilot about entering the Championship due to concerns about the prolonged (five-hour) effort required. ZK-GXG's flight track showed the expected pattern of thermalling and soaring to achieve the first two points of the racing task. However, below the Hunter Ridge the pilot made an error in judgement, flew too close to terrain and left no escape options, ultimately leading to the accident. The difficult soaring conditions likely subjected the pilot to prolonged physical and cognitive demands, possibly leading to fatigue. A level of fatigue could explain his decision to persevere with circling below the ridge. Several similar accidents have occurred involving younger/fitter pilots who were equally inexperienced in the South Island mountainous environment. Other Championship pilots reported they found the flying conditions challenging that day. Therefore, the pilot's age and fitness can only be considered a possible contributory factor in context of the environment he was in. All pilots are reminded to assess their fitness to fly both before the flight and as the flight progresses.

Flying in the Championship may have influenced the pilot's decision-making

It is possible that the pilot's decision-making prior to the accident was influenced by an unconscious bias to continue with the original plan despite changing conditions (plan continuation bias). He got into a hazardous situation by becoming fixated on the challenge of finding rising air in the difficult thermal conditions, rather than turning away earlier from the rising terrain. Alternative options were to land at the Dingleburn airstrip or conduct an outlanding on the valley floor (see Figures 2 and 6). Both were well within gliding range and annotated on the Oudie map. Several factors may have influenced his decision to continue to thermal in that location:

- His desire to complete the set task. An outlanding would mean he would not achieve the task that day. His family and gliding friends reported that flying in the South Island mountains was a longheld goal for the pilot. He did not have an expectation to place high in the Championship contest.
- His lack of familiarity with the area and outlanding sites.
- Possible concern about damaging the (rented) glider in an outlanding.
- The inconvenience to others of his retrieval so distant from Omararama.



Accident and Incident Summaries

Previous accidents have involved competition flying. The CAA Accident Report, ZK-GJO highlighted the adverse effect that competition flying can have on decision-making. *"In terms of human factors, with the attraction of a goal, mountain climbers have been cited as saying that withdrawing shortly before reaching the summit is exceedingly difficult. A strong motivation puts us inside a mental tunnel from which too often there is no exit".* Though not a conclusive contributory cause to this accident, the CAA reminds pilots again of the influence competition flying can have on decision-making, especially the risk of continuation bias. **Environmental factors**

The soaring conditions were challenging that day

Many witnesses stated that the soaring conditions were not easy that day but comparable to previous days with clear blue sky and variable winds. The thermals were reported as "choppy" "mashy" and "rough" by some. Pilots experienced in the area stated they deliberately stayed high above the ridges as they expected it to be rough lower down, and lift would be hard to find. The pilots in the glider that descended below the ridge to the accident site found it "rough" and that they "had to hunt around" for thermals to climb back above the ridge. A briefing was provided by the Championship Meteorological Officer and the pilot was cited by family and flying colleagues as having a keen interest in meteorology. However, "summer easterlies" were cited by many experienced local pilots to be "the most difficult [conditions]" and local knowledge was vital. Whilst the general airflow may be south-easterly, the winds are often quite different below the ridges. The Hunter Ridge is known to be particularly difficult to find good lift. On the day of the accident several phenomena existed which could have created local rotors and turbulence below the ridge:

- a general south-easterly flow above and over the ridge line
- thermal (solar) heating on the westerly face of the mountain
- an afternoon sea breeze from the west coast
- a local south-westerly airflow
- funneling up the valley from Lake Hawea.

These conditions contributed to ZK-GXG drifting closer to the ridge, and to the difficulty the pilot had in gaining lift. The witnesses stated that the conditions were "flyable that day" but would have been "challenging" for a pilot with limited experience in the local environment.

The South Island mountainous area is regarded as one of the world's most challenging gliding environments

Without exception, every witness stated that the South Island mountainous area is regarded by the worldwide gliding community to be one of the most challenging gliding environments. Several pilots (including local instructors) with between 30-50 years of local gliding experience said they still learn something every flight. Some of the comments included:

- "It can be quite tiring -harsh, demanding, unrelenting."
- "When flying low in these mountains you must be 100 percent and sometimes that's still not enough."
- "In 20 years of flying in New Zealand only now getting a handle on it. First 15 years I was still ironing out wrinkles. The conditions here are tricky."
- *"Flying conditions are enormously different from Australia -almost all thermal flying is well away from terrain. The [NZ] mountain thermals are more broken and turbulent than our [Australia] flatland thermals."*

Previous gliding accidents in the South Island have involved visiting pilots who were considered experienced glider pilots but inexperienced in the New Zealand mountainous environment. Pilots must know and fly within their limits and apply a much larger margin when flying in the South Island mountains. Fly with a local pilot especially in competitions when there are additional pressures.

The Championship operated in accordance with Gliding New Zealand (GNZ) procedures and Civil Aviation Rules

GNZ has standard procedures for conducting the Championship. This Championship has been running for many years and the procedures are progressively updated. The safety investigation reviewed the following procedures, with no concerns raised:



Accident and Incident Summaries

- daily task briefings (meteorology, pilot wellbeing, safety, task route, rules)
- pilot mentorship
- flight tracking and following
- post-flight debriefing of the pilot (conducted by the operator)
- emergency response plan (The overdue aircraft and emergency response procedures were implemented within 28 minutes of the accident. This is within the 60 minutes required by the GNZ Advisory Circular AC 1-05 Emergency Plans).

Though competitors described the conditions as challenging, no-one stated that it wasn't suitable for the day's flying to go ahead. The Championship committee had cancelled the previous day's flying and have done so in previous championships. There was no pressure for the tasks to go ahead and several pilots elected to return, or not fly, based on their personal limits. Given the information at the time, the Championship committee and the organisation had no specific reason to enforce the pilot's withdrawal from the day's flying or the Championship. Ultimately it was the pilot's decision to participate in and continue to fly the racing task that day.

SAFETY ACTIONS ALREADY TAKEN

The accident has been discussed within GNZ, GFA and wider gliding community. The accident has served as a sobering reminder of the risks of flying below and close to a mountain ridge. The operator has stated that they will be extremely conservative about renting gliders to solo visiting pilots, no matter how much overall gliding experience they may have. GNZ has updated GNZ Advisory Circular 2-13 Mountain & Ridge Soaring Safety Principles. The GNZ Flight Training Program, "Task Flying" and "Alpine Flying" sections will also contain more detailed guidance and information for mountain soaring glider pilots. **REFERENCES**

- **Ageing pilot** Civil Aviation Authority, 2000. "Growing Old Gracefully". Vector March/April 2000. Civil Aviation Authority New Zealand.
- Civil Aviation Authority, 2010. "The Ageing Pilot". Vector 2010. Civil Aviation Authority New Zealand.
- Mackay, P. 2012 "Risk-taking, Stress and Ageing". Proceedings from the GNZ Annual Conference 2012. http://gliding.co.nz/pilots/training/safety-information/
- Perkins, S. 2017. "<u>Don't Let AMD Stop you Flying High</u>". GNZ website. http://gliding.co.nz/wpcontent/uploads/2017/05/AMD.pdf

CAA fatal glider accident reports

- Civil Aviation Authority, 2002. Aircraft Accident Report Occurrence Number 02/99 Alexander Schleicher Segelflugzeugbau ASW20 ZK-GVW Near Omarama 22 January 2002. Civil Aviation Authority, New Zealand.
- Civil Aviation Authority, 2008. Aircraft Accident Report. Occurrence Number 06/4214; Powered Sailplane, Stemme S10-V, G-OJTA, Mount Prospect, Central Otago 15 November 2006. Civil Aviation Authority, New Zealand.
- Civil Aviation Authority, 2008. Aircraft Accident Report, Occurrence Number 07/4533; Alexander Schleicher Flugzeugbau ASG-29 D-2929 Turret Peaks, near Makarora, 21 December 2007. Civil Aviation Authority, New Zealand.
- Civil Aviation Authority, 2010 Aircraft Accident Report. Occurrence Number 08/497; WSK "PZL-Swidnik" S.A. PW-5 ZK-GJO, Waharoa, 11 February 2008. Civil Aviation Authority, New Zealand.
- Civil Aviation Authority, 2013. Aircraft Accident Report. Aircraft Accident Report Société Siren Pik-30 ZK-GST Impact with Terrain, Omarama, 18 January 2012. Civil Aviation Authority, New Zealand.
- Civil Aviation Authority, 2017. Safety Investigation Report Collision with terrain involving ZK-GZV Alexander Schleicher GmbH & Co. ASH 31 Mi Ben Ohau Range Otago, 06 February 2016. Civil Aviation Authority, New Zealand.

Dehydration

• Wishaw, K Dr. n.d. "<u>A Contrary view to the one that only water should be taken during long flights</u>". Gliding Kiwi http://gliding.co.nz/wp-content/uploads/2014/01/Ken-Wishaw.pdf



Accident and Incident Summaries

- Spiesser, S. n.d. "<u>Hydration in Flight</u>". Gliding Club of Victoria,
- Australia. http://www.glidingclub.org.au/fly/tasks/hydration-for-peak-xc-performance/
 Civil Aviation Authority, 2005. "Need a drink? The Dangers of Dehydration". Vector Issue 6
 - November/December 2005. Civil Aviation Authority, New Zealand.
- Civil Aviation Authority, 2019. "The Need for Water is Real". Vector Summer 2019. Civil Aviation Authority, New Zealand. Iremonger, G. 2011. "<u>Dehydrated?</u>" Soaring April 2011 http://gliding.co.nz/wp-content/uploads/2014/01/Dehydrated.pdf

Human factors -general

- Gliding New Zealand. Introduction & overview to HF on gliding http://gliding.co.nz/wpcontent/uploads/2014/05/GFAHF1intro.ppt
- Gliding New Zealand. Vision and Fatigue http://gliding.co.nz/wpcontent/uploads/2014/05/GFAHF3visionfatigue.ppt
- Helman, M. 2010. "<u>Complacency: What Me Worry?</u>" Soaring New Zealand http://gliding.co.nz/wp-content/uploads/2014/01/Complacency.pdf
- Gatland, A. 2010. "<u>Gliding Threat and Error Management or, How to Reduce Mistakes and Fly</u> <u>Safely</u>", Soaring August 2010 http://gliding.co.nz/wp-content/uploads/2014/01/TEM2.pdf
- Civil Aviation Authority, 2011. "Get-there-itis". Vector January/February 2011, Civil Aviation Authority, New Zealand.

Mountain flying

- CNVV, 2011. <u>Safety in Mountain Flying</u>. Gliding National Centre of Saint-Auban-sur-Durance (CNVV). http://gliding.co.nz/wp-content/uploads/2014/01/Safety-in-Mountain-Flying-CNVV.pdf
- Civil Aviation Authority, 2012. "Mountain Flying". Good Aviation Practice. Civil Aviation Authority, New Zealand
- Dale, G. 2016. <u>The Soaring Engine, Volume 1</u>. Alton, United Kingdom. http://thesoaringengine.com/
- Gliding New Zealand <u>Advisory Circular AC2-13</u> Mountain and Ridge Soaring Safety Principles http://gliding.co.nz/wp-content/uploads/2020/04/AC2-13v4.pdf

Date	22-Nov-2017	Regior	1	VSA		SOA	AR Repo	ort Nbr		S-	1097
Level 1	Airspace		Level 2	Airspac	e Infri	ingen	nent	Level	3	Airspace Ir	nfringement
A/C Mod	el 1		DG-2	00/17		A/C	Mode	2			
Injury	Nil	Dama	age	Nil	Pha	ase	Thern	nalling		PIC Age	67
The pilot was thermalling near an airspace boundary while on a cross-country flight and drifted into Class C											
airspace. The pilot subsequently recognised the error and immediately vacated the area. The pilot self-											
reported the incident. Investigation revealed the pilot was carrying appropriate charts but was not using											
electroni	c navigation aids.	The pilo	ot's CFI r	oted causal	facto	rs as	primari	ly pilot	comp	placency wh	ile flying in
good wea	good weather on a day of higher than normal convection. The pilot was counselled on the importance of										
constantly reviewing their location relative to airspace, especially when in close proximity to boundaries. The											
pilot also completed the UK CAA airspace infringement on-line training at: http://infringements.caa.co.uk/											

Date	23-Nov-2017	Region	1	NSWGA		SOA	AR Repo	ort Nbr		S-	1095
Level 1	Airspace		Level 2	Aircra	ift Sep	arati	on	Level	3	Near collis	ion
A/C Mod	el 1		DG-4	100		A/C	Model	2	Pipe	er Seneca	
Injury	Nil	Dama	age	Nil	Pha	ise	In-Flig	ght		PIC Age	72
The pilot	was on the final	leg of a 5	90km cr	oss-country	/ flight	t at 8	,500ft i	n Class	G air:	space when	they noticed
a twin-en	igine aircraft clim	nbing tow	ards the	m from the	e right	. The	pilot to	ok avo	iding	action by pu	ulling up, and
rolled ab	rolled about 30 degrees to the left to make the glider more visible. The other aircraft passed about 150										
metres b	metres behind and below. The glider pilot was not monitoring the Area Frequency at the time but was on										



Accident and Incident Summaries

one of the glider frequencies. When operating above 5,000 feet AMSL in Class G or E airspace, pilots are encouraged to monitor the area VHF frequency rather than a glider frequency. The use of the glider frequency as an aid to alerted see-and-avoid should only be necessary when multiple gliders are flying together. When flying alone, glider pilots should be monitoring the same frequencies as other airspace users.

Date	23-Nov-2017	Region		WAGA		SOA	AR Repo	ort Nbr		S-	1104
Level 1	Airspace	L	evel 2	Aircra	aft Sep	arati	on	Level	3	Near collis	ion
A/C Mod	el 1	SZD-48-1	"Janta	r Standard	2"	A/C	Model	2	Cirr	us	
Injury	Nil	Damag	é	Nil	Pha	ase	Thern	nalling		PIC Age	52
Two glide	ers got close whi	le thermalli	ng befo	ore the star	rt in th	ne WA	A State	Champ	ionsh	ips. The Jan	tar was
establish	ed in a thermal a	at a height o	f 5400	ft and was	positi	oned	opposi	te anot	ther g	lider when i	its pilot
observed	the Cirrus appr	bach the th	ermal fi	rom above	. The .	Janta	r pilot v	videne	d the	turn to prov	/ide
separatio	n but soon lost :	sight of the	Cirrus.	The Cirrus	pilot l	had n	ot sight	ted the	othe	r gliders and	1 believed
they wer	e thermalling alo	one. The ne	t time	the Jantar	sited	the C	irrus it	was in	front	and about 2	100ft below.
The Janta	ar pilot made a r	adio call to	advise t	he Cirrus	oilot tl	hat th	ney wer	e abov	e and	behind. The	e Cirrus pilot,
believing	the Jantar had j	ust joined t	ne ther	mal, ackno	wledg	ged th	ne call,	and ma	intaiı	ned altitude	and thermal
radius. Tł	ne Cirrus pilot lo	oked back a	nd abo	ve but did	not si	ght tł	ne Janta	ar. Shoi	rtly af	terwards th	e Jantar
pilot noti	ced the separati	on with the	Cirrus	reducing a	nd ma	ade a	radio c	all whil	e mai	noeuvring a	way from
potential	conflict. The Cir	rus pilot, or	hearir	ng the call,	looke	d abc	ove and	behind	d saw	the Jantar p	oull away.
The Cirru	s pilot made a ra	adio call adv	ising th	ney were le	eaving	the t	hermal	. A revi	ew of	f the flight t	races after
the flight	showed that bo	th gliders h	ad beei	n in the oth	ner's b	olind s	spot res	sulting	in a 'o	double-blind	l' situation
developir	ng.										

Date	24-Nov-2017	Regior	1	GQ		SOA	R Repo	ort Nbr		S-	1100
Level 1	Technical		Level 2		Syster	ns		Level	3	Other Syst	ems Issues
A/C Mod	el 1		Club Libe	elle 205		A/C	Model	2			
Injury	Nil	Dama	age	Nil	Pha	ise	Launo	h		PIC Age	74
During la	unch and at a he	ight of 13	300 ft the	tow rope	unexp	ectec	lly dep	arted tl	he gli	der. The pil	ot did not
activate t	he release. Upo	n landing	a visual a	and physica	al inve	stigat	ion did	l not id	entify	the reason	for the un-
comman	ded release. A te	st flight v	vas cond	ucted the f	ollowi	ng da	iy and t	the rela	ise ag	ain let go - ı	refer SOAR
report 11	.37.										

Date	25-Nov-2017	Region	1		VSA		SOA	R Repo	ort Nbr		S-	1102
Level 1	Operational		Level	12	Airc	raft Co	ontro	<u> </u>	Level	3	Control iss	ues
A/C Mod	el 1		Twin	Ast	ir -LP		A/C	Model	2			
Injury	Nil	Dama	age		Minor	Pha	se	Launc	h		PIC Age	60
During a outside t was the r runway s obscured	winch launch the he runway marke emains of a runv trip in use on the by clumps of fre the wing before	e glider's ers. The p vay light e day. The eshly mov	wing d bilot wa fitting e fitting wn graa	drop as a tha g w ss. 1	pped and, i ible to rais t had not l as about 2 The wing d	unbek e the been r 00mm rop o	nowr wing emo emo higł ccurr	n to the and co ved fro n and m ed whe	pilot, s ntinue m its or nade fro n the v	struck with f rigina om 90 ving r ficial	a PVC pipe the launch. I position or Omm PVC pij unner prem	situated The PVC pipe In the grass pe and was aturely ich did not
affect the airworthiness of the glider. The PVC pipe was removed.												

Date 25-Nov-2017 Region SAGA SOAR Report Nbr S-1103	.	Date	25-Nov-2017	Region	SAGA	SOAR Report Nbr	S-1103
---	----------	------	-------------	--------	------	-----------------	--------



Level 1	Operational		Level 2	ŀ	Airfran	ne		Level	3	Doors/Can	opies
A/C Mod	el 1		LS 7-V	VL		A/C	Model	2			
Injury	Nil	Damag	ge	Nil	Pha	se	Launc	h		PIC Age	
Shortly after take-off the pilot noticed the canopy was not properly secured. The pilot immediately landed,											
and inspection revealed the rear locating pin had not fully engaged. The pilot properly secured the canopy											
and relau	and relaunched. The reason for the failure of the pin to engage was not determined.										

Date	25-Nov-2017	Regior	۱	VSA		SOA	R Repo	ort Nbr		S-	1120
Level 1	Operational		Level 2	ŀ	Airfrar	ne		Level	3	Landing	
										gear/Indic	ation
A/C Mod	el 1		Arcus	бM		A/C	Model	2			
Injury	Nil	Dam	age	Nil	Pha	ise	In-Flig	ght		PIC Age	69
The pilot	advised that, wh	nen retra	cting the	undercarria	age po	ost lau	unch, tł	ne leve	r beca	me stuck h	alfway
between the up and down positions. Both pilots were able to use mutual hand forces to lock the											
undercarriage down and an uneventful landing ensued. Post flight inspection revealed a bolt in the											
overcentre mechanism of the left undercarriage leg was missing. The aircraft owner noted that the											
undercar	riage assembly h	nad been	disassem	bled, clean	ed an	d lub	ricated	the pro	evious	s year and tl	ne locknuts
had not b	een replaced as	they we	re deeme	d fit for fur	ther u	ise. It	appea	rs a loc	knut	had vibrated	d loose over
46 take-c	offs and landings	, enablin	g the bolt	to fall out.	The	undei	rcarriag	ge was	disass	embled, cle	aned,
lubricate	d and reassembl	ed using	new lock	nuts and Lo	octite.	FAA	Advisor	y Circu	lar A	C43-13-1B s	uggest that
locknuts may be reused if the prevailing torque is within specification. However locknuts are relatively											
cheap, so replacement of self-locking nuts in critical areas is good practice.											

	1										
Date	25-Nov-2017	Regior	า	GQ		SOA	NR Repo	ort Nbr		S-	1137
Level 1	Technical		Level 2		Syster	ns		Level	3	Other Syst	ems Issues
A/C Mod	el 1		Club Libe	lle 205		A/C	Model	2			
Injury	Nil	Dama	age	Nil	Pha	ise	Launc	h		PIC Age	70
The flight	t was to troubles	hoot an i	uncomma	nded relea	ise the	e prev	/ious da	ay (refe	er SOA	AR Report 1	100). During
take-off and at a height of approximately 150 ft, the glider flew through a vertical and the release activated.											
The pilot safely landed on the cross strip. Investigation revealed the release mechanism was not going into											
the 'over	-centre' position	as the ca	able was t	oo short. A	As a co	nseq	uence,	the be	ak wa	is not openi	ng
sufficiently wide to fully insert the ring. The length of the release cable was adjusted by connecting it to a											
lower position on the activating arm, thereby restoring the over-centre and beak mechanisms. The aircraft											
was test flown and has done a number of flights since with no further problems.											

Date	26-Nov-2017	Regior	۱	W	AGA		SOA	R Repo	ort Nbr		S-	1101
Level 1	Operational		Level	12	Aircı	raft Co	ontro	_	Level	3	Hard landi	ng
A/C Mod	el 1	SZ	ZD-50-3	3 "Pucha	acz"		A/C	Model	2			
Injury	Minor	Dam	age	Substa	ntial	Pha	se	Landi	ng		PIC Age	45
During fir	nal approach in l	olustery c	onditio	ons, the	glider	stalle	d on	to the g	ground	from	about 3 fee	t while
travelling	sideways result	ing in the	under	rcarriage	e strut	breal	king.	lt was r	eporte	d tha	t there was	significant
wind she	ar on short final											

Date	27-Nov-2017	Region		WAGA	SOAR Repo	ort Nbr	S-1106
Level 1	Operational	Lev	vel 2	Terrain Co	lisions	Level 3	Controlled flight into
							terrain



Accident and Incident Summaries

A/C Model 1	Jantar Stand	lard 2 (SZD48-:	1) A/C	Model 2			
Injury Nil	Damage	Substantial	Phase	Outlanding		PIC Age	52
During a short cross-cour	ntry flight an ou	tlanding becan	ne inevitat	ole and the pilo	ot ele	cted to land	d in an
uncropped paddock. The	pilot flew a circ	uit and inspec	ted the pa	ddock but did	not r	ecognise it s	sloped
downhill from the landing	g direction. Also	, grass cover c	obscured a	substantial dr	ainag	ge ditch abo	ut halfway
along the paddock in the	landing direction	on. The glider t	ouched do	wn normally b	out th	e downhill s	slope made
the landing roll longer th	an anticipated.	The glider was	still travel	ling fast when	the p	pilot noticed	l a sand
embankment along the d	lrainage ditch w	hen only abou	it about 20	metres ahead	l. The	main whee	el struck the
sand bank and immediate	ely collapsed, ar	nd the glider sl	id to a halt	on its fuselag	e. Su	bsequent in	spection
revealed the undercarria	ge to be substa	ntially damage	d. The pilo	t was debriefe	ed by	their CFI, w	ho
reinforced that slope is d	ifficult to detect	t but that the p	position of	dams, stream	s and	drainage di	itches are
good indicators of the dir	rection of slope.				1.4.0		
DRAII	NAGE DITCH	>					

Date	7-Dec-2017	Region		VSA		SOA	AR Repo	ort Nbr		S-	1110
Level 1	Operational	l	Level 2	Run	way E	Events Level 3		3	Runway in	cursion	
A/C Mod	el 1	Pi	iper PA-2	25-260		A/C Model 2					
Injury	Nil	Damag	ge Su	ıbstantial	Pha	ise Landing		ng		PIC Age	25

2



Accident and Incident Summaries

At around 12:00 midday, the tow plane was approaching the threshold of RWY 26 from the North East, in a steep low curve to align with runway. Gliders and several vehicles were involved in preparing for launch on the right-hand half of the runway opposite the RWY 26 threshold. As the tow plane flew toward a touchdown point, a vehicle was driven slowly across the runway and adjacent to the assembled gliders. The driver was in the process of returning to the hangers to retrieve a parachute to replace one they had inadvertently opened in the glider. As the perimeter road was unusable due to council earthworks, the driver elected to cross the runway. The driver was looking towards people on the right and gesturing to one of them, and so did not notice the tow plane landing to their left. Several people nearby identified the hazard and called to the driver to stop. Upon hearing the calls, the driver stopped short of the projected path of the tug but by then, the tug had touched down and was braking heavily. The tow pilot continued braking while diverting away from the vehicle, resulting in the tow plane tipping forward onto the propeller. Wheel marks on the runway show that the ground roll of the tug from touchdown to nose-over was about 60 metres. The tracks indicated heavy braking for most of this ground roll and curved slightly to the left consistent with the tug pilot steering away from the vehicle. The heavy braking track and the growing curvature of the track implies that the tug pilot saw the vehicle somewhere at or before touchdown. The tug stopped perhaps 10 or 20 metres short of, but clear from, the vehicle. Low engine revs, a composite propeller and drive belt resulted in limited shock loading on the transmission. One blade on the propeller was broken and the other blades suffered damaged by impact with the ground. The following potential causal factors were identified:

- the vehicle driver did not check that the airspace was clear before entering the runway;
- the tow pilot flew a non-standard low and curving approach under power to the landing point, which limited the opportunity to identify the developing hazard;
- the slow-moving vehicle may have appeared stationary in the pilot's field of view due to a lack of relative movement; and

Date	8-Dec-2017	Region		VSA		SOA	AR Repo	ort Nbr		S-	1144
Level 1	Operational	L	evel 2	Crew a	nd Cat	oin Sa	fety	Level	3	Flight crev	<i>i</i> tion
A/C Mod	el 1		LS 3-	а		A/C	Model	2			
Injury	Minor	Damage	e	Nil	Pha	ise	In-Flig	ght		PIC Age	

• the tow pilot had limited time to react once the risk of collision was identified.

The pilot was flying their second long-distance cross-country flight, during which they became progressively unwell to the point that the pilot elected to outland rather than continue. Post flight investigation of the pilot's symptoms suggested that the pilot either suffered from airsickness due to a lack of currency and turbulent conditions, or more likely due to a contaminated hydration pack. Inadequate maintenance will allow mould and bacteria build up in the hydration system, in the tube, mouthpiece, or the bladder itself. If a pilot is not finishing their water and allowing it to sit for long periods of time before drinking it again, they also risk allowing bacteria to grow. Water bottles and bladders with mould and bacteria in them are breeding grounds for stomach ailments. Properly cleaning the water bottle will reduce the risks considerably. To help prevent bacteria from growing your hydration pack, the following cleaning regime is recommended:

- Use hot water and two tablespoons of baking soda or bleach. Mix the solution inside your bladder and hold it up above your head while you pinch the bite valve, allowing the mixture to run through the tube.
- Let the bladder and cleaning solution to sit for about 30 minutes.
- Wash the reservoir with hot water and mild soap. Be sure to completely rinse away any bleach or cleaning solution before using again. Brushes are the best way to ensure you are scrubbing all the areas of the bladder clean.



Accident and Incident Summaries

• Be sure to air dry the bladder so no moisture is trapped inside, which can cause mould to grow. Inserting a bent wire coat hanger into the bladder aids the drying process by keeping the surfaces apart. The pilot purchased a new water bladder and now takes a travel sickness tablet before long flights.

Date	8-Dec-2017	Region		SAGA		SOA	AR Repo	ort Nbr		S-	1152
Level 1	Operational		Level 2	Airc	raft Co	ontro		Level	3	Hard landi	ng
A/C Mod	el 1		Discu	JS		A/C	Model	2			
Injury	Nil	Dama	ge	Nil	Pha	ise	Landi	ng		PIC Age	
	C . I · · · · I							ſ	FO 1	420 1	

On the day of this incident the wind was gusting to 12 knots and swinging from 50 to 130 degrees, and rain cells were visible from the airfield. Cloud base was 3,000ft and thermals were broken with some strong peaks. After a soaring flight of about one hour the pilot broke off the flight and headed to the airfield. The pilot joined circuit for RWY 05 and configured the aircraft for landing. Due to the wind conditions the pilot set the approach speed at 65 knots. The pilot reported *"In the flare when I was 2 to 4 feet above the runway ... I felt some lift immediately before the aircraft dropped like a stone onto the bitumen in the hardest landing I have experienced in over 30 years of flying both gliders and powered aircraft." The pilot returned the glider to the hangar, where it was inspected and found to be undamaged. Another pilot who landed shortly afterwards had a similar experience. It is likely the aircraft flew through turbulence, possibly created by trucks driving on the freeway that runs next to the runway boundary.*

Date	9-Dec-2017	Regior	1	GQ		SOA	AR Repo	ort Nbr		S-	1111	
Level 1	Airspace		Level 2	Aircra	aft Sep	arati	on	Level	3	Aircraft Se	paration	
										Issues		
A/C Mod	el 1	F	Piper PA-2	28R-180		A/C	Model	2				
Injury Nil Damage Nil Phase In-Flight PIC Age												
A powere opposite incident a	A powered aircraft was observed flying at low-level through the circuit of this Regional aerodrome in the opposite direction and in contravention of requirements promulgated in the ERSA. At the time of the incident gliders were in circuit.											

Date	9-Dec-2017	Region		NSWGA		SOA	R Repo	ort Nbr		S-	1112	
Level 1	Operational		Level 2	Mis	cellan	eous		Level	3	Rope/Ring	s Airframe	
										Strike		
A/C Mod	el 1	SZI	D-9 bis 1	E Bocian		A/C	Model	2				
Injury	Nil	Dama	ge	Minor	Pha	ise	Launc	h		PIC Age	65	
A cable b	reak occurred du	k occurred during a winch launch at approx. 800' AGL. The cable rebounded and struck the										
upper su	per surface of the starboard tailplane, punching two small holes in the ply-wood surface. The rope broke											
about 2 r	pout 2 metres from the trace when the glider was in full climb attitude at about 55kts with no layoff. At											
this point	nis point there would be a significant load on the rope. Immediately after the rope broke, and before the											
cable wa	able was released from the tow hook, the trace pivoted about the release under the influence of the											
airstream	n and possibly the	e elastic re	eaction o	f the rope	break	. Wh	en the	release	e was	activated th	ne trace fell	
away but	the weak link ur	it had suf	ficient u	pward rota	tion t	o rise	e just al	oove th	e tail	plane and v	vas collected	
by the lea	ading edge causir	ng the wea	ak link as	sembly to	pivot	dowr	n and ir	npact t	he up	per surface	. The club	
uses 9mr	n Supa-Dan poly	propylene	rope fitt	ed with a	5m tra	ace (n	io drog	ue chut	:e). T	he trace set	up is in	
general c	general conformance with the GFA Winch Launching Manual, although there was some elasticity in the											
system.	The club has bee	n using th	is trace o	onfigurati	on for	seve	ral yea	rs and ł	nas no	ot suffered a	a glider strike	
by a wea	k link unit after a	cable bre	ak befor	e this incid	lent. F	ollow	ving the	eir inve	stigat	ion of this ir	ncident,	



Accident and Incident Summaries

the club has decided to replace all rope traces with an inelastic material (steel or dyneema) encased in a stiffer tube. Consideration will also be given to changing the length of the trace to keep the weak link unit clear of the tailplane in similar circumstances.

Date	9-Dec-2017	Region		SAGA		SOA	AR Repo	ort Nbr		S-	1115
Level 1	Operational	Le	vel 2	Fu	el Rela	ated		Level	3	Exhaustior	า
A/C Mod	el 1	Pipe	er PA 2	25-235		A/C Model 2					
Injury	Nil	Damage		Nil	Pha	se	Launc	h		PIC Age	50

During an aerotow launch the tow plane ran out of fuel. The pilot conducted a safe 'dead-stick' landing on the airfield. The tow pilot was rostered to fly the afternoon shift and arrived at the aerodrome just before midday. The tow plane was at the launch point and the tail wheel was being inflated. The tow pilot conducted a brief take-over from the other tow plot but did not check the fuel level, as they believed it had only conducted two tows since refuelling. During the course of the day the pilot was monitoring the fuel level by reference to the Maintenance Release and flight log. After flying a further 8 launches, the tow pilot calculated there was enough fuel for three more launches but decided to fly one more launch and refuel. However, after returning from the planned last launch the tow pilot was asked to launch another glider on a training flight. After further calculation by reference to the flight log, the pilot believed there was enough fuel and flew three more launches. It was during the last of these launches that the tow plane ran out of fuel. Poor fuel management in aerotow operations is a problem which every pilot can help eliminate by maintaining high personal standards of safety in their planning. Tow pilots must be familiar with, and follow, the procedures recommended in the Pilot's Operating Handbook. Accurate fuel management starts with knowing exactly how much fuel is being carried at the commencement of a flight. This is easy to know if the aircraft tanks are full or filled to tabs. If the tanks are not filled to a known setting, then a different approach is needed to determine an accurate quantity of usable fuel. Accurate fuel management also relies on a method of knowing how much fuel is being consumed. Many variables can influence the fuel flow, such as changed power settings or the use of non-standard fuel leaning techniques. If they are not considered and appropriately managed, then the pilot's awareness of the remaining usable fuel may be diminished. Keeping fuel supplied to the engines during flight relies on the pilot's knowledge of the aircraft's fuel supply system and being familiar and proficient in its use. Adhering to procedures, maintaining a record of the fuel selections during flight, and ensuring the appropriate tank selections are made will lessen the likelihood of fuel starvation at what may be a critical stage of the flight. The chance of fuel exhaustion can be reduced by:

- using more than one source of information to obtain consistent results about the fuel on board before flight;
- the use of a consistent procedure that is regularly checked to know the exact rate of fuel consumption; and
- ensuring the pilot is fully familiar with the operation of the fuel system for both normal and abnormal operations. For further information, see ATSB publication "Avoidable Accidents No. 5 -Starved and exhausted: Fuel management aviation accidents": https://www.atsb.gov.au/media/4115276/ar-2011-112_no5.pdf.

Date	9-Dec-2017	Regior	า		VSA		SOA	AR Repo	ort Nbr		S-	1116
Level 1	Airspace		Leve	el 2	Aircra	ft Sep	arati	on	Level	3	Aircraft Se	paration
A/C Model 1 SZD-50-3 "Puchacz" A/C Model 2 PIK-20B												
Injury	Injury Nil Damage Nil Phase Thermalling PIC Age 78											
Two glide	Two gliders were observed from the ground thermalling together in opposite directions. The pilot of the PIK											
reported that while thermalling above the aerodrome at an altitude of 3,200 feet the Flarm sounded loudly												



Accident and Incident Summaries

and alerted to a potential threat below and to the right. The pilot altered heading away from the threat until the alarm ceased and then sighted the Puchacz about five to six hundred feet below and displaced laterally by a few hundred metres. The pilot of the Puchacz had been thermalling in the opposite direction nearby and had gradually moved closer to the PIK, thereby triggering an alarm.

Date	9-Dec-2017	Region		NSWGA	SO	AR Repo	ort Nbr	S	-1129
Level 1	Operational		Level 2	Ground (Operatio	ons	Level 3	Taxiing co collision	ollision/near
A/C Mod	el 1		TST-1	0M	A/0	Mode	2		
Injury	Nil	Dama	ige Su	ubstantial F	hase	Grou	nd Ops	PIC Age	75
The pilot	had earlier rigge	d and ins	pected th	ne glider, and	then at	tended	the mornin	ng briefing. T	he glider was
being tov	wed to the launch	n point ale	ong the s	outhern boun	dary of	the air	field, so the	e driver mad	e a taxying
call on th	e CTAF. The driv	er then ol	bserved t	he tow plane	positio	ning for	[.] a launch a	nd decided	to move
further a	way from the rur	nway. The	e driver, k	pelieving they	were cl	ear of t	he fuel dur	np fence, co	mmenced a
turn to th	ne left, whereupo	on the left	t wingtip	struck the fer	ice. The	driver	stopped ar	id exited the	e vehicle to
assess th	e situation. The	glider's wi	ingtip ha	d struck the fe	ence at a	a shallo	w angle, re	sulting in da	mage to both
the steel	fence and the gl	ider. The	damage	to the glider w	as seve	ere, witl	h the fusela	ige broken b	ehind the
engine-b	ay. The driver, w	ho is a ve	ry experi	enced pilot, st	tated "I	was try	ing to be v	ery slow, ca	reful, and
deliberat	e all morning, bu	it may hai	ve been h	nurrying a bit i	to get o	ut of th "	e way of th	e operation	at the very
moment	I needed to stop	and look	at the sit	uation from o	ut of th	e car."	20.70		A
	and the second	-			200		RE	1	Stat.
and the second	-	2020			2		in the second	01.	
and the second division of		-	a - interaction i	10 . A	-	-	-20	and the	
1.00			a lucar	International Pro-		анини	HARRING ME		Librarian I
-		5							
1 and	A lister	1.	-						
	1000	1							
			a ser	A				E Bade Bak	Cont and and
and the second second	100		~	ASIA		Lanes	and the second	C TO PROVE	and the Party of
	e p		1	1 7 1					Carlo Con
		1							
				The second	Pricate To			100	and the second
		1	Statement of the local division of the local	- Ch					and the second
			_		-				
						1	121 Test	and the second second	
21 . T		-				-		Res Property	State The State
				and the second s			all all a	Carries?	A CONTRACTOR
		and the second	No.	and the second second		- Bernard			A CONTRACTOR
		1	A BAR	Ne diselle			ANTIN		and the second se
	All All	North Line	0	Little Russel	Blue	200	1000		
	Alle .	Sec.			Ar Alle		11.	the light	
	Entering	and a second	the state	and the second second	Sale of	and the second	all the second		Matter State
100.00	A State		The second	Contraction of the	the s	19.9	and the second second second	and the second	1000
	A REAL PROPERTY OF A REAL PROPER	and the second se	The Party of the P	and the second se	and the second second	STATE OF	LA CAN	And in the other division in the other divis	

	Date	9-Dec-2017	Region	SAGA	SOAR Report Nbr	S-1155
--	------	------------	--------	------	-----------------	--------



Accident and Incident Summaries

Level 1	Operational		Level 2	Fire Fur	nes ar	nd Sm	noke	Level	3	Fire	
A/C Mod	el 1					A/C	Model	2			
Injury	Nil	Dam	age S	ubstantial	Pha	ase	Grour	nd Ops		PIC Age	
During th	e mid-afternooi	n a wind o	change n	ecessitated	a cha	nge o	of runw	ay and	the w	inch was to	wed to the
new runv	vay by the retrie	eve vehicl	e. The re	etrieve vehi	cle wa	is the	n parke	ed read	y to h	nook the cat	les to their
retaining	block when smo	oke was o	bserved	coming from	m und	ler th	e bonn	et. A sr	nall g	rass fire was	s noticed
under the	e vehicle. In the	absence	of firefig	nting equip	ment a	at the	e launcł	n site, c	lub m	nembers ret	rieved fire
extinguis	hers from the cl	ubhouse	and succ	essfully exti	inguis	hed t	he fire.	Follow	ing th	nis incident,	the club
reviewed	their firefightin	g capabili	ity. Mult	iple new fir	e exti	nguis	hers we	ere pur	chase	ed and instal	led at
multiple	locations around	d the han	gars, clul	phouse and	airfiel	d. Th	e Club'	s Safety	y Mar	nagement Sy	vstem was
updated	to include steps	required	to maint	ain the exti	nguisl	ners,	and sm	oke de	tecto	rs were fitte	d to the
sleeping	quarters. A club	member,	, who is a	ilso a memb	per of	the C	ountry	Fire Se	rvice	organised t	raining for
club men	nbers on extingu	isher use									

Date	10-Dec-2017	Region	1		NSWGA		SOA	AR Repo	ort Nbr		S-	1113
Level 1	Operational		Leve	el 2	Terra	in Col	lisior	าร	Level	3	Collision w	ith terrain
A/C Mod	el 1		DO	G-10	00S		A/C	Model	2	N/A		
Injury	Nil	Dama	age		Minor	Pha	ise	Landi	ng		PIC Age	71

During landing the glider drifted towards the runway boundary and the starboard wing contacted a cone marker. The student pilot was conducting a landing under instruction on the far right-hand side of the gliding strip as the left-hand side was occupied by a previously landed glider. The aircraft student pilot did not sufficiently correct for drift, and the aircraft flew towards the runway boundary resulting in the right wingtip extending over the alignment of the adjacent cone and gable markers. The instructor immediately took over but in affecting recovery the underside of the right wingtip grazed the top of a yellow cone marker which overturned but was not damaged. Subsequent inspection of the glider revealed a faint cord-wise yellow graze under the right wingtip, but the aircraft was otherwise undamaged. The most common instructing accident is 'instructor failed to take-over in time'. These accidents usually involve the trainee responding in an unforeseen way or failing to respond at all. Given that the overall idea is to let the trainee do as much as possible within their level of skill the instructor should never wait until the last moment - which can rapidly become 'too late' - before responding to a situation that is going awry. This is particularly true of any manoeuvres close to the ground.

Date	10-Dec-2017	Region		WAGA		SOA	R Repo	ort Nbr		S-	1114
Level 1	Operational		Level 2	Airc	raft Co	ontro	_	Level	3	Wheels up	landing
A/C Mod	el 1		Astir	CS		A/C	Model	2			
Injury	Nil	Dama	ge	Minor	Pha	ise	Outla	nding		PIC Age	57
The pilot	conducted a stra	aight-in ap	oproach t	o outland	in a pa	addoo	ck and t	the airc	raft la	anded with	the
undercar	riage retracted.	As the we	ather for	ecast for t	he day	/ was	good,	with 15	knot	s wind and	thermals
predicted	predicted to 9000ft, the pilot planned to fly a 310km closed triangle. The first two legs were completed in									npleted in	
good time, with the pilot concisely finding thermals to 8000ft. As the pilot rounded the second turnpoint for											
the leg h	ome, they notice	d the clou	ud was be	eginning to	over	deve	lop and	l lift wa	s diffi	icult to find.	About 20
kms from	n the turnpoint t	ne pilot wa	as at 3,00	00ft and sp	ent a	long	time w	orking	weak	lift. The pilo	ot eventually
climbed t	he glider back to	o 8,000ft a	and set co	ourse for th	ne 60k	tr	rip hom	ne. At th	nis po	int the navi	gation
compute	r was showing 6	the glider	to be 1,0	00ft below	/ glide	, so t	he pilo	t tracke	ed aw	ay from the	over-
developn	nent in search of	better air	r. Some v	veak lift wa	as foui	nd th	at impr	oved th	ne glio	de margin, k	out the glider
was still l	pelow the glide s	lope with	16kms to	o run. The	pilot n	nade	an inb	ound ra	idio c	all and advis	sed that an
outlandir	ng was likely. The	e pilot stat	ed that '	there were	e num	erous	s suitab	le pada	locks	in front so I	continued. I
sighted a	large flat clear	oaddock a	t 10 o'clc	ock to my t	rack tł	hat w	as idea	ıl for laı	nding	and aero of	r trailer



Accident and Incident Summaries

retrieve." When down to 800 ft AGL the pilot realised they would not make the airfield and turned left onto base leg for the earlier identified paddock. After turning final the pilot conducted a minimum energy landing with the tailwheel touching first. The pilot stated that *"the nose came down and kept going down! The fuselage touched the ground around the undercarriage doors without much downward force. Deceleration was rapid and straight. Wings remained clear of ground. I realised immediately I had not put the wheel down." The pilot noted that this was their longest cross-country flight and that <i>"stress levels had been high trying to get back...in worsening lift conditions."* Fatigue was also a contributory factor. As a consequence of fatigue and stress, and because the they did not fly a proper circuit, the pilot did not complete their prelanding checks that would have alerted them to the undercarriage being up. Fortunately, the aircraft only suffered minor damage to the undercarriage doors and a scuffed fuselage.

Date	10-Dec-2017	Region	1	NSWGA		SOA	AR Repo	ort Nbr		S-	1121
Level 1	Airspace		Level 2	Airspac	e Infri	ingen	nent	Level	3	Airspace In	nfringement
A/C Mod	el 1		Duo [iscus		A/C	Mode	2			
Injury	Nil	Dama	age	Nil	Pha	ase	In-Flig	ght		PIC Age	59
During de	uring de-briefing with the Duty Instructor at the end of the day's flying, the second pilot mentioned that										
they had	flown to a region	nal town	some 60	kms east of	f the a	erod	rome. \	Nhen q	uesti	oned as to v	whether the
aircraft h	ad kept clear of t	the restri	cted airs	pace in tha	t area	airsp	ace, th	e pilots	s advi	sed they we	ere unaware
of any air	space restriction	is. A subs	equent	check of the	e flight	: log r	eveale	d the g	lider p	penetrated	six
kilometre	es into the restric	ted airsp	ace for	L1 minutes.	The p	ilots	were c	ounsell	ed. Vi	iolations of	controlled
airspace can be avoided by remaining situationally aware, ensuring you have current airspace charts, and by											
thorough	ıly familiarising y	ourself w	ith local	airspace ar	nd oth	er ae	ronauti	ical issu	ies.		

Date	12-Dec-2017	Regior	1 I	NSWGA		SOA	R Repo	ort Nbr		S-	1117
Level 1	Airspace		Level	2 Aircra	ft Sep	arati	on	Level	3	Near collis	ion
A/C Mod	el 1		Ľ	.S 3		A/C	Model	2	Uni	dentified Tw	/in
Injury	Nil	Dama	age	Nil	Pha	ise	In-Flig	ght		PIC Age	50
The pilot avoiding than 200 issued by	was competing action when an metres. The glid Airservices Aust	in the NS unidentifi er pilot v rralia.	W State ied Twii vas mor	e Gliding Cha n-engine airc nitoring the g	mpion raft cr lider S	iships osse Safety	s. Durin d the g y Frequ	g the c lider's t ency as	ruise rack. s autł	the glider p Seperation norised by N	ilot took was less IOTAM

Date	12-Dec-2017	Regior	1	NSWO	6A	SOA	AR Repo	ort Nbr		S-	1118
Level 1	Operational		Level	2	Miscella	neous	;	Level	3	Rope brea	k/Weak link
										failure	
A/C Mod	el 1		Piper F	PA-25-235		A/C	Mode	2	N/A		
Injury	Nil	Dama	age	Nil	Ph	ase	Launo	h		PIC Age	71
The aero	tow rope broke	at a splice	e just a	s the tow p	oilot app	lied t	ake-off	power	. Insp	ection revea	aled the rope
comprise	d two sections s	pliced in	the mi	ddle. The r	ope bro	ke be	tween 1	the mid	ldle jo	ining splice	and the
glider rin	g splice in a sect	ion of oth	nerwise	e unremarl	able rop	e. W	hile the	e rope h	ad se	en significa	nt use, it had
been inspected before operations commenced that morning and no signs of the impending failure were										re were	
visible. Tl	ne rope was rep	aced.									

Date	12-Dec-2017	Region	1		VSA	SOAR Repo	ort Nbr		S-1119
Level 1	Airspace		Level	2	Airspace Infri	ngement	Level	3	Airspace Infringement
A/C Mod	el 1		Disc	cus-2	2b	A/C Mode	2		



Accident and Incident Summaries

Injury Nil Damage Nil Phase In-Flight PIC Age 74 While competing in the NSW State Gliding Championships, the pilot infringed restricted airspace. The pilot was counselled and received a 1000 point penalty. R525 PARKES [H24] RESTRICTED AREA GND - 5000ft MSL UDER 4790ft MSL VER RADIO TELESCOPE

Date	14-Dec-2017	Regior	า		GQ		SOA	AR Repo	ort Nbr		S-	1177
Level 1	Operational		Leve	el 2	Mis	cellar	eous	;	Level	3	Other Mise	cellaneous
A/C Mod	el 1		AS	5K-21	lMi		A/C	Model	2	N/A		
Injury	Nil	Dama	age		Minor	Pha	ise	Landi	ng		PIC Age	60
The glide	r suffered a mair	n wheel t	yre pı	uncti	ure while l	andin	gon	the mai	in bitur	nen r	unway. Inve	stigation
revealed	the inflation ster	n had sh	eared	l fror	n the inne	r tube	. The	reasor	n for th	s dan	nage was ur	determined
but thou	ght to be caused	by debri	s on t	he ru	unway.							

Date	14-Dec-2017	Region		GQ			AR Repo	ort Nbr		S-	1128
Level 1	Airspace		Level 2	Aircra	ift Sep	arati	on	Level	3	Near collis	ion
A/C Mod	el 1		LS 8	-18		A/C	Model	2	Zod	iac Ch 601 H	lds
Injury	Nil	Dama	age	Nil	Pha	ise	In-Flig	ght		PIC Age	29



Accident and Incident Summaries

The pilot of a Zodiac was conducting circuits onto the operational runway and observed three to four gliders operating from the airfield. On the Zodiac pilot's third circuit, and while transiting from crosswind to the downwind leg at a height of about 1200ft, a glider was observed thermalling in the circuit area at the same height. The Zodiac pilot made a broadcast of the CTAF advising they were entering downwind, while maintaining a visual on the glider. Just as the Zodiac pilot was about to conduct the pre-landing check list, the glider pilot turned out of the thermal and proceeded to cross in front of the powered aircraft at a similar height and passed within 100 metres. The Zodiac pilot did not need to take avoiding action and, upon landing, spoke with the gliding operation Duty Instructor and the glider pilot concerned. The glider pilot, who is very experienced, said they heard the Zodiac pilot's radio call but did not see the aircraft at any stage. It was also noted that the glider pilot was a visitor to the airfield and had not flown there in many months. The glider pilot stated: "I did not see him at all. I am quite disappointed with myself with this incident as I feel like I was keeping a very good lookout. I have spent the last day trying to understand how I missed it and it has been a big wake up call." The gliding CFI noted that the glider pilot, who was conducting the postmaintenance evaluation flight of a newly imported glider, may also have been distracted while using new and unfamiliar instrumentation. This near miss highlights the dangers of gliders operating in the vicinity of the live side of the circuit.

Date	15-Dec-2017	Region		VSA		SOA	R Repo	ort Nbr		S-	1125
Level 1	Operational		Level 2	Airc	raft Co	ontro	_	Level	3	Wheels up	landing
A/C Mod	el 1		Nimbus	s3dt		A/C	Model	2			
Injury	Nil	Dama	ge	Minor	Pha	se	Landi	ng		PIC Age	78
The glide	r landed on runv	vay 26 wit	h the un	dercarriag	e retra	cted	, suffer	ing min	or da	mage. The	command
pilot had	returned to the	airfield fro	om a 400	km cross-c	country	у соа	ching f	light. Co	ondit	ions during	the flight
were cha	Illenging, but there were good climbs to around 7,000ft and the pilots average 110kph around the										
task. Upon joining circuit, the pilots omitted to complete a pre-landing check and did not lower the											
undercarriage. The aircraft touched down on the grass runway and suffered minor abrasions to the lower									the lower		
fuselage.	It is not uncomr	non for pil	lots retur	ning from	a cros	s-col	untry fl	ight to l	becor	me focussed	l on the final
glide and	omit to configu	re the airc	raft for la	anding pric	or to jo	oining	g circuit	, and tl	hen fa	ail to compl	ete the pre-
landing c	hecks. Stress and	d fatigue a	re often	contributo	ory fact	tors.	When	nearing	the a	aerodrome,	pilots need
to transition from a 'soaring pilot' to a 'landing pilot' and configure the aircraft for landing. This includes									includes		
dumping	any water ballas	st, lowerin	g the und	dercarriage	e and s	settin	ng the f	laps. If t	these	actions are	completed
early, the	early, the likelihood of a mishap due to a failure to complete the pre-landing check list is reduced. For										
further g	uidance, refer to	Operation	nal Safety	y Bulletin ((OSB) C	01/14	1 – 'Circ	uit and	Land	ling Advice'.	

Date	15-Dec-2017	Regior	۱		SAGA		SOA	AR Repo	ort Nbr		S-	1153
Level 1	Operational		Lev	el 2	Mis	scellar	ieous		Level	3	Other Mise	cellaneous
A/C Mod	el 1			Discu	IS	iscellaneous Level 3 Other Miscella A/C Model 2 Phase Launch PIC Age 79 eges omitted to inform their CFI prior to flight						
Injury	Nil	Dama	age		Nil	Pha	ise	Launc	h		PIC Age	79
A pilot ex	ercising Level 1 I	ndepend	lent (Opera	ator privile	eges o	mitte	d to inf	orm th	eir CF	I prior to fli	ght (MOSP2,
Section 1	3.1.1 refers).											

Date	16-Dec-2017	Region GQ		GQ		SOA	AR Repo	ort Nbr		S-1122		
Level 1	Operational		Level 2	2 Airc	raft Co	ontro	j.	Level	3	Hard landi	ng	
A/C Mod	el 1		ASV	V 20F		A/C	Model	2				
Injury	Nil	Dama	age	Minor	Pha	ise	Landi	ng		PIC Age	56	
On comp	letion of a 3-hou	r flight, t	he glide	er was positio	oned f	or a l	eft circ	uit for t	the op	PIC Age 56		
weather	conditions gave a	quarter	ing tailv	wind, and thi	s was	expe	cted to	produ	ce soi	me turbulen	ice on final,	



Accident and Incident Summaries

so the pilot chose a to land with a higher speed than normal for the flap setting being used. The final approach, flare and round out was normal and no turbulence was detected. While the pilot was holding off about a metre above the ground, the starboard wing rapidly lifted, and the glider rolled left. The pilot used full aileron deflection to level the wings and the glider ballooned. Despite rapidly closing the airbrakes, the pilot was unable to prevent the glider touching down heavily. The undercarriage partially collapsed. Investigation revealed the glider was struck by a gust. The pilot's CFI noted that the "… contour of the buildings and other obstructions tend to exacerbate the effects noted on this day with that wind direction."

Date	17-Dec-2017	Region	1	NSWGA		SOA	AR Repo	ort Nbr		S-	1178
Level 1	Airspace		Level 2	. Aircra	ift Sep	arati	on	Level	3	Aircraft Se	paration
										Issues	
A/C Mod	el 1		Piper PA	-25-235		A/C	Model	2	Pipe	er Warrior	
Injury	Nil	Dama	age	Nil	Pha	ise	In-Flig	ght		PIC Age	

The glider towing combination was positioned on the glider runway to the left of the main runway. The glider pilot was conducting a solo flight. As the tow plane moved forward to take-up the slack in the tow rope, a Piper Warrior on a training flight was conducting a glide approach for a touch-and-go onto the main runway. The tow pilot was unaware of the position of the Piper Warrior, and the forward signaller had not sighted it on approach. Once the slack had been taken-up the forward signaller signalled "all out" to the tow pilot, who opened the throttle to commence the launch. The forward signaller sighted the Piper Warrior on short final just before the tow plane went passed and signalled the tow pilot to stop. Although the tow pilot saw the 'stop' signal, they elected to continue the launch due to the speed of the combination and his belief that he had identified the reason for the stop signal. The glider pilot reported not seeing the stop signal. The CFIs from the Gliding and powered operations reviewed the incident and concluded:

- Aircraft on powered glide approaches can be difficult to spot due to the low altitude profile and non-standard pattern. These aspects make it more difficult to visually identify traffic leading to a scheduled gliding combination departure;
- Radio transmission density was high, and it is possible that the ground crew and pilots missed the Piper Warrior pilot's radio call.
- The decision of the tow pilot to continue the take-off was reasonable. It was assessed that the risk of the combination infringing the main runway during take-off was low when compared to the risk of the glider running into the back of the tow plane. The CFI of the powered operation noted: *"It is not for us to utilise the safety management system to second guess (the tow pilot's) decision as the Pilot in Command using hindsight rather than supporting his command decision that resulted in a safer outcome based on his personal risk assessment for which he had seconds to make."*

Date	17-Dec-2017	Regior	n	VSA		SOA	AR Repo	ort Nbr		S-	1133
Level 1	Operational		Level 2	Run	iway E	vent	S	Level	3	Other Run	way Events
A/C Mod	el 1		LS 7-\	NL		A/C	Mode	2			
Injury	Nil	Dama	age	Minor	Pha	ase	Outla	nding		PIC Age	77
The expe	rienced pilot rele	pilot released from launch in a thermal and at the top of the climb headed off towards								towards	
some cur	cumulus clouds for another climb. Before reaching the clouds, the pilot turned back towards the										
airfield while the glider still had final glide. The pilot flew through sinking air and diverted to nearby hills in										arby hills in	
the searc	h for lift while st	aying in i	reach of s	uitable lan	ding a	reas.	The pi	ot stat	ed th	ey "tried to	determine
wind dire	ction from dams	and dus	t without	success." T	⁻he gli	der e	ncount	ered lif	t just	prior to the	e turn onto
final app	roach and the pi	ot made	several th	nermalling	turns	befor	re enco	unterir	ng sin	k. The pilot	resumed the
approach to the selected paddock, but a steep approach was necessary as the glider had drifted too close to									too close to		
the appro	oach boundary. 1	he pilot	tried to m	aintain the	e aimi	ng po	int by i	use of f	ull air	brake and e	elevator but
was unat	ole to prevent the	e speed f	orm build	ing-up. Th	e aircr	aft to	buched	-down	at spe	ed well into	o the



Accident and Incident Summaries

paddock. In order to avoid running onto the end fence, the pilot lowered the left wing to the ground and imitated a ground loop. The glider came to rest 25 metres from the fence. After exiting the glider, the pilot *"noticed that the wind direction had changed and was then a tailwind, although only a few knots."*

Date	18-Dec-2017	Regior	1 I	NSWGA SOAR R			R Repo	ort Nbr		S-	1123
Level 1	Operational		Level 2		Airfrar	ne Level 3		З	Fuselage/Wings/Empe		
										nnage	
A/C Mod	el 1		Piper PA-	25-235		A/C Model 2 N/A		N/A			
Injury	Nil	Dama	age	Nil	Pha	ase Launch			PIC Age	19	
While lini	While lining up for glider tow, the tow noticed in the mirror that the rear elevator inspection hatch was										
partially o	detached from tl	ne aircraf	t. The tov	v pilot parl	ked th	e tow	ı plane	and se	cured	the hatch.	The pilot
advised t	hat the hatch wa	as remove	ed to insp	ect the cor	ntrol c	ables	and su	irfaces	for th	e aircraft a	t the start of
the day a	s per the daily ir	spection	requirem	ents of CA	R Sch	edule	s 5 and	l 8. The	e pilot	t screwed al	I the screws
back in to	back in to what was believed to be a reasonable torque, but the front two screws worked loose during the										
day and parted company with the aircraft. The pilot replaced the missing screws and then tightened them											
more sec	urely.										

Date	18-Dec-2017	Regior	า	NSWGA SOAR Repo			ort Nbr		S-	1124	
Level 1	Operational		Level 2	Com	munic	atior	IS	Level 3		Other Com	nmunications
										Issues	
A/C Mod	el 1		DG-1(000S		A/C	Model	2	N/A	L.	
Injury	Nil	Dama	age	Nil	Pha	ise	In-Flig	ght		PIC Age	
Following take-off on a training flight, and at approximately 2000 feet AGL, the flight instructor noticed the											
radio had	been quiet for s	some tim	e. On ma	nipulation	of the	volu	me kno	b the i	nstru	ctor noticed	it had been
turned d	own. The volume	e was rea	djusted a	nd transmi	ssions	wer	e heard	l. Invest	tigatio	on identified	d that the
student p	pilot turned the r	adio volu	ime dowi	n so that th	e insti	ructo	r could	hear th	nem c	conduct the	pre take-off
checklist.	This incident oc	curred at	: a busy r	egional airp	ort th	at ha	is regul	ar publ	ic tra	nsport and p	powered
flight training operations, where radio alerted see-and-avoid is essential. Prior to flight, pilots must always											
ensure th	ne radio is on the	correct	frequenc	, that volu	me ar	ıd squ	uelch a	re corre	ectly s	set, and that	t the
micropho	one is positioned	for best	performa	ince.							

Date	18-Dec-2017	Regior	n	NSWGA		SOAR Report Nbr				S-1127		
Level 1	Operational		Leve	el 2	ŀ	Airfrar	me		Level 3		Fuselage/Wings/Empe	
											nnage	
A/C Mod	el 1		DG-1000S			A/C Model 2 N/A		N/A				
Injury	Nil	Dama	age		Nil	Pha	se	In-Flig	ght		PIC Age	76
During th	e pre-flight inspe	ection, th	ie stud	dent	pilot noti	ced ex	cessi	ve play	in the	tailpla	ane mountir	ng (the play
at the tai	at the tailplane tip was measured to be 10mm). The Flight Instructor confirmed this and grounded the											
aircraft. I	nvestigation ider	ntified th	at the	e Insp	pector who	o conc	lucte	d the d	aily ins	pectic	on earlier th	at morning
had dete	cted a small amo	unt of pl	ay in t	the t	ailplane b	ut con	sider	ed it to	be wit	hin lir	mits. Upon ı	removal of
the tailpl	ane, it was noted	l that the	e right	-har	nd locating	pin w	as lo	ose and	d could	be pa	artially rotat	ed with
fingers. T	he nuts on both	locating	pins w	vere	tightened	and t	he aiı	rcraft w	as retu	irned	to service.	The cause of
the nut b	the nut becoming loose was not determined but may have occured due to flight loading or an error in											
maintena	maintenance. It is important that aircraft are not flown with excessive play in the horizontal stabilser, as this											
can lead	to flutter and po	ssible str	uctura	al fai	ilure.							



Accident and Incident Summaries

Date	18-Dec-2017	Regior	gion NSWGA		١	SOAR Report Nbr				S-1163	
Level 1	Technical		Level 2 Powerp		plant/F	lant/Propulsion		Level 3		Transmission &	
										Gearboxes	
A/C Mod	A/C Model 1 Gr			ob G 103c Twin III SL			A/C Model 2				
Injury	Nil	Dam	age	Minor	Pha	ase Launch		PIC Age	70		
Shortly a	fter take-off and	l at a heig	ht of a	bout 300 ft	AGL, th	e pilo	ot of the	e self-la	unch	ing glider no	oticed a
change ir	n the engine not	e accomp	anied	by other no	ses. Su	spect	ing an e	engine	malfu	inction, the	pilot
switched	witched off the engine and safely conducted an off-field landing. Inspection revealed the engine drive belt										
had failed	had failed due to it being of a substandard quality. A replacement belt sourced from the manufacturer was										
fitted.											

Date 19-Dec-2017 Region SAGA SOAR Report Nbr S-11	175							
Level 1 Operational Level 2 Aircraft Control Level 3 Incorrect co	onfiguration							
A/C Model 1 ASK-21Mi A/C Model 2 N/A								
Injury Nil Damage Nil Phase Launch PIC Age !	55							
The aircraft had been involved in a winch launch failure during the initial ground roll. The student	t released							
the cable and applied the wheel brake, and the aircraft came to a stop about 10 metres down the runway.								
The ground crew elected to relaunch the aircraft from its new position. The student conducted the	he pre-flight							
checks and pre-launch challenge (CARD) as required and the aircraft was relaunched. During the in	initial							
ground run the instructor noticed the airbrake handle start to move back and moved it forward in	nto the							
locked position. The airbrake remained locked for the rest of the launch and the flight proceeded	l without							
further issue. During the post-flight debriefing, the student advised they had locked the brakes co	orrectly and							
also checked again on the pre-launch challenge. The instructor noted that the airbrake over-centr	re is quite							
strong, and the student may not have realised that the airbrakes were closed but not locked. Whe	en							
operated on the ground after the flight, the airbrakes did not exhibit any abnormal behaviour and no further								
issues were noted on subsequent flights. It is possible fatigue and heat issues may have contribute	ted to the							
incident. The Club's instructors will ensure students are well briefed on the force required to lock	k airbrakes.							

Date	23-Dec-2017	Region		GQ SOAR Report Nbr			S-1130					
Level 1	Operational	L	evel 2	Run	way E	vents Level 3		Runway excursion				
A/C Mod	el 1	Grob G	103A Twin II Acro		A/C	Model	2					
Iniury	Nil	Damage	a	Minor	Pha	ise	Landi	nø		PIC Age	76	

The sortie was a training flight involving a simulated outlanding on a section of the home airfield. The 'runway' was road between high grass that forms part of the perimeter track. During the ground roll, the main wheel caught in a rut and the glider ran off the starboard side of the 'runway'. The starboard wing caught in long grass, and the glider was turned through 90 degrees to the right. During the excursion the glider slid sideways for a period resulting in debris lodging between the tyre and hub of both the main and tail wheels. The main wheel inner tube was punctured, and the tyre later went flat. At this airfield the winds are predominantly from the east, so the club generally flies right-hand circuits. One of the Club's instructors likes to use a section at the far end of the runway for outlanding practice as it is not too familiar to the student. Upon review of this incident, the Club's Training Panel have decided not to conduct outlanding practice in this area in future but will use the cross strip, which is not often used.





Date	23-Dec-2017	Regior	۱	VSA SOA		SOAR Report Nbr		S-1136			
Level 1	Operational		Level 2	Grour	nd Ope	perations		Level 3		Other Ground Ops	
										Issues	
A/C Mod	el 1		Astir	CS		A/C Model 2					
Injury	Nil	Dam	age	Minor	Pha	ise	Grour	nd Ops		PIC Age	
Whilst de-rigging the glider, an inexperienced person was stationed on the right wingtip and was asked to											
hold it w	hile the left wing	g was rem	noved. It v	vas assume	ed the	pers	on was	familia	ar witl	n the proces	s, so they
were not	given a briefing	on what	to do. Wł	nen the left	t wing	was	remove	ed, the	perso	on on the rig	ht wingtip
was unpr	epared for the s	udden w	eight shift	and dropp	oed th	e win	ig. The	spa stu	ıb, wh	ich was still	in the
fuselage, angled upwards and damaged the wing carry-through structure. This incident serves as a reminder											
that complacency, making incorrect assumptions and not communicating effectively can easily lead to											
damage t	o equipment.										

Date	27-Dec-2017	Regior	۱ I	VSA		SOAR Report Nbr		S-	1131		
Level 1	Operational		Level 2		Airfrar	me Level 3		3	Landing	Landing	
										gear/Indic	ation
A/C Mod	el 1		LS 4	-a		A/C Model 2					
Injury	Nil	Dama	age	Minor	Pha	ase	Landi	ng		PIC Age	44
After a no	After a normal circuit and landing on the grass runway, the undercarriage collapsed during the ground roll.										
The botto	om of the fuselag	ge suffere	ed compr	ession crac	ks and	d full	thickne	ess pen	etrati	on of the co	mposite
structure	by small stones	, and the	undercar	riage door	s were	e bad	ly dama	aged. V	Vitnes	ses reporte	d the glider
was seen	on a stabilised a	pproach	with the	undercarri	age lo	were	d but c	ame to	rest	quickly after	r touching
down. In	down. Investigation revealed the undercarriage struts had failed, resulting in the undercarriage retracting										
back into the fuselage. The fuselage damage was repaired, new struts were fitted, and the aircraft was											
returned	to service.										



Date	27-Dec-2017	Regior	า	VSA	VSA SOAR Report		ort Nbr		S-	1139	
Level 1	Operational		Level	2	Airfrar	ne		Level 3		Landing	
										gear/Indic	ation
A/C Mod	lodel 1 LS 3-a			A/C Model 2							
Injury	Nil	Dam	age	Minor	Pha	se	Landi	ng		PIC Age	17
The pilot	The pilot had ballasted the glider to its maximum take-off weight with the intentions of completing a long										
cross-cou	intry flight. The a	ircraft w	as win	ch launched	with o	nly a	light he	eadwine	d, wh	ich coupled	with the
high wing	g loading resulted	d in a lau	nch to	only 1200ft A	GL. A	fter e	ncount	ering s	ink ar	nd nil lift, th	e pilot
elected t	o join circuit and	land. At	the tin	ne of touchdo	own, tł	ne gli	der was	s still fu	illy loa	aded with w	ater ballast.
The pilot	landed at a high	er speed	than u	isual to comp	ensate	e for t	the add	led wei	ght. S	hortly after	touching
down the	down the pilot noticed the glider decelerate more quickly than usual. Subsequent inspection revealed the										
tyre was	tyre was flat. It is believed the tyre probably moved on the rim during braking as a consequence of the heavy										
loading, r	esulting in the ir	iner tube	e tearir	ng near the va	lve.						

Level 1	Level 2	Level 3	Definition
Airspace	Aircraft Separation	Collision	An aircraft collides with another aircraft either airborne or on the runway strip, or a vehicle or person on the runway strip.
Airspace	Aircraft Separation	Issues	Airspace - Aircraft separation occurrences not specifically covered elsewhere.
Airspace	Aircraft Separation	Near collision	An aircraft comes into such close proximity with another aircraft either airborne or on the runway strip, or a vehicle or person on the runway strip, where immediate evasive action was required or should have been taken. (a) En-route (b) Thermalling (c) Circuit
Airspace	Airspace Infringement	Airspace Infringement	Where there is an unauthorised entry of an aircraft into airspace for which a clearance is required.
Airspace	Other	Other Airspace Events	Airspace occurrences not specifically covered elsewhere.
Consequential Events	Ditching	Ditching	When an aircraft is forced to land on water.
Consequential Events	Diversion / Return	Diversion / Return	When an aircraft does not continue to its intended destination, but either returns to the departure aerodrome or lands at an alternative aerodrome.
Consequential Events	Emergency / Precautionary descent	Emergency / Precautionary descent	<u>Emergency descent</u> - Circumstances that require the flight crew to initiate an immediate high rate descent to ensure the continued safety of the aircraft and its occupants.
Consequential Events	Emergency evacuation	Emergency evacuation	When crew and/or passengers vacate an aircraft in situations other than normal and usually under the direction of the operational crew.
Consequential Events	Forced / Precautionary landing	Forced / Precautionary landing	Forced landing – Circumstances under which an aircraft can no longer sustain normal flight and must land regardless of the terrain. Precautionary landing - A landing made as a precaution when, in the judgement of flight crew, a hazard exists with continued flight.
Consequential Events	Low Circuit	Low Circuit	Any occasion where a pilot flies a Low Circuit that was potentially hazardous.
Consequential Events	Other	Other Consequential Events	Consequential events not specifically covered elsewhere.
Environment	Weather	Icing	Any icing issue that affects the performance of an aircraft
Environment	Weather	Lightning strike	The aircraft is struck by lightning.
Environment	Weather	Other Weather Events	Weather occurrences not specifically covered
Environment	Weather	Turbulence/Windshear/Microburst	elsewhere. Aircraft performance and/or characteristics are affected by turbulence, windshear or a microburst.
Environment	Weather	Unforecast weather	Operations affected by weather conditions that were not forecast or not considered by the flight crew.
Environment	Wildlife	Animal strike	A collision between an aircraft and an animal.
Environment	Wildlife	Birdstrike	A collision between an aircraft and a bird. Wildlife related occurrences not specifically covered
Environment Operational	Wildlife Aircraft Control	Other Wildlife Events Airframe overspeed	elsewhere. The airspeed limit has been exceeded for the current aircraft configuration as published in the aircraft
Operational	Aircraft Control	Control issues	The flight crew encounter minor aircraft control difficulties while airborne or on the ground.
Operational	Aircraft Control	Hard landing	Damage occurs during the landing.
Operational	Aircraft Control	Incorrect configuration	An aircraft system is incorrectly set for the current and/or intended phase of flight.
Operational	Aircraft Control	In-flight break-up	The aircraft sustained an airborne structural failure or damage to the airframe, to the extent that continued flight is no longer possible.
Operational	Aircraft Control	Loss of control	When control of the aircraft is lost or there are significant difficulties controlling the aircraft either airborne or on the ground.
Operational	Aircraft Control	Other Control Issues	Aircraft control occurrences not specifically covered elsewhere.
Operational	Aircraft Control	Pilot Induced Oscillations	Any PIO occurrence occassioning damage.
Operational	Aircraft Control	Stall warnings	Any cockpit warning or alert that indicates the aircraft is approaching an aerodynamic stall.
Operational	Aircraft Control	Wheels up landing	An aircraft contacts the intended landing area with the landing gear retracted.

Operational	Aircraft Loading	Loading related	 The incorrect loading of an aircraft that has the potential to adversely affect any of the following: a) the aircraft's weight; b) the aircraft's balance; c) the aircraft's structural integrity; d) the aircraft's performance; e) the aircraft's flight characteristics.
Operational	Aircraft Loading	Other Loading Issues	Aircraft loading occurrences not specifically covered elsewhere.
Operational	Airframe	Doors/Canopies	When a door or canopy, or its component parts, has failed or exhibited damage.
Operational	Airframe	Furnishings & fittings	An internal aircraft furnishing or fitting, including its component parts, has failed or exhibited damage.
Operational	Airframe	Fuselage/Wings/Empennage	Damage to the fuselage, wings, or empennage not caused through collision or ground contact.
Operational	Airframe	Landing gear/Indication	When the landing gear or its component parts (including indications), has failed or exhibited damage.
Operational	Airframe	Objects falling from aircraft	Objects inadvertently falling from or detaching from an aircraft.
Operational	Airframe	Other Airframe Issues	Technical - Airframe occurrences not specifically covered elsewhere.
Operational	Airframe	Windows	A window or a component part has failed or exhibited damage.
Operational	Communications	Other Communications Issues	Communications occurrences not specifically covered elsewhere.
Operational	Communications	Transponder related	The incorrect setting of a code and/or usage of transponder equipment.
Operational	Crew and Cabin Safety	Cabin injuries	A cabin crew member or passenger has suffered an illness or injury.
Operational	Crew and Cabin Safety	Flight crew incapacitation	A Flight Crew member is restricted to nil or limited duties as a result of illness or injury.
Operational	Crew and Cabin Safety	Inter-crew communications	Relates specifically to a loss, or breakdown, of communication between flight crew or associated ground staff.
Operational	Crew and Cabin Safety	Other Crew and Cabin Safety Issues	Cabin safety occurrences not specifically covered elsewhere.
Operational	Crew and Cabin Safety	Passenger related	Where the actions of a passenger adversely or potentially affects the safety of the aircraft.
Operational	Crew and Cabin Safety	Unrestrained objects	When objects are not appropriately restrained for the aircraft operation or phase of flight.
Operational	Fire Fumes and Smoke	Fire	Any fire that has been detected and confirmed in relation to an aircraft operation.
Operational	Fire Fumes and Smoke	Fumes	When abnormal fumes or smells are reported on board the aircraft.
Operational	Fire Fumes and Smoke	Smoke	When smoke is reported to be emanating from: a) inside the aircraft; or b) an external component of the aircraft
Operational	Flight Preparation/Navigation	Aircraft preparation	Errors or omissions during the planning and/or pre-flight phase that affect or may affect aircraft safety in relation to: a) the aircraft's weight; b) the aircraft's balance; c) the aircraft's structural integrity; d) the aircraft's performance; e) the aircraft's flight characteristics.
Operational	Flight Preparation/Navigation	Lost / Unsure of position	When flight crew are uncertain of the aircraft's position and/or request assistance from an external source.
Operational	Flight Preparation/Navigation	Other Flight Preparation/Navigation Issues	Navigation - Flight planning occurrences not specifically covered elsewhere.
Operational	Flight Preparation/Navigation	VFR into IMC	An aircraft operating under the Visual Flight Rules enters Instrument Meteorological Conditions.
Operational	Fuel Related	Contamination	When the presence of a foreign substance is found in fuel.
Operational	Fuel Related	Exhaustion	When the aircraft has become completely devoid of useable fuel.
Operational	Fuel Related	Leaking or Venting	Relates specifically to the unplanned loss of fuel from a fuel tank or fuel system.
Operational	Fuel Related	Low fuel	The aircraft's supply of fuel becoming so low (whether or not the result of a technical issue) that the safety of the aircraft is compromised.
Operational	Fuel Related	Other Fuel Related Issues	Fuel related occurrences not specifically covered elsewhere.

Operational	Fuel Related	Starvation	When the fuel supply to the engine(s) is interrupted, but there is still usable fuel on board the aircraft.
Operational	Ground Operations	Foreign Object Damage/Debris	Any loose objects on an aerodrome have caused, or have the potential to cause, damage to an aircraft.
Operational	Ground Operations	Ground handling	Any ground handling and aircraft servicing that caused, or has the potential to cause injury or damage to a stationary aircraft.
Operational	Ground Operations	Jet blast/Prop/Rotor wash	Any air disturbance from a ground-running aircraft propeller, rotor or jet engine that has caused, or has the potential to cause, injury or damage to property.
Operational	Ground Operations	Other Ground Ops Issues	Ground operation occurrences not specifically covered elsewhere.
Operational	Ground Operations	Taxiing collision/near collision	An aircraft collides, or has a near collision, with another aircraft, terrain, person or object on the ground or on water during taxi.
Operational	Miscellaneous	Missing aircraft	The aircraft is reported as missing. Miscellaneous occurrences not specifically covered
Operational	Miscellaneous	Other Miscellaneous	elsewhere in this manual.
Operational	Miscellaneous	Rope break/Weak link failure	Towplane separation incident necessitating a modified circuit.
Operational	Miscellaneous	Rope/Rings airframe strike	Airframe struck by launch cable or rings. Includes entanglemt with rope.
Operational	Miscellaneous	Warning devices	Situations in which an aural or visual aircraft warning device activates to alert the flight crew to a situation requiring immediate or prompt corrective action.
Operational	Miscellaneous	Winch Performance Issue	Any incident caused by poor winch performance, such as power failure, or mechanical reasosn.
Operational	Runway Events	Depart/App/Land wrong runway	 An aircraft that: a) takes off b) lands, c) attempts to land from final approach d) operates in the circuit at, to or from an area other than that authorised or intended for landing or departure
Operational	Runway Events	Other Runway Events	Runway event occurrences not specifically covered elsewhere.
Operational	Runway Events	Runway excursion	An aircraft that veers off the side of the runway or overruns the runway threshold.
Operational	Runway Events	Runway incursion	The incorrect presence of an aircraft, vehicle or person on the protected area of a surface designated for the landing and take-off of aircraft.
Operational	Runway Events	Runway undershoot	Any aircraft attempting a landing and touches down prior to the threshold.
Operational	Terrain Collisions	Collision with terrain	Any collision between an airborne aircraft and the ground, water or an object, where the flight crew were aware of the terrain prior to the collision.
Operational	Terrain Collisions	Controlled flight into terrain (CFIT)	When a serviceable aircraft, under flight crew control, is inadvertently flown into terrain, obstacles or water without either sufficient or timely awareness by the flight crew to prevent the collision.
Operational	Terrain Collisions	Ground strike	When part of the aircraft drags on, or strikes, the ground or water.
Operational	Terrain Collisions	Wirestrike	When an aircraft strikes a wire, such as a powerline, telephone wire, or guy wire, during normal operations.
Technical	Powerplant/Propulsion	Abnormal Engine Indications	A visual or cockpit warning that indicates an engine is malfunctioning or operating outside normal parameters.
Technical	Powerplant/Propulsion	Engine failure or malfunction	An engine malfunction that results in a total engine failure, a loss of engine power or is rough running.
Technical	Powerplant/Propulsion	Other Powerplant/Propulsion Issues	Powerplant / Propulsion occurrences not specifically covered elsewhere.
Technical	Powerplant/Propulsion	Propeller malfunction	The failure or malfunction of an aircraft propeller or its associated components.
Technical	Powerplant/Propulsion	Transmission & Gearboxes	The failure or malfunction of an aircraft transmission/gearbox and/or its associated components.

Technical	Systems	Avionics/Flight instruments	The partial or complete loss of normal functioning of the avionics system or its components.
Technical	Systems	Electrical	The partial or complete loss of normal functioning of the aircraft electrical system.
Technical	Systems	Flight controls	The partial or complete loss of normal functioning of a primary or secondary flight control system.
Technical	Systems	Fuel	The partial or complete loss of normal functioning of the fuel system.
Technical	Systems	Hydraulic	The partial or complete loss of the hydraulic system.
Technical	Systems	Other Systems Issues	Technical - Systems occurrences not specifically covered elsewhere.