THE GLIDING FEDERATION OF AUSTRALIA



GFA AD 558

(ISSUE 2)

GFA AIRWORTHINESS DIRECTIVE

TYPE AFFECTED: DG-400, all Serial Numbers.

SUBJECT: Cracking of rear plate of propeller mount.

BACKGROUND: AD issued as a result of cracks found in one aircraft. Following

the discovery of cracks in several other aircraft the AD has been revised. The content of the AD is unchanged except that

periodically recurring inspections are now required.

DOCUMENTATION: DG-Flugzeugbau Technical Note No 826/42 and pages 0.3, 2A and

Diagram 6 of DG-400 Maintenance Manual form part of this AD.

ACTION REQUIRED: Proceed in accordance with the instructions in attached DG

Technical Note No 826/42.

WEIGHT AND BALANCE: Not affected.

IMPLEMENTATION: At the next 25 hour engine inspection, but in any case by 31

December 2001. Subsequent inspections must be performed at

each 25 hour engine inspection.

COMPLIANCE: The requirements of this GFA Airworthiness Directive are

mandatory. This Directive is issued pursuant to the Rules and

Regulations of the Gliding Federation of Australia.

SIGNED: John Viney For and on behalf of:

CHIEF TECHNICAL OFFICER AIRWORTHINESS

THE GLIDING FEDERATION OF AUSTRALIA

GFA AD 558 ISSUE: 2 11 August 2010 Page 1 of 1

DG Flugzeugbau GmbH 76646 Bruchsal

Technical Note

No. 826/42

Subject

: Powerplant / rear plate of the propellermount

Effectivity

DG-400 all serial no's

Accomplishment

: At the next 25 hour inspection, but at latest before December 31, 2001

Reason

: At one DG-400 cracks occurred in the rear plate of the propellermount starting at the outside diameter of the washer below the bolthead of the lower bolted connection.

page I from 1

Instructions

: Designation of parts see diagram 6 maintenance manual

1. Bolted connection of the rear plate of the propellermount 4M3 to the rear mounting blocks 4M5:

Remove the left mounting bolt and its washer first, if necessary heat the bolt to loosen the Loctite securing. Clean the plate in this area and check if the washer has left a mark in the plate and if cracks are visible. Cracks can be seen easily due to the oil residues which have penetrated into the crack. A mark of max. 0.1mm is acceptable. If the mark is deeper and / or if there are any cracks, the plate 4M3 has to be replaced. Check also the mounting blocks 4M5 for cracks and replace them if necessary.

Clean the inside threads according to the instructions on page 46d maintenance manual. Then assemble the new bolt M10x25 DIN912-8.8zn with the aluminium washer S48 next to the rear plate followed by the existing washer 10.5 DIN125 Stzn, use Loctite 243 or 672 (72b) to secure the bolt. Tighten the bolt with a torque wrench, torque 4 daNm (30 ft.lb.).

Proceed in the same manner with the right hand side bolt.

Note: Don't remove both bolts at the same time.

2. If the rear plate of the propellermount 4M3 or the mounting blocks 4M5 have to be exchanged proceed according to sections 4.6.4 and 4.6.5 of the maintenance manual.

3. Exchange the following maintenance manual pages against the new pages issued August 2001, marked TN 826/42: 0.3, 2a, diagram 6

Material

: Manual pages see instruction 3 2 bolts M10x25DIN912-8.8 zn

2 washers S48 if necessary:

rear plate of the propellermount 4M3

mounting blocks 4M5/1 and /2 (for starter motor Bosch American992807)

or 4M5/3 and /4 (for starter motor Bosch DG 0001160001)

Weight and balance

: influence negligible

Remarks

: Instructions No.1 and 2 are to be executed by the manufacturer or by a licensed workshop and to be inspected and entered in the aircraft logs by a licensed

inspector.

Bruchsal,

date: August 30. 2001

LBA - approved:

Author:

Dipl. Ing. Wilhelm Dirks

Wilhelm De

The German original of this TN has been approved by the LBA under the date of مولاً مولاً and is signed by Mr. Blume. The translation into English has been done

by best knowledge and judgement.

Type certification inspector:

Dipl. Ing. Swen Lehner

Swen Zelme

Instructions for continued airworthiness DG-400

	content	page	issued	Ē				
Diagrams								
1.	Elevator control circuit, adjust	ment	Febr.	87				
2. 2a	Rudder control circuit, undercar: Tail wheel	riage	July July					
3.	Aileron, flap and spoiler con- trol circuits, wheel brake		Febr.					
4.	Template for checking aileron de		Oct.	81				
5. 6.	Tow hook, water ballast release a Powerplant with Bosch electronic	_	April Aug.					
٠.	(for Ducati electronic boxes ref	er in	_	01.				
7.	addition to drawing 4 M 71 see expowerplant extension-retraction	nclosure) April	88				
8.	mechanism Fuel system		April	۵۵				
9.	Electrical system		July					
10.	Empty weight centre of gravity re	ange	Aprīl					
	Placards		June					
	Installation brake motor (Option		Sept.					
13.	Electrical system with Option BE	A.	Sept.	90				
Encl	osures							
	allation sketch EFWK "landing gea	r doors"						
	ing W 33 special wrenches		March					
	ing W 34 " "		March					
Installation sketch EFK additional tow hook Oct. 85 for aerotow								
Installation sketch EOD Dräger oxygen system July 7,84								
Inst	allation sketch 4EP ELT (3) ELT Po	ointer :	May 6	,91				
	llier Instructions for the mainter 0.01 A	nance	01	/89				
	ing 4 M 71 ducati ignition boxes		April	92				
Service-information 0-2/92 March 9								
	ice-information 0-4/92		Nov.	92				
	26/34 incl. Working instructions		Oct.	96				
No. 1 and No. 2								

Maintenance manual

DG-400

Manual amendments

No.	Page	Description	Date	Signature
32	0.3, 2a,	Powerplant	August	"
L	diagram 6	TN 826/42	01	

