GFA SOUNDED 1948	AIRWORTHINESS DIRECTIVE
	THE GLIDING FEDERATION OF AUSTRALIA Inc
	GFA AD 482 Issue 2 Date: 2 May 2019
C4/1-13 THE GATEWAY, BROADMEADOWS VICTORIA 3047 PHONE +61 (0) 3 9359 9865, FAX +61 (0) 3 9359 1613. ABN: 82 433 264 489	Note: This Airworthiness Directive is issued by the Gliding Federation of Australia
Type Certificate Holder	SZD Jezow
Manufacturer(s)	PZL Bielsko
Types/Models Affected	SZD-9bis Bocian 1D and 1E
Serial Numbers	All
Subject	Replacement Of The Wing Drag Fittings
Implementation	MANDATORY
Background	Factory fatigue testing has shown that the wing drag fittings are fatigue critical item.
	Issue 1 of AD 482 mandated replacement of the rear spar fittings in accordance with PZL Bielsko Bulletin BE-18/9bis/80 Bocian at 1,200 hours.
	Since Issue 1, the supply of new rear fittings has ceased and are unavailable. Issue 2 of AD 482 allows for an alternate means of compliance without replacing the rear fitting and carrying out ongoing inspections and restricting the aircraft to nil aerobatics. This limits the aircraft to typical operational stresses to less than 4 g which greatly extends the fatigue life of the wing rear fittings.
Documentation	 PZL Bielsko Bulletin BE-18/9bis/80 Bocian. GFA AD 158 Issue 2 dated 7 Apr 1998
Required Action(s)	1. For gliders which have less than 1,200 hours time in service the wing drag fitting must be replaced upon reaching 1200 hours.
	Gliders with more than 1,200 hours must have the wing drag fitting inspected in accordance with the requirements of GFA AD 158 Issue 2 before next flight. Inspection of the fittings may be performed by persons rated for Annual Inspections any type.
	If no cracks are found the part may continue in service until the next annual inspection when they must be replaced. If cracks are

found then the fitting must be	e replaced before next flight.
	nt of the fittings is available from the r Enclosures 1 and 2 for Bulletin BE-
Replacement of the fitting mu for Major Repairs Wood.	ust be performed by persons rated
hours and the replacement fi	ance : Gliders with more than 1200 ittings are unavailable. Create a new e 1 and apply it to the front cockpit ar instrument panel if fitted).
NO AI	EROBATICS
	d Spins Permitted)
AD 482 Issue 2	a Spins Fernittea)
Create a new cockpit allowab	rument Panel Placard
Figure 2 and apply them to the	he front and rear cockpit.
VH-XXX MAXIMUM FLI	GHT SPEEDS KNOTS IAS AD 482-2
Winch Launch Vw	62
Aero Tow Vt	75
Manoeuver Va Max Rough Air Vr	70 70
Air Brake Opening	97
Air Brake Full Open	97
Dive Smooth Air Vne	108
NO AER	OBATICS ALLOWED
WEAK LINK: AERO / WINCH / AUT	[0 600 kg
AERO TOW OFF NOSE RELEASE	WINCH / AUTO TOW OFF BELLY RELEASE
Figure 2: Allow	vable Airspeed Placard
	000 hours time in service: Enter an
	nce Release (Form 1) to inspect the ordance with the requirements of
	20 hours / 400 landings or the next
Annual Inspection (whicheve under GFA AD 158 Issue 1.	r is first) since the last inspection Inspection of the fittings may be for Annual Inspections any type.
Annual Inspection (whicheve under GFA AD 158 Issue 1. performed by persons rated 1 For aircraft with more than 3,	er is first) since the last inspection Inspection of the fittings may be

	GFA AD 158 Issue 2 every 60 hours / 200 landings or the next Annual Inspection (whichever is first) since the last inspection under GFA AD 158 Issue 1. Inspection of the fittings may be performed by persons rated for Annual Inspections any type.
Compliance, Compliance Time(s) and Frequency	Compliance with this Airworthiness Directive is mandatory and immediate on receipt of this AD. Compliance, including ongoing inspections taken pursuant to this Airworthiness Directive must be recorded in the aircraft log book.
	Compliance must be before next flight.
Effect on Weight and Balance	No effect on W&B.
Issuing Authority	Issued for and on behalf of The Gliding Federation of Australia Inc.
	Signed:
	B
	GFA Chief Technical Officer
Effective Date	2 May 2019