

## GFA AIRWORTHINESS DIRECTIVE

- TYPE AFFECTED:** Stemme powered sailplanes with light metal (aluminium alloy) control rods, as follows;  
S10-V, serial numbers 14-004 to 14-030, 14-042M and 14-047M;  
S10-VT, S/Ns 100-001 to 11-063, except for 11-002 and 11-009.  
Note: S10 models are affected if they have had light metal control rods fitted as a result of modifications after repairs, otherwise they are not affected.
- SUBJECT:** Checking of the curled or pressed ends of light metal control rods for visible cracks.
- BACKGROUND:** Cracks have been discovered in the ends of light metal control rods with curled or pressed ends in the area of the beading. See attached Service Bulletin.
- DOCUMENTATION:** Stemme Service Bulletin A31-10-059 (with compliance date extended to 31 October 2002) and Inspection Record D23-10S-001 form part of this AD.
- ACTION REQUIRED:** Carry out and record inspections as required by the above two Stemme documents.
- WEIGHT AND BALANCE:** Not affected.
- IMPLEMENTATION:** Within 100 flight hours, but in any case not later than 31 October 2002.
- COMPLIANCE:** The requirements of this GFA Airworthiness Directive are mandatory. This Directive is issued pursuant to the Rules and Regulations of the Gliding Federation of Australia.

SIGNED:

SENIOR TECHNICAL OFFICER AIRWORTHINESS

For and on behalf of:

THE GLIDING FEDERATION  
OF AUSTRALIA

<b>STEMME</b> F & D LBA.NSD.005	<b>Service Bulletin</b>		Document Number: <b>A31-10-059</b>
	<b>Inspection of control rods for cracks</b>		Am.-Index: 01.a
			Page: 4 of 5

This Service Bulletin provides from page 1 to 3 the original version in German, approved by the Luftfahrt-Bundesamt, and from page 4 to 6 a translated version in English. The translation has been performed to the best of our knowledge and judgement.

## 1 Subject:

Control of all light metal control rods in the area of the curled or pressed end-pieces for visible cracks.

**Note:** Light metal control rods can be identified by their yellowish-green colour as a result of their surface protection (anodisation). In comparison, the steel rods are either plain metallic or painted grey and carbon fibre rods are black.

## 2 Affected Powered Sailplane:

Type STEMME S10, models S10, S10-V and S10-VT / LBA Type Certificate No. 846, FAA Type Certificate: G58EU and G06CE.

All S/N with light metal control rods are affected:

- model S10-V: 14-004 up to 14-030, 14-038M, 14-042M and 14-047M,
- model S10-VT: 11-001 up to 11-063, excluded 11-002 und 11-009, as well as
- all other S/N of all models, including model S10 (S/N 10-xx), which have received new control rods in the result of repairs (i.e. new tail boom ==> see individual Maintenance Manual of the affected s/n).

**Note:** As part of repair works and / or replacement of the tail boom, light metal elevator control rods with the STEMME-part no. 10SH-LA have been built into the serial numbers 14-038M, 14-042M and 14-047M. No other control rods in these serial numbers are affected.

All curled / pressed end-pieces of the control rods of the following model are to be inspected:

- airbrake control rods: 10SB-RMA; 10SB-RMB; 10SB-RML; 10SB-RMR; 10SB-TIA
- elevator control rods: 10SH-LA; 10SH-RMA; 10SH-RMB
- aileron control rods: 10SQ-RMA; 10SQ-RMB; 10SQ-RMD; 10SQ-RVA; 10SQ-RVB; 10SQ-TA06; 10SQ-TAS; 10SQ-TAV; 10SQ-TIS
- Flap control rods: 10SW-RMD; 10SW-TIS, 10SW-TI05

**Note:** The CFRP- control rods in the airbrake control (Stemme-part number: 10SB-TIG) are not affected.

## 3 Time of compliance:

The mandatory inspections which are described in this SB must be performed within the next 100 flight hours, not later than march, 31. 2002.

## 4 Background Information:

The following types of individual cracks with a depth of between 0.08 in. and 0.39 in (2mm and 10mm) have been discovered on the light metal control rods with curled or pressed end-pieces in the area of the beading:

- Across the control rod: usually on the sides, but also in the dip of the compression. In the case of compressions, cracks usually in irregular / extremely cruciform compressions.
- Alongside the control rod: in the compression area, usually on the peak of the compression.
- *Longitudinal grooves on the surface, which look like a crack. They occur during the drawing process of the manufacture of the half-finished product and do not play a significant role in safety.*

The possibility cannot be safely eliminated that any existing deep cracks can increase in size and depth during the operation of the aircraft (e.g. as a result of high levels of stress and / or corrosion). It is for this reason that affected light metal control rods must be controlled and, if a defect is found, they are to be replaced.

It is not expected that new cracks will form in previously perfect control rods during the operation of the aircraft; therefore, a single, thorough control carried out in accordance with this SB is sufficient.

<b>STEMME</b> F & D LBA.NSD.005	<b>Service Bulletin</b>		Document Number: <b>A31-10-059</b>
	<b>Inspection of control rods for cracks</b>		Am.-Index: 01.a
			Page: 5 of 5

## 5 Actions:

### 5.1 Inspections:

A control of the curled / pressed end-pieces of the control rod takes place as part of routine maintenance works in accordance with the maintenance manual S10 and models (see control of model 2b / annual inspection in the maintenance manual S10-VT / or every 100 hours / annual inspection in maintenance manual S10 and S10-V); therefore at least once a year.

As part of this SB, one single, thorough inspection of the curled or pressed end-pieces of the control rods is to be carried out in accordance with the specified inspection report D23-10S-001, after which normal controls will be carried out in accordance with the specifications in the maintenance manual.

Furthermore, due to the cracks discovered, it is once again highlighted that the normal, routine control of the end-pieces of the control rods must be carried out carefully. This includes:

- The unscrewing of the ventilation slots on the plain flaps and ailerons, in order to control the wing with a lamp and mirror, and
- The opening of the control hole in the tail tube.

### 5.2 Modifications to the Manuals:

None.

## 6 Mass and balance:

Not affected.

## 7 Material:

- magnifying glass, lamp and mirror
- endoscope wich is suitable for the realisation of the SB:
  - stiffness borescopes with a rod diameter  $\leq 0.2$  in.(5 mm); line of sight 75-90°; visual field angle: at least 55°, with rotating rod,
  - Flexoscope with a rod diameter  $d \leq 0.2$  in (5 mm) is conditionally suitable ; with diameter  $d > 0.2$  in. (5 mm) is not suitable,
  - in result of their larger diameter are tilt prisma-borescopes conditional suitable,

If used a modern endoscope is a enlarger not necessary. A magnification up to twentyfold is realized in the dependance from the distance to the inspected object.

## 8 Associated documents:

The following documents are required for inspection:

Item	document number	type of document	title of document
1	D23-10S-001 / 01.a	inspection report	inspection report light metal control rods
2	A40-1x-xxx	maintenance manual	maintenance manual

## 9 Accomplishment and log entry:

An for the inspection euiped authorised mechanic may carry out the actions described in this Service Bulletin and must be checked and entered in the airplane's log book by a licensed inspector. The regulations on the keeping of service records must be adhered to.

**Note:** An aircraft maintenance organisation is normally euiped for the inspection. The Stemme service team is also euiped for an locally inspection. Please contact the service team via internet or phone for the coordination of the dates for inspection.

(End)

<b>STEMME</b> Entwicklungsbetrieb LBA.NSD.005	<b>Inspection record</b>		Dokumentnummer: <b>D23-10S-001</b>	
	<b>aluminium control rods according to SB A31-10-059</b>		Änd.-Index: 01.a	
			Seite: 3 (von 5)	

Serial No.:	Owner:	Date of inspection:	Inspector:
-------------	--------	---------------------	------------

No.	Cont of rod	Method of inspection	Result	Complaint		Sign
				YES	NO	
Cockpit section						
1.	10SQ-RVA	with magnifier, lamp and mirror				
2.	10SQ-RVB	with magnifier, lamp and mirror				
Frame section						
3.	10SB-RMA	with magnifier, lamp and mirror				
4.	10SB-RMB	with magnifier, lamp and mirror				
5.	10SB-RML	with magnifier, lamp and mirror				
6.	10SB-RMR	with magnifier, lamp and mirror				
7.	10SH-RMA	with magnifier, Lamp and mirror				
8.	10SH-RMB	with magnifier, lamp and mirror				
9.	10SQ-RMA	with magnifier, lamp and mirror				
10.	10SQ-RMB	with magnifier, lamp and mirror				
11.	10SQ-RMD (right)	with magnifier, lamp and mirror				
12.	10SQ-RMD (left)	with magnifier, lamp and mirror				
13.	10SW-RMD	with magnifier, lamp and mirror				
Tail boom						
14.	10SH-LA	inspection type A				
Center wing (TI) (right)						
15.	10SQ-TIS	with magnifier and lamp				
16.	10SW-TI05	inspection type B				
17.	10SW-TIS	wing root: inspection with magnifier and lamp; inside of the Center wing: inspection type C				
18.	10SB-TIA *1	with magnifier, lamp and mirror				
Center wing (TI) (left)						
19.	10SQ-TIS	with magnifier and lamp				
20.	10SW-TI05	inspection type B				
21.	10SW-TIS	wing root: inspection with magnifier and lamp; inside of the Center wing: inspection type C				
22.	10SB-TIA *1	with magnifier, lamp and mirror				



<b>STEMME</b> Entwicklungsbetrieb LBA,NSD.005	<b>Inspection record</b> <b>aluminium control rods according to SB A31-10-059</b>		Dokumentnummer: <b>D23-10S-001</b>
			Änd.-Index: 01.a Seite: 5 (von 5)
	Serial No.:	Owner:	Date of inspection:




Bild 1 / picture 1:  
 Beispiel eines signifikanten Anrisses in der Einrollung / example for a significant crack in the control rod