

GFA AD 591

(ISSUE 2)

GFA AIRWORTHINESS DIRECTIVE

TYPE AFFECTED:

All powered sailplanes fitted with Rotax engines as listed below -

912A to serial number 4,410.606; (correction of previous no:

4,414.606 Issue 1)

912F to serial number 4.412.858: 912S to serial number 4,922,971; 914F to serial number 4,420.394.

SUBJECT:

Replacement of the oil dipstick.

BACKGROUND:

The use of some modern oils can result in a slower return of oil from the crankcase to the oil tank under certain conditions. It is possible for this to cause the oil in the tank to fall below the minimum level. To help prevent this problem, the minimum level in the oil tank must be raised. This is achieved by a new dipstick with

new level marks

DOCUMENTATION:

Rotax Service Bulletins No SB-912-040 R1 & SB914-026 R1 form

part of this AD.

ACTION REQUIRED:

Carry out the actions required by the above-mentioned Service Bulletin. Note: Must now include the specified Operators and Maintenance Manuals Amendments, which weren't listed in Issue 1.

WEIGHT AND BALANCE: Increase of airframe weight of +0.4 Kg (0.88 Lbs). Moment of inertia may be affected depending on location of oil tank.

IMPLEMENTATION:

At the next oil change or within the next 100 hours of operation.

but in any case not later than 1 August 2003.

Note: The Rotax Service Bulletin requires a compliance date of 1 July 2003. However, as the bulletin did not arrive at the GFA Secretariat until mid-June, the compliance date is hereby extended to 1 August to allow a reasonable chance to order the new dipstick from the factory (ordering information is contained in the Service Bulletin). Revised bulletins arrived at the GFA 12 Sept 2003.

COMPLIANCE:

The requirements of this GFA Airworthiness Directive are This Directive is issued pursuant to the Rules and mandatory.

Regulations of the Gliding Federation of Australia.

SIGNED:

SEMOR TECHNICAL OFFICER AIRWORTHINESS

For and on behalf of:

THE GLIDING FEDERATION OF AUSTRALIA

GFA AD 591

ISSUE 2

17 September 2003

Page 1 of 5



SERVICE BULLETIN

INTRODUCTION OF A NEW OIL DIPSTICK FOR ROTAX, ENGINE TYPE 912 AND 914 (SERIES)

SB-912-040 R1 SB-914-026 R1

MANDATORY

Repeating symbols:

Please, pay attention to the following symbols throughout this document emphasizing particular information.

▲ WARNING: Identifies an instruction, which if not followed, may cause serious injury or even death.

■ CAUTION: Denotes an instruction, which if not followed, may severely damage the engine or could lead to

suspension of warranty.

◆ NOTE: Information useful for better handling.

1) Planning Information

1.1) Engines affected

All versions of the engine type:

- 912 A to S/N 4,410.606 - 912 F to S/N 4,412.858 - 912 S to S/N 4,922.971

- 914 F to S/N 4,420,394

1.2) Concurrent ASB/SB/SI and SL

Further to this Service Bulletin the following additional Service Instructions must be observed and complied with:

- SI-04-1997 Venting of lubrication system, current issue.

- SI-18-1997 Selection of motor oil and general operating tips, current issue.

- SI-27-1997 Oil level check, current issue.

- SI-912-010 Oil change, current issue.

- Si-914-011 Oil change, current issue.

1.3) Reason

It has been discovered, in some cases, that the new characteristics of some modern oils can result in a slower return of oil from the crankcase to the tank under certain conditions. This could possibly cause the oil tank level to fall to a level below the minimum. In order to help prevent this problem it is necessary to raise the minimum oil level in the tank. This is achieved by using a new dipstick with new level marks.

1.4) Subject

Introduction of a new oil dipstick for ROTAX, engine type 912 (Series) and 914 (Series).

1.5) Compliance

At the next oil change or within the next 100 hours of operation, but at the latest by July 1st 2003, the replacement of the oil dipstick must be conducted.

1.6) Approval

The technical content of this document is approved under the authority of MOT, DOA Nr. MOT. JA, 03.

1.7) Manpower

Estimated man-hours:

Engine installed in the aircraft --- manpower time will depend on installation and thus, no estimate is available from the engine manufacturer.

63120

П

AUGUST 2003

SB-912-040R1 SB-914-026R1

page 1 of 4

1.8) Mass data

change of weight - - - difference +0,4 kg (0.88 lb) for the airframe moment of inertia - - - affected depending upon the position of the oil tank in the airframe.

1.9) Electrical load data

no change

1.10) Software accomplishment summary

no change

1.11) References

In addition to this technical information refer to current issue of

- All relevant Service Instructions (SI)
- Maintenance Manual (MM)

1.12) Other publications affected

The following amendments will become effective with this Service Bulletin. The replacement pages have to be incorporated without delay into the respective documentation of the aircraft manufacturer:

Bezeichnung	TNr.	Ausg.	Datum	Rev.	Kapitel	Seite		
Operators Manual 912 Series	899370	0	1998 07 01	2	_			
Operators Manual 914 Series	899641	0	1998 12 01	2				
Maintenance Manual 912 Series	899372	0	1998 09 01	2				
Maintenance Manual 914 F	897812	0	1997 02 01	5				

1.13) Interchangeability of parts

- All old parts are stopped from further use and must be returned F.O.B. to a ROTAX_® Authorized Distributor or their Service Centers.
- Further sale, use or shipment of all old style oil dipstick part no. 956150 in inventory are prohibited and must these put be returned F.O.B. to a ROTAX_® Authorized Distributor or their Service Centers.
- All stored oil tanks must have the oil dipstick replaced by a new style dipstick,

2) Material Information

2.1) Material - cost and availability

Price and availability will be supplied on request by ROTAX, Authorized Distributors or their Service Centers.

2.2) Company support information

The damages or costs incurred, namely with respect to shipping costs, down time, loss of income, telephone
costs or costs of conversion to other engine versions or additional work, including simultaneous overhaul, are
not covered and will not be borne or reimbursed by ROTAX_e.

2.3) Material requirement per engine

Parts requirement:

In compliance with this Service Bulletin the following parts are required.

Fig.no.	New p/n	Qty/engine	Description	Old p/n	Application
(1)	956151	1	oil dipstick	956150	oil tank

2.4) Material requirement per spare part

None

2.5) Rework of parts

None

2.6) Special tooling/lubricant-/adhesives-/sealing compound - Price and availability

None

3) Accomplishment / Instructions

Accomplishment

All the measures must be taken and confirmed by the following persons or facilities:

- ROTAX_-Airworthiness representative
- ROTAX -Distributors or their Service Centers
- Persons approved by the respective Aviation Authority

▲ WARNING: Proceed with this work only in a non-smoking area and away from sparks or open flames. Switch off ignition and secure engine against unintentional operation. Secure aircraft against unauthorized operation. Disconnect negative terminal of aircraft battery.

▲ WARNING: Risk of scalds and burns! Allow engine to cool sufficiently and use appropriate safety gear while performing work.

▲ WARNING: Should removal of a locking device (namely lock tabs, self-locking fasteners) be required when undergoing disassembly/assembly, always replace with a new one.

◆ NOTE: All work has to be performed in accordance with the relevant Maintenance Manual.

3.1) Instructions

3.1.1) Replace of the oil dipstick

- Remove the oil dipstick part no. 956150 and replace by new oil dipstick part no. 956151.
- inspect the oil level to be performed SI-27-1997 "Oil level check", current issue.
- Add oil if necessary.
- ◆ NOTE: By changing the oil dipstick, the minimum oil level is raised by approx. 40 mm (1.57 in.) and the height between the "min." and "max." level is reduced to 30 mm (1.18 in.) (approx.0,45 litre).
- Restore aircraft to original operating configuration.
- Connect negative terminal of aircraft battery.

3.2) Testrun

Conduct test run including ignition and oil/coolant leak checks.

3.3) Summary


These instructions (section 3) have to be conducted in compliance with section 1.5.

◆ NOTE: The executed work are to be certified in the engine log book.

Approval of translation to best knowledge and judgment - in any case the original text in the German language and the metric units (SI-system) are authoritative.

4) Appendix

the following drawings should provide additional information:



♦ NOTE:

The illustrations in this document show the typical construction. They may not represent full detail or the exact shape of the parts which have the same or similar function.

Exploded views are **not** technical drawings and are for reference only. For specific detail, refer to the current documents of the respective engine type.