

# **GFA AD 597**

(ISSUE 1)

## **GFA AIRWORTHINESS DIRECTIVE**

TYPE AFFECTED: G 102 Club Astir II

S/No: 5001 up to 5061 (with suffix "C")

G 102 Standard Astir II

S/No: 5001 up to 5061 (with suffix "S")

G104 Speed Astir II

S/No: 4001 up to 4027

G104 Speed Act Jib Speed S/No: 4028 up to 4107

SUBJECT:

Modification of the Canopy Jettison System

BACKGROUND:

A Research Report issued by the College of Aachen has shown that utilization of the rear hinge will provide a simpler and more

effective means of jettisoning the canopy.

DOCUMENTATION:

Grob Service Bulletin No: MSB306-37/320-08, which forms part

of this AD.

**ACTION REQUIRED:** 

1. Replace the "CANOPY JETTISON AND EXIT" placard, located either on the RH canopy frame or seat shell with new

placards as shown in the Service Bulletin.

2. Remove the existing Canopy Jettison operating lever and cable

completely.

3. Insert Revisions into the Flight & Maintenance Manual.

WEIGHT & BALANCE:

No appreciable change

**IMPLEMENTATION:** 

Not later than 31 December 2003

COMPLIANCE:

The requirements of this GFA Airworthiness Directive are mandatory. This Directive is issued pursuant to the Rules and

Regulations of the Gliding Federation of Australia.

SIGNED:

SENIOR TECHNICAL OFFICER AIRWORTHINESS

For and on behalf of:

THE GLIDING FEDERATION OF AUSTRALIA

GFA AD Page 1 of 6 ISSUE: 1

LTA-Nr.: 2003-238



GROB Luft- und Raumfahrt Lettenbachstrasse 9 D-86874 Tussenhausen-Mattsies MSB306-37/320-08 Page 1 of 5 13 June 2003

## SERVICE BULLETIN NO. MSB306-37 MSB320-08

## I. TECHNICAL DETAILS

1.1 Category:

**MANDATORY** 

### 1.2 Airplanes affected:

TCDS-No. 306 (FAA TC No. G33EU):

G 102 CLUB ASTIR II

S/N 5001 - 5061 (with suffix "C")

G 102 STANDARD ASTIR II

S/N 5001 - 5061 (with suffix "S")

TCDS-No. 320 (FAA TC No. G33EU):

G 104 SPEED ASTIR II

S/N 4001 - 4027

G 104 SPEED ASTIR III

S/N 4028 - 4107

#### 1.3 Time of Compliance:

Not later than 31 December 2003

#### 1.4 Subject:

ATA-Code:

Modification of the Canopy Jettison System

#### 1.5 Reason:

A research report issued by the college of Aachen has shown, that the installation of a canopy joint, installed in the rear, represents the ideal solution for a canopy jettsion system. As such a canopy joint is already installed in the affected gliders, the canopy jettison system can be improved.



MSB306-37/320-08 Page 2 of 5 13 June 2003

#### **1.6 Concurrent documents:**

None

#### 1.7 Approval Note:

The technical information contained in this document has been approved under the authority of JAA Design Organization Approval No. LBA.NJA.008,

# 1.8 Accomplishment/ Instructions


1.8.1 A. At the RH canopy frame or seat shell the placard "Canopy jettison and Exit" must be replaced against the new placard (see manaul pages "Emergency Procedures"):

#### Canopy jettlson and exit

- a) Open the canopy, pull red canopy handles and turn 90° inwards!
- release the canopy,
  lift up the canopy with red handles to release canopy!
- c) unbuckle seat harness
- d) EXIT over left or right side
- e) Wait 1 3 seconds before pulling the rip cord

CAUTION: The canopy will be swept away by the wind force turning over the rear joint!

B. At the LH and RH canopy both placards "Canopy Catch" must be replaced by the new placards ("Canopy Catch + Emergency Jettlson"):





MSB306-37/320-08 Page 3 of 5 13 June 2003

- 1.8.2 The canopy jettison operating lever including operating cable must be removed as follows (refer to illustration on page 4):
  - remove the RH cockpit covering
  - remove bolt (37)
  - cut-off cable (57) and remove adjusting screw (48) and remove completely operating cable (64)
  - remove safety wire (69)
  - remove nut (49) and operating lever (27)
  - cut-off cable (57) from canopy joint
  - remove cable rest with socket (62) and nipple (23)
  - install RH cockpit covering
  - remove placard "Canopy Jettision" from canopy jettison operating lever



NOTE: The canopy can be removed for maintenance purposes by operating the red ball knob (58)

1.8.3 In the Flight and Maintenance Manuals the following revisions must be incorporated:

#### G 102 CLUB UND STANDARD II:

- Flight Manual:

Revision 3, 13.06.03

- Maintenance Manual:

Revision 1, 13.06.03

Italian issue:

- Flight Manual:

Revision 3, 13.06.03

Canadian Issue:

- Flight Manual:

Revision 3, 13.06.03

- Maintenance Manual:

Revision 2, 13.06.03

#### G 104 SPEED ASTIR II / IIb:

~ Flight Manual:

Revision 3, 13.06.03

\_....Maintenance Manual:

Revision 2, 13.06.03

#### 1.9 Repetitive Actions


None

#### 1.10 Mass (Weight) and CG:

negligible



MSB306-37/320-08 Page 4 of 5 13 June 2003





MSB306-37/320-08 Page 5 of 5 13 June 2003

## **II. PLANNING INFORMATION**

#### 2.1 Material & Availability:

- 1. The exchange pages for the manuals (format DIN A5) and the palcards according to 1.8.2 are attached to the Service Bulletin.
- 2. The removed parts (lever etc.) may be disposed.

#### 2.2 Special Tools:

**N/A** 

#### 2.3 Labour costs:

approx. 1 hour

#### 2.4 Reference documents:

N/A

#### 2.6 Credit:

N/A

## III. REMARKS

- 3.1 The correct execution of the instructions may be performed by a competent person and has to be certified in the logbook by an authorised inspector.
- 3.2 If you have sold your aircraft in the meantime, would you kindly pass this information on to the new owner and forward his address and aircraft S/N to us.
- 3.3 For questions and assistance please contact:

Rudi Vodermeier, Head of Product Support,

phone:

+49 8268 998139

fax:

+49 8268 998200

e-mail;

productsupport@grob-aerospace.de

Anerkannt durch Luftahrt-Bundesamt

Q 3. JUL. 2003

