



THE GLIDING FEDERATION OF AUSTRALIA

GFA AD 350

(ISSUE 5)

CANCELLED - REFER AD 512
GFA AIRWORTHINESS DIRECTIVE

(FOR CURRENT TBO REQUIREMENTS - REFER MOSP)

TYPE AFFECTED: All powered sailplanes fitted with Hoffmann variable pitch propellers.

SUBJECT: Time between overhaul of Hoffmann variable pitch propellers.

BACKGROUND: Hoffmann propeller have issued Service Bulletin E1U which lists the TBO of Hoffmann variable pitch propellers and becomes part of this AD.

DOCUMENTATION: Hoffmann Service Bulletin E1U and Hoffmann Technical Information E160 which form part of this AD.

ACTION REQUIRED: As described in Service Bulletin E1U.


WEIGHT AND BALANCE: Not Affected.

IMPLEMENTATION: Propeller removal and refitting to be carried out by the holder of an 1109 Airworthiness Authority authorised for this type of work.

Overhaul work must be done by the manufacturer or by an organisation holding a letter of approval for the individual type of propeller and the type of work required.

COMPLIANCE: The requirements of this GFA Airworthiness Directive are mandatory. This Directive is issued pursuant to the Rules and Regulations of the Gliding Federation of Australia.

SIGNED:


CHIEF TECHNICAL OFFICER AIRWORTHINESS

For and on behalf of:

©THE GLIDING FEDERATION
OF AUSTRALIA

GFA AD 350

ISSUE: 5

16 July, 1998

Page 1 of 6