



CANCELLED 26/09/2017

REFER MOSP SECTION 13 - SPECIFIC MAINTENANCE REQUIREMENTS

GFA AIRWORTHINESS DIRECTIVE

- TYPE AFFECTED:** Hoffmann variable pitch propellers, all models.
Used in but not limited to: Ximango AMT-200 AMT 200S; RF-5B Sperber; Grob G 109 and G 109 B; SF 25 C; H 36 Dimona; HK 36 TC, TS, TTC, TTS; ASK 14; IS-28M2; L 13 Vivat.
- SUBJECT:** TBO for Hoffmann variable pitch propellers.
- BACKGROUND:** To comply with the requirements for continued airworthiness, TBO are issued with this AD. All previous ADs issued on TBO of Hoffmann variable pitch propellers are hereby superseded (AD 350, AD 512 issues 1, 2 & 3).
- DOCUMENTATION:** Current version of Hoffmann Propeller Service Bulletin 61-10-03E 1AM is available from the Hoffman Propeller manufacturer's website or from the GFA secretariat on request.
- ACTION REQUIRED:** Amendment of the Maintenance Manual by the owner on receipt of latest SB.
- INTERPRETATION of SB:** In Table 2.4 some Hub models are shown with 1 or 2 sets of parentheses (), denoting that there may be 1 or 2 suffixes to the spec in the table. Likewise some Blade models show parentheses as a prefix. Example: HO-V629(R)-(1)/170FA is shown in the table as: HO-V() () 170 FA ,
- WEIGHT AND BALANCE:** Not affected.
- COMPLIANCE:** Ongoing maintenance has to ensure compliance with this AD. TBO hours listed in Hoffmann Propeller SB61-10-03E1AM current issue must not be exceeded. Calendar time overhaul requirements for each aircraft listed above may vary; refer to aircraft manufacturer's schedule. The requirements of this GFA Airworthiness Directive are mandatory. This Directive is issued pursuant to the Rules and Regulations of the Gliding Federation of Australia.

SIGNED:

GFA Chief Technical Officer

For and on behalf of:

THE GLIDING FEDERATION
OF AUSTRALIA