



AIRWORTHINESS ADVICE NOTICE

GFA AN 63

Issue 1

20.12.1983

Sheet 1 of 1

TYPE AFFECTED:

JANTAR SZD 38
SZD 38A

BACKGROUND:

Manufacturers Bulletin BK 019/83 states that the rubber clamps fastening the TM-4200 compensating vario flasks to the instrument panel floor may have deteriorated through age and lost their elastic property.

Rectification action - as outlined in pages 2 and 3 of the Manufacturer's Bulletin - available from GFA Secretariat.

NOTE: Jubilee clips may be used instead of the metal clamps recommended by the manufacturer.