

COMMONWEALTH OF AUSTRALIA  
DEPARTMENT OF TRANSPORT

AIRWORTHINESS DIRECTIVE GLIDERS:

G.F.A. A.D.116 Rolladen  
Schneider 78-162

GLIDER TYPE AFFECTED: LS 1 version f all serial numbers.

SUBJECT: Trim.

REASON: Wear of trim rod guide.

ACTION AND COMPLIANCE:

1. Within the next four weeks after the effective date of this A.D. unless already accomplished, the tolerance of trim rod guide must be checked in accordance with page 19 of the Service Manual and entered into checklist page 1-1.
2. If lateral play is more than 0.2 inches (5mm) the guide must be changed.
3. Page 19 edition 25/4/78 has been issued 28/6/78 G.F.A. A.D. 108.

TECHNICAL PUBLICATION OF THE MANUFACTURER:

Rolladen Schneider Technical Note No. 34 of March 25 1978.

This Technical Note becomes herewith part of this Airworthiness Directive and was issued 28/6/78 as G.F.A. A.D. 108 Rolladen Schneider T M 34.

ACCOMPLISHMENT AND LOG BOOK ENTRY:

Action may be accomplished by a person holding a G.F.A. Authorisation for the replacements of components on F.R.P. gliders. The work is to be entered in the aircraft's Log Book.

COMPLIANCE:

This directive is mandatory. This directive is issued pursuant to Air Navigation Regulations under the delegated authority of the Secretary of the Department of Transport.

DOUGLAS LYON

CHIEF TECHNICAL OFFICER AIRWORTHINESS

GLIDING FEDERATION OF AUSTRALIA.



Date of issue: 20th of September 1978.