

COMMONWEALTH OF AUSTRALIA
DEPARTMENT OF TRANSPORT

AIRWORTHINESS DIRECTIVE GLIDERS: G.F.A. AD/118 SCHLEICHER 6/ 78-303.

GLIDER TYPES AFFECTED: GERMAN TYPE CERTIFICATE No. 308.
ASW 19 serial numbers 19001 through 19232.
GERMAN TYPE CERTIFICATE No. 314.
ASW 20 serial numbers 20001 through 20113
except 20111.

SUBJECT:

Handhole cover in fuselage.

REASON:

Possible jamming of aileron and flap control by the handhole cover being pulled into the fuselage.

ACTION:

1. Tape the handhole cover in the fuselage carefully before every flight after effective date of this AD until accomplishment of action No. 2.
2. Unless already accomplished proceed in accordance with Technical note during the next annual inspection but not later than March 1979.

TECHNICAL NOTES OF THE MANUFACTURER:

1. Schleicher ASW 19 Technical Note No. 7 of September 11th 1978 and Schleicher ASW 20 Technical Note No. 4 September 11 1978 are not yet available from the Manufacturer and when to hand will be distributed in the form of an AD to all concerned.

COMPLIANCE:

This directive is mandatory. This directive is issued pursuant to Air Navigation Regulations under the delegated authority of the Secretary of the Department of Transport.



DOUGLAS LYON

CHIEF TECHNICAL OFFICER AIRWORTHINESS
GLIDING FEDERATION OF AUSTRALIA.

DATE OF ISSUE: 23rd of November 1978.

