

## AIRWORTHINESS ADVICE NOTICE

TYPE AFFECTED: LS-8a, LS-8-18

SUBJECT: Miscellaneous airworthiness information.

BACKGROUND: Rolladen-Schneider Technical Bulletin No 8011 provides for -

(a) Various items to be updated in the Flight and Maintenance Manuals (towhooks and annual inspections are mentioned in TB 8011).

(b) Optional relocation of battery from the tail fin to the baggage compartment to provide a decrease in the minimum cockpit load.

Copies of Technical Bulletin No 8011 and amended Flight and Maintenance Manual pages are available from the GFA Secretariat. Owners/operators are requested to state whether LS-8a or LS-8-18 documentation is required. There are approximately 50 pages for each version.

SIGNED:

  
CHIEF TECHNICAL OFFICER AIRWORTHINESS



For and on behalf of:

**THE GLIDING FEDERATION  
OF AUSTRALIA**