

## DEPARTMENT OF TRANSPORT

Start &amp; Flug 2

## AIR TRANSPORT GROUP

Airworthiness Directive - Gliders

Reference GFA/Start & Flug  
2/74.

Glider Types Affected H101 SALTO for all serial numbers

Subject Modification to canopy locking mechanism for  
improved operating security.

Required Action

Polyamide (Nylon) stop blocks are to be added to both canopy fastening mechanisms as shown on Dwg. No. GFA/Start & Flug 2/74-101-14-34. Parts are supplied by Australian Distributor, E. Schneider Pty. Ltd.


Background

This modification arises out of Start & Flug Technical Note No. 101-8.

Compliance


The modification is to be carried out before any aerobatic manoeuvres are carried out and for operation in Normal Category before 30th September, 1974. Compliance is mandatory.

This Airworthiness Directive is issued under the Air Navigation Regulations and the delegated authority of the Director-General of Civil Aviation.



Douglas Lyon  
Chief Technical Officer Airworthiness  
Gliding Federation of Australia.

Date of issue 26.8.74.



Distribution: Registered owners/Operators