

COMMONWEALTH OF AUSTRALIA

DEPARTMENT OF TRANSPORT

AIRWORTHINESS DIRECTIVE - GLIDERS

GFA/AD103/LET KUNOVICE 12

MANDATORY BULLETIN L13/046

Glider Type Affected: L13 Blanik all serial numbers.

Reason:

To supplement allowance for elevator deflection.


Measures:

In the Technical Manual of the L13 sailplane (all editions)  
Part 1 - Technical description Chapter 1 - Sailplane  
Specification Para 2 permissible allowances- play (tolerance)  
adjustment of control surfaces change the (upward) elevator  
deflection in the text and the associated figure to read  
 $32^{\circ} + 2^{\circ}$  instead of  $32^{\circ}$ .

Compliance:

To be carried out by the operator on receipt of this bulletin.  
This directive is mandatory.

The directive is issued pursuant to Air Navigation Regulations  
under the delegated authority of the Secretary of the Department  
of Transport.



Douglas Lyon

CHIEF TECHNICAL OFFICER AIRWORTHINESS  
GLIDING FEDERATION OF AUSTRALIA

Date of issue: 4th May 1978

Distribution:

Owners/Operators L13 Blanik

C.T.O.s A& Ops.

R.T.O.s A& Ops.

A.T.O.

T.L.O.

Department of Transport

R. Pollard

G. Getto

R. Martin

D. Vanstan

G. Simpkins

C. Willis

B. McKenzie

S. Chappell

W. Thompson

J. Dewhurst

E. Schneider Pty Ltd.

C.R. Hurst

Riley Aeronautics Pty Ltd.

P. Ansell

G. Higginson