

THE GLIDING FEDERATION OF AUSTRALIA

BUILDING 130, WIRRAWAY ROAD, ESSENDON AIRPORT, VICTORIA 3041.

GFA/AD 241

ROLLADEN SCHNEIDER

Issue 1

4th October, 1982

Sheet 1 of 1

AIRWORTHINESS DIRECTIVE GLIDER/POWERED SAILPLANE

LEFER 1416 CERTIFICATE HOLDERS WEBSITE

TYPE AFFECTED:

GLIDER LS4 (all Serial Nos).

SUBJECT:

Amendment of the Maintenance Manual

BACKGROUND:

The Manufacturers Technical Bulletin No. 4009 provides upgrading of the maintenance manual to match current edition.

REQUIREMENTS:

Exchange or add pages 0-2, 3-3, 4-3, 5-1, 6-2, 13-2 dated 1.10.1982 to Maintenance Manual edition dated 1-1-81. (Pages attached)

COMPLIANCE:

The requirements of this Airworthiness Directive are mandatory. This Airworthiness Directive is issued pursuant to Air Navigation Regulations under delegated authority from the Secretary of the Department of Aviation.

M.P. BURNS.

Sule Burn

CHIEF TECHNICAL OFFICER AIRWORTHINESS GLIDING FEDERATION OF AUSTRALIA.