



GFA AIRWORTHINESS DIRECTIVE

CANCELLED 20.04.2017

REFER TYPE CERTIFICATE HOLDERS CURRENT DATA

TYPE AFFECTED: LS-8, model LS-8A **only**, all serial numbers.

SUBJECT: Extension of service time.

BACKGROUND: Tests have shown that the life of FRP sailplanes may be extended to 12000 hours based on a multi-stage inspection program. The Maintenance Manual of the LS-8A contains the procedure for the inspection program.

DOCUMENTATION: Luftfahrt-Bundesamt (LBA) Airworthiness Directive 2001-200 and Rolladen-Schneider Technical Bulletin No 8010 Edition 15 November 2000 form part of this AD.

ACTION REQUIRED: At the appropriate time, carry out inspection program as required by the Maintenance Manual.

WEIGHT AND BALANCE: Not affected.

IMPLEMENTATION: Before reaching 3000 hours total time in service.

COMPLIANCE: The requirements of this GFA Airworthiness Directive are mandatory. This Directive is issued pursuant to the Rules and Regulations of the Gliding Federation of Australia.

SIGNED:		For and on behalf of:	
CHIEF TECHNICAL OFFICER AIRWORTHINESS		THE GLIDING FEDERATION OF AUSTRALIA	
GFA AD 555	ISSUE: 1	13 July 2001	Page 1 of 4