

AIRWORTHINESS ADVICE NOTICE

TYPE AFFECTED: Janus CM.

SUBJECT: Miscellaneous airworthiness information.


BACKGROUND: This AN records airworthiness information that is useful to know.

APPROVED MODIFICATIONS:

To obtain copies of the relevant Technical Note contact the GFA Secretariat.

1. External power supply. Schempp-Hirth Technical Note 809-2 describes the optional installation of an external power connection for use in starting and ground operation.
2. Optional engine installation. Schempp-Hirth Technical Note 809-5 describes the optional installation of a Rotax 535 C engine for serial numbers 1 through 28.
3. Optional propeller installation. Schempp-Hirth Technical Note 809-6 describes the optional installation of the following propellers HO 11 H-HM-158 b 127, HO 11 H-HM-158 b 130 and MT 158 R 125 - 1A.
4. Wedekind safety sleeves. Schempp-Hirth Technical Note 809-11 describes the optional installation of "Wedekind" safety sleeves for safetying of L'Hotellier couplings instead of the conventional safety pins.
5. New ignition system. Schempp-Hirth Technical Note 809-12 describes the optional installation of a Ducati ignition system should the current system require replacement as the original system is no longer available.
6. Propeller mount diagonal struts. Schempp-Hirth has reissued Technical Note 809-1 allowing the replacement of the original aluminium struts with GFRP units. This Technical Note is valid for serial numbers 1 through 37.

SIGNED:


CHIEF TECHNICAL OFFICER AIRWORTHINESS

For and on behalf of:

THE GLIDING FEDERATION
OF AUSTRALIA