



## AIRWORTHINESS ADVICE NOTICE

**TYPE AFFECTED:** Hoffmann HO-V62 Propeller  
**SUBJECT:** Miscellaneous airworthiness information.  
**BACKGROUND:** Type Certificate Data Sheet (TCDS) EASA.P.065  
**PROPELLOR OVERHAUL PERIOD:**

Advice was sought from EASA on the applicability of Hoffman HO-V62 Propeller calendar overhaul periods. The EASA approved Airworthiness Limitation Section (ALS) of the Instructions for Continued Airworthiness, reference EASA.P.065, is published in the applicable Operation and Maintenance Manual of which this section is empty. Further, the Airworthiness Limitation Section in the Hoffmann HO-V62 Component Maintenance Manual (CMM) DO157B is also empty.

For powered sailplanes with the Hoffmann HO-V62 Propeller, operating on the GFA System of Maintenance (SoM) electing to use the Hoffmann TBO, the calendar overhaul periods are a recommendation and are not mandatory.

Any Hoffmann HO-V62 Propeller subject to an Airworthiness Directive (AD), eg AD 276, must follow the requirements of the AD.

**SIGNED:**

A handwritten signature in black ink, appearing to be a stylized 'B' followed by a long horizontal stroke.

CHIEF TECHNICAL OFFICER

For and on behalf of:

**THE GLIDING FEDERATION  
OF AUSTRALIA**