

AIRWORTHINESS ADVISORY NOTICE

GFA/AN/26 GROB 1

This AN arises out of GROB TM102-5.

SUBJECT:

Deviation of record of measurements Einstellbericht (rigging report).

EFFECTIVITY:

Sailplane Astir CS from Serial No. 1001 - 1437.

ACCOMPLISHMENT:

Record of measurement Einstellbericht (rigging report) should be corrected on or before next periodical inspection.

REASON:

Incorrect figure for the range of wing sweep back.

INSTRUCTIONS:

The aircraft operator should place Items TM102-5 with the aircraft paper titled "EINSTELLBERICHT".

Note:- Disregard that figure 0 + 20 found in the column titled "SOLL" and following the heading of "TRAGFLUGELPFEILUNG" (sweepback) insert for such deleted figure the following:-

0 + 20
0 - 40

MATERIAL: None

WEIGHT & BALANCE: No change

REMARKS: None



Douglas Lyon
CHIEF TECHNICAL OFFICER AIRWORTHINESS
GLIDING FEDERATION OF AUSTRALIA

Date of Issue: 20th July, 1977.

Distribution: All Astir CS owners
C.T.O.s A & Ops.
R.T.O.s A & Ops.
A.T.O.
T.L.O.
Department of Transport
R. Pollard
G. Detto
R. Martin
D. Vanstan
G. Simpkins
C. Willis
B. McKenzie
S. Chappell
W. Thomson
J. Dewhurst
E. Schneider Pty. Ltd.
C.R. Hurst
Riley Aeronautics Pty. Ltd.
P. Ansell
G. Higginson