THE GLIDING FEDERATION OF AUSTRALIA



GFA AD 283

(ISSUE 2)

CANCELLED 7.03.2016

REFER MANUFACTURERS CURRENT DATA

GFA AIRWORTHINESS DIRECTIVE

TYPE AFFECTED: ASW 20

ASW 20L ASW 20B ASW 20BL ASW 20C ASW 20CL

SUBJECT: Life Extension to 12000 hours and manual amendments.

BACKGROUND: Fatigue tests have shown that the service life of the ASW 20 series

gliders many be increased to 12000 hours provided that each

aircraft is subject to a multi stage inspection program.

DOCUMENTATION: ASW 20 Technical Note No. 39.

ACTION REQUIRED: 1. Before 31 December, 1998 the Operations or Maintenance

Manual must be updated as follows:

ASW 20 Operations Manual 40a, 40b, 401 & 40s
ASW 20L Operations Manual 44a, 44b, 44l & 44s
ASW 20B Maintenance Manual 57, 58, 59 & 71
ASW 20BL Maintenance Manual 57, 58, 59 & 71
ASW 20C Maintenance Manual 57, 58, 59 & 71
ASW 20CL Maintenance Manual 57, 58, 59 & 71

Pages are available from Alexander Schleicher or their Australian

agent. The current address for Alexander Schleicher is:

Alexander Schleicher GmbH & Co.

PO Box 60

D-36161 Poppenhausen

GERMANY

SIGNED: Jonathon Shand For and on behalf of:

©THE GLIDING FEDERATION OF AUSTRALIA

CHIEF TECHNICAL OFFICER AIRWORTHINESS

GFA AD 283 ISSUE: 2 17 July, 1998 Page 1 of 2

GFA AD 283	ISSUE: 2	17 July, 1998	Page 2 of 2

Ph + 49 6658 890 Fax + 49 6658 8940

2. The procedures in the amended manual pages must be followed to extend the service life to a maximum of 12000 hours.

WEIGHT AND BALANCE: Not affected.

IMPLEMENTATION: Amendment of the manuals may be performed by the Certificate

Holder.

Life Extension Inspections must be performed by persons rated for

Surveys FRP.

COMPLIANCE: The requirements of this GFA Airworthiness Directive are

mandatory. This Directive is issued pursuant to the Rules and

Regulations of the Gliding Federation of Australia.