

GLIDING FEDERATION OF AUSTRALIA

CANCELLED 3-10-2018

AIRWORTHINESS DIRECTIVE GLIDERS:

GFA/AD 167 GROB 12

Superseded by IN306-34 Refer TC Holders Website

GLIDER TYPES AFFECTED: ASTIR CS, ASTIR CS77, ASTIR CS JEANS

REASON: Revision to Page 20 to Flight Manual. Page 20 dated 26.7.79 shows the weights and moments of ailerons, elevator and rudder. These figures are relevant for repairs and repainting. In these cases the control surfaces have to be weighed and balanced in accordance with the described procedure.

Original rudder surfaces as installed in the sailplanes (Astir CS, Astir CS77, Astir CS Jeans) are within the tolerances and need not be checked.

ACTION: Replace existing page 20 with the new page 20 (dated 26.7.79) enclosed.

COMPLIANCE: The requirements of this Directive are mandatory and are to be carried out immediately.

This Directive is issued pursuant to Air Navigation Regulations under the delegated authority of the Secretary to the Department of Transport.

Douglas Lyon

DOUGLAS LYON
CHIEF TECHNICAL OFFICER AIRWORTHINESS
GLIDING FEDERATION OF AUSTRALIA.

Date of issue: 20.12.79