



GFA AIRWORTHINESS DIRECTIVE

TYPE AFFECTED: AMT 200 Super Ximango

SUBJECT: Amendment of Flight and Maintenance Manual

BACKGROUND: Manufacturer's revision of the AMT 200 Flight and Maintenance Manuals.

DOCUMENTATION: Aeromot revised pages of Flight Manual No. 200-07 and Maintenance Manual No. 200-13

ACTION REQUIRED: Before the next Form 2 inspection or 31 July 1999 (whichever occurs first) the Flight and Maintenance Manuals must be updated.

AMT 200 Flight Manual: Exchange Pages 0.2, 0.5, 0.6, 0.8, 2.6, 2.13, 2.15, 2.16, 3.2, 3.3, 5.2.

AMT 200 Maintenance Manual: Exchange Pages 0.1, 0.3, 0.4, 0.9, 1.37, 1.38. Add Pages 1.41, 1.42, 1.45, 1.46, 1.47, 1.48.

Pages may be obtained from the GFA Secretariat.

WEIGHT AND BALANCE: Not affected.

IMPLEMENTATION: Pages may be exchanged by the Certificate Holder.

COMPLIANCE: The requirements of this GFA Airworthiness Directive are mandatory. This Directive is issued pursuant to the Rules and Regulations of the Gliding Federation of Australia.

SIGNED:

CHIEF TECHNICAL OFFICER AIRWORTHINESS

For and on behalf of:

©THE GLIDING FEDERATION
OF AUSTRALIA