



CANCELLED 21/05/2019

GFA AIRWORTHINESS DIRECTIVE

TYPE AFFECTED: LS8, Version LS8a only, all serial numbers with English manuals.

SUBJECT: Amendment to Flight Manual.

BACKGROUND: A correction is required to the wing water tank filling sequence.

DOCUMENTATION: The attached Rolladen-Schneider Technical Bulletin No 8009 forms part of this AD.

ACTION REQUIRED: Exchange pages in the Flight Manual in accordance with the requirements of TB 8009.

WEIGHT AND BALANCE: Not affected.

IMPLEMENTATION: Before use of water ballast.

COMPLIANCE: The requirements of this GFA Airworthiness Directive are mandatory. This Directive is issued pursuant to the Rules and Regulations of the Gliding Federation of Australia.

SIGNED:		For and on behalf of:	
CHIEF TECHNICAL OFFICER AIRWORTHINESS		THE GLIDING FEDERATION OF AUSTRALIA	
GFA AD 540	ISSUE: 1	29 August 2000	Page 1 of 7