



AIRWORTHINESS DIRECTIVE

CANCELLED 8/01/2019
REFER TYPE CERTIFICATE HOLDERS CURRENT DATA

TYPE AFFECTED: LS4 Sailplanes

BACKGROUND: Rolladen Schneider Technical Bulletin 4015 details amendments to the LS4 Maintenance Manual. (Attached as Appendix to this AD).

ACTION REQUIRED: Exchange the original manual pages for pages dated 1/3/83, namely:

0-1, 0-2, 3-2, 6-1 and 14-1 to 14-11.

Exchange to be as soon as possible.

COMPLIANCE: The requirements of this Airworthiness Directive are mandatory. This Directive is issued pursuant to Air Navigation Regulations under the delegated authority of the Secretary of the Department of Aviation.

Issued by:

Chief Technical Officer,
Airworthiness

Date 1/8/83

For and on behalf of:

GLIDING FEDERATION OF AUSTRALIA

Sheet 1 of 1